

ASS. REC. BY:

REF: es/smo19001263/Usd3

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person): Ng Sui wei shun of

8MO

Date/Time: 21/1/19 @ 11:13am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 2673G

Insured:

at Workshop m/s

8ME Motor

Tel:

67476106

of

1 Kaki Blk Ave 6 #02-15

Policy No:

018MTPV01010193

Claim No:

CMTD1900449

Sum Insured:

Excess:

TBA

Waived

Make of Veh:

D.O.A. 18/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:41am @ 21/1/19

Person Contacted:

Pei Ying

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJR 2673G-X

22/1/19

Revert via merimen - repairer agree LS not exceeding \$3000/

23/1/19

Rece approved from Irene ex Waived by merimen

23/1/19

Informed Pei Ying CIA on LS not exceeding \$3000/ & Waived by email

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
To Inspect Vehicle No: 5JR 26736
at Workshop m/s Sue
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

N/S	O/S

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: 9800
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes- or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: net 3676
Vehicle: IN / OUT

Veh No: 5JR 26736 Yr Regn: 17/6/09
Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Hyundai / Avante or 159
Colour: Grey A/C: Insured / Std / Nil / NA
Sp. Reading: 166003 T/Ratio: Insured / Std / Nil / NA
Eng/No: _____
C/No: KMH0U41BR9u782525
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/60R15
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front 6 mm Rear 6 mm
R/Bal. 6 mm L/Bal. 6 mm
D.O.A. 18/1/19 D.O.I. 21/1/19
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>21/2/19</u>	<u>L7A6124</u> <u>5-ml</u> <u>2/5 \$3000 cashed with AHG</u> <u>(\$ 2,575.00 Red - 46%)</u>
RECEIVED 21 FEB 2019	

Date/Time, File Pass to? 21/02/19
1) Tyres
Date/Time, File Return to?
2) _____

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 5
Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:
Transportation: 250
16
Photos
Others
TOTAL 260

Report Format :
Lump Sum / I.B.I: (\$ 3,000/- 45)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: NGO SAU WEI SHAWN	Date: 22 Jan 2019

Preliminary Advice

Vehicle No	: SJR2673G	Accident Date	: 18/01/2019
Make	: HYUNDAI AVANTE	Policy No.	: D18MTPV01010193
Assignment Date	: 21/01/2019	Excess	: S\$0.00
Date of Inspection	: 21/01/2019	Est. Duration of Repair	: 5.00
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,355.00
Revised Amount	:S\$	3,544.80
Check Items (Estimated)	:S\$	854.70
Total	:S\$	4,399.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	9,800.00
COE / PARF Rebate	:S\$	6,124.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,676.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer agree on Lump Sum repair not exceeding \$3000/-

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jan 2019 Sendback Est	21 Jan 2019 10:48 \$5,355.00	21 Jan 2019 11:13 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	KUAN CHAU FOO, ID: S7863268B, Tel: +6582005229, Email: NOEMAIL		
Vehicle Reg. No.:	SJR2673G	Date of Loss:	18/01/2019 12:00 - :59 [115 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / CMTD1900449	Policy/Cover Note No.:	D18MTPV01010193 (Comprehensive)
		Excess:	
Repairer:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5202]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/01/2019]		
Driver/Custodian:	KUAN CHAU FOO (40 / Male), NRIC: S7863268B, Tel: +6582005229		
Adj Asg. Remarks:	FOR EXCESS & AUTHORISATION, PLEASE REFER TO THE HANDLER		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results,									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 23 January 2019 11:35 AM
To: peiyong@smemotor.com.sg
Cc: Sebastian Kong; SUR
Subject: SJR 2673G-DOA: 18/1/2019 (SOMPO OD)

Dear Pei Ying,

As instructed by our client , please proceed to repair the insured vehicle **SJR 2673G on Lump Sum Repair not exceeding S3000/- or which ever lower, (Excess WAIVED-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler on behalf of Shirley

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Sent Message

This mail is associated with :

SJR2673G (CMTD1900449)

OD

Jan 18 2019 12:00PM

[KUAN CHAU FOO]

SME Motor Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 01/02/2019 16:26 PM.
To shawn.ngo@sompo.com.sg
CC sur@lkkauto.com
Subject SJR2673G (CMTD1900449) OD

Hi Shawn,

Kindly inform the supplementary amount is \$ 220.00 and still within the repair limit.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SJR2673G (CMTD1900449)

OD

Jan 18 2019 12:00PM

[KUAN CHAU FOO]

SME Motor Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From Sampo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on **23/01/2019 09:35 AM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4399.50) - SJR2673G - Claim Handler: NGO SAU WEI SHAWN

Approved:4399.50:EXCESS IS WAIVED

DOCUMENTS SUMMARY

There are no documents.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

Price Range

Depreciation

2009

Vehicle Type

[Home](#) » [Used Cars](#) » [Direct Owners](#) » [Hyundai Avante 1.6A](#)

Resources

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)

Car Tyres



Hyundai Avante 1.6A

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)
[Share](#)

Car Details

Price **\$13,000**
Depreciation **\$14,630 /yr**
[View models with similar depreciation](#)
Reg Date **24-Jul-2009**
(6mths 2days COE left)

Manufactured **2009**
Mileage **260,000 km (27.4k /yr)**
Transmission **Auto**
Engine Cap **1,591 cc**
Road Tax **\$738 /yr**
Power **89.7 kW (120 bhp)**
[View specs of the Hyundai Avante \(2007-2011\)](#)
Curb Weight **1,264 kg**
Features -

Accessories -

Description **VICOM Inspection Passed On 23 July. Road Tax Renewed Till Jan 2019. PARF \$5667.**
COE **\$15,291**
OMV **\$11,333**
ARF **\$11,333**
Dereg Value **\$6,433 as of today (change)**
No. of Owners **4**
Type of Veh **Mid-Sized Sedan**
Category **PARF Car, Direct Owner Sale**
Availability **Available**
DIRECT OWNER
[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)

Posted on: 11-Jan-2019 | Last Updated on: 17-Jan-2019


**100% F
PAPERW
SUPPORT
BOTH BU
& SELLER**

Seller Information

Contact Person(s) **Cherie**
Contact No. **915531**
Enquiry ☐ [Email](#)

ESSENTIAL TRANSACTION

[» Indemnity form](#)
[» Receipt](#)
[» Ownership Transfer](#)

**GET HELP WIT
PAPERWORK**

sgCarMart Connect handles paperwork - send us your con and we'll help with **Car Loans & Ownership Transfer**. FRE Adverised Vehicles.

[Upload your 5](#)
[Read our 8 Step Guide for](#)

Useful Services

[Compare](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3268B
Vehicle Details	
Vehicle No.:	SJR2673G
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Jan 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	G4FC9U668782
Chassis No.:	KMH DU41BR9U782525
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,302.00
Original Registration Date:	17 Jun 2009
First Registration Date:	17 Jun 2009
Transfer Count:	0
Actual ARF Paid:	\$11,302.00 <i>5857</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jun 2019
PARF Rebate Amount:	\$5,651.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jun 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$11,690.00
COE Rebate Amount:	\$473.00
Total Rebate Amount:	\$6,124.00

The information contained herein is correct as at 21 Jan 2019

OK

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883
 Tel: 6747 6106 (6 Lines) Fax: 6744 2368
 Email: service@smemotor.com.sg Website: www.smemotor.com.sg
 Co. & GST Reg. No: 201119451E

INSURER: Sompoo Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	19/SP/OD-066 (01)
Policy No:	D18MTPV01010193	Date of Loss:	18/01/2019
Vehicle Reg. No.:	SJR2673G	Driveable?	
Driver Age/Info:	40 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KUAN CHAU FOO	Contact No:	+6582005229
Driver:	KUAN CHAU FOO		
Make/Model:	HYUNDAI AVANTE, 1.6 (A)	Vehicle Reg. Date:	17/06/2009
Vehicle Colour:	GREY	Chassis No:	KMH DU41BR9U782525
Engine No:	G4FC9U668782		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	VEHICLE B SUDDENLY STOP. I CAN'T STOP IN TIME AND HIT ONTO VEHICLE B REAR PORTION.		
Remarks:	VEHICLE IN.		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	3,575.00
Labour	60.00
Paintwork Labour	1,720.00
Towing	0.00
	0.00
Gross Total (S\$)	5,355.00
+ GST 7.00% (S\$)	374.85
Nett Amount (S\$)	5,729.85

This claim is handled by: CHIA PEI YING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 21 Jan 2019)

Parts: 143

HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SJR2673G/21/01/2019 10:48

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET <i>12</i>	0.00	0.00	*395.00 F <i>X</i>
2	1		*FRT BONNET LOCK <i>7w1</i>	0.00	0.00	*35.00 F <i>✓</i>
3	1		*FRT GRILLE <i>6uc</i>	0.00	0.00	*150.00 F <i>X</i>
4	4		*FRT GRILLE CLIP <i>1er</i>	0.00	0.00	*8.00 F <i>✓</i>
5	1		*FRT BUMPER <i>m/2e</i>	0.00	0.00	*200.00 F <i>✓</i>
6	2		*FRT BUMPER RETAINER <i>2er</i>	0.00	0.00	*30.00 F <i>✓</i>
7	10		*FRT BUMPER CLIP <i>1er</i>	0.00	0.00	*20.00 F <i>✓</i>
8	1		*FRT BUMPER LOWER GRILLE <i>7w1</i>	0.00	0.00	*35.00 F <i>✓</i>
9	1		*FRT BUMPER SPONGE <i>2, 3er</i>	0.00	0.00	*70.00 F <i>✓</i>
10	1		*FRT BUMPER REINFORCEMENT <i>3er</i>	0.00	0.00	*135.00 F <i>✓</i>
11	2		*FRT BUMPER BEAM (BELOW HEADLAMP) <i>1 1</i>	0.00	0.00	*44.00 F <i>X</i>
12	2		*HEADLAMP <i>1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2</i>	0.00	0.00	*410.00 F <i>1/2</i>
13	1		*HEADLAMP SUPPORT PANEL <i>3uc/1er</i>	0.00	0.00	*750.00 F <i>✓</i>
14	1		*AIRCON CONDENSER <i>3er/2er</i>	0.00	0.00	*550.00 F <i>✓</i>
15	1		*RADIATOR <i>3er/2er</i>	0.00	0.00	*280.00 F <i>✓</i>
16	1		*FRT BUMPER UNDER COVER <i>1 1</i>	0.00	0.00	*28.00 F <i>X</i>
17	2		*HORN <i>1 1</i>	0.00	0.00	*110.00 F <i>X</i>

F=Franchise part.

Sub Total (S\$)	3,250.00
+ Margin on L,N Items 10.00% (S\$)	325.00
Total Parts (S\$)	3,575.00

SME Motor Pte Ltd/SJR2673G/21/01/2019 10:48. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

2318
1-2518

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRT NUMBER PLATE	35.00 ✓
2	1	RADIATOR COOLANT	25.00 ✓
Sub Total (S\$)			60.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New	20.00 ✓
2	REMOVE & REFIX AIRCON AND GAS	New	100.00 ✓
3	LABOUR CHARGE	New	800.00 600
4	SPRAY PAINTING	New	800.00 600
Gross Labour Cost (S\$)			1,720.00

SME Motor Pte Ltd/SJR2673G/21/01/2019 10:48. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

4149.8
3329.

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883
Tel: 6747 6106 (6 Lines) Fax: 6744 2368
Email: service@smemotor.com.sg Website: www.smemotor.com.sg
Co. & GST Reg. No: 201119451E

(SUPPLEMENTARY)

INSURER: Sampo Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	19/SP/OD-066 (01)
Policy No:	D18MTPV01010193	Date of Loss:	18/01/2019
Vehicle Reg. No.:	SJR2673G	Driveable?	
Driver Age/Info:	40 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KUAN CHAU FOO	Contact No:	+6582005229
Driver:	KUAN CHAU FOO		
Make/Model:	HYUNDAI AVANTE, 1.6 (A)	Vehicle Reg. Date:	17/06/2009
Vehicle Colour:	Grey		
Engine No:	G4FC9U668782	Chassis No:	KMH DU41BR9U782525
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	VEHICLE B SUDDENLY STOP. I CAN'T STOP IN TIME AND HIT ONTO VEHICLE B REAR PORTION.		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS

	Amount
Parts	220.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	220.00
+ GST 7.00% (S\$)	15.40
Nett Amount (S\$)	235.40
+ Previous Estimates (S\$)	5,729.85

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Jan 2019)
Parts: 143 HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: SME Motor Pte Ltd/SJR2673G/31/01/2019 15:17
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RADIATOR FAN ASSY <i>che / gm</i>	0.00	0.00	*200.00 F
Sub Total (S\$)						200.00
+ Margin on L,N Items 10.00% (S\$)						20.00
Total Parts (S\$)						220.00

F=Franchise part.

SME Motor Pte Ltd/SJR2673G/31/01/2019 15:17. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after body painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

SME Motor Pte Ltd/SJR2673G/31/01/2019 15:17. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO19001263/USD3N2

Date: 21/02/2019

REFERENCE

Insured/Claimant: KUAN CHAU FOO Policy No: D18MTPV01010193
Date of Loss: 18/01/2019 Nature of Claim: OD Claim No: CMTD1900449

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR2673G
Make & Model: HYUNDAI AVANTE, 1.6 (A) Engine No: G4FC9U668782
Reg. Date: 17/06/2009 (Man. Year: 2009) Chassis No: KMHU41BR9U782525
Colour: Grey Odometer: 166003 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$9,800.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R15 Rear Tyre Size: 195/60R15
Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,795.00	2,769.80	1,025.20	27.01
Miscellaneous Items	60.00	60.00	0.00	0.00
Labour	1,720.00	1,320.00	400.00	23.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,575.00	4,149.80	1,425.20	25.56
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	5,575.00	3,000.00	2,575.00	46.19
+ GST 7.00/7.00% (S\$)	390.25	210.00	180.25	46.19
Nett Amount (S\$)	5,965.25	3,210.00	2,755.25	46.19

INSPECTION

Date of Assignment: 21/01/2019 Present Location: SME Motor Pte Ltd (Kaki Bukit)
Date Inspected: 21/01/2019 Inspected At: SME Motor Pte Ltd (Kaki Bukit)
1 Kaki Bukit Ave 6 #02-15, AutoBay @
Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 21 Feb 2019)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SJR2673G)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Repair	395.00 F	*- F
2	1		*FRT BONNET LOCK	Twisted	35.00 F	*35.00 F
3	1		*FRT GRILLE	Serviceable	150.00 F	*- F
4	4		*FRT GRILLE CLIP	Necessary	8.00 F	*8.00 F
5	1		*FRT BUMPER	Dented/Deformed	200.00 F	*200.00 F
6	2		*FRT BUMPER RETAINER	Bent	30.00 F	*30.00 F
7	10		*FRT BUMPER CLIP	Necessary	20.00 F	*20.00 F
8	1		*FRT BUMPER LOWER GRILLE	Twisted	35.00 F	*35.00 F
9	1		*FRT BUMPER SPONGE	Torn	70.00 F	*70.00 F
10	1		*FRT BUMPER REINFORCEMENT	Bent	135.00 F	*135.00 F
11	2		*FRT BUMPER BEAM (BELOW HEADLAMP)	Not Necessary	44.00 F	*- F
12	1		*HEADLAMP	O/s Cracked/N/s Serviceable	410.00 F	*205.00 F
13	1		*HEADLAMP SUPPORT PANEL	Buckled/Cracked	750.00 F	*750.00 F
14	1		*AIRCON CONDENSER	Bent/Punctured	550.00 F	*550.00 F
15	1		*RADIATOR	Bent/Punctured	280.00 F	*280.00 F
16	1		*FRT BUMPER UNDER COVER	Not Necessary	28.00 F	*- F
17	2		*HORN	Not Necessary	110.00 F	*- F
Supplementary #1						
18	1		*RADIATOR FAN ASSY	Cracked/Jammed	200.00 F	*200.00 F

F=Franchise part.

Sub Total (\$\$)	3,450.00	2,518.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	345.00	251.80
Total Parts (\$\$)	3,795.00	2,769.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRT NUMBER PLATE (Bent)	35.00	35.00
2	1	RADIATOR COOLANT (Necessary)	25.00	25.00
Sub Total (S\$)			60.00	60.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	20.00	20.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	100.00
3	LABOUR CHARGE	New	800.00	600.00
4	SPRAY PAINTING	New	800.00	600.00
Gross Labour Cost (S\$)			1,720.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >