rom (Person): Karen (an	ASSIGNMENT (Office)  of FCI Date/Time: 4pm@ 241/19		
stimated Cost;	Bill to:		
OD / TP/ WS / TP RES / OD RES / )			
o Inspect Vehicle No:	31 × 189 84 Insured: SHB 32-96M		
t Workshop m/s	Feesteh Auto Tel: 67465405		
flcook			
olicy No:	Claim No:		
Sum Insured:	Excess:		
Make of Veh:	D.O.A. 23/01/2019		
CA / REV / REP. / REV 24 HRS	11/61		
Pate/Time 4.12pm@24119	H.O.D. Endorsement		
11 110 3 7 111	Person Contacted: Vehicle IN OUT		
Date/Time Action/Instruction (	) Estimate		
28/1/19 Informed FCI pending est from repairer by email			
offilly informed for	Denoting est month repaired by chair		

08/11/13) Wei REF:	701/	
ASS. REC. BY: Mer. Cus		6
V A	SSIGNMENT	
From: Date:	Veh No: SJY/PJFY Yr Regn: 1/0	
Estimated Cost:	Type: M.Carl M.Cycle   Bus   Van   Lorry   Taxi   Prime Mover	
OD ITP INS ITP RES I OD RES I EVA I INV I MY	Truck/Trailer or 14/	
To Inspect Vehicle No:	Make Toyota Esting 0.02362	
at Workshop m/s	Colour Seige A/C: Insured / Std / NI / NA	
of	Sp.Reading / Std / NI / NA	
Insured:	Eng/No:	
Policy No.	CINO: 2 ACRED 0 11 4645	
Claims No.	Gen. Cond. Good / Fair / Poor / Burnt	
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or	
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or	
Make of Veh:	Modi: NII S/Rim I STD A/Rim or	
122 173 CO 113 CO	Tyre Size: F:	
(Policy Condition)	R:	
Remark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /	
repair at the time of inspection.	точо / уоко ог	
Bal, or Market Value: 3 4/C ·	Front Rear	
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal. mm	
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm	
Est Repairs: 7 days Res.: Yes or No	D.O.A. 23/1/19 D.O.I. 24/1/19	
Lum Sum: 70 % 3 Val.: Yes- or No	Survey held at	
Luin Sunt.	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or	
CA / REV / REP. / 24 HRS Que ( 4 Vehicle: If		
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.	
Date / Time   Action / Instruction	56 1 22// (22//2	
heur 61A 27A 20258	1405. 4 whi neft 13782	
10 11 10 11 10 10 10	with Alex (Red )4, 203.90, 7190	
5/5/17/2/2 2000 CONT. (MAX	who have the	
1 10 -000 D DUNG (ESH) 171	A: \$ 20,258 NV: \$ 13,742	
Note: mv: \$34k (ESt) [7]		
	RECEIVED 0 5 MAR 2019	
Curry Daniel Daniel Banari	Days Of Repair: 7 23×15=3	345
Cate/Time, File Pass to? : Preli. Report	Resurvey No. of Trip: 2 Survey Fee: 170+345	
1) : Final Report Date/Time, File Return to?	Transportation: 50	
Α	dd Fee:   Site Insp (\$ )S+RSS  50+30	
2) 5/3 - typst	: Interview (\$ ) Photos 80 134	
Report Format : cw	: Tech. Invs (\$ ) Others	
Lump Sum / I.B.I: (\$ 9600 2	:Weekend (\$ )	
	7dtx 19 799	



Auto Consultants Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

D19000644MFSH

Our ref:

CS/FCI19001275/Uvd3

DATE: 05/3/2019

The Motor Claims Department

MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

### INITIAL INSPECTION REPORT OF VEHICLE NO.SJY 1898U

We thank for your instruction on 24/1/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 24/1/2019 at the premises of M/s FASTECH AUTO PTE LTD


Workshop Estimate Amount	: S\$33,803.90	
Revised Estimate Amount	: S\$9,600.00 (LUMP SUM)	
"Check" Items Amount	:S\$	
Market Value	: S\$	
LTA Reimbursement Value	: S\$	
Nett Value	: S\$	

Description of Damage:

The vehicle sustained damages at the

rear portion

nearside



front


Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA

Licensed Appraiser



MS First Capital Insurance Limited Co. Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

#### MOTOR SURVEY ASSIGNMENT

Date

23-01-2019

Our Ref No. D19000644MFSH

Accident Date

23-01-2019

Claim Type. Third Party

Insured Vehicle

SHB3296M

Third Party Vehicle. SJY1898U

Survey Location

1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY

Contact Person.

NANCY LAM

Contact No.

67465405/67465405

Fax No. 67458520

Survey Type

WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

#### THIRD PARTY SURVEY REQUEST

Cc: Workshop

FASTECH AUTO PTE LTD

Attention, NIL

Cc : TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

KARENT

#### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

#### Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Tuesday, 5 March 2019 9:58 AM

To:

'CWS Motor Claims'

Cc:

'Karen Tan'; SUR

Subject:

RE: SURVEY ASSESSMENT - D19000644MFSH/1, SJY 1898U

Attachments:

SJY 1898U PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJY 1898U

Date of survey: 24/1/2019 Number of days: 7 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Monday, 28 January 2019 9:41 AM

To: 'CWS Motor Claims' < cwsmotorclaims@msfirstcapital.com.sg>

Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D19000644MFSH/1, SJY 1898U

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SJY 1898U on 24/1/2019.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 24 January 2019 4:49 PM

To: 'CWS Motor Claims' < cwsmotorclaims@msfirstcapital.com.sg>; assignments < assignments@lkkauto.com>

Cc: 'Karen Tan' < karentan@msfirstcapital.com.sg>; SUR < sur@lkkauto.com > Subject: RE: SURVEY ASSESSMENT - D19000644MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Thursday, 24 January 2019 4:00 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims < <a href="mailto:cwsmotorclaims@msfirstcapital.com.sg">cwsmotorclaims@msfirstcapital.com.sg</a>; Karen Tan <a href="mailto:karentan@msfirstcapital.com.sg">karentan@msfirstcapital.com.sg</a>;

Subject: PRI: SURVEY ASSESSMENT - D19000644MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software. www.avg.com

## Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Monday, 28 January 2019 9:41 AM

To:

'CWS Motor Claims' 'Karen Tan'; SUR

Cc: Subject:

RE: SURVEY ASSESSMENT - D19000644MFSH/1, SJY 1898U

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SJY 1898U on 24/1/2019.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 24 January 2019 4:49 PM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D19000644MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Thursday, 24 January 2019 4:00 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims < cwsmotorclaims@msfirstcapital.com.sg >; Karen Tan < karentan@msfirstcapital.com.sg >

Subject: PRI: SURVEY ASSESSMENT - D19000644MFSH/1

Dear Sir/Mdm,

We refer to the above reference. Please find attached the necessary documents for survey. Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards, Admin Team Claim Workflow System Motor Claims Department MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software. www.avg.com

#### SGCARMART.COM

Login Sign up

Submit (

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

**Photos** 

More Actions


Forum


Resources

Advanced



## MAVIVA ...you can go to any workshop you preferred!







Share











Company

#### Seller Information

	<ul> <li>dealer's pricelist</li> <li>47 vehs sold   23 vehs available</li> </ul>
Address	1 Bukit Batok Crescent #02-54
Location	Search cars nearby this location WCEGA Plaza
Office No	66848884

Zenith Automobile

Contact Person(s) Simon

98197237 88088825 George

## **Useful Services**



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.

Free Valuation



» more Financial info

0

Transfer Fee **Down Payment** 

Compare

\$25

\$14,340 (change) Maximum 70% Loan 🚱

https://www.sgcarmart.com/used\_cars/info.php?ID=789256&DL=1238

## SGCARMART.COM

Login Sign up

New Cars

**Used Cars** 

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

500+ dealers competed to buy my car!



- Sell ur Car for More Cash
- Highest Price or Get \$100 Free
- Get Paid Now, Handover Later

SELL YOUR CAR



Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD! 8/2016 Outback 2.5i L,5 Star Euro NCAP Rating



Market Cheapest \$88k,depre\$9.9k Yearly,5 Year Agent Warranty, Iowner, sta Grad A Quality Motor StarAd



Browse by Category

Post an Ad

V

Estima

Ways of Selling

Sort by Date Posted Advanced Search 🐹 ✓ 20 results/page ✓

Make

Model

Depreciation.

Reg Date

Eng Cap

Arry

Submit (

Status

Search Selection

6 vehicles

Estima

Advertiser Login

Any

Any

2010

Any

Available

Toyota Estima 2.4A Aeras G

\$47,500

\$14,470 /yr

21-Dec-2010

2.362 cc 150,000 km

MPV

Available

Rare 1 Owner Car! Luxury Specs! New Road Tax! New Tyres! Tip Top Condition! Hot Favorite Estima! Smooth Drive With Responsive Engine! Best Choice To Renew COE For Great New 10 Years! Hurry And Call No... Tags: 2010 Toyota Estima, 2010 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota

Posted: 24-Jan-2019

12-Apr-2010

2,362 cc

MPV

Available

Toyota Estima 2.4A X (New 10-yr COE)

\$69,800

\$6,970 /yr

Complimentary 6 Months Pre-Owned Warranty. 100% Genuine Mileage, Regularly Serviced And Maintained. 100% Accident Free, STA/VICOM Evaluation Welcome! Flexible And High Loan Packages Available, Trade-I...

Posted: 21-Jan-2019

Tags: 2010 Toyota Estima, 2010 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used

Toyota Estima 2.4A Aeras G

\$44,800

\$15,220 /yr

25-Oct-2010

2.362 cc

Just Arrived! Cheapest In The Market! CNY Fast Sales! Super Low Mileage Done By Non Smoker Previous Owner! 100% Loan Available! 100% Accident Free! High Trade In Available! Call Now For A Non Obligato...

Posted: 19-Jan-2019

Tags: 2010 Toyota Estima, 2010 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used



Toyota Estima 2.4A Aeras G

\$47,800

\$26,190 /vr

12-Mar-2010

2,362 cc

123,000 km

Available

Available

Monthly Installment \$1350, Guaranty Buy Back At \$30,000 After 14 Month.

Posted: 12-Jan-2019

Tags: 2010 Toyota Estima, 2010 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used



Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Estima 2.4A Aeras G

\$75,800

\$7,570 /yr

09-Jun-2010

2,362 cc

103.000 km

MPV

Available

(New 10-yr COE) Original Facelift Model, Don't Need To Worry About Inspection And Insurance Claim. Major Maintenance And Make Over Done With Fresh New Paint Done Up And Top Engine Overhaul. Nice 3 Digit Bidded Car Pl...

Tags: 2010 Toyota Estima; 2010 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used

TELMOM ID

Toyota Estima 2.4A X (New 10-yr COE)

Posted: 15-Dec-2018

\$73,800

\$7,370 /vr

08-Jan-2010

2,362 cc

MPV

Available

Reliable And Well Loved 8 Seater MPV Commonly Seen On The Roads! Most Durable And Efficient MPV! A Combination Of Space, Comfort And Elegance For Your Love Ones While On The Road! Different Bank/In Ho...

Posted: 24-Nov-2018 Tags: 2010 Toyota Estima, 2010 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota



# > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID:	6007B	
Vehicle Details		
Vehicle No.:	SJY1898U	
Vehicle to be Exported:	No	
Intended Deregistration Date:	24 Jan 2019	
Vehicle Make:	TOYOTA	
Vehicle Model:	ESTIMA 2.4X A	
Primary Colour:	Gold	
Manufacturing Year:	2010	
Engine No.:	2AZF397432	
Chassis No.:	ACR500114645	
Maximum Power Output:	125.0 kW (167 bhp)	
Open Market Value:	\$31,205.00	
Original Registration Date:	12 May 2010	
First Registration Date:	12 May 2010	
Transfer Count:	3	
Actual ARF Paid: Intended PARF Rebate Details	\$31,205.00 15602	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	11 May 2020	
PARF Rebate Amount: Intended COE Rebate Details	\$17,162.00	
COE Expiry Date:	11 May 2020	
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	10	
QP Paid:	\$23,889.00	
COE Rebate Amount:	\$3,096.00	
Total Rebate Amount:	\$20,258.00	

The information contained herein is correct as at 24 Jan 2019

ОК

		N. F. Anthorisa
=+0==011 41	UTO DIE LID	Llele
	UTO PTE LTD	1/ 9/22
BLK1 KAKI B		L/5 9 1000
#01-46/48/50	AUTOBAY	20/1/18 John
SINGAPORE	E 417883	241.(()
VEHICLE NO:S	SJY 1898U	
QTY	PARTICULAR	
1 PCS	REAR WINDSCREEN	1 \$1,880.10 X
1 PCS	REAR WINDSCREEN MOULDING	pel \$138.90
1 PCS	TAILGATE /685110	30dy79 \$1,866.10
1 PCS	TAILGATE REAR LOGO	\$68.50
1 PCS	TAILGATE 'ESTIMA' EMBLEM	nec \$79.20
1 PCS	TAILGATE 'X' EMBLEM	Nec \$66.50
2 PCS	TAILGATE REFLECTORS @\$485.10	1 ≤ \$970.20 ×
1 PCS	TAILGATE CENTRE REFLECTOR	11 \$366.50 X
1 PCS	TAILGATE INNER LOCK	m/Jm \$509.10
1 PCS	TAILGATE LOCK STRIKER	1-1 \$66.80 X
1 PCS	TAILGATE LOCK REMOTE	D-7e \$344.50
1 PCS	TAILGATE WEATHERSTRIP	12 \$299.10
	TAILGATE INNER TRIM BOARD	De/cm \$745.10
1 PCS	TAILGATE INNER TRIM BOARD CLIPS	NU \$50.00
1 SET	TAILGATE INNER SIDE TRIM GARNISH @\$115.30	4-1 \$230.60×
2 PCS	TAILGATE INNER SIDE TRIM GARNIST & TOURS	11 \$295.30 X
1 PCS		71 \$1,450.00
1 PCS		3-enf \$133.00
2 PCS	REAR BUMPER SIDE RETAINERS @\$66.50	∠ 7 \$250.00 X
2 PCS	REAR BUMPER INNER SPONGES @\$125.00	\$67.00 ×
2 PCS	REAR BUMPER TOW COVERS @\$33.50	193.20×
2 PCS	REAR BUMPER REFLECTORS @\$96.50	Gent \$178.20
2 PCS	REAR BUMPER SIDE HOLDERS @\$89.10	300 \$899.10
1 PCS	REAR END PANEL	\$266.50
1 PCS	REAR END PANEL TOP GARNISH	Be St 10/34C \$1,120.10
1 PCS	REAR FLOOR PANEL	-0/
1 PCS	REAR FLOOR PANEL TOP BOARD	\$845.30 \\ \$1,105.10 X
1 PCS	REAR FENDER O/S	Pe / 759 \$1,596.20
2 PCS	REAR FENDER INNER TRIM BOARDS @\$798.10	
1 PCS	REAR FENDER INNER TRIM BOARD CLIPS	2
1 PCS	REAR WHEEL HOUSING PANEL O/S	
1 PCS	REAR FENDER GLASS O/S	M \$1,005.30 X
2 PCS	TAILLAMPS @\$688.10	cm \$1,376.20
1 PCS	REAR AIR CON BLOWER O/S	\$2,862.10 ×
1 PCS	REAR BACK ROLL SEAT ASSY	\$3,800.00× \$26,523.90
	S.NETT	122/22
1 SET	REAR BUMPER REVERSE SENSOR	8 5 % 1   slight \$280.00 200
	REAR END PANEL SEALANT	14 \$50.00 V
1 PCS	REAR WINDSCREEN SEALANT	NU \$50.00 40
1 PCS	REAR FENDER GLASS SEALANT O/S	11, \$50.00 ×
1 PCS		shell \$380.00
1 SET	REAR REVERSE CAMERA	

e - 8

1 PCS	REAR FENDER GLASS SOLAR FILM	√ √ \$350.00 X
1 PCS	TAILGATE TOP SPOILER	17 \$680.00×
	LABOUR CHARGES:	2
	TO CHECK WIRING	\$80.00 30
	TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00 £0
	TO DISMANTLE & REPLACING REAR WINDSCREEN & FENDER	GLASS \$300.00 / 20
	TO DISMANTLE & REFIX SEAT , CUSHION UPHOLSTREY	\$180.00 / 3 3
	TO MOUNT VEHICLE ON CAR O-LINER	380.00 × \$380.00 ×
	TO SPRAY RUSF PROOFING	\$150.00 /00
	TO TRANSFER TAILGATE MECHANISM	\$150.00 60
	TO DISMANTLE & REFIX FUEL TANK	100.00 × \$100.00 ×
	TO REFILL REAR AIR CON GAS	\$120.00 /00
	TO CONDUCT WHEEL ALIGNMENT	41 \$100.00 X
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTENED	\$2,000.00 /30
	& REPLACING PARTS	/1
	TO PUTTY & SPRAY PAINTING	\$1,800.00 /200
		TO \$33,803.90

12066.77

The Auth Transmittent's hence notify
the Commercial her following:

The commercial her following:

The commercial her pay pointing:

The commercial her to confirmation:

The commercial her is confirmation:

The commercial her is charged produced basis

The commercial her is charged produced basis

The commercial her is charged by required by Repairer

Signatural

Date:



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internati	onale Des Experts En Autom	obile
MS F	FIRST CAPITAL IN	SURANCE LTD	Ref : CS/FCI1900127	75/Uvd3n2
	OBINSON ROAD 01 CITY HOUSES	INGAPORE 068877	Date: 06-03-2019 Code: FCI2	
1.		Policy Particulars	:- THIRD PARTY CLAIR	M
	Insured Veh.	SHB 3296M	Veh. Inspected	SJY 1898U
	Policy No.		Coverage (\$)	0.00
	Claim No.	D19000644MFSH	Excess (\$)	0.00
	Assign From	KARENT	Assign Date	24/01/2019
2.		Vehicle Part	ticulars & Condition	
	Make & Model	TOYOTA ESTIMA (A)	c.c	2362
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	ACR500114645	Colour	BEIGE
	Odometer	158176	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Condi	tions of Tyres	ENGLISH CONTRACTOR
		Size	Make	Balance
	R/H Front Tyre	225/50 R18	YOKOHAMA	6 mm
	L/H Front Tyre	225/50 R18	YOKOHAMA	6 mm
	R/H Rear Tyre	225/50 R18	YOKOHAMA	6 mm
	L/H Rear Tyre	225/50 R18	УОКОНАМА	6 mm
4.		Descrip	tion of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE R	EAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.			ral Information	
	Accident Date	23/01/2019	Inspection Date	24/01/2019
	Survey held at	FASTECH AUTO PTE LTD		
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a.		DESCRIPTION OF STREET	Remarks	
	B)THE INSPECTION	NSISTENT TO ACCIDENT REPO ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS,	ITHOUT PREJUDICE" BAS	SIS. SED REPAIRS.
5b.		Estimat	e Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	7 Working Day	/s



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 1898U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN	NOT NECESSARY	1,880.10	19-
1	REAR WINDSCREEN MOULDING	NECESSARY	138.90	138.90
1	TAILGATE	BADLY DENTED	1,866.10	1,685.10
1	TAILGATE REAR LOGO	NECESSARY	68.50	68.50
1	TAILGATE "ESTIMA" EMBLEM	NECESSARY	79.20	79.20
1	TAILGATE "X" EMBLEM	NECESSARY	66.50	66.50
2	TAILGATE REFLECTORS @\$485.10	NOT NECESSARY	970.20	-
1	TAILGATE CENTRE REFLECTOR	NOT NECESSARY	366.50	-
1	TAILGATE INNER LOCK	DENTED / JAMMED	509.10	509.10
- 1	TAILGATE LOCK STRIKER	NOT NECESSARY	66.80	-
1	TAILGATE LOCK REMOTE	DAMAGED	344.50	344.50
-1	TAILGATE WEATHERSTRIP	TWISTED	299.10	299.10
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	745.10	745.10
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
2	TAILGATE INNER SIDE TRIM GARNISH @\$115.30	NOT NECESSARY	230.60	
1	TAILGATE OUTER CHROME HANDLE	NOT NECESSARY	295.30	-
1	REAR BUMPER	DISTORTED	1,450.00	665.10
2	REAR BUMPER SIDE RETAINERS @\$66.50	BENT	133.00	133.00
2	REAR BUMPER INNER SPONGES @\$125.00	NOT NECESSARY	250.00	-
2	REAR BUMPER TOW COVERS @\$33.50	NOT NECESSARY	67.00	-
2	REAR BUMPER REFLECTORS @\$96.60	NOT NECESSARY	193.20	
2	REAR BUMPER SIDE HOLDERS @\$89.10	BENT	178.20	178.20
	REAR END PANEL	BADLY DENTED	899.10	899.10
- 1	REAR END PANEL TOP GARNISH	DEFORMED / TORN	266.50	266.50
1	REAR FLOOR PANEL	BADLY DENTED / BUCKLED	1,120.10	1,120.10
1	REAR FLOOR PANEL TOP BOARD	DENTED / WARPED	845.30	845.30
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	1,105.10	4.5
2	REAR FENDER INNER TRIM BOARDS @\$798.10	DEFORMED / TORN	1,596.20	1,596.20
1	REAR FENDER INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00

Report Ref No. CS/FCI19001275/Uvd3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR WHEEL HOUSING PANEL O/S	TO REPAIR SEE LABOUR	1,350.10	
1	REAR FENDER GLASS O/S	NOT NECESSARY	1,005.30	
2	TAILLAMPS @\$688.10	CRACKED	1,376.20	1,376.20
1	REAR AIR CON BLOWER O/S	NOT NECESSARY	2,862.10	1.5
1	REAR BACK ROLL SEAT ASSY	NOT NECESSARY	3,800.00	
	LESS 25% DISCOUNT		-	-2,778.93
			26,523.90	8,336.77
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR FENDER GLASS SEALANT O/S (SN)	NOT NECESSARY	50.00	3.
-1	SET REAR REVERSE CAMERA (SN)	SHORTED	380.00	380.00
1	REAR FENDER GLASS SOLAR FILM (SN)	NOT NECESSARY	350.00	
1	TAILGATE TOP SPOILER (SN)	NOT NECESSARY	680.00	
	26 (2)		1,840.00	670.00
	LABOUR		1000	
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	
	TO DISMANTLE & REPLACING REAR WINDSCREEN.		300.00	120.00
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.		180.00	100.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	
	TO SPRAY RUSF PROOFING.		150.00	
	TO TRANSFER TAILGATE MECHANISM.		150.00	60.00
	TO DISMANTLE & REFIX FUEL TANK.	NOT NECESSARY	100.00	
	TO REFILL REAR AIR CON GAS.		120.00	100.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	1
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTENED & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER O/S AND REAR WHEEL HOUSING PANEL O/S.		2,000.00	1,300.0



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		1,800.00	1,200.00
			5,440.00	3,060.00
	GRAND TOTAL		33,803.90	12,066.77

R	ECOMMENDED COST OF LUMP SUM REPAIRS	9,600.00
(1	TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/FCI19001275/Uvd3n2

MARKET VALUE: \$34,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$20,258.00=NETT VALUE: \$13,742.00

CHUA KANG SENG Licensed Appraiser