

RONG SHENG AUTO ENGINEERING TRADING

NO 42 TOH GUAN ROAD EAST

01-79 ENTERPRISE HUB

SINGAPORE 608583

TEL : 8239 0099

REG NO : 53181821K

QUOTATION/ESTIMATE

VEHICLE NO :SMD1313R

RE: REPAIR VEHICLE ON TOYOTA ALTIS SMD1313R

DATE :18/01/2019

TO : FWD SINGAPORE PTE LTD

REFER NO :RSA/2019/01/0001

PARTS DESCRIPTIONLIST ITEMS

	QTY	UNTIL PRICE	AMOUNT
1 BONNET	1	\$ 991.80	\$ 991.80 <i>bt✓</i>
2 BONNET HINGE LH	1	\$ 96.58	\$ 96.58 <i>RY✓</i>
3 BONNET LOCK	1	\$ 90.70	\$ 90.70 <i>RY✓</i>
4 FRONT BUMPER	1	\$ 598.80	\$ 598.80 <i>de✓</i>
5 FRONT BUMPER REINFORCEMENT	1	\$ 356.10	\$ 356.10 <i>bt✓</i>
6 FRONT BUMPER SIDE RETAINER LH	1	\$ 56.80	\$ 56.80 <i>nei✓</i>
7 FRONT BUMPER LOWER GRILLE	1	\$ 132.96	\$ 132.96 <i>mis✓</i>
8 FRONT BUMPER CLIPS	10	\$ 4.90	\$ 49.00 <i>we✓</i>
9 FRONT BUMPER FOG LAMP LH	1	\$ 276.89	\$ 276.89 <i>one✓</i>
10 FRONT BUMPER FOG LAMP OUTER COVER LH	1	\$ 98.30	\$ 98.30 <i>ent✓</i>
11 FRONT SUPPORT PANEL	1	\$ 636.90	\$ 636.90 <i>bt✓</i>
12 FRONT FENDER LH	1	\$ 346.28	\$ 346.28 <i>bt✓</i>
13 FRONT FENDER INNER SEAL LH	1	\$ 147.98	\$ 147.98 <i>nei✓</i>
14 FRONT FENDER INNER CLIPS LH	10	\$ 5.10	\$ 51.00 <i>nei✓</i>
15 FRONT FENDER EMBLEM VVTI LH	1	\$ 52.80	\$ 52.80 <i>nei✓</i>
16 FRONT FENDER TOP GARNISH LH	1	\$ 25.30	\$ 25.30 <i>mis✓</i>
17 AIR DUCT LH	1	\$ 45.75	\$ 45.75 <i>de✓</i>
18 FUSE BOX LH	1	\$ 425.30	\$ 425.30 <i>de✓</i>
19 HEADLAMP LH	1	\$ 535.20	\$ 535.20 <i>one✓</i>
20 FRONT FENDER INNER PANEL LH	1	\$ 235.96	\$ 235.96 <i>Rt✓</i>
21 FRONT LOWER ARM LH	1	\$ 325.80	\$ 325.80 <i>?</i>
22 FRONT SHOCK ABSORBER LH	1	\$ 311.47	\$ 311.47 <i>?</i>
23 FRONT KUNCKLE ARM LH	1	\$ 561.81	\$ 561.81 <i>?</i>
24 FRONT KUNCKLER ARM BEARING LH	1	\$ 96.41	\$ 96.41 <i>?</i>
25 RESONATOR BOX	1	\$ 126.89	\$ 126.89 <i>de✓</i>

TOTAL :	\$6,582.78	\$6,672.78
LESS 25%	\$1,645.70	\$1,668.20
TOTAL :	\$4,937.09	\$5,004.59

SMD1313R

PAGE 2

S/NETT ITEMS

- 15 SPORT RIM LH
16 FRONT TYRE LH

\$450.00
\$180.00

\$450.00 *300*
\$180.00 *80% @ 144*

TOTAL : \$630.00 \$630.00

TOTAL SPARE PARTS : \$5,567.09 \$5,634.59

LABOUR DESCRIPTION

AMOUNT

1 LABOUR FOR PANEL BEATING	\$1,600.00 <i>1000</i>
2 LABOUR FOR SPRAYPAINTING	\$1,000.00 <i>900</i>
3 TO RUST PROOF ON REAR ACCIDENT AREAS	\$200.00 <i>40</i>
4 LABOUR FOR REMOVE AND REFIX LH FRONT UNDERCARRIAGE	\$250.00 <i>120?</i>
5 LABOUR FOR REPAIR & STRAIGHTEN LH FRONT CHASSIS FRAME	\$300.00 <i>X</i>
6 WIRING CHECK	\$120.00 <i>40</i>
7 TOWING	\$120.00 <i>80</i>
8 FRONT WHEEL ALIGNMENT	\$160.00 <i>80</i>

TOTAL LABOUR : \$3,750.00

TOTAL PARTS AND LABOUR : \$9,384.59

Reg. No
53181821K

PREPARE BY : ERIC KEE

Taylor 97495749
12/1/19 - up

Lumpsum

Resurvey after repair.

0 9 days

See Taylor@LKKAuto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: