

SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
NCIDENT NO. : /20190116/0921		LOCATION OF FIRE: Open Space Car Park Next to Block 348D, Yishun Avenue 11 Singapore 764348	
FIRE REPORTED ON : 16 January 2019			
TIME OF CALL: 21:45:03 hrs			
STATION COVERAGE : Yishun Fire Station			
2. INCIDENT INFORMATION			
FIRE INVOLVED: The engine of an Audi car (SFS2846S).			
METHOD OF EXTINGUISHMENT: By SCDF crew using a hose reel jet, a compressed air foam backpack and a 38mm hose line jet from fire appliances.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the engine was damaged. The front part of the car, including the windscreen, was also damaged. The adjacent Volkswagen car (SKH1805R) sustained heat and smoke damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
CINDY HAN			
for COMMISSIONER SINGAPORE CIVIL DEF	ENCE FORCE		

This is a computer generated Fire Report. No signature is required.