



## Case Details

**Case Reference Number :** TAX/01/19/2072     
 **Company Type :** SMRT Taxis Pte Ltd     
 **Insurance Company Name :** AXA Insurance Singapore Pte Ltd  
**Type of Repair :** Accident Repair     
 **Estimation ID :** EST-5377-ID     
 **Accident Date and Time :** 14/01/2019 04:05 PM  
**Vehicle Registration Number :** SHC4752B     
 **Assigned By :** Taxi Claims Manager Team     
 **Vehicle Age(In Months) :** 33

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PANEL, ROOF SIDE, / LH SIDE	1	134.80	134.80	25.00	101.10	Replace	0	0	Check	
One Time Key In	Main			PANEL, ROOF SIDE OUTER LH	1	134.80	134.80	25.00	101.10	Replace	0	0	Not Give	NN
One Time Key In	Main			RAIL, ROOF SIDE LH	1	273.60	273.60	25.00	205.20	Replace	1	0	Repair	DD
One Time Key In	Main			DOOR RR/LH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair	SR
One Time Key In	Main			DOOR LOCK RR/LH	1	709.30	709.30	25.00	531.97	Replace	0	0	Not Give	NN
One Time Key In	Main			HINGE LOWER LHR, DOOR	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	NN
One Time Key In	Main			HINGE UPPER LHR, DOOR	1	81.70	81.70	25.00	61.28	Replace	0	0	Not Give	NN
One Time Key In	Main			CHECK ASSY, FR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Give	NN
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Not Give	NN
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0	Not Give	NN

<b>Total Spare Part Cost</b>	49,993.55	<b>Surveyor Total</b>	8,975.50
<b>Lump Sum Discount (%)</b>	0.00	<b>Lump Sum Dis (%)</b>	0
<b>Final Spare Part Cost</b>	49,993.55	<b>Final Sur Total</b>	8,975.50

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	0	0	Check	
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	0	0	Not Give	NN
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	NN
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	NN
One Time Key In	Main			FENDER LINER RR/RH	1	141.30	141.30	25.00	105.98	Replace	0	0	Not Give	NN
One Time Key In	Main			DUCT ASSY, QUARTER	2	70.40	140.80	25.00	105.60	Replace	2	105.60	Replace	BUC
One Time Key In	Main			BACK ASSY, REAR SIDE SEAT, RH	1	643.80	643.80	25.00	482.85	Replace	0	0	Not Give	NN
One Time Key In	Main			QUARTER GLASS RR/RH	1	846.50	846.50	25.00	634.88	Replace	0	0	Not Give	NN
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	NN
One Time Key In	Main			DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair	
One Time Key In	Main			DOOR LOCK RR/RH	1	709.30	709.30	25.00	531.97	Replace	0	0	Not Give	NN
One Time Key In	Main			HINGE LOWER RHR, DOOR	1	52.00	52.00	25.00	39.00	Replace	0	0	Not Give	NN
One Time Key In	Main			HINGE UPPER RHR, DOOR	1	81.70	81.70	25.00	61.28	Replace	0	0	Not Give	NN
One Time Key In	Main			DOOR LOCK STRIKER	1	40.50	40.50	25.00	30.38	Replace	0	0	Not Give	NN
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	NN

Total Spare Part Cost	49,993.55	Surveyor Total	8,975.50
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	49,993.55	Final Sur Total	8,975.50

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace ▾	NEC
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Check ▾	
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Check ▾	
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Check ▾	
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Check ▾	
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	1	233.33	Replace ▾	SCR
One Time Key In	Main			FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	1	252.09	Replace ▾	SCR
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Check ▾	
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	1	13.88	Replace ▾	SCR
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace ▾	CRA
One Time Key In	Main			BRACKET, FR TURN CENTER LH	1	58.20	58.20	25.00	43.65	Replace	0	0	Check ▾	
One Time Key In	Main			BRACKET, FR TURN UPPER LH	1	24.40	24.40	25.00	18.30	Replace	0	0	Check ▾	
One Time Key In	Main			BRACKET, FR TURN LOWER LH	1	26.00	26.00	25.00	19.50	Replace	0	0	Check ▾	
One Time Key In	Main			LENS & BODY, FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	1	460.62	Replace ▾	SCR
One Time Key In	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Check ▾	

Total Spare Part Cost 49,993.55

Surveyor Total 8,975.50

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 49,993.55

Final Sur Total 8,975.50

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,460.40	1,460.40	25.00	1,095.30	Replace	0	0	Check	
One Time Key In	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace	CRA
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	ORF
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	NEC
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Check	
One Time Key In	Main			FENDER LINER PAD, FR WHEEL LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	NA
One Time Key In	Main			PROTECTOR, FRONT FENDER SIDE PANEL LH	1	114.50	114.50	25.00	85.88	Replace	0	0	Check	
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Check	
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair	
One Time Key In	Main			DOOR FRT/LH	1	894.40	894.40	25.00	670.80	Replace	1	0	Repair	
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	NEC
One Time Key In	Main			PILLAR, FR BODY, LH	1	363.10	363.10	25.00	272.33	Replace	1	0	Repair	
One Time Key In	Main			SEAL, FRONT FENDER TO COWL SIDE, LH	1	15.20	15.20	25.00	11.40	Replace	1	11.40	Replace	NEC
One Time Key In	Main			COOLANT	1	12.32	12.32	0.00	12.32	Replace	0	0	Check	
One Time Key In	Main			QUARTER GLASS FRT/LH	1	234.90	234.90	25.00	176.18	Replace	0	0	Not Give	NN

Total Spare Part Cost	49,993.55	Surveyor Total	8,975.50
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	49,993.55	Final Sur Total	8,975.50

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	DEF
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	NEC
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	1	154.27	Replace	DD
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	1	104.70	Replace	DD
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	1	104.70	Replace	DD
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check	
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	Shorts
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	NEC
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	1	54.15	Replace	DEF
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace	DEF
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	1	66.68	Replace	NEC
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	1	49.28	Replace	NEC
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	CRA

Total Spare Part Cost	49,993.55	Surveyor Total	8,975.50
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	49,993.55	Final Sur Total	8,975.50

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	NN	
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	1	385.88	Replace	DEF	
One Time Key In	Main			EXHAUST HEAT SHIELD, REAR	1	107.40	107.40	25.00	80.55	Replace	0	0	Check		
One Time Key In	Main			EXHAUST TAIL PIPE	1	656.20	656.20	25.00	492.15	Replace	0	0	Not Give	NN	
One Time Key In	Main			EXHAUST PIPE FRT	1	4,184.70	4,184.70	25.00	3,138.52	Replace	0	0	Not Give	NN	
One Time Key In	Main			SUPPORT EXHAUST PIPE, NO.4	2	40.30	80.60	25.00	60.45	Replace	0	0	Not Give	NN	
One Time Key In	Main			SUPPORT, EXHAUST REAR	2	33.60	67.20	25.00	50.40	Replace	0	0	Not Give	NN	
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace	DD	
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	NEC	
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	NEC	
One Time Key In	Main			TAILGATE DOOR GLASS	1	1,090.90	1,090.90	25.00	818.18	Replace	1	818.18	Replace	CRA	
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	NEC	
One Time Key In	Main			TAILGATE LOWER WINDOW GLASS	1	721.30	721.30	25.00	540.97	Replace	1	540.97	Replace	CRA	
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace	NEC	
One Time Key In	Main			TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Check		

Total Spare Part Cost	49,993.55	Surveyor Total	8,975.50
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	49,993.55	Final Sur Total	8,975.50

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Check	
One Time Key In	Main			TAILGATE DOOR STAY LH	1	241.50	241.50	25.00	181.13	Replace	0	0	Check	
One Time Key In	Main			TAILGATE DOOR STAY RH	1	241.50	241.50	25.00	181.13	Replace	0	0	Check	
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Check	
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Check	
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	1	378.67	Replace	
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Check	
One Time Key In	Main			TAILGATE TRIM, LH	1	85.90	85.90	25.00	64.43	Replace	0	0	Check	
One Time Key In	Main			TAILGATE TRIM, LOWER	1	180.70	180.70	25.00	135.52	Replace	0	0	Check	
One Time Key In	Main			TAILGATE TRIM, RH	1	88.30	88.30	25.00	66.22	Replace	0	0	Check	
One Time Key In	Main			TAILGATE TRIM, UPPER	1	49.60	49.60	25.00	37.20	Replace	0	0	Check	
One Time Key In	Main			TAILGATE, BOARD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0	Check	
One Time Key In	Main			WIRE, BACK DOOR, NO.1	1	582.40	582.40	10.00	524.16	Replace	0	0	Check	
One Time Key In	Main			MOTOR ASSY, RR WIPER	1	734.60	734.60	10.00	661.14	Replace	0	0	Check	
One Time Key In	Main			ARM, RR WIPER	1	84.70	84.70	25.00	63.53	Replace	0	0	Check	

DEF

Total Spare Part Cost	49,993.55	Surveyor Total	8,975.50
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	49,993.55	Final Sur Total	8,975.50

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BLADE ASSY, REAR WIPER	1	55.00	55.00	25.00	41.25	Replace	0	0	Check	
One Time Key In	Main			CAMERA ASSY, TELEVISION, RR	1	1,436.60	1,436.60	10.00	1,292.94	Replace	0	0	Check	
One Time Key In	Main			SWITCH ASSY, BACK DOOR OPENER	1	146.10	146.10	10.00	131.49	Replace	0	0	Check	
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	1	575.10	Replace	BUC
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	NEC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	NEC
One Time Key In	Main			FENDER LINER RR/LH	1	141.30	141.30	25.00	105.98	Replace	0	0	Check	
One Time Key In	Main			LID ASSY, FUEL	1	102.00	102.00	25.00	76.50	Replace	0	0	Check	
One Time Key In	Main			CABLE SUB-ASSY, FUEL LID	1	63.90	63.90	25.00	47.92	Replace	0	0	Check	
One Time Key In	Main			RETAINER, FUEL LID CABLE	1	5.90	5.90	25.00	4.43	Replace	0	0	Check	
One Time Key In	Main			CAP ASSY, FUEL TANK	1	68.10	68.10	25.00	51.07	Replace	0	0	Not Give	NN
One Time Key In	Main			PIPE SUB-ASSY, FUEL NECK	1	230.80	230.80	25.00	173.10	Replace	0	0	Not Give	NN
One Time Key In	Main			TUBE, FUEL TANK	1	36.10	36.10	25.00	27.08	Replace	0	0	Not Give	NN
One Time Key In	Main			TANK SUB-ASSY, FUEL	1	745.10	745.10	25.00	558.83	Replace	0	0	Not Give	NN
One Time Key In	Main			QUARTER GLASS RR/LH	1	168.10	168.10	25.00	126.07	Replace	1	126.07	Replace	NEC

Total Spare Part Cost	49,993.55	Surveyor Total	8,975.50
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	49,993.55	Final Sur Total	8,975.50

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace ▾	NEC
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give ▾	NN
One Time Key In	Main			WHEEL, DISC	1	1,490.20	1,490.20	25.00	1,117.65	Replace	0	0	Not Give ▾	NN
One Time Key In	Main			REINFORCEMENT, ROOF SIDE INNER LH	1	60.30	60.30	25.00	45.22	Replace	0	0	Check ▾	
One Time Key In	Main			REINFORCE, ROOF SIDE OUTER LH	1	91.90	91.90	10.00	82.71	Replace	0	0	Check ▾	
One Time Key In	Main			REINFORCEMENT, BACK DOOR SIDE LH	1	89.50	89.50	25.00	67.13	Replace	0	0	Check ▾	
One Time Key In	Main			EXTENSION, QUARTER PANEL FRONT LH	1	83.50	83.50	25.00	62.63	Replace	0	0	Check ▾	
One Time Key In	Main			EXTENSION, QUARTER PANEL REAR LH	1	108.50	108.50	10.00	97.65	Replace	0	0	Check ▾	
One Time Key In	Main			PANEL, ROOF SIDE, INNER LH	1	134.80	134.80	25.00	101.10	Replace	0	0	Check ▾	
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	1	45.22	Replace ▾	NEC
One Time Key In	Main			LICENSE PLATE LAMP	2	35.70	71.40	25.00	53.55	Replace	0	0	Check ▾	
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace ▾	BUC
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace ▾	BUC
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace ▾	NEC
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	1	45.60	Replace ▾	NEC

Total Spare Part Cost	49,993.55	Surveyor Total	8,975.50
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	49,993.55	Final Sur Total	8,975.50

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	NEC
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	1	0	Repair	
One Time Key In	Main			3RD BRAKE LAMP	1	231.30	231.30	10.00	208.17	Replace	0	0	Not Give	NA
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	NEC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	NEC
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Check	
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	Check	
One Time Key In	Main			REINFORCEMENT, RR	2	34.60	69.20	25.00	51.90	Replace	0	0	Check	
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0	Check	
One Time Key In	Main			MEMBER SUB-ASSY, RR LH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check	
One Time Key In	Main			MEMBER SUB-ASSY, RR RH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check	
One Time Key In	Main			MEMBER SUB ASSY, REAR FLOOR CROSS NO.1	1	436.40	436.40	25.00	327.30	Replace	0	0	Check	
One Time Key In	Main			MEMBER SUB ASSY, REAR FLOOR CROSS NO.2	1	655.70	655.70	25.00	491.78	Replace	0	0	Check	

Total Spare Part Cost 49,993.55

Surveyor Total 8,975.50

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 49,993.55

Final Sur Total 8,975.50

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FLOOR PANEL RR/LH	1	102.00	102.00	25.00	76.50	Replace	0	0	Check	
One Time Key In	Main			FLOOR PANEL RR/RH	1	209.90	209.90	25.00	157.43	Replace	0	0	Check	
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0	Check	
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	0	0	Check	
One Time Key In	Main			BOARD, RR FLOOR	1	392.30	392.30	25.00	294.23	Replace	0	0	Check	
One Time Key In	Main			BOARD ASSY, RR RH	1	379.20	379.20	25.00	284.40	Replace	0	0	Check	
One Time Key In	Main			SPACER, RR FLOOR	1	130.60	130.60	25.00	97.95	Replace	0	0	Check	
One Time Key In	Main			BOX, DECK FLOOR, COVER LH	1	230.10	230.10	25.00	172.57	Replace	0	0	Check	
One Time Key In	Main			BOX, DECK FLOOR, LH	1	196.80	196.80	25.00	147.60	Replace	0	0	Check	
One Time Key In	Main			COVER ASSY, TONNEAU	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	
One Time Key In	Main			CUSHION, SPARE WHEEL	1	230.80	230.80	25.00	173.10	Replace	0	0	Check	
One Time Key In	Main			PROTECTOR, SPARE	1	143.70	143.70	25.00	107.77	Replace	0	0	Check	
One Time Key In	Main			CARRIER, SPARE	1	19.70	19.70	25.00	14.77	Replace	0	0	Check	
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	NN
One Time Key In	Main			WHEEL, DISC	1	1,490.20	1,490.20	25.00	1,117.65	Replace	0	0	Not Give	NN

Total Spare Part Cost	49,993.55	Surveyor Total	8,975.50
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	49,993.55	Final Sur Total	8,975.50

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BREAKDOWN SIGN	1	35.00	35.00	0.00	35.00	Replace	0	0	Check	
One Time Key In	Main			PANEL ASSY, DECK LH	1	307.00	307.00	25.00	230.25	Replace	0	0	Check	
One Time Key In	Main			PANEL ASSY, DECK RH	1	307.00	307.00	25.00	230.25	Replace	0	0	Check	
One Time Key In	Main			GARNISH SIDE UPPER, LHR	1	261.70	261.70	25.00	196.27	Replace	0	0	Check	
One Time Key In	Main			BATTERY	1	278.00	278.00	10.00	250.20	Replace	0	0	Check	
One Time Key In	Main			BATTERY ASSY, HV	1	5,544.40	5,544.40	10.00	4,989.96	Replace	0	0	Check	
One Time Key In	Main			BATTERY CLAMP	1	16.10	16.10	25.00	12.08	Replace	0	0	Check	
One Time Key In	Main			BATTERY TRAY	1	42.80	42.80	25.00	32.10	Replace	0	0	Check	
One Time Key In	Main			WIRE, FRAME	1	1,680.90	1,680.90	25.00	1,260.68	Replace	0	0	Check	
One Time Key In	Main			WIRE, ENGINE, NO.3	1	74.00	74.00	10.00	66.60	Replace	0	0	Not Give	
One Time Key In	Main			WIRE, FLOOR	1	1,675.00	1,675.00	10.00	1,507.50	Replace	0	0	Check	
One Time Key In	Main			WIRE, FLOOR, NO.2	1	1,305.40	1,305.40	10.00	1,174.86	Replace	0	0	Check	
One Time Key In	Main			RECEIVER, DOOR CONTROL	1	239.70	239.70	10.00	215.73	Replace	0	0	Check	
One Time Key In	Main			PANEL SUB-ASSY, QTR	1	326.70	326.70	25.00	245.02	Replace	0	0	Check	
One Time Key In	Main			PANEL SUB-ASSY, QTR	1	588.40	588.40	25.00	441.30	Replace	0	0	Check	

NA

Total Spare Part Cost 49,993.55

Surveyor Total 8,975.50

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 49,993.55

Final Sur Total 8,975.50

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			Remarks	
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)		Repair/Replace
One Time Key In	Main			PANEL SUB-ASSY, QTR WHEEL HOUSE	1	588.40	588.40	25.00	441.30	Replace	0	0	Check	
One Time Key In	Main			PANEL, QUARTER WHEEL HOUSE, OUTER LH	1	326.70	326.70	25.00	245.02	Replace	0	0	Check	
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.02	Replace	0	0	Check	
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	1	493.56	Replace	CRA
One Time Key In	Main			TROUGH, BACK DOOR LH	1	110.90	110.90	10.00	99.81	Replace	0	0	Check	
<b>Total Spare Part Cost</b>									49,993.55	<b>Surveyor Total</b>		8,975.50		
<b>Lump Sum Discount (%)</b>									0.00	<b>Lump Sum Dis (%)</b>		0		
<b>Final Spare Part Cost</b>									49,993.55	<b>Final Sur Total</b>		8,975.50		

**Labour's Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	845.00	400	
2	Main	TO REPAIR REAR PORTION	2,028.00	800	
<b>Total:</b>			<b>2,873.00</b>	<b>1,200.00</b>	

**Spray Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
4	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
5	Main	TO RESPRAY RIM	540.00	50	
6	Main	TO RESPRAY FRONT PILLAR LH	180.00	80	
7	Main	TO RESPRAY FRONT DOOR LH	378.00	200	
<b>Total:</b>			<b>7,542.00</b>	<b>1,710.00</b>	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
8	Main	TO RESPRAY REAR BUMPER	378.00	200	
9	Main	TO RESPRAY TAIL GATE	378.00	200	
10	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	50	
11	Main	TO RESPRAY REAR SPOILER	180.00	80	
12	Main	TO RESPRAY REAR PANEL	180.00	0	
13	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	
14	Main	TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0	
15	Main	TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0	
16	Main	TO RESPRAY BATTERY PANEL	180.00	0	
17	Main	TO RESPRAY REAR MEMBER,RH	180.00	0	
18	Main	TO RESPRAY REAR MEMBER,LH	180.00	0	
19	Main	TO RESPRAY RH REAR WHEEL HOUSE	180.00	0	
20	Main	TO RESPRAY REAR LH WHEEL HOUSE	180.00	0	
21	Main	TO RESPRAY FUEL LID COVER	180.00	0	
22	Main	TO RESPRAY RH RAIL ROOF SIDE	180.00	0	
23	Main	TO RESPRAY LH RAIL ROOF SIDE	180.00	50	
24	Main	TO RESPRAY MEMBER SUB-ASSY, CENTER FLOOR CROSS , NO.2	180.00	0	
25	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	0	
26	Main	TO RESPRAY TROUGH BACK DOOR LH	180.00	0	
27	Main	TO RESPRAY REAR FENDER LH	378.00	200	
28	Main	TO RESPRAY REAR FENDER RH	378.00	0	
29	Main	TO RESPRAY RH REAR DOOR	378.00	0	
30	Main	TO RESPRAY REAR DOOR LH	378.00	200	
<b>Total:</b>			<b>7,542.00</b>	<b>1,710.00</b>	

\* Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	126.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	300.00	100	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
5	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	
6	Main	TO TOP UP A/C GAS	120.00	0.00	
7	Main	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	0	
8	Main	TO REMOVE / REFIT SEAT	120.00	0	
9	Main	TO ALIGN CHASSIS	350.00	0	
10	Main	TO REMOVE & REFIT FUEL TANK	120.00	0	
11	Main	TO REMOVE & REFIT EXHAUST	120.00	0	
12	Main	TO TRANSFER DOOR MECHANISM	240.00	0	
13	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	850.00	850.00	
14	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	50	
15	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	
16	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	40	
17	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	50	
18	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	0	
19	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120	
20	Main	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0	
21	Main	TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	50	
22	Main	TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	120.00	0	
23	Main	TO REMOVE AND REFIT WIRE HARDESS	250.00	0	
<b>Total:</b>			<b>4,746.00</b>	<b>1,400.00</b>	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
24	Main	TO REMOVE AND REFIT BATTERY ASSY HV	120.00	0	
25	Main	TO REPLACE SUNDRY PARTS	100.00	0	
26	Main	TO WASH AND VACUUM	60.00	0	
<b>Total:</b>			<b>4,746.00</b>	<b>1,400.00</b>	

## Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	49,993.55	8,975.50
Total Labour Cost	2,873.00	1,200.00
Total Spray Painting	7,542.00	1,710.00
Other	4,746.00	1,400.00
Overall Total	65,154.55	13,285.50
Lump Sum Repair Option	<input type="checkbox"/>	<input type="checkbox"/>
Lump Sum Total	0.00	13,285.50
Surveyor Approved Amount		13,285.50
No of Repair Days*	22	7
Remarks		P/P repair, photo before paint.
Surveyor Name		Hwee jie
Signature		
Survey Date	21/01/2019	

Save Clear

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: