

INS. CASE OWNER:

CC

4/Asm 1900

1357, R. 8039

LKK:
IDAC:

94466

ASSIGNMENT

Ram

11/4/19

Date / Time:

21/4/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLA 6969J

Name of Insured:

Koh Motor Co

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

18/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

59m01B63

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLA 6969J

SLA 6969J

SLM 578M



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SLM 578M - X; SLA 6969J - X

OTNR. sent out 1st letter.

23-1-19 # 240

CPUED ON (CONFINED ACCIDENT) ON 11/03/19 IN 3 VEH CC DI WORE THE 2ND VEH- INFORM TP CLAIM AGREE TO SETTLE AND AMUSE ABOUT 100 SHARE.

EMAIL WSP LIABILITY CLEAR.

3/2/19
5/2/19

- DS Ann cur

- file -> MC to close

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

23-1-19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time: 06/03/19

Confirm with: UACK

Confirm by: MRS

Repair Cost:

PP

SS 13276.23

(

14 days)

Reduction:

52 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

38

Repair Cost:

W/Loss:

SS 13276.23 (as per ARA mandate)

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS 960.00

(

16 x 60 days)

Loss of Income (LOI):

SS

(

x days)

LOR only

☐

LOU only

☒

LOR + LOU

☐

LOR + LOI

☐

(Tick only one)

GIA/LTA Search

SS 2.00

Medical:

SS 131.65

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS 14369.88

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 14369.88

Name 1:

Koh Motor Co sdn Bhd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

B 350.00

8/2/19

Paul

REF:

1757/121 (2)

1333F

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SJM 578M**

at Workshop no: **KAH MOTOR**

of **235, ALEXANDRA RD**

Insured: **AGM (AKA)**

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition) **1pm own unit**

Remark: The veh had commenced its **jack** repair at the time of inspection.

Bal. or Market Value: **74K**

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: **14** days Res: Yes or No

Lum Sum: **-** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Year No: **SJM 578M** Vt Page: **2018 APR**

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or: _____

Make: **HONDA HRV 1.5 A** **OK** **1496**

Colour: **GREY** A/C: Insured / Std / NI / NA

Sp Reading: **15752** T/Ratio: Insured / Std / NI / NA

Eng/No: _____

C/Nr: **JHMRU18306X203714**

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size F: **215/60R16**

R: **-**

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: **6** mm R/Bal: **6** mm


L/Bal: **6** mm L/Bal: **6** mm

D.O.A: **18/01/19** D.O.I: **11/02/19**

Survey held at: **KAH MOTOR**

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision



Date / Time	Action / Instruction
-------------	----------------------

DIP: + 12,961.69 (RED: + 6,060.95 32%)

Date/Time: File Pass to? ☐ : Preli. Report

File: ☐ : Final Report

Date/Time: File Return to? _____

Report Format: _____

Lump Sum / I.B.I: \$ _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ Site Insp \$ _____

☐ Interview \$ _____

☐ Tech. Insp \$ _____

☐ Weekend \$ _____

1. _____

2. _____

3. _____

4. _____

5. _____

6. _____

7. _____

8. _____

9. _____

10. _____

11. _____

12. _____

13. _____

14. _____

15. _____

16. _____

17. _____

18. _____

19. _____

20. _____

21. _____

22. _____

23. _____

24. _____

25. _____

26. _____

27. _____

28. _____

29. _____

30. _____

31. _____

32. _____

33. _____

34. _____

35. _____

36. _____

37. _____

38. _____

39. _____

40. _____

41. _____

42. _____

43. _____

44. _____

45. _____

46. _____

47. _____

48. _____

49. _____

50. _____

51. _____

52. _____

53. _____

54. _____

55. _____

56. _____

57. _____

58. _____

59. _____

60. _____

61. _____

62. _____

63. _____

64. _____

65. _____

66. _____

67. _____

68. _____

69. _____

70. _____

71. _____

72. _____

73. _____

74. _____

75. _____

76. _____

77. _____

78. _____

79. _____

80. _____

81. _____

82. _____

83. _____

84. _____

85. _____

86. _____

87. _____

88. _____

89. _____

90. _____

91. _____

92. _____

93. _____

94. _____

95. _____

96. _____

97. _____

98. _____

99. _____

100. _____



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Like Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SJM578M

Chassis No : JHMRU1830GX203774

Model : HRV LX-SIN CVT YM 2016

Owner's Name : TAN BEE GUAT

Ins Policy No. :

Date of Accident : 15/1/2019

Acknowledged by Repairer
Signature: _____
Date: _____

Document No. : SQT19000345
Date : 19. Jan 2019
Customer No. : WZA006

Page 1

Svc Advisor :
Engine No : L15B4533775
Date | Time : 19, Jan 2019 10:48:35 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:TAN BEE GUAT OWNER INSURER:AVIVA LTD ACC DATE:18/01/2019 SURVEYED BY: DATE: REF NO: TP INSURER:AXA TP VEH:SLQ 6969 J						
33505-T7A-J01	REFLECTOR ASSYR.RR. <i>X NN</i>	1	156.30	25	117.22	8.21	125.43
33555-T7A-J01	REFLECTOR ASSYL.RR. <i>X NN</i>	1	156.30	25	117.22	8.21	125.43
04715-T7A-900ZZ	FACE.RR.BUMPER <i>DE</i>	1	463.70	25	347.77	24.34	372.11
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER <i>X NN</i>	1	94.10	25	70.57	4.94	75.51
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER <i>X NN</i>	1	94.10	25	70.57	4.94	75.51
71593-T7A-J00	SPACER R.RR.BPR S <i>nn</i>	1	16.90 <i>11.50</i>	25	12.67	0.89	13.56
71598-T7A-J00	SPACER L.RR.BPR S <i>nn</i>	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP.BUMPER <i>nn</i>	8	2.30	25	13.80	0.97	14.77
68100-T7A-J20ZZ	TAIL GATE COMP <i>PA</i>	1	855.70	25	641.77	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE <i>nn</i>	1	98.70	25	74.02	5.18	79.20
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER <i>8nn</i>	1	105.30	25	78.97	5.53	84.50
75722-T7W-A01	EMBLEMRR. <i>nn</i>	1	13.30	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM.RR. I-VTEC <i>nn</i>	1	14.50	25	10.87	0.76	11.63
74890-T7A-J12ZS	GARNISH ASSYRR.LICENSE <i>X NN</i>	1	189.80	25	142.35	9.96	152.31
75701-T5A-000	EMBLEMH <i>nn</i>	1	10.70	25	8.02	0.56	8.58
66100-T7A-300ZZ	PANEL COMPRR. <i>PA</i>	1	373.10	25	279.82	19.59	299.41
04655-T7A-310ZZ	PANEL SETRR.FLOOR <i>nn</i>	1	675.50	25	506.62	35.46	542.08
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER <i>nn</i>	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5 <i>nn</i>	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER <i>nn</i>	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT <i>nn</i>	1	4.80	25	3.60	0.25	3.85

owing:
spray painting
(s) during resurvey
to confirmation
on a "Without Prejudice" basis
(s) is allowed
must be resurveyed and
approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SJM578M
Chassis No : JHMRU1830GX203774
Model : HRV LX-SIN CVT YM 2016
Owner's Name : TAN BEE GUAT
Ins Policy No. :
Date of Accident : 15/1/2019

Document No. : SQT19000345 **Page** 2
Date : 19. Jan 2019
Customer No. : WZA006
Svc Advisor :
Engine No : L15B4533775
Date | Time : 19. Jan 2019 10:48:35 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
Sum Item					2703.36	189.24	2,892.60
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1	150.00		150.00	10.50	160.50
BOJSE	BODY JOINT SEALANT FOR END PANEL	1	150.00		150.00	10.50	160.50
BOJSE	BODY JOINT SEALANT FOR FLOOR PANEL	1	150.00		150.00	10.50	160.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	380.00		380.00	26.60	406.60
BOMISC1	REMOVE & RE-INSTALL REAR VIEW CAMERA(N)	1	450.00		450.00	31.50	481.50
BOMISC1	RESET & CALIBRATE SMART ENTRY SYSTEM (N)	1	450.00		450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. (N)	1	560.00		560.00	39.20	599.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00		800.00	56.00	856.00
BODAMKIT	WINDSCREEN DAM KIT.	1	200.00		200.00	14.00	214.00
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BKRP02M	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS.	1	7500.00		7500.00	525.00	8025.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4500.00		4500.00	315.00	4815.00
Sum Labor					15950.00	1,116.50	17,066.50

Survey By

Date & Time

Excess

Status

Signature

Total Amount 18,653.36 1,305.74 19,959.10

Total (Inclusive of GST) 19,959.10

Printed on 19/1/2019 11:43:27 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

and per 3.5
Amount paid 12407.69



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: ****1333F / TAN BEE GUAT
Chassis No: JHMRU1830GX203774
License No: SJM578M
Mileage: 1575
Engine No: L15B4533775

Document No: SVO19008866
Printed By: JACKNG
Order Date: 11. February 2019
Order Time: 1:19:17 PM
Service Advisor: JACK NG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incld GST
74940-TZ5-A01	BUZZER ASSYSMART	1	60.40	25	45.30	3.17	48.47
65513-T7A-300ZZ	STIFFENERRR.JACK UP	1	61.40	25	45.05	3.22	49.27
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	43.90	25	32.92	2.30	35.22
90321-SLE-000	NUTHEX CAP 5MM	1	2.80	25	2.10	0.15	2.25
90321-SLE-000	NUTHEX CAP 5MM	1	2.80	25	2.10	0.15	2.25
74800-T7A-J02	LOCK ASSYTAILGATE	1	78.90	25	59.17	4.14	63.31
74646-T7A-010	COVERRR.FLOOR UN	1	120.70	25	90.52	6.34	96.86
84550-T7A-J00	BOX ASSY,CARGO FLOOR	1	129.50	25	97.12	6.80	103.92
SUM PARTS:					375.28	26.27	401.55
TOTAL SGD					375.28	26.27	401.55

Total Payable (SGD)

401.55

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
Chassis No: JHMRU1830GX203774
License No: SJM578M
Mileage: 1575
Engine No: L15B4533775

Document No: SVO19008866
Printed By: JACKNG
Order Date: 11. February 2019
Order Time: 1:19:17 PM
Service Advisor: JACK NG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:TAN BEE GUAT OWNER INSURER:AVIVA LTD ACC DATE:18/01/2019 SURVEYED BY: DATE: REF NO: TP INSURER:AXA TP VEH:SLQ 6969 J SUPPLEMENTARY PART						
04715-T7A-900ZZ	FACE,RR BUMPER	1	463.70	25	347.77	24.34	372.11
71593-T7A-000	SPACERR,RR,BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-T7A-J00	SPACER,L,RR,BPR S	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER	8	2.30	25	13.80	0.97	14.77
68100-T7A-J20ZZ	TAIL GATE COMP	1	855.70	25	641.77	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE	1	98.70	25	74.02	5.16	79.20
75722-T7W-A01	EMBLEMRR.	1	13.30	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM,RR, I-VTEC	1	14.50	25	10.87	0.76	11.63
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
66100-T7A-300ZZ	PANEL COMPRR.	1	373.10	25	279.82	19.59	299.41
04655-T7A-310ZZ	PANEL SETRR,FLOOR	1	675.50	25	506.62	35.46	542.08
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
74940-TZ5-A01	BUZZER ASSYSMART S	1	60.40	25	45.30	3.17	48.47
65513-T7A-300ZZ	STIFFENERRR,JACK UP S	1	61.40	25	46.05	3.22	49.27
84640-T7A-J01ZA	LINING ASSYRR,PANEL S	1	43.90	25	32.92	2.30	35.22
90321-SLE-000	NUTHEX CAP 5MM S	1	2.80	25	2.10	0.15	2.25
90321-SLE-000	NUTHEX CAP 5MM S	1	2.80	25	2.10	0.15	2.25
74800-T7A-J02	LOCK ASSYTAILGATE S	1	78.90	25	59.17	4.14	63.31
74646-T7A-010	COVERRR,FLOOR UN S	1	120.70	25	90.52	6.34	96.86
84550-T7A-J00	BOX ASSY,CARGO FLOOR S	1	129.50	25	97.12	6.80	103.92
	SUM PARTS:				2,477.69	173.43	2,651.12
BOSUN		1	50.00		50.00	3.50	53.50
	SUNDRIES						
BOJSE	1610	1	100.00		100.00	7.00	107.00
	BODY JOINT SEALANT FOR TAILGATE						
BOJSE	1610	1	100.00		100.00	7.00	107.00
	BODY JOINT SEALANT FOR END PANEL						
BOJSE	1610	1	100.00		100.00	7.00	107.00
	BODY JOINT SEALANT FOR FLOOR PANEL						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
Chassis No: JHMRU1830GX203774
License No: SJM578M
Mileage: 1575
Engine No: L15B4533775

Document No: SVO19008866
Printed By: JACKNG
Order Date: 11. February 2019
Order Time: 1:19:17 PM
Service Advisor: JACK NG

BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	280.00	280.00	19.60	299.60
BOMISC1	0671 REMOVE & RE-INSTALL REAR VEW CAMERA(N)	1	450.00	450.00	31.50	481.50
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)	1	450.00	450.00	31.50	481.50
BKTG02R	0671 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. (N) ALIGN TAILGATE.(N)	1	560.00	560.00	39.20	599.20
BMI03D	1757 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	560.00	560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00	100.00	7.00	107.00
BG02D	1757 REMOVE & INSTALL RR. WINDSCREEN. (N)	1	560.00	560.00	39.20	599.20
BKRP02M	0671 CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS. ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.	1	4,480.00	4,480.00	313.60	4,793.60
BP06R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2,700.00	2,700.00	189.00	2,889.00

SUM LABOUR: 10,490.00 734.30 11,224.30

TOTAL SGD 12,967.69 907.73 13,875.42

Total Payable (SGD) 13,875.42

GST Amount is calculated from individual line(s)



MANDATE IA (S9M01B63)

Type

🔗 Question

Message

Liability: Insured involved in 3 vehicle chain collision insured was the 2nd vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$13,875.43 (w/GST) Loss of Rental: \$2,033.00 (19days x \$100)(w/GST) LTA Search: \$7.49 Total: \$15,915.92 Immediate Advice with Mandate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (06/03/2019)

Reply

MATERIAL (SPECIAL NETT ITEM)	NETT LABOUR (NOT ABLE TO BE ADJUST)	ADJUSTED LABOUR
SUNDRIES - \$50	REMOVE & RE-INSTALL REAR VIEW CAMERA - \$450	INSPECT RR LIGHTING MECHANISMS, PERFORM WATER LEAKAGE - \$280
BODY JOINT SEALANT FOR TAIGATE - \$100	REMOVE & CALIBRATE SMART ENTRY SYSTEM - \$450	REMOVE & REINSTALL REAR COMPARTMENT LININGS (WIRING) - \$560
BODY JOINT SEALANT FOR END PANEL - \$100	REMOVE & TRANSFER ITEM TO NEW TAILGATE - \$560	
BODY JOINT SEALANT FLOOR PANEL - \$100	REMOVE & INSTALL REAR WINDSCREEN - \$560	
WINDSCREEN DAM KIT - \$100		
TOTAL: \$450	TOTAL: \$2,020	TOTAL: \$840

TO REPAIR, REMOVE, REPLACE AND WELDING - (8DAYS X \$560) = \$4,480

TO SPRAY PAINT ON THE EFFECTED AREA - (6PANEL X \$450) = \$2,700

LABOUR @ \$560 PER DAY

PAINTING @ \$450 PER PANEL

by Underbody protection
 2,000g & 200g.
 End panel - K New panel - \$
 replan...
 7.5 days 7.5 days.
 Spraydown Chassis weather
 1000 lever

Hsiao Tong (LKKAuto)

From: Desmond Toh <desmondtoh@honda.com.sg>
Sent: Tuesday, 2 July 2019 3:53 PM
To: Hsiao Tong (LKKAuto)
Cc: Jerome Tan
Subject: FW: SJM578M - TP CLAIM AGAINST SLQ6969J DOA: 18.01.2019

Without prejudice

Dear Hsiao Tong,

If you got difficulty closing this case and AXA still insist the labour is too high, the only way I can help is to deduct one day \$560.00 from the labour but the LOU or LOR must remain. we treat this as a special case and we only do it for once and for all. Please inform AXA to expedite this payment if we have to deduct the labour.

Best Regards

Desmond Toh

Kah Motor Co Sdn Bhd

Website : www.honda.com.sg



Visit our
Facebook page

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Saturday, 22 June, 2019 10:06 AM
To: Desmond Toh <desmondtoh@honda.com.sg>
Subject: RE: SJM578M - TP CLAIM AGAINST SLQ6969J DOA: 18.01.2019

Without Prejudice

Hi Desmond,

We are reviewing the matter and will get back to you by next week.

Kindly hold hands.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Re:MANDATE IA (S9M01B63)

Type

 Question

Message

PLS PROCEED FOR SETTLEMENT AS FOLLOWS: Repair Cost : \$13,276.23 (w/GST) Loss of Rental: \$1,926.00 (18days x \$100)(w/GST) LTA Search: \$7.49 Total: \$15,209.72 *main labour: Cut off & renew rear panel, renew all damaged parts, to offer at \$3920.00 instead of \$4480*

Reply

⏪ RE: Re:MANDATE IA (S9M01B63)

Type

🔔 Question

Message

Hi, KC, we would like to reseek mandate to include medical fee. The breakdown of our proposal is as follows: - 1) Repair Cost : \$13,276.23 (w/GST) + 2) Loss of Use: \$960.00 (16days x \$60.00) + 3)LTA/GIA Search Fee: \$2.00 + 4) Medical Fee: \$131.65 = Total: \$14,369.88. Kindly let us have your mandate / approval. Thank you. Hsiao Tong
- 02 July 2019

Reply

<< **Re:RE: Re:MANDATE IA (S9M01B63)**

Type

🔗 Question

Message

PLS PROCEED

Reply



Service Request Details

Claim
S9M01B63

Reference
CC4/ASM19001357/R1ea3 

Loss Date
18 January 2019

Report Date
21 Jan 2019 8:44:36 AM

Request Date
21 January 2019

Due Date
21 January 2020

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement

Actions

Next Step
Finish the work

Complete Work

More ▾

Vehicle Information

Make
TPVD HONDA

Model
HRV 1.5

Service Address

Primary Contact/Insured

LOW CHOONG LANG
75A BRANKSOME ROAD, 436573, Singapore

MOTOR.OPERATIONS@GNM.COM.SG

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions
NON-REPORTED

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

New Message

TYPE	
SENT	2/7/19 4:19 PM
FROM	CHAN Kian Chuan
SUBJECT	Re:RE: Re:MANDATE IA (S9M01B63)
BODY	PLS PROCEED

TYPE 

SENT 2/7/19 4:15 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT RE: Re:MANDATE IA (S9M01B63)

BODY Hi, KC, we would like to reseek mandate to include...



TYPE 

SENT 18/5/19 6:36 PM

FROM CHAN Kian Chuan

SUBJECT Re:MANDATE IA (S9M01B63)

BODY PLS PROCEED FOR SETTLEMENT AS FOLLOWS: Repair Co...



TYPE 

SENT 6/3/19 2:06 PM

FROM CHAN Kian Chuan

SUBJECT Re:MANDATE IA (S9M01B63)

BODY WE ARE OF THE VIEW THAT LABOUR IS ON THE HIGH SIDE...



SENT 6/3/19 1:56 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT MANDATE IA (S9M01B63)

BODY Liability: Insured involved in 3 vehicle chain col...



TYPE ?

SENT 23/1/19 11:53 AM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT RE: DS

BODY PLEASE SHARE / LINK OI GIA



TYPE ?

SENT 22/1/19 9:19 PM

FROM CHAN Kian Chuan

SUBJECT DS

BODY PLS PROCEED DS WITH QUANTUM TO BE AGREED



TYPE ?

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

VNI

BODY

Please be informed that vehicle currently not in t...



Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 3 July 2019 9:33 AM
To: Desmond Toh
Cc: Jerome Tan
Subject: RE: SJM578M - TP CLAIM AGAINST SLQ6969J DOA: 18.01.2019 *LKK REF: CC4/ASM19001357/R1pa3
Attachments: EXPRESS SETTLEMENT FORM_SJM578M.pdf

Without Prejudice

Dear Desmond,

Thank you for your email.

We confirm settlement as follows: -

1. Cost of Repair (w/GST)	\$13,276.23 (\$12,407.69 + 7%GST)
2. Loss of Use (16days x \$60.00)	\$ 960.00
3. LTA/ GIA Search Fee	\$ 2.00
4. Medical Fee	\$ 131.65
Total	\$14,369.88

Please duly sign the documents enclosed and return to us for our necessary action.

Thank you.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Desmond Toh <desmondtoh@honda.com.sg>
Sent: Tuesday, 2 July 2019 3:53 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: Jerome Tan <jerometan@honda.com.sg>
Subject: FW: SJM578M - TP CLAIM AGAINST SLQ6969J DOA: 18.01.2019

Without prejudice

Dear Hsiao Tong,

If you got difficulty closing this case and AXA still insist the labour is too high, the only way I can help is to deduct one day \$560.00 from the labour but the LOU or LOR must remain. we treat this as

a special case and we only do it for once and for all. Please inform AXA to expedite this payment if we have to deduct the labour.

Best Regards

Desmond Toh

Kah Motor Co Sdn Bhd

Website : www.honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Sent: Saturday, 22 June, 2019 10:06 AM

To: Desmond Toh <desmondtoh@honda.com.sg>

Subject: RE: SJM578M - TP CLAIM AGAINST SLQ6969J DOA: 18.01.2019

Without Prejudice

Hi Desmond,

We are reviewing the matter and will get back to you by next week.

Kindly hold hands.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Desmond Toh <desmondtoh@honda.com.sg>

Sent: Wednesday, 19 June 2019 9:10 AM

To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: SJM578M - TP CLAIM AGAINST SLQ6969J DOA: 18.01.2019

Dear All,

Any outcome for the above case.

Best Regards

Desmond Toh

Kah Motor Co Sdn Bhd

Website : www.honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page

From: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Sent: Tuesday, 14 May, 2019 2:09 PM
To: Desmond Toh <desmondtoh@honda.com.sg>
Subject: RE: SJM578M - TP CLAIM AGAINST SLQ6969J DOA: 18.01.2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Desmond,

We refer to the email below.

Our principle in the view that the labour is too high, would it be able to low down further.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Desmond Toh <desmondtoh@honda.com.sg>
Sent: Wednesday, 8 May 2019 2:13 PM
To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Subject: RE: SJM578M - TP CLAIM AGAINST SLQ6969J DOA: 18.01.2019

Gentle Reminder

Dear Asher,

Any outcome on the above case.

Best Regards

Desmond Toh

Kah Motor Co Sdn Bhd

Website : www.honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page

From: Desmond Toh
Sent: Monday, 8 April, 2019 3:34 PM
To: 'Asher Sng (LKKAuto)' <AsherSng@lkkauto.com>
Subject: FW: SJM578M - TP CLAIM AGAINST SLQ6969J DOA: 18.01.2019

Dear Asher,

Above is the attach LOD.

Ignore the last LOD.

Best Regards

Desmond Toh

Kah Motor Co Sdn Bhd

Website : www.honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page

From: Desmond Toh

Sent: Monday, 8 April, 2019 3:31 PM

To: 'Asher Sng (LKKAuto)' <AsherSng@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>

Cc: Sum Wai Teck <wtsum@honda.com.sg>; Jerome Tan <jerometan@honda.com.sg>; Winson Chow <winsonchow@honda.com.sg>

Subject: FW: SJM578M - TP CLAIM AGAINST SLQ6969J DOA: 18.01.2019

Your Ref: SLQ6969J

Our Ref: SJM578M

M/s: AXA Insurance Singapore Pte Ltd

C/o: LKK Auto Consultants Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Asher Sng / Case Handler

Dear Asher,

Above is the attached document for third party direct settlement claim.

Kindly provide us your finalized settlement & payment as your soonest.

Will appreciate your response after receiving this email.

Best Regards


Desmond Toh

Kah Motor Co Sdn Bhd

Website : www.honda.com.sg



Visit our
Facebook page



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

◀ Service Request Details

Claim

S9M01B63

Reference

None ✎

Loss Date

January 18, 2019

Request Date

January 21, 2019

Due Date

January 28, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJM578M

Make

TPVD HONDA

21-01-2019 @ 9:50am
Jack veh not in.

Service Address

Primary Contact/Insured

LOW CHOONG LANG
75A BRANKSOME ROAD, 436573, Singapore

MOTOR.OPERATIONS@GNM.COM.SG

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

NON-REPORTED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[Back to Messages](#)

Catherine Chong (LKK Auto)

From: Jack Ng <jackng@honda.com.sg>
Sent: Saturday, 19 January, 2019 11:06 AM
To: SG AXA Insurance SM Claims Service Team; SG AXA Insurance SM AXA SGP - Motor Survey
Subject: ACCIDENT BETWEEN SJM 578 M AND YOUR INSURED SLQ 6969 J
Attachments: GIA REPORT.PDF

Categories: Santosh

Dear all,

Kindly register for direct settlement, attached is the GIA report for your reference.

Kindly let me know who to look for to survey this case.

Thank you and have a great days ahead

Cheers !!!

Best Regards,
Jack Ng
Hp: 8288 6309
Email : Jackng@honda.com.sg
BODY REPAIR AND PAINT CENTRE
255 Alexandra Road Singapore 159937
DID : +65 6514 5481 FAX : +65 6362 5015
Kah Motor Co. Sdn. Bhd.
(A MEMBER OF ORIENTAL HOLDING BERHAD)
Website: www.honda.com.sg



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

21 January, 2019

LOW CHOONG LANG
75A BRANKSOME ROAD
SINGAPORE 436573

Dear Sir,

OUR REF : CC4/ASM19001357/ea3 // S9M01B63
YOUR REF : SLQ 6969J
ACCIDENT INVOLVING SLQ 6969J & SJM 578M ON 18/01/2019 ALONG/ AT
NICOLL HIGHWAY TOWARDS MOUNTBATTEN ROAD

We write to inform you that we are the appointed loss adjuster by your motor insurer, AXA insurance Pte Ltd to deal with the third party claim against your motor policy.

We refer to the above subject matter. We have received third party claim(s) against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. Omission to report the accident will result in a loss of your No Claim Discount (NCD) upon renewal of your policy, and will prejudice any claim(s) by or against you. We would appreciate it if you could urgently file a report at our approved reporting centre.

The report has to be lodged at any of AXA Premium Workshops or reporting centres (subject to your policy). For the list of AXA Premium Workshops conveniently located throughout Singapore, please refer to the back of your Certificate of Insurance or the accompanying folder, or visit <https://www.axa.com.sg/customer-care/personal/motor/owndamageaccidentreporting>.

Your full co-operation is required. Kindly submit the following when lodging the report which list is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)



Kah Motor Co. Sdn. Bhd.
(A Member of Oriental Holdings Berhad)
Body Repair & Paint Centre
6A Mandal Estate
Singapore 728903
Tel : +65 6841 3838
Fax : +65 6362 5015
www.honda.com.sg

M/s: AXA Insurance Singapore Pte Ltd

Date : 4/5/2019

8 Shenton Way
#27-01
Singapore 068811

Attn: Motor Claims Department

Your ref : SLQ 6969 J

Our ref : SJM 578 M

Dear Sir / Madam,

THIRD PARTY DIRECT SETTLEMENT

ACCIDENT INVOLVING SJM 578 M AND SLQ 6969 J ON 18/01/2019

We refer to the item(s) marked (✓) below:

- (✓) We refer to your email dated 23/01/2019.
- (✓) We enclosed herewith the repair invoice / Third Party Direct Settlement Agreement.
- () Kindly forward the discharge voucher for our client's signature within **2 weeks** via email to : **desmondtoh@honda.com.sg**
- (✓) We return your discharge voucher duly completed.
- (✓) Kindly expedite settlement the following :-

Repair Cost	13216.23 \$513,874.42	payable to Kah Motor Co. Sdn. Bhd.
GIA Search Fee	\$2.00	payable to Kah Motor Co. Sdn. Bhd.
Loss of Use	\$560.00 x 14 Working days + 2 Sunday= \$960.00	payable to Tan Bee Guat
Medical Bill	\$131.65	payable to Tan Bee Guat
- (✓) Kindly let us have your cheque made in favour of the above mentioned name(s) for our transmission as soon as possible.
- (✓) Letter of Authority, Discharge voucher, Medical Bill, GIA search

Thank you.

Yours faithfully,



Jack ng

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Wednesday, 23 January 2019 2:44 PM
To: 'MOSTLYLYON@GMAIL.COM'
Subject: ACCIDENT INVOLVING SLQ 6969J AND SJM 578M ALONG NICOLL HIGHWAY ON 18/01/2019

23 JAN 2019

LOW CHOONG LANG

Dear Sir/ Mdm

OUR REF : CC4/ASM19001357/ea3
YOUR REF : SLQ 6969J
ACCIDENT INVOLVING SLQ 6969J AND SJM 578M ALONG NICOLL HIGHWAY ON 18/01/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s KAH MOTOR CO SDN BERHAD acting on behalf of the owner of SJM 578M against your motor insurance policy.

Basing on the circumstances of the accident reported by both parties, where your vehicle was involved in a three (3) vehicle chain collision and your vehicle was the 2nd vehicle that rear-ended the Third Party Vehicle SJM 578M. We are of the opinion that we cannot be absolved from liability.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ashersng@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 6051 or email us at ashersng@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

LETTER OF AUTHORITY

TO WHOM IT MAY CONCERN

ACCIDENT INVOLVING (OWNER'S VEHICLE NO.) SJM 578M &
(THIRD PARTY'S VEHICLE NO.) SLQ 6969J ON 18/01/19.
ALONG Nicola Highway towards Mambatu Bottom Road.

I hereby authorize Kah Motor Co. Sdn Bhd (Kah Motor) and its agents or any person authorized by Kah Motor to do all or any of the following:

- To submit, resolve and make any claim(s) which I may have against the 3rd party insurers.
- To execute, sign discharge voucher/indemnity forms and all necessary documents in connection with and arising out of the above claim.
- Any payment should be made in favour of my name / Kah Motor Co. Sdn. Bhd.

La-Zee Just

Owner Signature

(Co stamp & authorized signature if is Co registered vehicle)

Name : TAN BEE GUAT (Karen)

NRIC No : 50191333/F.

Vehicle No : SJM 578M.

Date : 11th Feb 2019.

Letter of Authority (Insured)



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SLQ 6999J (Insd veh)	Model: Honda HRV (1495cc)
	SJM 578M (TP veh)	
Date of Accident/ Time:	18/01/2019	

Repair Estimate	: \$ 20,360.69	
Final Repair Cost (w/GST)	: \$ 13,276.23	
Loss of Use	: \$ 960.00	16 days at \$ 60.00 per day
Rental (if any)	: \$ -	days at \$ per day
LTA / GIA Search Fee	: \$ 2.00	
Others: (Medical Fee)	: \$ 131.65	
	: \$ -	
Final Settlement Sum	: \$ 14,369.88	

Payee Name : KAH MOTOR CO SDN BERHAD

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: 28
	BOLA Liability: 100 (%)	Assessed Liability (*): 0 (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks:		

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / Invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

KAH MOTOR CO. SDN. BHD.
BODY REPAIR & PAINT CENTRE
8 MANDAI ESTATE
SINGAPORE 728505

KAH MOTOR CO. SDN. BHD.
BODY REPAIR & PAINT CENTRE
8 MANDAI ESTATE
SINGAPORE 728505

Signature of Workshop Representative / Workshop stamp

Name of Representative: Desmond Toh

Date: 05/07/2019

Signature of Witness / Workshop stamp (if applicable)

Name of Witness: Jerome Tan

Date: 05/07/2019

Signature of AXA's surveyor/representative:

Name of AXA's surveyor /Representative:

Date:



MRB



Service Tax Invoice

Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

6A Mandal Estate, SINGAPORE 729903

Mandal Parts Centre

Phone No. : +65 6841 3838 Fax No. :

GST Reg No. M200050223

Company Ref. No. S60FC13803

AXA INSURANCE S'PORE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE, 068811

Customer No. : WZA006

Payment Term : 30 Days

Invoice No. : SINV-BM19001086
Invoice Date : 05/07/19
Order No. : SVO19008866
Reference :
Job Card No. : 07788
Date/Time Received : 19/01/19 / 10:48:35 AM
Licence No. : SJM578M
Model : HRV LX-SIN CVT YM 2016
Car Chassis No. : JHMRU1830GX203774
Car Engine No. : L15B4533775
Mileage : 1575
Service Advisor : JACK NG 1838
Served By : DESMOND TOH
Page : 1

No.	Description	Qty.	UoM	U. Price	Disc %	Amount	7% GST Amount	Incid GST
	TP DIRECT SETTLEMENT (J/NO:)							
	OWNER:TAN BEE GUAT							
	OWNER INSURER:AVIVA LTD							
	ACC DATE:18/01/2019							
	SURVEYED BY:							
	DATE:							
	REF NO:							
	TP INSURER:AXA							
	TP VEH:SLQ 6969 J							
04715-T7A-900ZZ	FACE,RR.BUMPER	1	Each	463.70	25	347.77	24.34	372.11
71593-T7A-000	SPACERR.RR.BUMPER SIDE	1	Each	11.50	25	8.62	0.60	9.22
71598-T7A-J00	SPACER,L.RR.BPR S	1	Each	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER	8	Each	2.30	25	13.80	0.97	14.77
68100-T7A-J20ZZ	TAIL GATE COMP	1	Each	855.70	25	641.77	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE	1	Each	98.70	25	74.02	5.18	79.20
75722-T7W-A01	EMBLEMRR.	1	Each	13.30	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	Each	14.50	25	10.87	0.76	11.63
75701-T5A-000	EMBLEMH	1	Each	10.70	25	8.02	0.56	8.58
	Sum Item					1,127.51		1206.43
	Sum Job No. 1					1,127.51		1206.43
BOSUN	1610 SUNDRIES	1	Hours	50.00		50.00	3.50	53.50
BOJSE	1610 BODY JOINT SEALANT FOR TAILGATE	1	Hours	100.00		100.00	7.00	107.00
BOJSE	1610 BODY JOINT SEALANT FOR END PANEL	1	Hours	100.00		100.00	7.00	107.00
BOJSE	1610 BODY JOINT SEALANT FOR FLOOR PANEL	1	Hours	100.00		100.00	7.00	107.00
BML02I	1610 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	Hours	280.00		280.00	19.60	299.60
BOMISC1	0671 REMOVE & RE-INSTALL REAR VIEW CAMERA (N)	1	Hours	450.00		450.00	31.50	481.50
BOMISC1	0671 RESET & CALIBRATE SMART ENTRY SYSTEM (N)	1	Hours	450.00		450.00	31.50	481.50
BKTG02R	0671 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. (N) ALIGN TAILGATE.(N)	1	Hours	560.00		560.00	39.20	599.20
BMI03D	1757 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	Hours	560.00		560.00	39.20	599.20
BODAMKIT	0671 WINDSCREEN DAM KIT.	1	Hours	100.00		100.00	7.00	107.00
BG02D	1757 REMOVE & INSTALL RR. WINDSCREEN.(N)	1	Hours	560.00		560.00	39.20	599.20
BKRP02M	0671 CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS.	1	Hours	3,920.00		3,920.00	274.40	4,194.40

Printed by: DESMOND TOH on: 05 Jul 2019 at 11:16:22 AM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions. Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms. Interest will be charged at 2% per month on overdue amounts.

Please give us your feedback by scanning the QR Code using mobile device.





Service Tax Invoice

Kah Motor Co. Sdn. Bhd.
(A Member of Oriental Holdings Berhad)
6A Mandal Estate, SINGAPORE 729903
Mandal Parts Centre
Phone No. : +65 6841 3838 Fax No. :

GST Reg No. M200050223
Company Ref. No. 580FC1380G

AXA INSURANCE S'PORE PTE LTD
MOTOR CLAIMS DEPT
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE, 068811

Customer No. : WZA006
Payment Term : 30 Days

Invoice No. : SINV-BM19001086
Invoice Date : 05/07/19
Order No. : SVO19008866
Reference :
Job Card No. : 07788
Date/Time Received : 19/01/19 / 10:48:35 AM
Licence No. : SJM578M
Model : HRV LX-SIN CVT YM 2016
Car Chassis No. : JHMRU1830GX203774
Car Engine No. : L15B4533775
Mileage : 1575
Service Advisor : JACK NG 1838
Served By : DESMOND TOH
Page : 2

No.	Description	Qty.	UoM	U. Price	Disc %	Amount	7% GST Amount	Incl GST
BP06R	1610 ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS, SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) SUPPLEMENTARY PART	1	Hours	2,700.00		2,700.00	189.00	2,889.00
	Sum Labor					9,930.00		10625.1
66100-T7A-300ZZ	PANEL COMPRR.	1	Each	373.10	25	279.82	19.59	299.41
04655-T7A-310ZZ	PANEL SETRR.FLOOR	1	Each	675.50	25	506.62	35.46	542.08
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	Each	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	Each	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	Each	19.30	25	14.47	1.01	15.48
76711-T8A-003	CAPPVOT	1	Each	4.81	25	3.61	0.25	3.86
91501-S70-003	FASTENER BW/SHIELD	4	Each	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	Each	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	Each	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	Each	60.00		120.00	8.40	128.40
74940-TZ5-A01	BUZZER ASSYSMART	1	Each	60.40	25	45.30	3.17	48.47
65513-T7A-300ZZ	STIFFENERRR.JACK UP	1	Each	61.40	25	46.05	3.22	49.27
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	Each	43.90	25	32.92	2.30	35.22
90321-SLE-000	NUTHEX CAP 5MM	1	Each	2.80	25	2.10	0.15	2.25
90321-SLE-000	NUTHEX CAP 5MM	1	Each	2.80	25	2.10	0.15	2.25
74800-T7A-J02	LOCK ASSYTAIL.GATE	1	Each	78.90	25	59.17	4.14	63.31
74646-T7A-010	COVERRR.FLOOR UN	1	Each	120.70	25	90.52	6.34	96.86
84550-T7A-J00	BOX ASSY.CARGO FLOOR	1	Each	129.50	25	97.12	6.80	103.92
	Sum Item					1,350.19		1444.7
	Sum Job No. 2					11,280.19		12089.8

Sum Labor	9,930.00	695.10	10,625.10
Sum Item	2,477.70	173.43	2,651.13
Total SGD	12,407.70	868.53	13,276.23
Total Payable (SGD)			13,276.23

Printed by DESMOND TOH on 05 Jul 2019 at 11:16:22 AM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions.
Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms.
Interest will be charged at 2% per month on overdue amounts.

Please give us your
feedback by scanning
the QR Code using
mobile device.



Jack Ng

From: Desmond Toh
Sent: Saturday, January 19, 2019 11:29 AM
To: Jack Ng
Cc: Jerome Tan
Subject: SJM578M



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-011002
Date of Request: 19/01/2019

Your Ref No: Online Purchase

Kah Motor Co Sdn Bhd
15 Ubi Road 4
Singapore 408610

Dear Sir/Madam,

Enquiry Date: 19/01/2019
Enquiry By: Toh Lee Soon Desmond
TP Vehicle No.: SLQ6969J
Accident Date: 18/01/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLQ6969J	AXA Insurance Pte Ltd	28/11/2018-27/11/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

TAX INVOICE

Our Ref No: GR-19-011002

Date of Request: 19/01/2019

Your Ref No: Online Purchase

Kah Motor Co Sdn Bhd
15 Ubi Road 4
Singapore 408610

Dear Sir/Madam,

Enquiry Date 19/01/2019

Enquiry By Toh Lee Soon Desmond

TP Vehicle No. SLQ6969J

Accident Date 18/01/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Melvin Tan Cardiology Practice Pte Ltd

38 Irrawaddy Road #06-40 Mt Elizabeth Novena Specialist Ctr
Singapore 329563 Tel: 6733 3568 Fax: 6733 5668

GST Reg No : 19-9800254-H

Co Reg No : 19-9800254-H

TAX INVOICE

TAN,BEE GUAT (KAREN)
78C FERNHILL ROAD

S(259129)

Invoice No. : 59484
Our Reference : 12983
Date : 19 Jan 2019

PATIENT : TAN,BEE GUAT (KAREN) (S0191333F)

DESCRIPTION	UNIT PRICE	QTY	TOTAL (\$)	DISC (%)	NET TOTAL FEE (\$)
CONSULTATION	120.00	1.00	120.00		120.00
LEXOTAN 1.5MG	0.50	6.00 TABS	3.00		3.00
ROUNDING DIFFERENCE	0.04	1.00	0.04		0.04
Sub-Total					123.04
Add GST 7.0%					8.61
Total Amount Payable					131.65
CARD Payment Received - Receipt No. 58682					131.65
Outstanding Balance					0.00

All Cheques should be crossed and made payable to :

Melvin Tan Cardiology Practice Pte Ltd

This is a computer generated invoice which does not require a signature

E & O.E

DR MELVIN E.H. TAN

MBBS (S'pore), MRCP (Ireland), FAMS (Cardiology)
Clinical & Interventional Cardiologist
MELVIN TAN CARDIOLOGY PRACTICE
38 Irrawaddy Road #06-40
Mount Elizabeth Novena Specialist Centre
Singapore 329563
Tel: (65) 6733 3588 Fax: (65) 6733 5668



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM19001357/R1pa3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN		Date : 24-07-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLQ 6969J	Veh. Inspected	SJM 578M	
Policy No.	GA315358/1	Coverage (\$)	0.00	
Claim No.	S9M01B63	Excess (\$)	0.00	
Assign From		Assign Date	21/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA HRV 1.5 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JHMRU1830GX203774	Colour	GREY	
Odometer	15752	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/01/2019	Inspection Date	11/02/2019	
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 578M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REFLECTOR ASSYR.RR. (SN) (CONSISTENT)	NOT NECESSARY	117.22	-
1	REFLECTOR ASSYL.RR. (SN) (CONSISTENT)	NOT NECESSARY	117.22	-
1	FACE,RR.BUMPER (SN) (CONSISTENT)	DEFORMED	347.77	347.77
1	FACER.RR.BUMPER CORNER (SN) (CONSISTENT)	NOT NECESSARY	70.57	-
1	FACEL.RR.BUMPER CORNER (SN) (CONSISTENT)	NOT NECESSARY	70.57	-
1	SPACER R,RR.BPR S (SN) (CONSISTENT)	NECESSARY	12.67	8.62
1	SPACER L,RR.BPR S (SN) (CONSISTENT)	NECESSARY	12.67	12.67
8	CLIP ,BUMPER (SN) (CONSISTENT)	NECESSARY	13.80	13.80
1	TAIL GATE COMP (SN) (CONSISTENT)	BENT	641.77	641.77
1	WEATHERSTRIPTAILGATE (SN) (CONSISTENT)	NECESSARY	74.02	74.02
1	SWITCH ASSYTAILGATE OPENER (SN) (CONSISTENT)	NOT NECESSARY	78.97	-
1	EMBLEMRR (SN) (CONSISTENT)	NECESSARY	9.97	9.97
1	EMBLEM ,RR.I-VTEC (SN) (CONSISTENT)	NECESSARY	10.87	10.87
1	GARNISH ASSYRR.LICENSE (SN) (CONSISTENT)	NOT NECESSARY	142.35	-
1	EMBLEMH (SN) (CONSISTENT)	NECESSARY	8.02	8.02
1	PANEL COMPRR (SN) (CONSISTENT)	BENT	279.82	279.82
1	PANEL SETRR.FLOOR (SN) (CONSISTENT)	BUCKLED	506.62	506.62
1	RUBBER CR.WINDSHIELD DAMPER (SN) (CONSISTENT)	NECESSARY	14.47	14.47
1	DAMPERSTD 5X5 (SN) (CONSISTENT)	NECESSARY	6.37	6.37
1	RUBBER CL.WINDSHIELD DAMPER (SN) (CONSISTENT)	NECESSARY	14.47	14.47
1	CAPPIVOT (SN) (CONSISTENT)	NECESSARY	3.60	3.60
4	FASTENER BW/SHIELD (SN) (CONSISTENT)	NECESSARY	15.90	15.90
2	FASTENER B	NECESSARY	7.95	7.95
2	FASTENER AW/SHIELD (SN) (CONSISTENT)	NECESSARY	5.70	5.70
2	WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	120.00	120.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	50.00
1	BUZZER ASSYSMART (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	45.30	45.30
1	STIFFENERRR.JACK UP (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	46.05	46.05
1	LINING ASSYRR.PANEL (SN) (CONSISTENT) (ADDITIONAL)	CUT	32.92	32.92

Report Ref No. CC4/ASM19001357/R1pa3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	NUTHEX CAP 5MM (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	2.10	2.10
1	NUTHEX CAP 5MM (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	2.10	2.10
1	LOCK ASSYTAILGATE (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	59.17	59.17
1	COVERRR.FLOOR UN (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	90.52	90.52
1	BOX ASSY,CARGO FLOOR (SN) (CONSISTENT) (ADDITIONAL)	BENT	97.12	97.12
			3,178.64	2,527.69
	LABOUR			
	BODY JOINT SEALANT FOR TAILGATE.		150.00	100.00
	BODY JOINT SEALANT FOR END PANEL.		150.00	100.00
	BODY JOINT SEALANT FOR FLOOR PANEL.		150.00	100.00
	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER.		380.00	280.00
	REMOVE & REINSTALL REAR VIEW CAMERA.		450.00	450.00
	RESET & CALLIBRATE SMART ENTRY SYSTEM.		450.00	450.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE .		560.00	560.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		800.00	560.00
	WINDSCREEN DAM KIT.		200.00	100.00
	REMOVE & INSTALL RR.WINDSCREEN .		560.00	560.00
	CUT OFF & RENEW RR PANEL .RENEW ALL DAMAGE PARTS.		7,500.00	4,480.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		4,500.00	2,700.00
			15,850.00	10,440.00
	GRAND TOTAL		19,028.64	12,967.69
	RECOMMENDED COST OF REPAIRS			12,967.69

Report Ref No. CC4/ASM19001357/R1pa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

S9M01063

Reference

CCA/ASM19001357/R1pa042

Loss Date

18 January 2019

Report Date

21 Jan 2019 8:44:36 AM

Request Date

21 January 2019

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

SJMS78M

Make

TOYOT HONDA

Model

HRV 1.5

Service Address

...

Primary Contact/Insured

LOW CHOONG LANG
75A BRANKSOME ROAD, 436573, Singapore
MOTOR.OPERATIONS@GNM.COM.SG

Claim Handler

CHAN Kian Chuan
656804269
kianchuan.chan@axa.com.sg

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Additional InstructionsNON-REPORTED

Document Type	Document SubType	NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document TypeDocument SubType Upload Documents						
Accident Statement						
Reports & Statement						
Meritman						
Invoice						
Surveyor/ Assessor expense						
LKK Invoice3 (6).pdf						
LKK AUTO CONSULTANTS PTE LTD (TP)						
26 July 2019						

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
 MEDICAL FEE.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 July 2019
 LK03Inspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 July 2019
 LKKAdjustment1a (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 July 2019
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 July 2019
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	26 July 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	26 July 2019
 WORKSHOP INVOICE.pdf	Invoice	Register	LKK AUTO CONSULTANTS PTE LTD (TP)	26 July 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	26 July 2019
 MEDICAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 July 2019
 LTA FRBF COE Rebate Details.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	6 March 2019
 Immediate Advice with Mandate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 March 2019
 LKK Survey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 March 2019
 LKK Resurvey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 March 2019
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	16 February 2019

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
 EMAIL FROM WORKSHOP FOR TP REG-III	Letters and Correspondence	Others	NIKAM Santosh Pandurang	21 January 2019
 Ltr to Insured -non reporting.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	21 January 2019