

1/30/2018

INS. CASE OWNER:

Lynneley

CC 4, Asm 1900

1359,

Agazyl

LKK:
IDAC:

94488

Surveyor:

Admin

DOI:

ASSIGNMENT

21/1/19

Date Time:

21/1/19

Registered in Merimen:

Pre-assign / CCU / FTE

SMD 9561M

S9MO1Avo



Insured Vehicle No.:

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SJS9742P

INSRS:
WSP:
Tel:
Liability:
RMKS:Progressive
Car CareINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

23/1

JY

5/7/19

11/2/19

11/2/20

11/2/20

SJS9742P - S/FCL 2288/14632:000 (1/1/19)

SMD 9561M - X

Rec car send TP (Pending LOD)

LOD in via email - seek mandate (Pending approval)

offer ETC \$1300 (Pending acceptance)

File -> (ult to meet as per)

File pass to MK to close.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

207 FEB 14 19

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5 1119.97

(2 days)

Reduction: \$1010.46 % 49

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed)

BOLA S/N No.: NIL

If NO or B 28, Ass. Lia:

Repair Cost:

\$5 1,198.37

Loss of Rental (LOR):

\$5 -

(days)

Loss of Use (LOU):

\$5 100.00

(5 50 x 2 days)

60 x 2 = 120

Loss of Income (LOI):

\$5 -

(5 x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$5 2.00

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/Independent)

Legal Cost

\$5 -

(1720 37)

Total:

\$5 1700.37

Global Sum \$5:

(1700)-

1) Claim status:

Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

#350.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1:

\$5 1300.00

Name 1:

Progressive Car Care Pte Ltd

Payee 2: (Strike if N.A.)

\$5 -

Name 2:

Payee 3: (Strike if N.A.)

\$5 -

Name 3:

COPY SENT
11/07/2020

REF: ASM(AXA)

1359/A①

ASSIGNMENT

From: Date: 21/07/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJS 9742P

at Workshop with Progressive

of Blk 6022A Ubi Rd 1 #01-45

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition) 12pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bat or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Sent: Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJS9742P - Yc Page: 2009 Sept

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Jazz cc 1497

Colour: Red AC Insured / Std / NI / NA

Sp Reading: 138265 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM6E885095201480

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 165/55R16
R: 185/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bat 06	mm	R/Bat 06	mm
U/Bat 06	mm	U/Bat 06	mm

D.O.A. D.O.I. 21/01/19

Survey held at Progressive (Ubi)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPAXA

MV: 16K

PV: 12.3K

Nett: 3.7K

(Red = \$1010.46 / 47%)

17-4-19 \$1,119.97

Date/Time: File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1. ...

1. Phone

1. Other

Report Format:

Lump Sum / I.B.F. (\$) 1

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Inv (\$☐ Workshop (\$

TOTAL

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: TP 0119 - 5368
 Assessment number: TP 0119 - 5368
 Version: 1810
 Date calculated: 03/14/2019 03:56 PM

Full Report
 Registration: SJS9742P
 Printed: 15/03/2019 10:07 AM

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1R	55.15
Surface-/Blend Paint	15.13
Surface Painting Plastic	2.34
Material-constant Metal	9.00
Material-constant Plastic	28.60
Total	110.22

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0283	FRONT BUMPER	04711TF0G60ZZ		330.00
0293	FRT TOWING EYE COVER	71104TF0000ZH		12.00
0317	L/F OUT BUMPER BRKT	71198TF0003		9.00
0318	R/F OUT BUMPER BRKT	71193TF0003		9.00
0351	FRT LWR BUMP GRILLE	71103TF0G60		85.00
0651	L/FOG LAMP COVER	33952TF0E11ZM		60.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			505.00
u: Used parts	Addition(+15.00%)			75.75
	Total			580.75

Extras

Code	Description	Price SGD
1001	AUDATEX FEE	42.00*
	Total Extras	42.00

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: TP 0119 - 5368
Assessment number: TP 0119 - 5368
Version: 1810
Date calculated: 03/14/2019 03:56 PM

Full Report
Registration: SJS9742P
Printed: 15/03/2019 10:07 AM

Final Calculation

	SGD	SGD
Parts	505.00	
Addition(+15.00%)	75.75	
Total Parts		580.75
Labour Time Base 10 WU/h		
Total 35.0 WU X 45.00 SGD/h	157.50	
Total of Labour		157.50
Total Of Extras		42.00
Paint Work Time Base 10 WU/h		
Labour Cost 51.0 WU X 45.00 SGD/h	229.50	
Material Cost	110.22	
Total Paint Including Material		339.72
Repair Cost Excludes GST		1,119.97
GST (+7.0%)		78.40
Repair Cost Included GST		1,198.37

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: TP 0119 - 5368
Assessment number: TP 0119 - 5368
Version: 1712
Date calculated: 01/19/2019 09:47 AM

Full Report
Registration: SJS9742P
Printed: 01/19/2019 9:47 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Wayne Lim	Currency:	SGD
Claim Reference:	TP 0119 - 5368	Date of Incident:	2019-01-17
Estimated Repair Time:	4	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	JAZZ(GE6/8:GG1)
Sub Model:	BASE MODEL
Model Sheet Number:	35 AL 01
Registration:	SJS9742P
VIN number:	JHMGE88509S201480
Odometer:	137977

Model Specs

FROM MODEL 2009	AUTO AIR CON	SPORT BUMPER	XENON HEADLAMPS
FOG LAMPS	1.5 LTR 88KW	AUTO GEARBOX 5 SPEED	WHEELS 5.5J X 15
PRODUCTION IN JAPAN	GRILLE TRIM CHROMED	TWO PACK STRT COLOUR	PREPARE OFF VEHICLE

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: TP 0119 - 5368
Assessment number: TP 0119 - 5368
Version: 1712
Date calculated: 01/19/2019 09:47 AM

Full Report
Registration: SJS9742P
Printed: 01/19/2019 9:47 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
8101C1)	R + R LEFT FRONT BUMPER BRACKET		1.0	4.50
8101C2)	R + R RIGHT FRONT BUMPER BRACKET		1.0	4.50
8101A2	RENEW FRONT BUMPER		6.0	27.00
8101B1)	R + R FRONT BUMPER SUPPORT		2.0	9.00
8101A2 B	ADD/WORK FOR FRONT FOG LAMPS		2.0	9.00
712103)	R + R LEFT HEADLAMP		4.0	18.00
712102)	R + R R/HEADLAMP (L/HEADLAMP REMOVED)		3.0	13.50
NO NUMBER	ADJUST HEADLAMP		2.0	9.00
8131A6	R + R LEFT FRONT WHEELHOUSE INSERT		3.0	13.50
8131A7	R + R RIGHT FRONT WHEELHOUSE INSERT		3.0	13.50
1009	FRONT PANEL CPL REPAIR		10.0*	45.00

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: TP 0119 - 5368
 Assessment number: TP 0119 - 5368
 Version: 1712
 Date calculated: 01/19/2019 09:47 AM

Full Report
 Registration: SJS9742P
 Printed: 01/19/2019 9:47 AM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	3.70	37.0	166.50
Total of Labour			166.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO PACK STRT COLOUR	WU Price SGD
	FRONT BUMPER NEW PART PAINT K1R	12.0 ✓
	FRT TOWING EYE COVER NEW PART PAINT K1R	3.0 ✓
	L/F BUMPER COVER NEW PART PAINT K1R	3.0 ✓
	L/FOG LAMP COVER NEW PART PAINT K1R	3.0 ✓
	L/F WING SURFACE PAINT	5.0
	FRONT PANEL CPL SURFACE PAINT	6.0

Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1R	53.75 ✓
0293	FRT TOWING EYE COVER NEW PART PAINT K1R	0.35 ✓
0643	L/F BUMPER COVER NEW PART PAINT K1R	1.05
0651	L/FOG LAMP COVER NEW PART PAINT K1R	1.05
0741	L/F WING SURFACE PAINT	5.63 ✓
1009	FRONT PANEL CPL SURFACE PAINT	9.50 ✓

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		32.0	
Preparation Main Work Metal	0.30	3.0	13.50
Preparation Comp. Work Plastic	1.00	10.0	45.00
Total	10 WU/h	4.50	45.0

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1R	56.20
Surface-/Blend Paint	15.13
Material-constant Metal	9.00
Material-constant Plastic	28.60
Total	108.93

Spare Parts

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: TP 0119 - 5368
 Assessment number: TP 0119 - 5368
 Version: 1712
 Date calculated: 01/19/2019 09:47 AM

Full Report
 Registration: SJS9742P
 Printed: 01/19/2019 9:47 AM

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0283	FRONT BUMPER	04711TF0G60ZZ	Reland	✓ 330.00
0293	FRT TOWING EYE COVER	71104TF0000ZH	Reland	✓ 12.00
0317	L/F OUT BUMPER BRKT	71198TF0003	Free	✓ 9.00
0318	R/F OUT BUMPER BRKT	71193TF0003	Free	✓ 9.00
0319	L/F UPP BUMPER BRKT	71190TF0000	Free	+ 15.00
0340	FRT BUMPER SUPPORT	71130TF0000ZZ	Free	+ 80.00
0350	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		X 20.00
0351	FRT LWR BUMP GRILLE	71103TF0G60	Reland	✓ 85.00
0561	L/F HEADLAMP	33151TF0N51	not in	X 500.00
0637	L/F FOG LAMP	33951TF0E11	not in	X 195.00
0643	L/F BUMPER COVER	33957TF0E11	not in	+ 15.00
0651	L/FOG LAMP COVER	33952TF0E11ZM	missing	✓ 60.00
0789	L/F WING CLAMP KIT	USE SINGLE PARTS	Free	+ 20.00
0790	R/F WING CLAMP KIT	USE SINGLE PARTS	Free	+ 20.00
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 1,370.00
u: Used parts				Addition(+15.00%) 205.50
Total				1,575.50

Extras

Code	Description	Price SGD
1000	FRT NO PLATE not in	35.00* +
1001	AUDATEX FEE not in	42.00* ✓
Total Extras		77.00

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: TP 0119 - 5368
 Assessment number: TP 0119 - 5368
 Version: 1712
 Date calculated: 01/19/2019 09:47 AM

Full Report
Registration: SJS9742P
Printed: 01/19/2019 9:47 AM

Final Calculation

	SGD	SGD
Parts	1,370.00	
Addition(+15.00%)	205.50	
Total Parts		1,575.50
Labour Time Base 10 WU/h		
Total 37.0 WU X 45.00 SGD/h	157.50	166.50
Total of Labour		166.50
Total Of Extras		77.00
Paint Work Time Base 10 WU/h		
Labour Cost 45.0 WU X 45.00 SGD/h	229.50	
Material Cost	202.50	
Total Paint Including Material	110.23	108.93
		311.43
Repair Cost Excludes GST		2,130.43
GST (+7.0%)		149.13
Repair Cost Included GST		2,279.56

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Adrian King
 P/P.21/01/19
 02 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	2275G
Vehicle Details	
Vehicle No.:	SJS9742P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5L AT ABS D/AB HID 2WD 5DR
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	L15A71001770
Chassis No.:	JHMGE88509S201480
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$22,306.00
Original Registration Date:	17 Sep 2009
First Registration Date:	17 Sep 2009
Transfer Count:	0
Actual ARF Paid:	\$22,306.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Sep 2019
PARF Rebate Amount:	\$11,153.00
Intended COE Rebate Details	
COE Expiry Date:	16 Sep 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,020.00
COE Rebate Amount:	\$1,174.00
Total Rebate Amount:	\$12,327.00

The information contained herein is correct as at 22 Jan 2019

OK

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: TP 0119 - 5368
Assessment number: TP 0119 - 5368
Version: 1810
Date calculated: 03/14/2019 03:56 PM

Full Report
Registration: SJS9742P
Printed: 15/03/2019 10:07 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Ray Lin	Currency:	SGD
Claim Reference:	TP 0119 - 5368	Date of Incident:	2019-01-17
Estimated Repair Time:	4	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	JAZZ(GE6/8:GG1)
Sub Model:	BASE MODEL
Model Sheet Number:	35 AL 01
Registration:	SJS9742P
VIN number:	JHMGE88509S201480
Odometer:	137977

Model Specs

FROM MODEL 2009	AUTO AIR CON	SPORT BUMPER	XENON HEADLAMPS
FOG LAMPS	1.5 LTR 88KW	AUTO GEARBOX 5 SPEED	WHEELS 5.5J X 15
PRODUCTION IN JAPAN	GRILLE TRIM CHROMED	TWO PACK STRT COLOUR	PREPARE OFF VEHICLE

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: TP 0119 - 5368
Assessment number: TP 0119 - 5368
Version: 1810
Date calculated: 03/14/2019 03:56 PM

Full Report
Registration: SJS9742P
Printed: 15/03/2019 10:07 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
8101C1)	R + R LEFT FRONT BUMPER BRACKET		1.0	4.50
8101C2)	R + R RIGHT FRONT BUMPER BRACKET		1.0	4.50
8101A2	RENEW FRONT BUMPER		6.0	27.00
8101B1)	R + R FRONT BUMPER SUPPORT		2.0	9.00
8101A2 B	ADD/WORK FOR FRONT FOG LAMPS		2.0	9.00
712103)	R + R LEFT HEADLAMP		4.0	18.00
712102)	R + R R/HEADLAMP (L/HEADLAMP REMOVED)		3.0	13.50
8131A6	R + R LEFT FRONT WHEELHOUSE INSERT		3.0	13.50
8131A7	R + R RIGHT FRONT WHEELHOUSE INSERT		3.0	13.50
1009	FRONT PANEL CPL REPAIR		10.0*	45.00

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: TP 0119 - 5368
 Assessment number: TP 0119 - 5368
 Version: 1810
 Date calculated: 03/14/2019 03:56 PM

Full Report
 Registration: SJS9742P
 Printed: 15/03/2019 10:07 AM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	3.50	35.0	157.50
Total of Labour			157.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h	
Code	Description - TWO PACK STRT COLOUR	WU	Price SGD
	FRONT BUMPER NEW PART PAINT K1R	12.0	
	FRT TOWING EYE COVER NEW PART PAINT K1R	3.0	
	L/FOG LAMP COVER NEW PART PAINT K1R	3.0	
	L/F BUMPER COVER SURFACE PAINT PLAST.	3.0	
	R/F BUMPER COVER SURFACE PAINT PLAST.	3.0	
	R/FOG LAMP COVER SURFACE PAINT PLAST.	3.0	
	L/F WING SURFACE PAINT	5.0	
	FRONT PANEL CPL SURFACE PAINT	6.0	

Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1R	53.75
0293	FRT TOWING EYE COVER NEW PART PAINT K1R	0.35
0651	L/FOG LAMP COVER NEW PART PAINT K1R	1.05
0643	L/F BUMPER COVER SURFACE PAINT PLAST.	0.78
0644	R/F BUMPER COVER SURFACE PAINT PLAST.	0.78
0652	R/FOG LAMP COVER SURFACE PAINT PLAST.	0.78
0741	L/F WING SURFACE PAINT	5.63
1009	FRONT PANEL CPL SURFACE PAINT	9.50

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		38.0	
Preparation Main Work Metal	0.30	3.0	13.50
Preparation Comp. Work Plastic	1.00	10.0	45.00
Total	10 WU/h	51.0	229.50



New Cars

Used Cars

Sell My Car

Directory

Products


Insurance

Articles

Forum

Resources

CHEAPEST CAR INSURANCE RENEWAL

Choice of
\$0 excessOption of any
workshop

GET A CHEAPER QUOTE NOW!



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2007 Suzuki Swift 1.5A (COE Till 08/2022).



Car In Good Condition New
Compressor And Coil Regular
Scheduled Servicing.
Direct Owner StarAd



**1 CERTIFIED PRE-OWNED
MERCEDES-BENZ**



A view our cars

Browse by Category



Save Search



Print

Sort by Date Posted

20 results/page

7 vehicles

Search

jazz

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

jazz

Any

Any

2010

Any

Any

Any

Available



Honda Jazz 1.5A L Skyroof

\$19,800

\$8,520 /yr

08-Jan-2010

1,497 cc

-

Hatchback

Available

Selling Cheap With Low Depreciation In The Market Yet Negotiable. New Road Tax Till July 2019. White Sporty Jazz. With The Power Of 1.5L Car Yet A Great Fuel Efficient Of 13.9km/l. SkyRoof Model. Very...

Roadlink Auto Pte Ltd

Posted: 20-Jan-2019 Tags: 2010 Honda Jazz, 2010 Honda jazz, Honda Jazz, Honda jazz, Honda jazz, Honda jazz, Honda jazz, Used Honda



Honda Jazz 1.5A L

\$20,300

\$8,920 /yr

20-Jan-2010

1,497 cc

-

Hatchback

Available

Best Short Term Japanese Make Honda Jazz 1.5A Hatchback In Stock Now! Low Fuel Consumption! Low Road Tax Probably Best Or COE Renewal Another 12 Months Later! Full Serviced Done By Kah Motor Agent! LD...

Posted: 22-Jan-2019 Tags: 2010 Honda Jazz, 2010 Honda jazz, Honda Jazz, Honda jazz, Honda jazz, Honda jazz, Honda jazz, Used Honda



Honda Jazz 1.3A L

\$18,200

\$8,610 /yr

26-Jan-2010

1,339 cc

129,500 km

Hatchback

Available

Easy To Maintain Car Colour Which Suit Drivers Of All Age And Genders. The Most Reliable And Down To Earth Hatchback Car In The Market. One Of The Most Fuel Efficient Vehicle For Your Next Short Term ...

Posted: 25-Jan-2019 Tags: 2010 Honda Jazz, 2010 Honda jazz, Honda Jazz, Honda jazz, Honda jazz, Honda jazz, Honda jazz, Used Honda



Honda Jazz 1.3A

\$19,000

\$9,170 /yr

10-Feb-2010

1,339 cc

131,664 km

Hatchback

Available

1 Owner Only, One Of The Best And Sellable Short Term Ride Honda Jazz 1.3A In Stock Now, Super Low Mileage Clocked 131,664km! Lowest Fuel Consumption! Low Maintenance Cost! With Such A Best Condition ...

Posted: 26-Jan-2019 Tags: 2010 Honda Jazz, 2010 Honda jazz, Honda Jazz, Honda jazz, Honda jazz, Honda jazz, Honda jazz, Used Honda

GET YOUR
COE
RENEWAL
LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Honda Jazz 1.5A L

\$24,786

\$11,010 /yr

20-Apr-2010

1,497 cc

149,000 km

Hatchback

Available

1 Careful Owner With Low Mileage Done, Car Maintained By Reputable Workshop, Wear And Tear Replaced, Well Known For Fuel Efficiency, New Road Tax.

Posted: 19-Jan-2019 Tags: 2010 Honda Jazz, 2010 Honda jazz, Honda Jazz, Honda jazz, Honda jazz, Honda jazz, Honda jazz, Used Honda



Honda Jazz 1.3A L

\$25,800

\$9,410 /yr

06-Oct-2010

1,339 cc

140,000 km

Hatchback

Available

100% Loan Approval With Low Interest Rate! Kah Motor Agent Servicing Done, Depreciation At \$8K Plus Only, High PARF At \$9,763. New Road Tax Till Apr 2019, Most Reliable Jap Hatchback In Market, Instal...

Posted: 04-Oct-2018 Tags: 2010 Honda Jazz, 2010 Honda jazz, Honda Jazz, Honda jazz, Honda jazz, Honda jazz, Honda jazz, Used Honda



Honda Jazz 1.5A L

\$28,800

\$9,010 /yr

08-Dec-2010

1,497 cc

108,360 km

Hatchback

Available

Well Kept! Fully Serviced At Kah Motors, Buy With Peace Of Mind. Lowest Depreciation With Highest OMV. Low Mileage Of 13.3k Km Per Year. Known For Fuel Efficiency, Call For Viewing Appointment Now.

Posted: 14-Jan-2019 Tags: 2010 Honda Jazz, 2010 Honda jazz, Honda Jazz, Honda jazz, Honda jazz, Honda jazz, Honda jazz, Used Honda

SHORTLISTED

POSTED

Compare

Save this search criteria, to get email alerts whenever a match is found.



Save Search

◀ Service Request Details

Claim

S9M01AV0

Reference

None 

Loss Date

January 17, 2019

Request Date

January 21, 2019

Due Date

January 28, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration

SJS9742P

Make

TPVD HONDA

21-01-2019 @ 10:11am
Lily wh not in

Service Address

2/2

Primary Contact/Insured

LEONG WEY HSIEN (LIANG WEIXIAN)
BLK 81 REDHILL LANE, #03-55, 150081, Singapore

LWXIAN@SINGNET.COM.SG

Claim Handler

KHONG Lynn
68804892
lynn.khong@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Download Invoice

Catherine Chong (LKK Auto)

From: Peiwen <peiwen@procarcare.com.sg> on behalf of Claims <claims@procarcare.com.sg>
Sent: Saturday, 19 January, 2019 2:34 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: Lily; Soo Leong Keat
Subject: PROGRESSIVE/TP/SJS 9742 P(SMD 9561 M) /DOA 17.01.2019/EST \$2279.56
Attachments: 19012019143158.pdf

Categories: Pragati

Hi Sir,

Please refer to the attached and arrange survey.
Vehicle is NOT IN workshop.

Thank You.

Regards,

Pei Wen NG
Claims Advisory
Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 01-45/46 Singapore 408716
T: +65 6741 5336 | F: +65 6741 7208
E: claims@procarcare.com.sg
W: www.procarcare.com.sg



**With effect from 1 Sep 2018, Progressive Automotive Pte Ltd has been rebranded as Progressive Car Care Pte Ltd. You may now reach us at our new email addresses (@procarcare.com.sg). We look forward to your continued support*

 <MANDATE IA> - S9M01AV0 {ACCIDENT INVOLVING
SMD 9561M (OI) & SJS 9742P (TP) ON 17/01/2019}

Type

 Question

Message

Liability: 100% Informed OI on TP claim and NCD issue. Agreed to settle at best. We seek your mandate at \$1320.37(claiming LOU). Mandate IA had been uploaded in Smartclaim. Kindly let us have your approval/instruction. Thanks - Cecilia 05/07/2019

[Reply](#)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 5/7/2019

Survey Details:

Date of loss	17-Jan-19
Date of appointment	21-Jan-19
Date of survey	21-Jan-19
Location of survey	PROGRESSIVE CAR CARE PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SJS9742P
Make and Model	HONDA JAZZ 1.5L AT ABS
Date of registration	17-Sep-09
Parf Rebate	
Market Value	\$ 16,000.00
Parf Rebate	\$ 12,332.00
Nett Loss	\$ 3,668.00

Repair details:

Initial Estimate	2,130.43
------------------	----------

Proposed/Revised repair cost:

Parts	\$ 622.75
Check items (estimate)	\$ -
Labour	\$ 497.22
Total	\$ 1,119.97
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>2 days</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 1,198.37	W/GST
Loss of use	\$ 120.00	2days x \$60
Loss of rental		
Loss of income		
LTA search fees	\$ 2.00	
Others		
Proposed Total	1320.37	

<< **Re:<MANDATE IA> - S9M01AV0 {ACCIDENT INVOLVING SMD 9561M (OI) & SJS 9742P (TP) ON 17/01/2019}**

Type

🔗 Question

Message

Proceed with advised quantum. Thanks

Reply

THIRD PARTY DISCHARGE VOUCHER

I / ~~we~~ Tan Chit Sin agreed to accept the sum of
(S\$ 1320.37) in full and final
settlement of all claims that I / We or may hereafter have against the driver / owner of motor
vehicle no. SMD 9561M and / or AXA Insurance Pte Ltd.
for damage / loss to motor vehicle no. SJS9742P arising from an accident on
17/1/19 along MND carpark. I / We hereby
authorized you to make payment without admission of liability on the part of
_____ or your insured direct to M/s PROGRESSIVE CAR CARE PTE LTD.

PROGRESSIVE CAR CARE PTE LTD
Blk 3022A Ubi Road 1 # 01-45/46
Singapore 408716
Tel: 6741 5336 Fax: 6741 7208
Email: claims@procarcare.com.sg

As
SIGNATURE OF CLAIMANT

NRIC:

46922759

[Signature]
SIGNATURE OF WITNESS



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

=====**GST REG. NO: M2-0119201-3 CO. REG. NO: 199307741M**=====

PROGRESSIVE CAR CARE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY
ATTN : WENDY / PEI WEN / LEONG KEAT

TP 5385

InvisiShield GLASS
Dept Direct: 6417 9701 / 6745 0009



Wiper blades: HWB (Nippon Wiper blade), Slipor (Made in Korea),
Forch (Made in Germany)

Spark-plugs: Nippon Denso NGK (Made in Japan)

TAX INVOICE : AR201903-01684
DATE : 04/03/2019
CUSTOMER ID : PRO005
VEH REG. NO. : SJS9742P
TERMS : 30 days
PO NO.
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	H04711-TE066022	FRONT BUMPER	U1	1	330.00	330.00
	GE8 KMC		HL1-C14			

SUB-TOTAL : 330.00
ADD GST 7.00 % 23.10

E. & O.E TOTAL AMOUNT SGD : 353.10

[P] 04/03/2019 4:39:16PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 04/03/2019 4:38:55PM

JAE Auto Pte. Ltd.

Sales Executive : EDMUND

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司 JAE AUTO PTE LTD

Bld: 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729572
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 189307741M

PROGRESSIVE CAR CARE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY
ATTN: WENDY / PEI WEN / LEONG KEAT

Wendy o/r

WINDSCREEN GLASS
Dept Over: 0417 0701 / 0702 0000



Dept Over: 0205 0000

Dept Over: 0205 0001

Dept Over: 0417 0000



Dept Over: 0417 0000

Dept Over: 0417 0000

Dept Over: 0417 0000

Dept Over: 0417 0000

Wiper blades: NYB (Nippon Wiper blades), Sliiper (Made in Korea),
Porch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201903-01714
DATE : 04/03/2019
CUSTOMER ID : PRO005
VEH REG. NO. : SIS9742P
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	SrLoc	QTY	UPRICE	AMOUNT
1	H71193-TG0-T01T GE6	SPACER FR RH	U1 HL2-B16-J	1	9.00	9.00
2	H71198-TG0-T01T GE6	SPACER FR LH	U1 HL2-B16-J	1	9.00	9.00
3	H71104-TF0-0002Q GE6	COVER FR TOWING HOOK	U1 HL2-C24-G	1	12.00	12.00

SUB-TOTAL : 30.00
ADD GST 7.00 % 2.10

E. & O.E TOTAL AMOUNT SGD : 32.10

[P] 04/03/2019 5:08:04PM

[E] 04/03/2019 5:01:45PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : EDMUND



This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

==== GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M. =====

PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TBL : 67415336 FAX : 67417208 LILY / 68444802 WENDY

ATTN : WENDY

TP 9368

WINDSCREEN GLASS
Dept Direct: 6417 9761 / 6045 9222



Dept Direct: 6325 9010

Dept Direct: 6325 9011

Dept Direct: 6417 9722



Dept Direct: 6417 9724

Dept Direct: 6417 9725

Dept Direct: 6417 9726

Dept Direct: 6417 9727

Wiper blades: HWB (Nippon Wiper blade), Silpor (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso JIGS (Made in Japan)

TAX INVOICE AR201903-02066

DATE 05/03/2019

CUSTOMER ID PRO005

VEH REG. NO. SJS9742P

TERMS 30 days

PO NO.

PAGE NO. Page 1 of 1

CURR. SGD

SO STOCKID	DESCRIPTION	Size/Qty	QTY	U/PRICE	AMOUNT
1 H71103-TE0-G60 GER KAC	GRILLE FR BUMPER LOWER	1/1 H71103	1	35.00	35.00

SUB-TOTAL : 85.00
ADD GST 7.00 % 5.95

===== E S O E TOTAL AMOUNT SGD : 90.95 =====

[P] 05/03/2019 11:56:13AM

[E] 05/03/2019 11:53:47AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : EDMUND



This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

25.04.2019

Our Ref: TP 0119-5368

AXA INSURANCE PTE LTD
8 Shenton Way # 24-01
AXA Tower
Singapore 068811

Attn: Motor Claims Department

Dear Sir,

ACCIDENT INVOLVING VEHICLE: SJS 9742 P & SMD 9561 M ON 17.01.2019

We are the authorized repair workshop for the owner of motor vehicle no: **SJS 9742 P**, which was involved in the above captioned accident with your insured vehicle: **SMD 9561 M**. The vehicle owner has requested and authorized us to assist him in presenting the claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

01)	Cost of Repair (incl gst)	\$	1,198.37
02)	GIA Search Fee	\$	2.00
03)	Reimbursement - Loss of Use (02days x \$60/day)	\$	120.00
		\$	1,320.37


We enclosed herewith the following documents to support the claims:-

- a) Letter of Authorisation / GIA report(s) / Insurance Certificate, etc...
- b) Final Tax Invoice / GIA Search Fee Invoice

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you


Pei Wen
For Progressive Car Care Pte Ltd
Email: claims@procarcare.com.sg

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWER
S068811

ATTN: Motor Claim Department

Your Ref No: TP 0119-5368
Claim Type: Third Party
Accident Date: 17/01/2019
TP Veh Reg No: SMD 9561 M

Claim No: EST1504472
Final No: PS1503400
Date: 25 Apr 2019
Policy No: 2100225744
Veh Reg No: SJS9742P
Make/Model: HONDA JAZZ 1.5L AT
ABS D/AB HID 2WD 5DR
Chassis No: JHMGE88509S201480
Engine No: L15A71001770
Reg. Date: 17/09/2009

Final Repair BillSJS9742P

Description	Quantity	Price	Amount
		<u>S\$</u>	<u>S\$</u>
Spare Parts			
1 COST OF REPAIR	1 UNIT	1,119.97	
		1,119.97	1,119.97
Total			S\$ 1,119.97
Add GST @ 7%			78.40
Total Amount Payable			S\$ 1,198.37

TOTAL: SINGAPORE DOLLAR ONE THOUSAND ONE HUNDRED NINETY EIGHT AND CENTS THIRTY SEVEN ONLY

For Progressive Car Care Pte Ltd
PROGRESSIVE CAR CARE PTE LTD
Blk 3022A Ubi Road 1 # 01-45/46
Singapore 408716
Tel: 6741 5336 Fax: 6741 7208
Email: claims@procarcare.com.sg
AUTHORISED SIGNATURE

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19001359/Aga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:LYNN

Date : 12-02-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMD 9561M	Veh. Inspected	SJS 9742P
Policy No.		Coverage (\$)	0.00
Claim No.	S9M01AV0	Excess (\$)	0.00
Assign From		Assign Date	21/01/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JHMGE88509S201480	Colour	RED
Odometer	138265	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/55 R16	YOKOHAMA	6 mm
L/H Front Tyre	185/55 R16	YOKOHAMA	6 mm
R/H Rear Tyre	185/55 R16	YOKOHAMA	6 mm
L/H Rear Tyre	185/55 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/01/2019	Inspection Date	21/01/2019
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 9742P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (WCP) (CONSISTENT)	DEFORMED	330.00	330.00
1	FRT TOWING EYE COVER (WCP) (CONSISTENT)	DEFORMED	12.00	12.00
1	L/F OUT BUMPER BRKT (WCP) (CONSISTENT)	NECESSARY	9.00	9.00
1	R/F OUT BUMPER BRKT (WCP) (CONSISTENT)	NECESSARY	9.00	9.00
1	L/F UPP BUMPER BRKT (WCP) (CONSISTENT)	NOT NECESSARY	15.00	-
1	FRT BUMPER SUPPORT (WCP) (CONSISTENT)	NOT NECESSARY	80.00	-
1	FRT BUMPER CLAMP KIT (WCP) (CONSISTENT)	NOT NECESSARY	20.00	-
1	FRT LWR BUMP GRILLE (WCP) (CONSISTENT)	DEFORMED	85.00	85.00
1	L/F HEADLAMP (WCP) (CONSISTENT)	NOT NECESSARY	500.00	-
1	L/F FOG LAMP (WCP) (CONSISTENT)	NOT NECESSARY	195.00	-
1	L/F BUMPER COVER (WCP) (CONSISTENT)	NOT NECESSARY	15.00	-
1	L/FOG LAMP COVER (WCP) (CONSISTENT)	MISSING	60.00	60.00
1	L/F WING CLAMP KIT (WCP) (CONSISTENT)	NOT NECESSARY	20.00	-
1	R/F WING CLAMP KIT (WCP) (CONSISTENT)	NOT NECESSARY	20.00	-
	COST PLUS 15%		205.50	75.75
			1,575.50	580.75
SPECIAL NETT ITEMS				
1	FRT NO PLATE (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	AUDATEX FEE (SN) (CONSISTENT)	NECESSARY	42.00	42.00
			77.00	42.00
LABOUR				
	37.0 WU X 45.00 SGD/H.		166.50	157.50
	LABOUR COST 45.0 WU X 45.00 SGD/H.		229.50	229.50
	MATERIAL COST.		110.22	110.22
			-	-
			-	-
			-	-
			506.22	497.22
GRAND TOTAL			2,158.72	1,119.97

Report Ref No. CC4/ASM19001359/Aga3q2

**RECOMMENDED COST OF REPAIRS****1,119.97**

Report Ref No. CC4/ASM19001359/Aga3q2

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.

Service Request Details

Claim

59M01AVD

Reference

CC4/AS419001359/Ag3a2

Loss Date

17 January 2019

Report Date

17 Jan 2019 8:00:00 AM

Request Date

21 January 2019

Date Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

5J59742P

Make

TPVD HONDA

Model

JAZZ-1.5 (A)

Service Address

...

Primary Contact/Insured

LEONG WEY HSIEN (LIANG WEXIAN)

BLK 81 REDHILL LANE, #03-55, 150081, Singapore

LWXIAN@SINGNET.COM.SG

Claim Handler

KHONG Lynn

68804892

lynn.khong@axa.com.sg

Actions

Next Step

Wait for: Approve Invoice

Add Invoice

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (6).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKK Inspection (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
 LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
 GUA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
 PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
 AUTHORISATION TO ACT FORM_0001.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
 LETTER TO GI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
 PWIF_COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019
 LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019
 MANDATE IA DO 05072019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	24 January 2019
 SJ59742P - TP VEHICLE4	Evidence	Videos	KHONG Lynn	21 January 2019
 P2178461_PS.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	KHONG Lynn	21 January 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
■ PRI EMAIL RECIEVED FROM WORKSHOP.mig	Letters and Correspondence	Workshop	RATAN BHOSALE Pragati	21 January 2019
■ SJ59742P TP GIA.PDF	Reports & Statement	GIA Report	RATAN BHOSALE Pragati	21 January 2019
■ SH09561M INSD GIA.PDF	Reports & Statement	GIA Report	RATAN BHOSALE Pragati	21 January 2019