

INS. CASE OWNER:

CC6 / ALH 1900

1366, Aca'sg

LKK:  
IDAC:

Surveyor:

UMP

DOI:

21/1/19

Date / Time:

21/1/19

Registered in Merimen:

Pre-assign / CCU / FTE

GBF 9602 Z



Insured Vehicle No.:

Claim No.:

Name of Insured:

Daimler Fleet Management

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SGJ 6748B



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premium  
Car 2

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SGJ 6748B - X

GBF 9602 Z - 03/ALH 1900 (19496181962) : 21/1/19

21/1/19. Sent out by letter.

Break WSP liability close.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

21/1/19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: AJP

Repair Cost:

S\$ 5,400

( 8 days) Reduction:

4% %

Email

Call

FINAL SETTLEMENT

Date/Time: 04.06.19

Confirm with: ALH TENG

Email

Call

Final Liability:

S\$ 100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lin: 0%

Repair Cost:

S\$ 5,400.00

3 VEH (1.00.2ND)

Loss of Rental (LOR):

S\$ 1,000.00

( 10 days) x 100

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 7.95

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+320

Total:

S\$ 6,401.45

Global Sum S\$:

FINAL PAYMENT

Date/Time: 04.06.19

Confirm with: ALH TENG

Email

Call

Payee 1:

S\$ 6,401.45

Name 1:

PREMIUM CRZ SERVICES PTE LTD

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

Adrian

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % J Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Vehicle: IN / OUT

Person Contacted: \_\_\_\_\_

Veh No: 8456748B Yr Regn: 2006, JulyType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Latio cc 1498Colour: Gold A/C: Insured / Std / Nil / NASp. Reading: 191461 T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: JN1BAAC1120001212Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SR / STD A/Rim orTyre Size: F: 195/60R15R: 195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Roadstone

Front

R/Bal: 06 mmL/Bal: 06 mm

D.O.A. \_\_\_\_\_

Survey held at

Rear

R/Bal: 06 mmL/Bal: 06 mmD.O.I. 21/01/19Premium CarzDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AG.COE Expiry: 30/06/2026.45: +5,400 (RED: +4,581.63 46%)MV: 41KPV: 34.61cNett: 6.4K.

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic &amp; Add.

S + RS, SI

Photos

Others

TOTAL

Co. Reg. No. 201416720C  
 1 Kaki Bukit Ave 6 #01-80 Autobay@Kaki Bukit Singapore 41/083  
 Tel : 6636 9000 Fax : 6636 9113

Date : 21/01/2019

TO: AIG Asia Pacific Insurance Pte Ltd  
 AIG Building  
 78 Shenton Way, #07-16  
 Singapore 079120

Our Customer : Chng Yai Wun  
 Vehicle No : SGJ6748B  
 Model : Nissan Latio 1.5L T  
 Manufacture Year : 2006  
 Date of Accident : 21/01/2019  
 Total Estimate Repair Days : 12  
 Total Pages : 2

Attn : Motor Claims Department  
 Fax : 6415 3727

Asher

Re: Repair Estimate For Third Party Claim against GBF9602Z

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper <i>Replaced</i>	1	\$609.90	\$609.90	✓
2	Rear bumper bracket RH <i>3 ended</i>	1	\$91.70	\$91.70	✓
3	Rear bumper bracket LH	1	\$91.70	\$91.70	✓
4	Rear bumper foam <i>Replaced</i>	1	\$147.20	\$147.20	✓
5	Rear end panel <i>Replaced</i>	1	\$491.80	\$491.80	✓
6	Tail lamp panel RH <i>3 ended</i>	1	\$164.80	\$164.80	✓
7	Tail lamp panel LH	1	\$164.80	\$164.80	✓
8	Boot lid <i>Replaced</i>	1	\$764.60	\$764.60	✓
9	Rear end fender RH <i>Replaced</i>	1	\$957.00	\$957.00	+
10	Rear end fender LH <i>Replaced</i>	1	repair	repair	+
11	Rear fender inner trim RH <i>3 ended</i>	1	\$242.40	\$242.40	+
12	Rear fender inner trim LH <i>3 ended</i>	1	\$242.40	\$242.40	+
13	Spare tyre panel <i>Replaced</i>	1	\$771.40	\$771.40	+
14	Spare tyre board <i>Replaced</i>	1	\$615.20	\$615.20	455
	Total			\$5,354.90	
	Less 30%			\$1,606.47	
	Sub Total 1			\$3,748.43	
B.	Spare Parts (Nett)				
1	Rear bumper clip <i>new</i>	8	\$4.90	\$39.20	✓
2	Rear bumper side retainer RH <i>3 ended</i>	1	\$35.20	\$35.20	✓
3	Rear bumper side retainer LH	1	\$35.20	\$35.20	✓
4	Rear end panel garnish <i>Replaced</i>	1	\$82.00	\$82.00	✓
5	Rear end panel garnish clip <i>new</i>	8	\$4.90	\$39.20	10
6	Boot lid lock <i>Replaced</i>	1	\$112.50	\$112.50	✓
7	Boot lid lower catch <i>Replaced</i>	1	\$58.20	\$58.20	✓
8	Boot lid chrome <i>Replaced</i>	1	\$283.10	\$283.10	✓
9	Boot lid "Nissan" logo <i>3 ended</i>	1	\$52.50	\$52.50	✓
10	Boot lid "Latio" emblem <i>3 ended</i>	1	\$64.60	\$64.60	✓
11	Boot lid hinge <i>Replaced</i>	2	\$51.10	\$102.20	+
12	Boot lid weatherstrip <i>Replaced</i>	1	\$68.80	\$68.80	✓
13	Rear license plate lamp <i>Replaced</i>	2	\$54.00	\$108.00	+
14	Tail lamp RH <i>Replaced</i>	1	\$252.30	\$252.30	✓
15	Tail lamp LH <i>Replaced</i>	1	\$252.30	\$252.30	✓
16	Rear fender inner trim clip <i>new</i>	16	\$4.90	\$78.40	+
17	Air vent RH <i>3 ended</i>	1	\$48.00	\$48.00	+
18	Air vent LH	1	\$48.00	\$48.00	+
19	Rear windscreen moulding <i>Replaced</i>	1	\$140.90	\$140.90	x

Co. Reg. No. 201416720C  
 1 Kallu Bukit Ave 8 #01-00 Autobay@Kallu Bukit Singapore 417883  
 Tel: 6636 9100 Fax: 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
20	Exhaust silencer <i>Best</i>	1	\$478.00	\$478.00	✓
21	Exhaust silencer mounting <i>new</i>	2	\$34.70	\$69.40	+
	<i>1926.10</i> <i>1733.49</i>		<b>Total</b>	\$2,448.00	
			Less 10%	\$244.80	
			<b>Sub Total 2</b>	\$2,203.20	
<b>C</b>	<b>Spare Parts (S/Nett)</b>				
✓ 1	Rear number plate w/casing <i>new Best</i>	1	\$70.00	\$70.00	✓
2	Reverse sensor (Set) <i>Revised</i>	1	\$250.00	\$250.00	200
3	Rear windscreen sealant <i>new</i>	1	\$60.00	\$60.00	+
4	Chinese wording <i>new</i>	1	\$60.00	\$60.00	30.
	<i>300</i>		<b>Sub-Total 3</b>	\$440.00	
	<b>Total for Parts</b>			\$6,391.63	
<b>D.</b>	<b>Labour</b>				
1	To check wiring.			\$120.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,400.00	1000: 1100.
3	Spray painting all affected parts & areas.			\$1,400.00	1200
4	To spray anti-rust undercoat.			\$120.00	50
5	To remove and refit rear windscreen glass.			\$120.00	+
6	To remove and replace exhaust silencer.			\$180.00	80
7	To remove and refit rear seats, rear wheelhouse inner garnish, floor carpet & upholstery to facilitate repairs.			\$250.00	80
	<b>Total Labour</b>			\$3,590.00	
	<b>Total Repair Cost</b>			\$9,981.63	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours faithfully,

Aun Teng  
 f Premium Carz Services Pte Ltd

Adrian Lj  
 L/S 21/01/19.  
 08 Days.  
 Supplimentary: 19476  
 total: 6783.30  
 L/S: 54K ✓

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

Date : 22/01/2019

TO: AIG Asia Pacific Insurance Pte Ltd  
AIG Building  
78 Shenton Way, #07-16  
Singapore 079120

Our Customer : Chng Yai Wun  
Vehicle No : SGJ6748B  
Model : Nissan Latio 1.5L T  
Manufacture Year : 2006  
Date of Accident : 21/01/2019  
Total Estimate Repair Days : 12  
Total Pages : 1

Attn : Motor Claims Department  
Fax : 6415 3727

Re: Supplementary Repair Estimate For Third Party Claim against GBF9602Z

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
B.	Spare Parts (Nett)				
1	Tail lamp lower bracket RH <i>3rd</i>	1	\$30.70	\$30.70	✓
2	Tail lamp lower bracket LH	1	\$30.70	\$30.70	✓
3	Tail lamp gasket RH <i>2nd</i>	1	\$35.00	\$35.00	✓
4	Tail lamp gasket LH	1	\$35.00	\$35.00	✓
5	Boot lid sensor <i>2nd</i>	1	\$85.00	\$85.00	✓
	<b>Total</b>			<b>\$216.40</b>	
			Less 10%	<b>\$21.64</b>	
	<b>Total Supplementary Repair Cost</b>			<b>\$194.76</b>	

216.40  
194.76

*Adrian L*  
*1/2 22/01/19.*

Yours faithfully,

*Aun Teng*  
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	81001
Vehicle Details	
Vehicle No.:	SGJ6748B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	NISSAN
Vehicle Model:	LATIO 1.5L T
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	HR15368171
Chassis No.:	JN1BAAC11Z0001212
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,378.00
Original Registration Date:	19 Jul 2006
First Registration Date:	19 Jul 2006
Transfer Count:	3
Actual ARF Paid:	\$18,016.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE PARF Rebate Details	
COE Expiry Date:	30 Jun 2026
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$46,454.00
COE Rebate Amount:	\$34,556.00
Total Rebate Amount:	\$34,556.00

The information contained herein is correct as at 22 Jan 2019

OK







Co. Reg. No: 201416729C  
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883  
Tel : 6636 9100 Fax : 6636 9113

Date : 08/05/2019

Your Ref : CC6/AIG19001366/Aea3

Our Ref : 0362/SGJ6748B/TP/PC/0119

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
**AIG BUILDING**  
**78 Shenton Way, #07-16**  
**Singapore 079120**  
**Attn : Motor Claims Dept.**

Dear Sir/Madam

**ACCIDENT INVOLVING SGJ6748B & GBF9602Z ON 21/01/2019 ALONG WEST COAST HIGHWAY TOWARDS JALAN BAHAR**

We refer to the above accident.

The accident was caused solely by the negligence of your insured and as a result, we had incurred the following Costs and Losses: -

Costs of Repair (Lump Sum)	\$ 5,400.00
Rental Fee (10 days at \$120/day)	\$ 1,200.00
LTA TP Search Fee	\$ 7.45
<b>Claimed Amount</b>	<b><u>\$ 6,607.45</u></b>

Enclosed are the supporting documents for your perusal:

1. Invoice 0362
2. Rental Agreement/Receipt
3. LTA Tax Invoice/Receipt
4. Certificate of Insurance
5. Satisfaction Voucher
6. Letter of Authority and Indemnity

Please let us hear from you within the next 14 days.

Yours faithfully



**PREMIUM CARZ SERVICES PTE LTD**





Co. Reg. No.: 201416720C  
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883  
Tel: 6636 9100 Fax: 6636 9113

## SATISFACTION VOUCHER

Our ref.: 0362/SGJ6748B/TP/PC/0119  
To : AIQ Asia Pacific Insurance Pte Ltd

ACCIDENT INVOLVING SGJ6748B AND GBF96027 ON 21/01/2019  
ALONG WEST COAST HIGHWAY TOWARDS JALAN BAHAR

I/We hereby acknowledge having received from Premium Carz Services Pte Ltd, 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883, my/our vehicle number SGJ6748B which has been repaired to my/our satisfaction and acceptance. I/We admit that the payment of \*SGD \_\_\_\_\_ account for such repairs is in full discharge of my/our claim.

Dated : 30 day of January 2019

Signature : 

Owners' name: Chng Yai Wen

NRIC/Co. Reg.: S15781001

Address : Blk 776 Bedok Reservoir Road

#14-21

Singapore 471453



## CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance  
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

**POLICY NUMBER: PNPV2019-00001037 (Comprehensive - Classic Plan)**

Car plate number: SGJ6748B

Your name (As the policyholder): Chng Yai Wun

Coverage start date: 19/01/2019

Coverage end date: 18/01/2020

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

---

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 21/12/2018

**Abhishek Bhatia**  
Chief Executive Officer  
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888  
or email us at [contact.sg@fwd.com](mailto:contact.sg@fwd.com) if any details  
in this Certificate of Insurance need to be changed.

**REPUBLIC OF SINGAPORE DRIVING LICENCE**



CHNG YAI WUN  
 Date of Birth: 25 Aug 1963  
 Date of Issue: 02 Jan 2000

1000091224C

**REPUBLIC OF SINGAPORE**  
 IDENTITY CARD NO. S15781001



CHNG YAI WUN  
 @TJONG KHENG KEONG  
 莊庆强  
 Race: CHINESE  
 Date of Birth: 25-08-1963 M  
 Country of Birth: SINGAPORE

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES**

Class	Description	Valid Until
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	07 Nov 1981
Class 4	Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms	14 Jan 1986
Class 5	Motor Vehicles which are not constructed themselves to carry any load and the weight of which unladen exceeds 2250 kilograms	15 Mar 1986

Licence No: S15781001

AP 426A

1487786

S15781001

Model Group: 24-11-1993

APT BLK 776 BEDOK RESERVOIR ROAD 214-21  
 SINGAPORE 470253

NRIC No: S15781001 Date: 27/07/2017

**Asher Sng (LKKAUTO)**

---

**From:** Asher Sng (LKKAUTO)  
**Sent:** Monday, 8 April 2019 3:37 PM  
**To:** benny.chong@daimler.com  
**Subject:** DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.

**Our Ref: CC6/AIG19001366/Aea3**

08 APRIL 2019

**DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.**

Dear Sir/Madam,

**ACCIDENT INVOLVING GBF 9602Z / SGJ 6748B / OTHERS ON 21/01/2019**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Asher  
Case Handler  
DID: 6841 6051  
FAX: 6741 4108  
Email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)



Co. Reg. No.: 201418720C  
1 Kaki Bukit Ave 6 #01-80 Autobay@Kaki Bukit Singapore 417883  
Tel : 6636 9100 Fax : 6636 9113

## LETTER OF AUTHORITY AND INDEMNITY

ACCIDENT INVOLVING VEHICLE NO. SJQ6748B AND GBF9602Z  
AT/ALONG WEST COAST HIGHWAY TOWARDS JALAN BAHAR  
ON 21 DAY JANUARY MONTH 2019 YEAR

- a) I/We, the owner of vehicle no. SJQ6748B hereby instruct and authorize you to commence repair to the said vehicles.
- b) You are further authorized to appoint solicitors on my/our behalf and give the solicitors full instructions as if the appointment are given by me/us with respect to the conduct of my/our claims against third party driver and/or his insurers including if necessary, to commence legal proceedings in Court in my/our name against the third party.
- c) You have my/our full authority to instruct my/our solicitors to negotiate a settlement with the third party and/or his insurers on such terms as you deem fit. Upon settlement of my claim, you are authorized to sign any Discharge Voucher or any document to confirm my acceptance of the settlement as full and final discharge of my claim, on my behalf.
- d) Upon resolving my/our claim, you are authorized to agree with my/our solicitors on the amount of their professional cost and disbursements for acting for me/us and to relieve payment of the balance of the settlement sum on my/our behalf directly into your account.
- e) In the event that, I/we am/are required to attend at my/our solicitors' office or to attend court in connection to my/our claim, I/we shall render full co-operation.
- f) In the event that my/our claim against the third party and/or his insurers is Not successful or cannot be proceeded with, I/we authorized you to make a claim against my/our own insurers for the cost of repairs and any other losses recoverable under my/our policy of insurance. In this respects, I/we understand and accept that the excess amount applicable under the policy of insurance shall be borne by me/us. I/we shall also be personally liable to bear all legal cost incurred by you in claiming back for the repair cost by your Solicitors.
- g) If for whatever reasons, my/our insurers reject my/our claim for indemnity for the cost of repairs and/or any losses recoverable under the policy of insurance or make any offer to pay less than the amount claimed by you, I/we agree to undertake to pay the full amount of your repair bill and survey fees and any other expenses reasonably incurred on my/our behalf or to pay you the difference in amount, as the case may be.
- h) I/we have read and understand the above statement and agreed.

Dated this 21 day JANUARY month 2019 year

Signature

Name

CHING KAI WUN


NRIC/ROC No.

S15781001E

Address

BLK 776 Bedok Reservoir  
Road, #14-21  
Singapore 479253

Company Stamp



**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **PREMIUM CARZ SERVICES PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$5,400.00** (Repair Cost), **S\$1,000.00** (Loss of Use/Rental), **S\$7.45** (Disbursement) for vehicle no. **SGJ 6748B** that was damaged pursuant to the accident which occurred on **21/01/2019** (date) along **WEST COAST HIGHWAY TWDS JLN BAHAR** (location) involving vehicle no/s **GBF 9602Z**.

This is pursuant to the inspection conducted on **21/01/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **CHNG YAI WUN** ("the third party claimant") of vehicle no. **SGJ 6748B** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SGJ 6748B** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 12 (day) of June (month) 2019 (year)



**LWP**

Signed by appointed surveyor



Signed by "the workshop" (with chop)

settlement herein is strictly in relation to 3<sup>rd</sup> party  
property damage claim and is without prejudice  
to personal injuries claim



Co. Reg. No: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

INVOICE: 0362

Date : 08/05/2019

**Bill To :**

**AIG Asia Pacific Insurance Pte Ltd**

AIG Building

78 Shenton Way, #07-16

Singapore 079120

**Our Customer**

Name : Chng Yai Wun

IC No. : S15781001

Address : 776 Bedok Reservoir Road

#14-21

Singapore 479253

Vehicle No : SGJ6748B

Date of Accident : 21/01/2019

Model : Nissan Latio

No.		Qty	Unit Price	Amount
1	To supply labour and materials to repair the above-mentioned vehicle to its pre-accident condition (Lump Sum)	1	-	\$5,400.00
TOTAL				\$5,400.00

For Premium Carz Services Pte Ltd

\* All cheque should be crossed and make payable to "Premium Carz Services Pte Ltd"





## DAWN ENTERPRISES

21 SELETAR WEST FARMWAY 1  
SINGAPORE 798125  
TEL: 6383 2661 FAX: 6484 2836  
REG. NO. 430058/000

No. 19560

Date, 30/1/19

### OFFICIAL RECEIPT

Received from

Chay Yai Wun

the sum of Dollars

One thousand two hundred only

being Payment Of

SSN 1340 C (21/1/19 - 30/1/19)

DAWN ENTERPRISES

\$

1200/-

Cash/Cheque No.



# DAWN ENTERPRISES

21 Seletar West Farmway 1  
Singapore 798125  
Tel: 63832661 Fax: 64842836  
Reg No.430058/00D

Premium Carz

SGJ67485

Nº 36386

21/1/19

## RENTAL AGREEMENT

DATE

### HIRER'S PARTICULARS

Name Chng Tai Wun  
Address 776 Bedok Reservoir Rd  
#14-21  
5479253  
IC or Passport No. 15781001 Country \_\_\_\_\_  
Occupation \_\_\_\_\_  
Date of Birth \_\_\_\_\_ Age \_\_\_\_\_  
Driving Licence No. \_\_\_\_\_ Date Passed \_\_\_\_\_  
Tel: (HP) 96190488 (Residence) \_\_\_\_\_

### DRIVER'S PARTICULARS

Name \_\_\_\_\_  
Address \_\_\_\_\_  
IC or Passport No. \_\_\_\_\_ Country \_\_\_\_\_  
Occupation \_\_\_\_\_  
Date of Birth \_\_\_\_\_ Age \_\_\_\_\_  
Driving Licence No. \_\_\_\_\_ Date Passed \_\_\_\_\_  
Tel: (Office) \_\_\_\_\_ (Residence) \_\_\_\_\_

### IMPORTANT NOTES:

1. No Insurance Coverage if the driver is below 24yrs old or less than 2 years driving licence.
2. This vehicle is licensed to carry <sup>04</sup> passengers only.
3. Hirer is liable to pay first \$ <sup>2000</sup> as excess all claims any accident plus loss of earning while damaged vehicle is under repair.
4. For usage to Malaysia subject to higher excess all claims of \$55,000.00 and different rental rate.
5. Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
6. No refund will be given for vehicle returns early.
7. No refund will be given for petrol left in vehicle. TU=1123724907
8. Hirer is liable to pay all parking fee and traffic summonses.
9. Vehicles to be return during office hour only.
10. No Service on Public Holiday and Sunday.

### CHARGES

10 Day at \$ 120.00	per days	\$1200.00
Day at \$	per week	
Day at \$	per month	
TOTAL AMOUNT		\$1200.00
AMOUNT PAID		\$1200.00
BALANCE DUE		
Days Extension From	To	
Amount Deposit (refundable) \$		

### SCHEDULE

### MODEL

SDV 1340 C

T/with

Date	Time	Mileage
21/1/19	10:35 am	
30/1/19	3:30 pm	

FROM

21/1/19

TO

30/1/19

I/we have read and understood the terms and conditions above and hereby agreed to abide

*[Signature]*

*[Signature]*

> Back to OneMotoring



Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701  
GST Registration No. : M4-0006529-2

Print Date/Time : 21 Jan 2019 / 11:49:51

Receipt Date/Time : 21 Jan 2019 / 11:49:51

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-190121-001158

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
-----	--	--------------------------------	-------------------------	-------------------------------

Result of Insurance Enquiry - GBF9602Z

As at 21 Jan 2019/08:10:00

Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.

1 Insurance Enquiry - GBF9602Z  
Enquiry Fee  
20190121114852405098

Sub-Total	7.00	0.49	7.49
Total Before Rounding	7.00	0.49	7.49
Rounding Difference			0.04
Total Amount Payable			7.45

Paid By

20190121114906963 Direct Debit: eNETS Debit  
(Internet Banking) 7.45

Total			7.45
Cash Change			0.00
Tendered Amount			7.45
Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jan 2019 <a href="#">Edit Reg</a>		21 Jan 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$5,400.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,400.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.,</b> Co. Reg. No.: 1998037782								
Main Claimant:	<b>CHNG YAI WUN,</b> ID: S15781001								
Vehicle Reg. No.:	<b>SGJ6748B</b>	Date of Loss:	21/01/2019 08:00 - :59 [150 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 9209718841SG</b>	Policy/Cover Note No.:	0999994197 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>GBF9602Z</b>	Policy No. (Claimant):	PNPV2019-00001037						
		Excess:							
Repairer:	<b>Premium Carz Services Pte Ltd (HQ)</b> 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki, 417883 Kaki Bukit - Tel: 66369100								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Foo, Chit Yan</b> ] Chityan.Foo@aig.com								
Claimant's Insurer:	<b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... [Final Rpt due 30/01/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG (25/01/2019): No OI GIA Report									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents




































\*SGJ6748B (9209718841SG)  
[GBF9602Z]











































TP

CHNG YAI WUN

Jan 21 2019 8:00AM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]  
Premium Carz Services Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Letters/Correspondences</b>			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
2	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
3	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
4	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
5	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
6	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
7	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
8	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
9	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
10	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
11	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
12	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
13	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
14	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
15	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
16	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
17	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
18	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
19	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
20	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
21	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
22	08/05/19 10:39	General View	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
23	08/05/19 10:39	Reinspection Photo	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
24	08/05/19 10:39	Reinspection Photo	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
25	08/05/19 10:39	Reinspection Photo	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
26	08/05/19 10:39	Reinspection Photo	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
27	08/05/19 10:39	Reinspection Photo	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
28	08/05/19 10:39	Reinspection Photo	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
29	08/05/19 10:39	Reinspection Photo	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
30	08/05/19 10:39	Reinspection Photo	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
31	08/05/19 10:39	Reinspection Photo	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
32	08/05/19 10:39	Reinspection Photo	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
33	08/05/19 10:39	Reinspection Photo	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>
34	08/05/19 10:39	Reinspection Photo	 Load JPG <input type="checkbox"/>	<input type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	08/05/19 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/01/19 21:29	TP GIA REPORT	 Load PDF	
2	25/01/19 15:59	Non reporting letter	 Load PDF	
3	04/06/19 10:00	LETTER TO OI	 Load PDF	
4	19/06/19 09:08	WORKSHOP INVOICE	 Load PDF	
5	19/06/19 09:08	AUTHORISATION TO ACT FORM	 Load PDF	
6	19/06/19 09:08	Release Voucher	 Load PDF	
7	19/06/19 09:08	RENTAL RECEIPT	 Load PDF	
8	19/06/19 09:08	LTA SEARCH	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	03/04/19 16:21	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBF9602Z (Insd veh)	Model:	NISSAN LATIO 1.5 L T (A)
	SGJ6748B (TP veh)		
Date of Accident:	21/01/2019		

Global Sum Settlement	:	[ ] Yes	[ X ] No	
Repair Estimate	: \$	10,176.39		
Final Repair Cost	: \$	5,400.00		
Loss of Use	: \$	days at \$0.00 per day		
Rental (if any)	: \$	1,000.00	10	days
LTA / GIA Search Fee	: \$	7.45		
Others:	: \$	0.00		
	: \$			
Final Settlement Sum	: \$	6,407.45		

**Is Third Party Workshop GIA Registered?**    [ ] YES    [ X ] NO    (Kindly indicate below)

**A) For Non GIA Registered Workshop:**    Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

**B) For GIA Registered Workshop:**    BOLA Applicable: Yes/ No    BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%)    Assessed Liability (\*): \_\_\_\_ 0 \_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Premium Carz Services Pte Ltd	: \$	6,407.45
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

19 Jun  
2019

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19001366/AEA3Q2

Date: 19/06/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994197  
**Claimant Vehicle No :** SGJ6748B **Insured Vehicle No :** GBF9602Z  
 Date of Loss: 21/01/2019 Nature of Claim: TP Claim No: 9209718841SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGJ6748B**  
 Make & Model: NISSAN LATIO, 1.5 L T (A) Engine No: HR15368171  
 Reg. Date: 19/07/2006 (Man. Year: 2006) Chassis No: JN1BAAC11Z0001212  
 Colour: Gold Odometer: 191461 km  
 Engine Capacity: 1498 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15  
 Front Left Side: Roadstone 6 mm Rear Left Side: Roadstone 6 mm  
 Front Right Side: Roadstone 6 mm Rear Right Side: Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,586.39	4,251.32	2,335.07	35.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	2,540.00	1,050.00	29.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,176.39</b>	<b>6,791.32</b>	<b>3,385.07</b>	<b>33.26</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,176.39</b>	<b>5,400.00</b>	<b>4,776.39</b>	<b>46.94</b>
<b>+ Car Rental (10.0 x S\$100.00/day) (S\$)</b>		1,000.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>6,407.45</b>		

### INSPECTION

Date of Assignment: 21/01/2019  
 Date Inspected: 21/01/2019 Inspected At: Premium Carz Services Pte Ltd (HQ)  
 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki  
 Singapore 417883  
 Estimated Period of Repair: 8.0 days

---

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	609.90 FL	*609.90 FL
2	1		*REAR BUMPER BRACKET RH	Dented	91.70 FL	*91.70 FL
3	1		*REAR BUMPER BRACKET LH	Dented	91.70 FL	*91.70 FL
4	1		*REAR BUMPER FOAM	Deformed	147.20 FL	*147.20 FL
5	1		*REAR END PANEL	Dented	491.80 FL	*491.80 FL
6	1		*TAIL LAMP PANEL RH	Dented	164.80 FL	*164.80 FL
7	1		*TAIL LAMP PANEL LH	Dented	164.80 FL	*164.80 FL
8	1		*BOOT LID	Dented	764.60 FL	*764.60 FL
9	1		*REAR END FENDER RH	Repair	957.00 FL	*- FL
10	1		*REAR END FENDER LH (NPA)	Repair	0.00 FL	*- FL
11	1		*REAR FENDER INNER TRIM RH	Not Necessary	242.40 FL	*- FL
12	1		*REAR FENDER INNER TRIM LH	Not Necessary	242.40 FL	*- FL
13	1		*SPARE TYRE PANEL	Repair	771.40 FL	*- FL
14	1		*SPARE TYRE BOARD	Deformed	615.20 FL	*495.00 FL
15	8		*REAR BUMPER CLIP	Necessary	39.20 FN	*39.20 FN
16	1		*REAR BUMPER SIDE RETAINER RH	Necessary	35.20 FN	*35.20 FN
17	1		*REAR BUMPER SIDE RETAINER LH	Necessary	35.20 FN	*35.20 FN
18	1		*REAR END PANEL GARNISH	Cracked	82.00 FN	*82.00 FN
19	8		*REAR END PANEL GARNISH CLIP	Necessary	39.20 FN	*10.00 FN
20	1		*BOOT LID LOCK	Damaged	112.50 FN	*112.50 FN
21	1		*BOOT LID LOWER CATCH	Damaged	58.20 FN	*58.20 FN
22	1		*BOOT LID CHROME	Deformed	283.10 FN	*283.10 FN
23	1		*BOOT LID NISSAN LOGO	Necessary	52.50 FN	*52.50 FN
24	1		*BOOT LID LATIOMBLEM	Necessary	64.80 FN	*64.80 FN
25	2		*BOOT LID HINGE	Not Necessary	102.20 FN	*- FN
26	1		*BOOT LID WEATHERSTRIP	Cut	68.80 FN	*68.80 FN
27	2		*REAR LICENSE PLATE LAMP	Not Necessary	108.00 FN	*- FN
28	1		*TAIL LAMP RH	Cracked	252.30 FN	*252.30 FN
29	1		*TAIL LAMP LH	Cracked	252.30 FN	*252.30 FN
30	16		*REAR FENDER INNER TRIM CLIP	Not Necessary	78.40 FN	*- FN
31	1		*AIR VENT RH	Not Necessary	48.00 FN	*- FN
32	1		*AIR VENT LH	Not Necessary	48.00 FN	*- FN
33	1		*REAR WINDSCREEN MOULDING	Not Necessary	140.90 FN	*- FN
34	1		*EXHAUST SILENCER	Bent	478.00 FN	*478.00 FN
35	2		*EXHAUST SILENCER MOUNTING	Not Necessary	69.40 FN	*- FN
36	1		*REAR NUMBER PLATE W/CASING	Bent	70.00 FS	*70.00 FS
37	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
38	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
39	1		*CHINESE WORDING	Necessary	60.00 FS	*30.00 FS
40	1		*TAIL LAMP LOWER BRACKET RH	Damaged	30.70 FN	*30.70 FN
41	1		*TAIL LAMP LOWER BRACKET LH	Damaged	30.70 FN	*30.70 FN
42	1		*TAIL LAMP GASKET RH	Necessary	35.00 FN	*35.00 FN
43	1		*TAIL LAMP GASKET LH	Necessary	35.00 FN	*35.00 FN
44	1		*BOOT LID SENSOR	Damaged	85.00 FN	*85.00 FN

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,459.30</b>	<b>5,361.80</b>
- List Item Discount on L Items 30.00/30.00% (\$\$)	1,606.47	906.45
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	266.44	204.03

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	6,586.39	4,251.32

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	120.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	1,400.00	1,100.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	1,400.00	1,200.00
4	TO SPRAY ANTI-RUST UNDERCOAT	New	120.00	50.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	0.00
6	TO REMOVE AN REPLACE EXHAUST SILENCER	New	180.00	80.00
7	TO REMOVE AND REFIT REAR SEATS ,REAR WHEELHOUSE INNER GARNISH,FLOOR CARPET & UPHOLSTERY TO FACILITATE REPAIRS	New	250.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>3,590.00</b>	<b>2,540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >