

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

19/01/2019

Owner: FAVORIDE PTE LTD

*Not Authorised
Lily B?
Perry Ate Paint
5-6 days*

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID - SLU6809S

1pc	front bonnet	R	\$ 980.00	✓
2pcs	front bonnet hinge @\$85.00		\$ 170.00	✓
1pc	front bonnet inner cardboard	R	\$ 285.50	X
8pcs	front bonnet inner cardboard clip @\$5.00	nn	\$ 40.00	X
1pc	front bonnet inner lock	D.I	\$ 274.10	✓
2pcs	front headlamp @\$2250.00	n/s m	\$ 4,500.00	✓
2pcs	front headlamp panel @\$281.50	n/s Bu	\$ 563.00	✓
1pc	front headlamp LH HID control uni		\$ 581.85	?
1pc	front bumper	R	\$ 972.45	✓
15pcs	front bumper clip @\$5.00	nn	\$ 75.00	✓
1pc	front bumper "TOYOTA" logo	nn	\$ 95.85	✓
1pc	front bumper centre grille	cm	\$ 381.85	✓
2pcs	front bumper towing cover @\$85.50	n/s m	\$ 171.00	✓
2pcs	front bumper fog lamp @\$295.85	n/s ?	\$ 591.70	
2pcs	front bumper fog lamp cover @\$181.50	n/s	\$ 363.00	X
1pc	front bumper top rubber	nn	\$ 281.70	✓
1pc	front bumper top garnish	Bu	\$ 277.10	✓
10pcs	front bumper top garnish clip @\$5.00	nn	\$ 50.00	✓
1pc	front bumper lower grille	D.I	\$ 281.85	✓
1pc	front bumper lower garnish		\$ 281.10	?
1pc	front bumper top reinforcement	R	\$ 561.60	✓
1pc	front bumper top sponge	cm	\$ 172.40	✓
2pcs	front bumper side retainer @\$131.35	D.I	\$ 262.70	✓
1pc	front support top panel	Bu	\$ 381.45	✓
2pcs	front support side panel @\$375.25		\$ 750.50	?
2pcs	front support panel side garnish @\$177.75		\$ 355.50	?
1pc	front support panel lower panel		\$ 370.50	?
1pc	front air-con condenser		\$ 1,150.00	?
1pc	front air-con condensor motor		\$ 281.50	?
1pc	front air-con condensor motor fan		\$ 171.50	?
1pc	front air-con condensor pipe 1		\$ 181.25	?
1pc	front air-con condensor pipe 2		\$ 191.50	?

balance c/f

\$ 16,047.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Prices are subject to confirmation
- This survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and supplied with approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

輝 陽 汽 車 有 限 公 司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

19/01/2019

Owner: FAVORIDE PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID - SLU6809S

	balance b/f		\$ 16,047.45
1pc	front radiator		\$ 1,520.00 7
1pc	front radiator top hose	12	\$ 121.50 X
1pc	front radiator lower hose		\$ 120.50 7
1pc	front radiator cowling		\$ 255.80 7
1pc	front radiator cowling motor		\$ 291.50 7
1pc	front radiator cowling motor fan		\$ 171.50 7
1pc	front LH fender	11	\$ 981.85 X
1pc	front RH fender "HYBRID" emblem	12	\$ 65.85 —
			<u>\$ 19,575.95</u>
	less 25%		<u>\$ 4,893.99</u>
			<u>\$ 14,681.96</u>
1set	front number plate & casing	12 s.nett	\$ 50.00 45.50
	remove & refit air-con & gas		\$ 120.00 100/
	remove & refit radiator & coolant		\$ 120.00 50/
	tuffkote		\$ 120.00 60/
	wiring		\$ 180.00 20/
	spray painting		\$ 1,200.00 800/
	labour charges		<u>\$ 1,400.00 700/</u>
	Total		<u><u>\$ 17,871.96</u></u>

