



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)

0

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	20/01/2019
Vehicle Reg. No.:	SGF4789S	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LEE KOK SENG (LI GUOSHENG)		
Make/Model:	TOYOTA VIOS, 1.5 E (A)	Vehicle Reg. Date:	12/04/2006
Vehicle Colour:	SILVER		
Engine No:	1NZX393608	Chassis No:	MR053HY4204178874
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %	Nett Item Discount:	10.00 %
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	MOVA AUTOMOTIVE PTE LTD (FAN YOONG)		

COST OF CLAIMS	Amount
Parts	8,422.75
Miscellaneous Items	10.00
Labour	4,010.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	12,442.75
+ GST 7.00% (\$\$)	870.99
Nett Amount (\$\$)	13,313.74

This claim is handled by: ALAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Jan 2019)
Parts: 143 TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGF4789S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	25.00	0.00	*480.00 FL
2	2		*FRONT BUMPER SIDE RETAINER	25.00	0.00	*60.00 FL
3	2		*FRONT FOG LAMP COVER	25.00	0.00	*180.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	25.00	0.00	*260.00 FL
5	20		*FRONT BUMPER CLIPS	25.00	0.00	*100.00 FL
6	2		*FRONT FENDER L & R	25.00	0.00	*620.00 FL
7	2		*FRONT FENDER INNER SHIELD	25.00	0.00	*220.00 FL
8	20		*INNER SHIELD CLIPS	25.00	0.00	*100.00 FL
9	2		*FRONT FENDER SIGNAL LAMP	25.00	0.00	*120.00 FL
10	1		*FRONT GRILLE	25.00	0.00	*198.00 FL
11	2		*HEADLAMP	25.00	0.00	*860.00 FL
12	2		*HEADLAMP PANEL	25.00	0.00	*230.00 FL
13	2		*HEADLAMP CLIPS	25.00	0.00	*20.00 FL
14	1		*LH FRONT DOOR	25.00	0.00	*979.00 FL
15	2		*LH FRONT DOOR HINGE	25.00	0.00	*200.00 FL
16	1		*LH FRONT DOOR CHECKER	25.00	0.00	*110.00 FL
17	1		*LH FRONT DOOR PROTECTOR	25.00	0.00	*130.00 FL
18	1		*LH FRONT DOOR RUBBER	25.00	0.00	*230.00 FL
19	1		*LH FRONT DOOR INNER TRIM	25.00	0.00	*430.00 FL
20	1		*LH FRONT DOOR PILLAR	25.00	0.00	*770.00 FL
21	2		*LH FRONT SPORT RIMS	25.00	0.00	*1,300.00 FL
22	1		*LH FRONT LOWER ARM	25.00	0.00	*230.00 FL
23	1		*LH FRONT KNUCKLE	25.00	0.00	*380.00 FL
24	1		*LH FRONT SHOCK ABSORBER	25.00	0.00	*240.00 FL
25	1		*LH FRONT ABSORBER MOUNTING	25.00	0.00	*130.00 FL
26	1		*LH FRONT WHEEL BEARING	25.00	0.00	*160.00 FL
27	1		*LH FRONT STABILIZER LINK	25.00	0.00	*110.00 FL
28	1		*LH FRONT WHEEL HOUSE PANEL - TBA	25.00	0.00	-
29	1		*REAR BUMPER	25.00	0.00	*480.00 FL
30	2		*REAR BUMPER SIDE RETAINER	25.00	0.00	*80.00 FL
31	1		*REAR AXLE	25.00	0.00	*700.00 FL
32	1		*REAR EXHAUST ASSY	25.00	0.00	*420.00 FL
33	2		*REAR EXHAUST MOUNTING	25.00	0.00	*60.00 FL
34	1		*RH FRONT WHEEL BEARING	25.00	0.00	*110.00 FL
35	2		*FRONT TYRE L & R	0	0.00	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,097.00
- List Item Discount on L Items (\$\$)	2,674.25
Total Parts (\$\$)	8,422.75

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (\$\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO INSPECT FRONT LIGHTING WATER & LEAKAGE TEST	New	40.00
2	TO REMOVE & REPLACE FRONT & REAR UNDERCARRIAGE DAMAGED PARTS	New	500.00
3	TO CHECK ALL WHEEL ALIGNMENT	New	80.00
4	TO REMOVE & INSTALL CARPET, SEAT, GARNISHES, IN ORDER TO CUT OFF LH FRONT DOOR PILLAR	New	200.00
5	TO CUT OFF LH FRONT DOOR PILLAR, LH FRONT WHEEL HOUSE PANEL & STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS	New	1,500.00
6	TO REMOVE & TRANSFER ITEMS TO LH FRONT NEW DOOR	New	80.00
7	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	60.00
8	TO APPLY RUST PROOF ON AFFECTED AREAS	New	150.00
9	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	1,400.00
Gross Labour Cost (\$\$)			4,010.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >