

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email:ben@allswellmotor.com.sg

(3rd party claim against India insured SNC8704P)

Estimate repair

Vehicle No. : SU9149T
 Make & Model : Honda Vezel
 Chassis No. :
 Date of survey :

Submitted by : BM
 COE expiry : 17-12-2027
 Engine No. :

S/No	Part Description	Qty	Unit Price	Price	Disposition by
	Labour Description				
01	Putty / sandpaper / spray (adjust) polish and wash (Front bumper, fender, fender arc)	01	\$600.00	4500 4500	
	1 Day				
	part by part.				
	After repair photos.				
	Gene Quf.				
	24/1/19				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company					
Acknowledged by Repairer Signature: _____ Date: _____					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.