

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8045H

DATE 21/1/2019 11:26

MAKE :

MODEL : MERCEDES BENZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 1,510.00
	Rear Bumper Bracket Lower (LH/RH) ?		\$ 135.00	\$ 270.00
	Rear Bumper Bracket Top (LH/RH) ?		\$ 125.00	\$ 250.00
	Rear Bumper Retainer Mounting (LH/RH) ?		\$ 115.00	\$ 230.00
	SUB TOTAL			\$ 2,260.00
	LESS 20%			\$ 452.00
	DISCOUNTED TOTAL			\$ 1,808.00
	Rear Bumper Sensor ✓			\$ 388.00
	Labour Charge			200
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00 200
	Wiring Charge			\$ 30.00 X
	Remove/Refix Reverse Sensor			\$ 120.00 20
	TOTAL LABOUR			\$ 850.00
	ESTIMATE TOTAL			\$ 3,046.00
Kok Li 100% 21/1/19 1505L 2 hrs 4/5 After Repair photo LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • All prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK/Kalvin

L/Sun

Lee

CHINA