

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305262005

OMER

IS COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

IESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

JUNT CARD NO.

REGN NO.:

SH 9124A

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN

21.01.2019 10:05

YR OF MANU.

30.05.2015

TARGET DATE

CHASSIS CODE

KMHLB41UMFU069379

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 21.01.2019


NATURE: 3P 21.01.19 -C

S/NO

LABOR CODE

DESCRIPTION

FRONT



OKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SH 9124A

JU AXA

Vehicle No.:

SH 9124A

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9124A

DATE 21/1/2019 15:19

MAKE :

MODEL : HYUNDAI i40

AXA
JH
Lbum

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 553.00	
	Rear Bumper Clip 10 pcs ✓			\$ 22.00	
	Tail Lamp (RH) ✓			\$ 697.80	
	Rear Fender (RH) X			\$ 2,171.40	
	Rear Windscreen Moulding X			\$ 28.30	
	Rocker Panel Hornish (RH) ✓				
	Rear Door (RH) X repair				
	Front Door (RH) X repair				
	Rear Door Hand Stair				
	SUB TOTAL			\$ 3,472.50	
	LESS 20%			\$ 694.50	
	DISCOUNTED TOTAL			\$ 2,778.00	
	Rear Bumper Advertisement Logo ✓			\$ 50.00	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
	Rear Windscreen Sealant X			\$ 46.00	Nett
				\$ 346.00	
	Labour Charge				
	Panel Beating			\$ 800.00	
	Spray Painting Charge			\$ 600.00	Less fees
	Wiring Charge			\$ 30.00	20
	Tuff Kote			\$ 50.00	X
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	X
	Remove/Refix Rear Windscreen Glass			\$ 120.00	X
	Remove/Refix Reverse Sensor			\$ 80.00	20
				\$ 1,830.00	
				\$ 4,954.00	

Kalim LKK

22/1/19 1010hrs

3 hrs

45

After Repair p lot

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Any modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

TOTAL LABOUR

ESTIMATE TOTAL

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

Our Job Ref No 305262005

Date : 24/01/2019

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

: SH 9124A

Date of Accident : 21/01/2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AXA --- BJ3429B
###

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges ###

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

\$2,150.00

3. Estimated normal period for repairs: 3 working days

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : 

Name : Kahi

Date : 24/1/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Final Amount Subject to Insurance Approval