

# BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Date: 22<sup>th</sup> Jan 2019, Tuesday

M/s EQ Insurance Pte Ltd  
5 Maxwell Road  
Tower Block MND Complex  
#17-00  
Singapore 069110

By EMAIL Only: [eassignments@lkkauto.com](mailto:eassignments@lkkauto.com)

Dear Sir / Madam,

REF: Your Insured Vehicle GX 6744M

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)  
ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SLT 9231T & GX 6744M ON 17/01/2019 WITHIN WOODLANDS AVENUE 12 @ 0930 HRS.

Our client's vehicle – SLT 9231T was damaged in the above accident.

A copy of the Singapore Accident Statement report filed is enclosed.

As a result of the accident, the vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us have the list of surveyors to conduct a pre-repair survey of the vehicle within 2 working days.

Please be informed that the said vehicle can be inspected at:

Name of Workshop: **Best Solution Autocare Pte Ltd**

Address: **53 Ubi Avenue 1 #03-01 Paya Ubi Industrial Park S(408934)**

Contact Person: **Ms LEE CUIPING**

Telephone No: **6744 0777**

Fax No: **6744 2377**

Please note that if we do not receive any reply from you within the stipulated timeline, you will be deemed to have waived your rights to a pre-repair inspection. In view of that, we shall proceed to repair the vehicle without further reference to you.

Thank You.

BEST SOLUTION AUTOCARE PTE LTD



Authorized Signatory

