

REF: CSCTE19001518/Jvd3

Special Instruction:

ASS. REC. BY:

Surveyor: Hue He
 From (Person): Irene Tay

ASSIGNMENT (Office)

of CTI

Date/Time: 23/1/19 @ 2:33pm

Estimated Cost:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIR 2378K

Insured:

PC 76864

at Workshop m/s

World Auto

Tel:

6362 1776

of

No. 1 Krunji Loop

Policy No:

DMB1SN18326718000

Claim No:

PC76864

Sum Insured:

Excess:

D.O.A.

17/01/2019

Make of Veh:

(Client's Record)

24/1/2019

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

lup

Date/Time:

2:33pm @ 23/1/19

Person Contacted:

Aimee

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SIR 2378K - NBA / CTI 19001175 / Y</u>
	<u>PC 76864 - NBA / ETI 19001175 / Y</u>

DOA: 17/1/19

DOA: 17/01/2019

Hwee L2

REF: CTE

ASSIGNMENT

From: _____ Date: **24/01/2019**

Estimated Cost: _____

OD: ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SLR 2378K**

at Workshop mis: **World Auto**

of: **No. 1 Kranji Loop**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **up**

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SLR 2378K** Regn: **4 Aug 2017**

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Honda Vezel** C.C: **1496**

Colour: **Green** A/C: **Insured / Std / NI / NA**

Sp. Reading: **110684** T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: **RU31225924**

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Mod: **Nil / SRim** / STD A/Rim or

Tyre Size: **F: 215/60 R16**

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Giti**

Front: _____ Rear: _____

R/Bal. **6** mm R/Bal. **6** mm

L/Bal. **6** mm L/Bal. **6** mm

D.O.A. **17/1/19** D.O.I. **24/1/19**

Survey held at **World Auto**

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

MV - \$88,000

PV - \$44,240

NV - \$43,760

RECEIVED 07 MAR 2019

7/3/19 Confirmed L/s \$3200/- with 4 days of repair. (Red 3797-60, 549)

Date/Time: File Pass to?

☐ : Preli. ReportDays Of Repair: **4**

1)

☐ : Final ReportResurvey No. of Trip: **1**

Date/Time: File Return to?

Survey Fee:

2) **7/3- typist**Add Fee: ☐ Site Insp (\$)

Transportation

☐ Interview (\$)

Photos

Report Format:

☐ Tech. Invs (\$)

Others

Lump Sum / I.B.I. (\$)

☐ Weekend (\$)

TOTAL

merimen**3200/2****220**

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jan 2019		23 Jan 2019 14:33 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	LCRF PTE LTD		
Vehicle Reg. No.:	SLR2378K	Date of Loss:	17/01/2019 17:00 - :59
Claim Type:	TP / PC7686U	Policy/Cover Note No.:	DMB1SN18326718000
Vehicle Reg. No. (Insured):	PC7686U	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 63621776		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/02/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Wednesday, 23 January 2019 2:10 PM
To: ainee31@worldauto.com.sg
Cc: assignments; Admin A
Subject: FW: Request for Third Party Motor Claim Survey (SLR2378K) DOA: 17-01-2019
Attachments: SLR2378K 17012019 TP.PDF; SLR2378K 17012019 HVH.pdf

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and our telephone conversation a moment ago.

We will appoint LKK to conduct PRS.

Aside to LKK:

Please assist to liaise with World Auto.

Thank you.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: ainee31@worldauto.com.sg [mailto:aine31@worldauto.com.sg]
Sent: Wednesday, 23 January, 2019 11:27 AM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Cc: 'Daniel Tan' <worldautopl@yahoo.com.sg>; kana@worldauto.com.sg; Claims Dept of CTI

<claimsdept@sg.cntaiping.com>

Subject: RE: Request for Third Party Motor Claim Survey (SLR2378K) DOA: 17-01-2019

Dear Irene

Here is the attachment please do a necessary follow up

Ainee

**Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250**

From: ainee31@worldauto.com.sg <ainee31@worldauto.com.sg>

Sent: Monday, January 21, 2019 10:28 AM

To: 'claimsdept@sg.cntaiping.com' <claimsdept@sg.cntaiping.com>; 'Irene Tay' <irene.tay@sg.cntaiping.com>

Cc: 'Daniel Tan' <worldautopl@yahoo.com.sg>; 'kana@worldauto.com.sg' <kana@worldauto.com.sg>

Subject: Request for Third Party Motor Claim Survey (SLR2378K) DOA: 17-01-2019

Good afternoon,

We would like to request for a Third Party Motor Claim Survey, details as follow;

Our Vehicle: SLR2378K

Your Insured: PC7686U

DOA: 17-01-2019

Our vehicle is currently in the workshop, address as follow;

World Auto Pte Ltd

No.1, Kranji Loop

Singapore 739535

Please response immediately upon receiving this request, send us your list of Loss Adjustor for our choice within 48 hours.

Kindly note that should you fail to response to us within the above stipulated timeline, we may, at our discretion, appoint our own Loss Adjustor to perform this PRI.

Ainee

**Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250**

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Chin Tai ping

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/01/2019 16:56
Date Of Accident	17/01/2019 17:35
Exact Location Of Accident	UPPER SERANGOON RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR2378K
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 HYBRID (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995069
Cover Note Number	

Driver

Name of Driver	PAN WEIXUAN
NRIC No	S8233242A
Date Of Birth	14/10/1982
Occupation	OUTDOOR
Date Of Driving Pass	29/07/2005
Driving Experience	13 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90694579
Fax Number	
Contact Number	
Email Address	NOEMAIL

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On Thursday, 17th Jan, around 1735, a bus was travelling in front of me. We both filter^{left} into Serangoon Ave 2. I switch into lane 1 after filter in while the bus is still in lane 2. ~~Her~~ Out of a sudden, the bus cut into my lane without signalling, I was not in time to brake, causing his rear (right side) to hit my front left. It was raining at the point of time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER 079909

Attention : Motor Claim Department

Contact : 6389 6111

Estimate : ES190033

Date : 21/01/2019

Vehicle Num. : SLR 2378K (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 21/01/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

1.	1	FRONT BUMPER	Repair DEF	820 900.00 X ✓
2.	1	FRONT HEADLAMP - LH	CRA	1,850.00 ✓
3.	1/LH	FRONT HEADLAMP LOWER BRACKET	NN	78.00 X
4.	1/LH	FRONT HEADLAMP TOP BRACKET	NN	68.00 X
5.	1	FRONT LOWER BUMPER	DU	300.00 ✓
6.	1/LH	FOG LAMP COVER	NN	68.00 X
7.	1	FRONT WHEEL ARCH MOULDING LH	MIS	250.00 ✓
8.	1	FRONT FENDER LH	Repair	550.00 X
9.	1	FRONT FENDER UNDER DUST COVER LH	NN	250.00 X
10.	1	FRONT FENDER HYBRID EMBLEM LH	NEC	56 89.00 ✓
11.	1	SIDE SKIRT LH	NN	430.00 X
12.	1	FRONT BUMPER RETAINER LH	CRA	45 89.00 ✓

List TotalS\$:

4,922.00

20.00% Discount S\$:

984.40

3,937.60

SPECIAL NETT ITEMS :

1.	1	FRONT BUMPER CLIP	NEC	30 40.00 ✓
2.	1	FRONT FENDER UNDER DUST COVER CLIPS	NN	40.00 X
3.	1	SIDE SKIRT CLIPS	NN	40.00 X

Special Nett Total S\$:

120.00

LABOUR :

TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.

46 180.00 X

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE PTE LTD
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER 079909

Attention : Motor Claim Department
 Contact : 6389 6111

Estimate : ES190033

Date : 21/01/2019
 Vehicle Num. : SLR 2378K (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 21/01/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		✓COMPUTERISED ALIGNMENT		180.00 X
		REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS		650 1,400.00
		PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)		650 1,000.00 ✓
		TO REMOVE, REARRANGE ALL ELECTRICAL WIRING, CHECK LIGHTINGS & RESET HEADLAMP FOCUSING		30 180.00 ✓
		Labour Total S\$:		2,940.00

E. & O.E.**Total S\$: 6,997.60**

=====

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total - \$3200/-

Hwee Jie - Lkk

24/1/19

L/s 4 days

Photo after paint

es

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jan 2019		23 Jan 2019 14:33 Edit Adj Rpt	S\$3,200.00 Edit Estimates	S\$3,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	LCRF PTE LTD		
Vehicle Reg. No.:	SLR2378K	Date of Loss:	17/01/2019 17:00 - :59 [17 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / PC7686U	Policy/Cover Note No.:	DMB1SN18326718000
Vehicle Reg. No. (Insured):	PC7686U	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 63621776		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 01/02/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR2378K (PC7686U)
[PC7686U]
TP
LCRF PTE LTD
Jan 17 2019 5:00PM
[-]
World Auto Pte Ltd - Kranji

Upload Documents Upload Photos Compose New Letter

View View in Browser

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/01/19 10:14	General View	Load JPG	☒
2	25/01/19 10:14	General View	Load JPG	☒
3	25/01/19 10:14	General View	Load JPG	☒
4	25/01/19 10:14	General View	Load JPG	☒
5	25/01/19 10:14	General View	Load JPG	☒
6	25/01/19 10:14	General View	Load JPG	☒
7	25/01/19 10:14	General View	Load JPG	☒
8	25/01/19 10:14	General View	Load JPG	☒
9	25/01/19 10:14	General View	Load JPG	☒
10	25/01/19 10:14	General View	Load JPG	☒
11	25/01/19 10:14	General View	Load JPG	☒
12	25/01/19 10:14	General View	Load JPG	☒
13	25/01/19 10:14	General View	Load JPG	☒
14	25/01/19 10:14	General View	Load JPG	☒
15	25/01/19 10:14	General View	Load JPG	☒
16	25/01/19 10:14	General View	Load JPG	☒
17	25/01/19 10:14	General View	Load JPG	☒
18	25/01/19 10:14	General View	Load JPG	☒
19	25/01/19 10:14	General View	Load JPG	☒
20	25/01/19 10:14	General View	Load JPG	☒
21	25/01/19 10:14	General View	Load JPG	☒
22	25/01/19 10:14	General View	Load JPG	☒
23	31/01/19 16:43	Photo After Spray	Load JPG	☒
24	31/01/19 16:43	Photo After Spray	Load JPG	☒
25	31/01/19 16:43	Photo After Spray	Load JPG	☒
26	31/01/19 16:43	Photo After Spray	Load JPG	☒
27	31/01/19 16:43	Photo After Spray	Load JPG	☒
28	31/01/19 16:43	Photo After Spray	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119001518/JVD3S2
Date: 08/03/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN18326718000
Claimant Vehicle No: SLR2378K Insured Vehicle No: PC7686U
Date of Loss: 17/01/2019 Nature of Claim: TP Claim No: PC7686U

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR2378K**
Make & Model: HONDA VEZEL HYBRID, 1.5 Z (A) Engine No: LEB5925936
Reg. Date: 04/08/2017 (Man. Year: 2016) Chassis No: RU31225924
Colour: Green Odometer: 110684 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Giti 6 mm Rear Left Side: Giti 6 mm
Front Right Side: Giti 6 mm Rear Right Side: Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,057.60	2,686.80	1,370.80	33.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,330.00	1,610.00	54.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,997.60	4,016.80	2,980.80	42.60
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	6,997.60	3,200.00	3,797.60	54.27
+ GST 7.00/7.00% (S\$)	489.83	224.00	265.83	54.27
Nett Amount (S\$)	7,487.43	3,424.00	4,063.43	54.27

INSPECTION

Date of Assignment: 23/01/2019
Date Inspected: 24/01/2019 Inspected At: NO.1 KRANJI LOOP
Estimated Period of Repair: 4.0 days Repairer: World Auto Pte Ltd

Adjuster: ONG HWEE JIE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2019)
Parts:	M1-SUV	HONDA VEZEL HYBRID 1.5 Z (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR2378K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	900.00 FL	*820.00 FL
2	1		*FRONT HEADLAMP - LH	Cracked	1,850.00 FL	*1,850.00 FL
3	1		*LH FRONT HEADLAMP LOWER BRACKET	Not Necessary	78.00 FL	*- FL
4	1		*LH FRONT HEADLAMP TOP BRACKET	Not Necessary	68.00 FL	*- FL
5	1		*FRONT LOWER BUMPER	Dented	300.00 FL	*300.00 FL
6	1		*LH FOG LAMP COVER	Not Necessary	68.00 FL	*- FL
7	1		*FRONT WHEEL ARCH MOULDING LH	Missing	250.00 FL	*250.00 FL
8	1		*FRONT FENDER LH	Repair	550.00 FL	*- FL
9	1		*FRONT FENDER UNDER DUST COVER LH	Not Necessary	250.00 FL	*- FL
10	1		*FRONT FENDER HYBRID EMBLEM LH	Necessary	89.00 FL	*56.00 FL
11	1		*SIDE SKIRT LH	Not Necessary	430.00 FL	*- FL
12	1		*FRONT BUMPER RETAINER LH	Cracked	89.00 FL	*45.00 FL
13	1		*FRONT BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
14	1		*FRONT FENDER UNDER DUST COVER CLIPS	Not Necessary	40.00 FS	*- FS
15	1		*SIDE SKIRT CLIPS	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,042.00	3,351.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	984.40	664.20
Total Parts (\$\$)	4,057.60	2,686.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS.	New	180.00	0.00
2	COMPUTERISED ALIGNMENT.	New	180.00	0.00
3	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.	New	1,400.00	650.00
4	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER / OUTER).	New	1,000.00	650.00
5	TO REMOVE, REARRANGE ALL ELECTRICAL WIRING, CHECK LIGHTINGS & RESET HEADLAMP FOCUSING.	New	180.00	30.00
Gross Labour Cost (S\$)			2,940.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >