

Address

INS. CASE OWNER

val

CC 4 AXA1900 1576

9/11/19

LKK

IDAC

Surveyor

Admin

DOI

ASSIGNMENT

27/1/19

Date / Time

27/1/19

Registered in Merimen

Pre-assign / CCU / FTE

SKU 5774X



Insured Vehicle No.

SAVY ANNE HU JINT PONTA HO

Claim No.

SA MOI BCHI / 95178

Name of Insured

Policy No.

VPA / 1018 W31

Insured Tel No.

HP: 98 269 24 JINT PONTA

Make / Model

Toyota

Excess Sec II :SS

D.O.A: 27/1/19

Place of Accident

Upp Thomson Rd

Is driver the owner?

(YES / NO)

Nature of Accident

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

GZ 5461A



INSRS:
WSP:
Tel:
Liability:
RMKS:

my solution



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

27/1/19
my

GZ 5461A-X

SEV 4870X-X

STAGE

DATE / PIC

Non-Reporting hr (1st)

Non-Reporting hr (2nd)

Non-Reporting hr (Final)

Notification hr (if non-pickup)

Call OI:

24-1-19 JUY

After call hr to OI:

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

Confirm by:

Admin

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Admin

Repair Cost:

SS 3700.00

17 days

Reduction:

7201.92 = 67

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(gross / Assessed) BOLA S/N No. : 27.

If NO or B 28, Ass. Lia:

Repair Cost:

SS

3759.00

Loss of Rental (LOR):

SS

640.00

(15 days)

Loss of Use (LOU):

SS

640.00

(15 days)

Loss of Income (LOI):

SS

640.00

(15 days)

LOR only

☐

LOU only

☒

LOR + LOU

☐

LOR + LO

☐

(Tick only one)

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost:

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4350

Total:

SS

4606.45

Global Sum SS:

4600.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

4600.00

Name 1:

My solution Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
20/2/2020

ASS. REC. BY:

REF:

ASSIGNMENT

Adrian

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GZ5461A

Yr Regn:

2006, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit L300

c.c 2477

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

303930

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMAJNP15V6A001186

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake:

Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

185R14C

R:

185R14C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Chuo Yang

Front

06

Rear

R/Bal.

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

23/01/19

Survey held at:

MG solution

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP AXA

COR Expiry: 31/05/21

29-4-19 L/S \$4K

L/S \$3700/- (Red: \$3791.93 / 6271)

MV: 16K

PV: 10.7K

Nett: 5.3K

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19001536/jb3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 23-01-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKV 5774X	Veh. Inspected	GZ 5461A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/01/2019
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/01/2019	Inspection Date	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA	DATE	: 21/01/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: GZ5461A		
MODEL	: MITSUBISHI L300		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 21-Jan-19
		TIME	: 09:50HRS
THIRD PARTY REQUESTOR / CONTACT	:	JACK LI	

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Distorted</i>	1	\$ 899.00	\$ 899.00
2	TAILGATE TOP LOCK <i>Jammed</i>	1	\$ 199.50	\$ 199.50
3	TAILGATE LOWER CATCH <i>new</i>	1	\$ 65.00	\$ 65.00
4	TAILGATE INNER BOARD <i>Not new</i>	1	\$ 128.00	\$ 128.00
5	TAILGATE INNER HANDLE <i>Not new</i>	1	\$ 118.00	\$ 118.00
6	TAILGATE WEATHERSTRIP <i>cut</i>	1	\$ 218.00	\$ 218.00
7	TAILGATE WEATHERSTRIP TOP COVER <i>Best</i>	1	\$ 68.00	\$ 68.00
8	TAILGATE UPPER STOPPER <i>Not new</i>	2	\$ 26.00	\$ 52.00
9	TAILGATE DAMPER <i>Not new</i>	2	\$ 228.00	\$ 456.00
10	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 196.00	\$ 196.00
11	TAILGATE KEYLOCK <i>Not new</i>	1	\$ 223.00	\$ 223.00
12	TAILGATE OUTER PROTECTOR <i>2nd</i>	1	\$ 155.30	\$ 155.30
13	TAIL LAMP <i>Not new</i>	2	\$ 256.00	\$ 512.00
14	TAIL LAMP PANEL <i>Not new</i>	2	\$ 193.00	\$ 386.00
15	TAIL LAMP LOWER BRACKET <i>Not new</i>	2	\$ 53.00	\$ 106.00
16	REAR BUMPER <i>Distorted</i>	1	\$ 420.00	\$ 420.00
17	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 52.00	\$ 104.00
18	REAR SIDE BUMPER <i>Missing</i>	2	\$ 103.00	\$ 206.00

19	REAR BUMPER SIDE REFLECTOR <i>new</i>	2	\$ 68.00	\$ 136.00	-
20	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 63.00	\$ 126.00	+
21	REAR END PANEL <i>Discontinued</i>	1	\$ 455.00	\$ 455.00	←
22	REAR END PANEL TOP GARNISH <i>Best new</i>	1	\$ 98.00	\$ 98.00	+
23	REAR END PANEL TOP PANEL <i>new</i>	1	\$ 384.00	\$ 384.00	+
24	REAR END PANEL BOTTOM (EXTENSION) <i>Best</i>	1	\$ 228.00	\$ 228.00	-
25	REAR FLOOR PANEL <i>Rejis</i>	1	\$ 869.00	\$ 869.00	x.
26	REAR FLOOR PANEL COVER BOARD <i>new</i>	1	\$ 159.00	\$ 159.00	+
27	EXHAUST PIPE <i>new</i>	1	\$ 520.00	\$ 520.00	+
28	EXHAUST PIPE MOUNTING <i>new</i>	1	\$ 32.00	\$ 32.00	+

3284.80

2956.32

TOTAL PRICE \$ 7,518.80

LESS 10% \$ 751.88

SUB TOTAL PRICE \$ 6,766.92

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	30
2	TAILGATE INNER TRIM BOARD CLIP (SET) <i>new</i>	1	\$ 45.00	\$ 45.00	+
3	TAILGATE WINDSCREEN SEALANT <i>2 new</i>	1	\$ 60.00	\$ 60.00	30
4	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	30
5	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	-
6	STICKER 70KM/H <i>new</i>	1	\$ 30.00	\$ 30.00	15
7	STICKER 5 PAX <i>new</i>	1	\$ 30.00	\$ 30.00	15
8	TAIL LAMP CLIP (SET) <i>new</i>	2	\$ 50.00	\$ 100.00	10
9	TAILLAMP PANEL SEALANT <i>new</i>	2	\$ 50.00	\$ 100.00	+
10	REAR END PANEL SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	60
11	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 120.00	\$ 120.00	+
12	REVERSE SENSOR <i>new</i>	1	\$ 200.00	\$ 200.00	+

220

TOTAL \$ 945.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING AND REPLACE PARTS	\$ 1,600.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	750	
3	TUFF COAT	\$ 60.00	40	
4	WIRNING, BULB CHECKING	\$ 60.00	30	

Adrian Lij
4/2 23/01/19
OTRys.

5	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓	
6	TRANSFER TAILGATE MECHANISM	\$ 120.00	80	
7	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 120.00	X	
8	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X	

TOTAL

\$3,380.00

1820

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,711.92

TOTAL LABOUR COST : \$ 3,380.00

TOTAL REPAIR COST : \$ 11,091.92

total: 4996.32

L/S 4K

07 Days.

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3284.8 x 50% = 1642.40

total: 1642.40 + 220 + 1820 = 3712

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Business
Owner ID:	4290L
Vehicle Details	
Vehicle No.:	GZ5461A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	23 Jan 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	L300 HR M
Primary Colour:	White
Manufacturing Year:	2006
Engine No.:	4D56LB6038
Chassis No.:	JMAJNP15V6A001186
Maximum Power Output:	-
Open Market Value:	\$12,331.00
Original Registration Date:	01 Jun 2006
First Registration Date:	01 Jun 2006
Transfer Count:	1
Actual ARF Paid:	\$617.00
Imported Vehicle Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Imported Vehicle COE Details	
COE Expiry Date:	31 May 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,721.00
COE Rebate Amount:	\$10,700.00
Total Rebate Amount:	\$10,700.00
Remarks	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 23 Jan 2019

OK

500+ dealers competed to buy my car!



- Sell ur Car for More Cash
- Highest Price or Get \$100 Free
- Get Paid Now, Handover Later

SELL YOUR CAR





Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Coe Renewal Toyota Vios 1.5A



Driveaway \$2300 (inc: 1 Yr Insurance & Adv) 2.88%p.a
Monthly \$468 By Gv Finance
Gv Credit Pte Ltd. StarAd





HIN LUNG AUTO
Ho Bee Group

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years of car sale

Browse by Category  Save Search  Print Sort by Date Posted  20 results/page 

1 vehicles

Search [Advanced Search](#) [Search](#) [View All](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mitsubishi	L300	Any	Any	Any	Any	Any	Any	Available



☐ **Mitsubishi L300 (COE till 09/2021)**

Fuel Type: Diesel

Tip Top Condition, No Repair Needed, Well Maintain By Previous Owner, See To Believe, Act Fast, Call For Appointment.

Net Link Partners Pte Ltd

 **Posted:** 23-Jan-2019 Topic: 2009 Mitsubishi L300, 2005 Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi L300, Mitsubishi L300

\$19,800

\$7,400 /yr

27-Sep-2006

2,477 cc

-

Van

Available

Save this search criteria, to get email alerts whenever a match is found.  Save Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
--	------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads 20 results/page

sgCarMart is the number one car classified for potential import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagon, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, compare rates & car insurance. Find buy used Mitsubishi L300, Mitsubishi L300 Singapore, used Mitsubishi L300 Singapore, used Mitsubishi L300, used vehicles Singapore or even buy used Mitsubishi L300 Singapore. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, travel, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com









UNPUBLISHED HISTORY

Compare 

LETTER OF AUTHORITY

Name : GREAT AIRCON
Address : 22 SIN MING LANE
#06-76 MIDVIEW CITY S (573969)
Contact No : _____
TO: AXA INSURANCE PTE LTD

Dear Sirs,

ACCIDENT INVOLVING G2 5461A AND SKV 5774X ON 21/1/19
AT/ALONG Upper Thomson Road towards Lorrie Road after
SIN ming Ave.

I/We, GREAT AIRCON, am/are the registered owner of
motor car no. G2 5461A

Please note that I have assigned all compensations monies due to me/us in the above said accident
to **M/S MG SOLUTION PTE LTD.**

I/We, hereby authorize you to release all compensation monies pertaining to the above-mentioned
accident to **M/S MG SOLUTION PTE LTD** and forward your settlement cheque to **M/S MG SOLUTION**
PTE LTD whom I had authorized to collect the said compensation monies.

Thank you



Signature of Claimant

Witness By

MG SOLUTION PTE LTD
23 Kaki Bukit Ave 4 (South Wing) #02-03B
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
GST Reg. No. : 201427944N

MOTOR CLAIM DISCHARGE

INSURED: GREAT AIRCON
CAR/ LORRY/CYCLE: REG NO: G2 5461A POLICY NO:
ACCIDENT CLAIM NO:

I / We confirm that I / we have taken delivery of Car / Lorry / Motor Cycle
Registered No. G2 5461Afrom the repairers,
Messrs MG SOLUTION PTE LTD

And that all repairs necessary as a result of an accident in which the said vehicle was involved on or
about the 21 day of 01 2019 have been completed to my / our satisfaction, and that
I / we have no further claim on the above company in Respect thereof.

Date: Signature:

Co's Stamp: NRIC No:



23/01/2019 - PRI

27/01/2019 - Sunday

Vehicle In - 23/01/2019

Vehicle Out - 30/01/2019

Low - 8 days x \$150
\$1,200



Service Request Details

Claim

S9M01BCH

Reference

None 

Loss Date

January 21, 2019

Request Date

January 23, 2019

Due Date

January 30, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

23 01 2019 @ 12:13pm
Hong veh ~~acc~~ in
Adrian

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

GZ5461A

Make

TPVD MITSUBISHI



Service Address

...

Primary Contact/Insured

HO JUAT FONG SALLY ANNE @HO JUAT FONG
BLK 113 BISHAN STREET 12, #02-112 BISHAN VIEW, 570113, Singapore
98228934

Claim Handler

OH Vale
6568804897
vale.oh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: MG Solution <mg3solution@gmail.com>
Sent: Wednesday, 23 January, 2019 9:12 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: GZ5461A -(PRE-INSPECTION); YOUR REF : SKV5774X ON 21/01/2019
Attachments: GZ5461A-(PRE-INSPECTION) ; YOUR REF SKV5774X.pdf

Categories: Santosh

Dear person in charge,

Please refer to attach file and arrange for pre-inspection.

Thank You.

Best Regards,

MS HONG

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing)

#02-03B Vicom Inspection Centre

Singapore 415933

Tel : 6744 4165

Fax : 6744 4604



Auto
Consultants
Pte Ltd

Company Registration No. 199407188R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 15/6/2019

Survey Details:

Date of loss	21-Jan-19
Date of appointment	23-Jan-19
Date of survey	23-Jan-19
Location of survey	MG SOLUTION

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	GZ 5461A
Make and Model	MITSUBISHI L300 2477CC
Date of registration	1-Jun-06
Parf Rebate	
Market Value	\$ 16,000.00
Parf Rebate	\$ 10,700.00
Nett Loss	\$ 5,300.00

Repair details:

Initial Estimate	11,091.92
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 3,176.32
Check items (estimate)	
Labour	\$ 1,820.00
Total	\$ 4,996.32
Lump Sum(if applicable)	\$ 4,000.00

Number of days for repair	7 DAYS
---------------------------	--------



Auto
Consultants
Pte Ltd

Company Registration No. 199607186R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (865) 62563561 FAX.: (865) 62564315

Remarks:

WE HAVE NOT AUTHORIZED REPAIRS.HEAD TO REAR ; BOLA 27

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 4,280.00	GST INCLUDED
Loss of use	\$ 800.00	\$100 x 8 days
LTA search fees	\$ 7.45	
Proposed Total	\$ 5,087.45	



Re:RE: MANDATE IA - MG SOLUTION - GZ 5461A

Type

🔔 Question

Message

Hi, 1) Kindly advise missing bumper whether potentially due to accident or may be lost before incident. 2) This is a commercial vehicle > 3yrs. Kindly advise based on LS COR in terms of i) Parts less 50%, ii) Parts less 25-30% & overall 20% iii) cost + 15%. Thanks

Reply

*TO clarify to
Admin. on parts.*



RE: Re:RE: MANDATE IA - MG SOLUTION - GZ 5461A

Type

🔔 Question

Message

Hi Lynn, We re-seek mandate of COR(w/GST): \$3959.00, LOU: \$800.00 (8days x \$100), LTA search: \$7.45.
Total: \$4766.45. For your approval/instruction please. Thanks - CCL 16/03/2020

Reply



RE: Re:RE: MANDATE IA - MG SOLUTION - GZ 5461A

Type

🔔 Question

Message

Proceed LS COR parts less 50%. Thanks

Reply



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 20-1427944-N)

TAX INVOICE

Bill To:

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

INVOICE No : TI 209085

PB No : 198024

Date : 19-March-2020

ATTN : MOTOR CLAIMS DEPARTMENT

Vehicle Number : GZ 5461A

QTY	DESCRIPTION	AMOUNT
1	To carried out accident repair as per surveyor's recommendation (Lump Sum)	\$ 3,700.00
BEFORE GST		3,700.00
7% GST		259.00
TOTAL		\$ 3,959.00

Cheque should be made payable to **MG Solution Pte Ltd**



Co's stamp & Authorised Signature



Re:RE: Re:RE: MANDATE IA - MG SOLUTION - GZ 5461A

Type

🔔 Question

Message

Hi CCL, proceed. Thanks

Reply



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 201427944N)

Date : 11/02/2019
Your Ref : SKV5774X
To : AXA INSURANCE SINGAPORE PTE LTD
Attn : Motor Claims Department

Dear Sir/Mdm,

**RE: ACCIDENT INVOLVING VEHICLE GZ5461A & SKV5774X ON 21/01/2019 AT
ALONG UPPER THOMSON ROAD TOWARDS LORNIE AFTER SIN MING AVE.**

We refer to the above matter.

Attached copies of the following for your kind perusal:

- 1) Proforma Bill No.198024 @ S\$3,959.00 (Inclusive Of 7% GST)
- 2) Loss of Use @ S\$1,200.00 (8 Days x S\$150)
- 3) LTA Search @ S\$7.45
- 4) Authorisation to Act
- 5) GIA Report

Hope the above is in order and kindly let us have your confirmation soon.

Tax invoice will be issue upon amount finalized.

Thank You.

Yours faithfully,

Sharon Chia

HP: 9188 6931

E-mail: mg3solution@gmail.com

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19001536/Aga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 27-03-2020



ATTN:VALE OH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKV 5774X	Veh. Inspected	GZ 5461A
Policy No.	VPA/P1982031	Coverage (\$)	0.00
Claim No.	S9M01BCH	Excess (\$)	0.00
Assign From		Assign Date	23/01/2019

2. Vehicle Particulars & Condition

Make & Model	mitsubishi L300	c.c	2477
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JMAJNP15V6A001186	Colour	WHITE
Odometer	303930	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185 R14C	CHAO YANG	6 mm
L/H Front Tyre	185 R14C	CHAO YANG	6 mm
R/H Rear Tyre	185 R14C	CHAO YANG	6 mm
L/H Rear Tyre	185 R14C	CHAO YANG	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/01/2019	Inspection Date	23/01/2019
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GZ 5461A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE (CONSISTENT)	DISTORTED ✓	899.00	899.00
1	TAILGATE TOP LOCK (CONSISTENT)	JAMMED ✓	199.50	199.50
1	TAILGATE LOWER CATCH (CONSISTENT)	NOT NECESSARY ✓	65.00	-
1	TAILGATE INNER BOARD (CONSISTENT)	NOT NECESSARY ✓	128.00	-
1	TAILGATE INNER HANDLE (CONSISTENT)	NOT NECESSARY ✓	118.00	-
1	TAILGATE WEATHERSTRIP (CONSISTENT)	CUT ✓	218.00	218.00
1	TAILGATE WEATHEESTRIP TOP COVER (CONSISTENT)	BENT ✓	68.00	68.00
2	TAILGATE UPPER STOPPER @\$26.00 (CONSISTENT)	NOT NECESSARY ✓	52.00	-
2	TAILGATE DAMPER @\$228.00 (CONSISTENT)	NOT NECESSARY ✓	456.00	-
1	TAILGATE WINDSCREEN MOULDING (CONSISTENT)	NECESSARY ✓	196.00	196.00
1	TAILGATE KEYLOCK (CONSISTENT)	NOT NECESSARY ✓	223.00	-
1	TAILGATE OUTER PROTECTOR (CONSISTENT)	DEFORMED ✓	155.30	155.30
2	TAIL LAMP @\$256.00 (CONSISTENT)	NOT NECESSARY ✓	512.00	-
2	TAIL LAMP PANEL @\$193.00 (CONSISTENT)	NOT NECESSARY ✓	386.00	-
2	TAIL LAMP LOWER BRACKET @\$53.00 (CONSISTENT)	NOT NECESSARY ✓	106.00	-
1	REAR BUMPER (CONSISTENT)	DISTORTED ✓	420.00	420.00
2	REAR BUMPER SIDE RETAINER @\$52.00 (CONSISTENT)	NECESSARY ✓	104.00	104.00
2	REAR SIDE BUMPER @\$103.00 (CONSISTENT)	MISSING ✓	206.00	206.00
2	REAR BUMPER SIDE REFLECTOR @\$68.00 (CONSISTENT)	NECESSARY ✓	136.00	136.00
2	REAR NUMBER PLATE LAMP @\$63.00 (CONSISTENT)	NOT NECESSARY ✓	126.00	-
1	REAR END PANEL (CONSISTENT)	DISTORTED ✓	455.00	455.00
1	REAR END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY ✓	98.00	-
1	REAR END PANEL TOP PANEL (CONSISTENT)	NOT NECESSARY ✓	384.00	-
1	REAR END PANEL BOTTOM (EXTENSION) (CONSISTENT)	BENT ✓	228.00	228.00
1	REAR FLOOR PANEL (CONSISTENT)	TO REPAIR SEE LABOUR ✓	869.00	-
1	REAR FLOOR PANEL COVER BOARD (CONSISTENT)	NOT NECESSARY ✓	159.00	-
1	EXHAUST PIPE (CONSISTENT)	NOT NECESSARY ✓	520.00	-
1	EXHAUST PIPE MOUNTING (CONSISTENT)	NOT NECESSARY ✓	32.00	-
	LESS 10% DISCOUNT		-751.88	-

Report Ref No. CC4/ASM19001536/Aga3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 50% DISCOUNT		-	-1,642.40
			6,766.92	1,642.40
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN) (CONSISTENT)	CRACKED ✓	50.00	30.00
1	SET TAILGATE INNER TRIM BOARD CLIP (SN) (CONSISTENT)	NOT NECESSARY ✓	45.00	-
1	TAILGATE WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY ✓	60.00	30.00
1	TAILGATE WINDSCREEN INNER SEAL (SN) (CONSISTENT)	NECESSARY ✓	60.00	30.00
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY ✓	30.00	30.00
1	STICKER 70KM/H (SN) (CONSISTENT)	NECESSARY ✓	30.00	15.00
1	STICKER 5 PAX (SN) (CONSISTENT)	NECESSARY ✓	30.00	15.00
2	SET TAIL LAMP CLIP @\$50.00 (SN) (CONSISTENT)	NECESSARY ✓	100.00	10.00
2	TAILLAMP PANEL SEALANT @\$50.00 (SN) (CONSISTENT)	NOT NECESSARY ✓	100.00	-
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NECESSARY ✓	120.00	60.00
1	REAR END PANEL INSULATION SEAL (SN) (CONSISTENT)	NOT NECESSARY ✓	120.00	-
1	REVERSE SENSOR (SN) (CONSISTENT)	NOT NECESSARY ✓	200.00	-
			945.00	220.00
	<u>LABOUR</u>			
	PANEL BEATING AND REPLACE PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL .		1,600.00	800.00
	SPRAY PAINTING TO AFFECTED AREA.		1,200.00	750.00
	TUFF COAT.		60.00	40.00
	WIRING BULB CHECKING.		60.00	30.00
	REMOVE AND REFIX TAILGATE WINDSCREEN.		120.00	120.00
	TRANSFER TAILGATE MECHANISM .		120.00	80.00
	REMOVE AND REFIX REAR REVERSE SENSOR .	NOT NECESSARY ✓	120.00	-
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY ✓	100.00	-
			3,380.00	1,820.00
	GRAND TOTAL		11,091.92	3,682.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,700.00

Report Ref No. CC4/ASM19001536/Aga3q2



Report Ref No. CC4/ASM19001536/Aga3q2

A handwritten signature in black ink, appearing to read 'A. Ling'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

SPM01BCH

Reference

CC4/ASM19001336/Agas3q2

Loss Date

21 January 2019

Report Date

22 Jan 2019 8:46:00 AM

Request Date

17 June 2019

Due Date

Vendor Name

LKX AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

CZ5A63A

Make

TPVO MITSUBISHI

Model

L300 HR M

Service Address

...

Primary Contact/Insured

HO JUAT FONG SALLY ANNE @HO JUAT FONG

BLK 113 BISHAN STREET 12, #02-112 BISHAN VIEW, 570113, Singapore

98228934

Claim Handler

KHONG Lynn

68804892

lynn.khong@axa.com.sg

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKXInvoice1 (7).pdf	Invoice	Surveyor/ Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	31 March 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKKInspection (3).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKKAdjustment's (4).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 AMENDED LOD AND INVOICE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 March 2020
 LETTER TO INSURED .pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	15 June 2019
 MANDATE IA-MG SOLUTION-CZ 5461A.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	15 June 2019
 TP ESTIMATE_MARKED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	15 June 2019
 RE-SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	15 June 2019
 SURVEY PHOTOS .pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	15 June 2019
 EMAIL FROM WORKSHOP FOR TP REC.mig	Letter and Correspondence	Others	NIKAM Santosh Pandurang	23 January 2019
 CIA SRV5724X INED.PDF	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	22 January 2019
 P19E2031_P5.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	KHONG Lynn	22 January 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 P1982031_CI.pdf	Forms / Claim Documents	Policy Schedule / Coverhole / Certificate of Insurance	KHONG Lynn	22 January 2019