

Adrian

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: 2100505869

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: 600

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 90K.

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 0488 \$ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % J Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLM5745R Yr Regn: 2017, March

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Audi A3 Sedan c.c. 999

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 46993 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WAU2228VXH1017120

Gen. Cond:  Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil /  STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU /  PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm	
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm	
D.O.A. <u>16/1/19</u>		D.O.I. <u>23/01/19</u>	

Survey held at: Premium

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or Front N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>OP ALG.</u>
<u>24/1/19</u>	<u>Revert via merimen</u>
<u>24/1/19</u>	<u>Rec approved from Victor by merimen</u>
<u>24/1/19</u>	<u>Informed Nora c/A ex \$600 by email</u>
<u>04/06/19</u>	<u>Confirmed P/P \$ 8,025.60 @ 4 days with Adrian (\$ 8,847.40 Red - 52%)</u>

RECEIVED 21 JUN 2019

Resurvey No of Trip - 0

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:		Survey Fee:	Date:
1) <u>Typist</u>	2) _____	IN	OUT	Basic & Add.	<u>200</u>
3) _____	4) _____			\$ + RS, SI	<u>11</u>
5) _____	6) _____			Photos	
Preli. Report:				Others	
Final Report: <u>\$ 8,025.60 P/P</u>				TOTAL	<u>211</u>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

<b>To:</b> AIG Asia Pacific Insurance Pte. Ltd. AIG Building 78 Shenton Way #08-16 Singapore 079120	<b>From:</b> LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
<b>Attn:</b> Foo, Chit Yan	
<b>Date:</b> 24 Jan 2019	
<h3><u>Preliminary Advice</u></h3>	

Vehicle No	: SLM5745R	Accident Date	: 16/01/2019
Make	: AUDI A3	Policy No.	: 2100505869
Assignment Date	: 23/01/2019	Excess	: S\$0.00
Date of Inspection	: 23/01/2019	Est. Duration of Repair	: 4.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,873.00	
Revised Amount	:S\$	9,432.00	
Check Items (Estimated)	:S\$	500.00	
<b>Total</b>	<b>:S\$</b>	<b>9,932.00</b>	
Lump Sum Repair	:S\$		
<b>Total Loss Consideration</b>			
New for Old Value	:S\$		
Pre-Accident Value	:S\$	90,000.00	
COE / PARF Rebate	:S\$	54,669.00	
Salvage Value	:S\$		
Margin for Repair	:S\$	35,331.00	

### Remarks

( X )		The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
( )		The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
( )		Other comments :

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 6 June 2019 5:49 PM  
**To:** 'Boo seng yak'  
**Cc:** Adrian Ling (LKKAuto); SUR; 'Carrine Leong'; jiyee.yap@premiumauto.com.sg;  
'Chang Chee Sing'  
**Subject:** RE: FINAL REVISION - SLM5745R - OD AIG -SURVEYED 23 JAN 19

Dear Mr Boo,

Confirmed final fig \$ 8025.60 @ 4 days of repairs before excess \$ 600/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Boo seng yak [mailto:boojohnny@gmail.com]  
**Sent:** Tuesday, 21 May 2019 4:11 PM  
**To:** Adrian Ling <adrianling@lkkauto.com>; Veron Chen <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiyee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>  
**Subject:** FINAL REVISION - SLM5745R - OD AIG -SURVEYED 23 JAN 19

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$8025.60 @ 4 days.

your early closure is well appreciated.

Best regards - jb

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 24 January 2019 3:59 PM  
**To:** 'NORA '; 'Claims'; SUR; Admin A  
**Subject:** RE: OD claim for SLM 5745 R-DOA: 16/1/2019

Dear Nora,

As instructed by our client , please proceed to repair the insured vehicle **SLM 5745R (Excess 600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Veron Chen** | Case Handler **on behalf of Shirley**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** NORA <nora.khai@premiumauto.com.sg>  
**Sent:** Thursday, 24 January 2019 3:52 PM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>; 'Claims' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** RE: OD claim for SLM 5745 R-DOA: 16/1/2019

Dear Veron,

As per your kind request.

Thank you.

Best Regards,

**Norah Khai**  
Claims Manager

**Premium Automobiles Pte Ltd** (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183

e. [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg) w. [www.audi.com.sg](http://www.audi.com.sg)

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



[http://www.audi.com.sg/sea/brand/sg/audi\\_promotions/promotions/car\\_promotions/new-audi-q2-2017.html](http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html)

**Email Disclaimer**

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

---

**From:** Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]

**Sent:** Thursday, 24 January 2019 8:31 AM

**To:** NORA ; 'Claims'; SUR; Admin A

**Subject:** RE: OD claim for SLM 5745 R-DOA: 16/1/2019

Dear Nora,

Please forward us CI.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** NORA <[nora.khai@premiumauto.com.sg](mailto:nora.khai@premiumauto.com.sg)>

**Sent:** Wednesday, 23 January 2019 11:14 AM

**To:** 'Claims' <[claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: OD claim for SLM 5745 R

Dear All,

Please assist for approval.

Thank you.

Best Regards,

**Norah Khai**  
Claims Manager

**Premium Automobiles Pte Ltd** (Reg No: 199902271W)  
55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183

e. [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg) w. [www.audi.com.sg](http://www.audi.com.sg)

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



[http://www.audi.com.sg/sea/brand/sg/audi\\_promotions/promotions/car\\_promotions/new-audi-q2-2017.html](http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html)

**Email Disclaimer**

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

---

**From:** Claims [<mailto:claims@premiumauto.com.sg>]

**Sent:** Tuesday, 22 January 2019 1:57 PM

**To:** 'SUR'; 'Admin A'

**Cc:** 'Claims Dept'

**Subject:** OD claim for SLM 5745 R

Good afternoon all ,

Here is the attached estimate for your kind reference .

Note : There is a survey arranged on 23/01/2019 @ 11am (owner waiting) . Kindly assist for the arrangement .

Thank you .

Best Regards,

Phua

Claims Advisor

Premium Automobiles Pte Ltd (Reg No: 199002271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg) w. [www.audi.com.sg](http://www.audi.com.sg)

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



## View Received Message

This mail is associated with :

**\*SLM5745R (7723195490SG)**  
OD  
Jan 16 2019 4:15PM  
[ANG LI-HSIEN, SAMUEL]  
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 24/01/2019 15:29 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$9432.00) - SLM5745R - Claim Handler: Dally Amri, Mimi Zarina

Approved:9432.00:Re-inspection to be done for damage check and supplementary items / labour.

### DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring 

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	97851
Vehicle Details	
Vehicle No.:	SLM5745R
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Jan 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	CHZ142518
Chassis No.:	WAUZZZ8VXH1017120
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,582.00
Original Registration Date:	31 Mar 2017
First Registration Date:	31 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$16,415.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2027
PARF Rebate Amount:	\$12,311.00
Intended COE Rebate Details	
COE Expiry Date:	30 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,765.00
COE Rebate Amount:	\$42,358.00
<b>Total Rebate Amount:</b>	<b>\$54,669.00</b>

The information contained herein is correct as at 24 Jan 2019

OK

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE  
6 Raffles Quay #18-00 Singapore 248680  
Tel (65) 6774 0010 Fax (65) 6774 0090  
Operating Hours: Monday to Friday, 09:00 - 17:00  
URL: [www.gia.org.sg](http://www.gia.org.sg) / 011 Reg. No.: M40017730

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MPA119008171-01 Vehicle Registration No: SLM5745R  
Name (as shown in NRIC) : SAMUEL ANG-HSIEN, SAMUEL NRIC/FIN/Passport No : S7829785I  
[\* Vehicle Driver / Vehicle Owner] [\*] Please delete as appropriate  
Address : BLK 159 YUNG PING ROAD Singapore ( 610159 )  
Contact (Tel) : 98193118 Mobile No. : 98193118  
Email Address : NOEMAIL  
Date of Accident : 16/01/2019 Time of Accident : 16.15  
Place of Accident : ALEXANDRA ROAD POST OFFICE CAR PARK  
Insurance Company : AIG ASIA PACIFIC INSURANCE PTE. LTD.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To add in TP vehicle registration No. SLZ 6871 J

\_\_\_\_\_  
Policyholder / Driver's Signature  
Date:

\_\_\_\_\_  
Reporting Centre Personnel's Signature

Name: WONG KHONG SENH, GONG  
NRIC/FIN No.: S208743A  
Date: 19/1/19



# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khal@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0094/2019/PH  
**Date** : 22-Jan-19

Vehicle not in workshop. Kindly arrange for survey.

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**  
**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Ang Li Hsien , Samuel  
**Address** : Blk 159 Yung Ping Road  
#03-03  
: (S) 610159  
**Telephone** : HP +65 98281078  
**Type of Claim** : Own damage Claims  
**Policy No.** : 2100505869  
**Vehicle No** : **SLM 5745 R**  
**Model Code** : Audi A3 Sedan 1.0 TFSI (A)  
**Model / Year** : 31/3/2017  
**Engine No** : CHZ 142518  
**Chassis No** : WAUZZZ8VXH1017120  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 16-Jan-19

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLM 5745 R.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ <del>2,100.00</del>	750
3	To respray front bumper and lhs front fender.	\$ <del>1,500.00</del>	1100
4	To carry out diagnostic check.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ <u>4,152.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLM 5745 R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>rehand</i>	\$1,830.00 ✓	1464.00
2	FRONT BUMPER FIXING PARTS <i>xl on</i>	\$170.00 ✗	
3	FRONT BUMPER GUIDE SECTION - LH <i>xl on</i>	\$35.00 ✗	
4	FRONT BUMPER GRILLE - CENTER <i>xl on</i>	\$146.00 ✗	
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>xl on</i>	\$488.00 +	
6	FRONT BUMPER CLOSING ELEMENT <i>xl on</i>	\$270.00 +	
7	FRONT BUMPER COVER TRIM - LH <i>xl on</i>	\$148.00 ✗	
8	ADAPTER WHEEL HOUSING LINER - LH <i>xl on</i>	\$34.00 +	
9	RADIATOR GRILLE <i>xl on</i>	\$1,301.00 +	
10	CLOSING ELEMENT <i>xl on</i>	\$174.00 ✗	
11	AIR GUIDE GRILLE - LH <i>Do cut</i>	\$171.00 ✓	136.40
12	FRONT REINFORCEMENT <i>xl on</i>	\$660.00 +	
13	FOAM FILLER PIECE <i>xl on</i>	\$172.00 +	
14	FOAM FILLER PIECE COVER <i>xl on</i>	\$111.00 ✗	
15	COVER <i>xl on</i>	\$111.00 +	
16	CAUTION' SIGN STICKER <i>xl on</i>	\$13.00 ✗	
17	FRONT FENDER - LH <i>Repair</i>	\$778.00 ✗	
18	ATTACHMENT PARTS FOR FENDER	\$65.00 +	
19	BRACKET FOR FENDER - LH	\$35.00 ✗	
20	FENDER BRACE	\$88.00 ✗	
<b>SUB TOTAL SPARE PARTS CHARGES</b>		<b>\$ 6,800.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLM 5745 R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	WHEEL HOUSING LINER - LH <i>Not on</i>	\$158.00	X
22	ATTACHMENT PARTS FOR WHEEL HOUSING LINER <i>Not on</i>	\$81.00	X
23	LED HEADLIGHT - LH <i>cut</i>	\$5,029.00	✓ 4023.20
24	HEADLIGHT LIFT CYLINDER <i>not on</i>	\$128.00	X
25	FRONT NUMBER PLATE <i>not on</i>	\$25.00	X
26	SUNDRIES <i>Not Nec.</i>	\$500.00	? X
<b>TOTAL SPARE PARTS CHARGES</b>		<b>\$ 12,721.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 4,152.00</b>	
<b>GRAND TOTAL</b>		<b>\$ 16,873.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :

Adrian Ling

Surveyed Date :

23/01/19.

Authorised Date :

Excess Cost :

Liability :

Remarks :

~~Authorised Repairs~~  
Not Authorised, 04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/0094/2019/PH  
Date : 22-Jan-19

Vehicle not in workshop. Kindly arrange for survey.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Hi Adrian

4 days - ok - jb - 21 May 19

Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Ang Li Hsien , Samuel  
Address : Blk 159 Yung Ping Road  
#03-03  
(S) 610159  
Telephone : HP +65 98281078  
Type of Claim : Own damage Claims  
Policy No. : 2100505869  
Vehicle No : **SLM 5745 R**  
Model Code : Audi A3 Sedan 1.0 TFSI (A)  
Model / Year : 31/3/2017  
Engine No : CHZ 142518  
Chassis No : WAUZZZ8VXH1017120  
Mileage :  
Date In :  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 16-Jan-19

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLM 5745 R .

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	\$ 360.00
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00	\$ 750.00
3	To respray front bumper and lhs front fender.	\$ 1,500.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
	<b>TOTAL LABOUR CHARGES</b>	<b>: \$ 4,152.00</b>	<b>\$ 2,402.00</b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLM 5745 R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$1,830.00	\$ 1,464.00
2	FRONT BUMPER FIXING PARTS	\$170.00	
3	FRONT BUMPER GUIDE SECTION - LH	\$35.00	
4	FRONT BUMPER GRILLE - CENTER	\$146.00	
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$488.00	
6	FRONT BUMPER CLOSING ELEMENT	\$270.00	
7	FRONT BUMPER COVER TRIM - LH	\$148.00	
8	ADAPTER WHEEL HOUSING LINER - LH	\$34.00	
9	RADIATOR GRILLE	\$1,301.00	
10	CLOSING ELEMENT	\$174.00	
11	AIR GUIDE GRILLE - LH	\$171.00	\$ 136.40
12	FRONT REINFORCEMENT	\$660.00	
13	FOAM FILLER PIECE	\$172.00	
14	FOAM FILLER PIECE COVER	\$111.00	
15	COVER	\$111.00	
16	CAUTION' SIGN STICKER	\$13.00	
17	FRONT FENDER - LH	\$778.00	
18	ATTACHMENT PARTS FOR FENDER	\$65.00	
19	BRACKET FOR FENDER - LH	\$35.00	
20	FENDER BRACE	\$88.00	
<b>SUB TOTAL SPARE PARTS CHARGES</b>		<b>\$ 6,800.00</b>	<b>\$ 1,600.40</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLM 5745 R.

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
		<i>c/f</i>		\$ 1,600.40
21	WHEEL HOUSING LINER - LH		\$158.00	
22	ATTACHMENT PARTS FOR WHEEL HOUSING LINER		\$81.00	
23	LED HEADLIGHT - LH		\$5,029.00	\$ 4,023.20
24	HEADLIGHT LIFT CYLINDER		\$128.00	
25	FRONT NUMBER PLATE	S/N	\$25.00	
26	SUNDRIES		\$500.00	
	<b>TOTAL SPARE PARTS CHARGES</b>	:	<b>\$ 12,721.00</b>	<b>\$ 5,623.60</b>
	<b>TOTAL LABOUR CHARGES</b>		<b>\$ 4,152.00</b>	<b>\$ 2,402.00</b>
	<b>GRAND TOTAL</b>		<b>\$ 16,873.00</b>	<b>\$ 8,025.60</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
**Attn: Motor Claims Dept**  
**Yr Ref: SLM 5745 R**

Norah Khai  
6768 9911  
6841 1183  
Nora.khai@premiumauto.com.sg  
Body & Paint Dept  
PA/OD/0094/2019/KS

18 June 2019

from  
Telephone +65-  
Telefax +65-  
EMail  
Our department  
Our Ref  
Your Ref  
Date

Dear Sir,

1

total pages

**RE: INSURANCE CLAIM FOR SLM 5745 R, Audi A3 SEDAN 1.0 TFSI**

With reference to the above-mentioned vehicle, no. **SLM 5745 R**, claimant, **Mr. Ang Li-Hsien, Samuel**, please find the related document per attached.

1. A copy of the Original invoice no. 85013933 – S\$7,945.39.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai  
Claims Dept

Encls

AIG – SLM 5745 R

Premium Automobiles Pte Ltd  
Showroom  
9 Leng Kee Road  
Singapore 159090  
Telephone (65) 6566 1111  
Telefax (65) 6471 3733

Service & Parts Centres  
55 Ubi Rd 1  
Singapore 408699  
Telephone (65) 6336 2323  
Telefax (65) 684 11183

# Premium Automobiles Pte Ltd



**Audi Centre Singapore**  
281 Alexandra Road  
Singapore 159936  
Main Telephone 6836 2223  
Main Telefax 6471 3733

**Alexandra Service Centre**  
281 Alexandra Road  
Singapore 159936  
Main Telephone 6388 2223  
Main Telefax 6475 1023

**Ubi Service Centre**  
55 Ubi Road 1  
Singapore 408699  
Main Telephone 6388 2223  
Main Telefax 6841 1163

**Customer Service**  
Service Appointment 6366 2323  
24-hour Breakdown Service 9828 1233  
Email customer.care@premiumauto.com.sg

## INS TAX INVOICE

Page 1 17:32

Company Reg. No. 199902271W  
GST Reg. No. 199902271W

Customer

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013933 Date : 17/06/2019 Order : SLM5745R Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SLM5745R (V 31753)	Regn Date: 31/03/2017	Mileage: 56711	WIP No.: 40150
Model: A3 SEDAN 1.0 TFSI 8VMANG	Chassis: WAUZZZ8VXH1017120	Engine: CHZ 142518	Dept: U
You have been assisted by :- UB-Tony Foong ( 33 )			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLI REPAIR LHS FRONT FENDER. RE-ORGANISE CRASH MANAGEM COMPONENTS. REINSTALL ALL PARTS REMOVED.	750.00	1.00	750.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK.	192.00	1.00	192.00
X	A8V0941773D	(A)(G)HEADLIGHT 24/0	1.00	5029.00	4,023.20
X	A8V5807065R GRU	COVER	1.00	1830.00	1,464.00
X	A8V5807681AA9B9	GRILL	1.00	170.50	136.40

Parts 5,623.60  
Labour 0.00  
Sublet 2,402.00  
Menus 0.00  
Lubricant 0.00

Sub-Total 7,425.60

7% GST 519.79

Grand Total 7,945.39



Received by

For & on behalf of  
Premium Automobiles Pte Ltd

# Premium Automobiles

## Telefax

to AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Motor Claims Dept  
Yr Ref: SLM 5745 R

Norah Khai  
6768 9828  
6841 1183

Body Repair

PA/OD/0094/2019/SM  
15<sup>TH</sup> January 2019

from  
Telephone +65-  
Telefax +65-  
Mobile +65-  
Our department  
Your Claim Ref  
Our Ref  
Date

1

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

**Make & Model** : Audi A3 1.0 TFSI S TRONIC  
**Vehicle Chassis No.** : WAUZZZ8VXH1017120  
**Vehicle Regn No.** : SLM 5745 R  
**Vehicle Mileage** : 48722 KM  
**Vehicle Owner** : Mr. Ang Li-Hsien , Samuel  
**Certificate No** : 2100505869  
**Own Damage Excess** : S\$ 642.00 (Inclusive 7% GST)  
**Accident Date** : 16/01/2019  
**Place** : Alexandra Road Post Office Car Park  
**Repair Cost** : \$7,945.39.  
**WIP No.** : 40150  
**Repairer's Name** : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd  
Showroom  
9 Leng Kee Road  
Singapore 159090  
Telephone (65) 6566 1111  
Telefax (65) 6471 3733

Service & Parts Centres  
55 Ubi Road 1  
Singapore 408699  
Telephone (65) 6366 2323  
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

**Owner / Insured Signature** :



**Time** :

**Date** :

15/2/19

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jan 2019		23 Jan 2019 16:52 <a href="#">Edit Adj Rpt</a>	<b>S\$8,025.60</b> <a href="#">Edit Estimates</a>	<b>S\$8,025.60</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

  

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

  

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	ANG LI-HSIEN, SAMUEL, ID: S7829785I, Tel: +6598281078		
Vehicle Reg. No.:	SLM5745R	Date of Loss:	16/01/2019 16:00 - :59 [21 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 7723195490SG	Policy/Cover Note No.:	2100505869 (Comprehensive) Coverage: 31/03/2018 - 30/03/2019
		Excess:	S\$600.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 01/02/2019]		
Driver/Custodian:	ANG TONG CHENG (70 / Male), NRIC: S03047977, Tel: +6598193118 Email: NOEMAIL		

  

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>• AIG_SG (24/01/2019): Alert - Adj Mandate Approved (S\$9432.00) - SLM5745R - Claim Handler: Dally Amri,...</li> <li>• AIG_SG (24/01/2019): SLM5745R / OD / 16/01/2019 / Coverage &amp; Excess update</li> </ul>		

  

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Claim Documents

\*SLM5745R (7723195490SG)  
OD  
Jan 16 2019 4:00PM  
[ANG LI-HSIEN, SAMUEL]  
Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View Use Viewer		
<b>Assessment Reports</b>										1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	24/01/19 08:58	<b>Adjuster Immediate Advice</b>							Load HTM			
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	24/01/19 08:40	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
2	24/01/19 08:40	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
3	24/01/19 08:40	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
4	24/01/19 08:40	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
5	24/01/19 08:40	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
6	24/01/19 08:40	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
7	24/01/19 08:40	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
8	24/01/19 08:41	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
9	24/01/19 08:41	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
10	24/01/19 08:41	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
11	24/01/19 08:41	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
12	24/01/19 08:41	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
13	24/01/19 08:41	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
14	24/01/19 08:41	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
15	24/01/19 08:41	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>		
<b>Documentation</b>										1 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	24/01/19 08:48	<b>Singapore Accident Statement</b>							Load PDF			
2	24/01/19 08:48	<b>Driver's Driving License</b>							Load PDF			
3	24/01/19 08:48	<b>MARK ESTIMATE</b>							Load PDF			
4	24/01/19 15:54	<b>Certificate of Insurance</b>							Load PDF			
5	06/06/19 16:15	<b>ESTIMATE MARKED.pdf</b>							Load PDF			
6	24/06/19 08:39	<b>WORKSHOP INVOICE</b>							Load PDF			
7	24/06/19 08:39	<b>DISCHARGE VOUCHER</b>							Load PDF			

## Linked Accident Report Documents

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View Use Viewer		
<b>Assessment Reports</b>										1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)						Thumbnail	Print			
1	17/01/19 19:10	<b>Accident Statement</b>							Load HTM			
2	19/01/19 08:42	<b>Addendum Sheet</b>							Load JPG	<input checked="" type="checkbox"/>		
3	19/01/19 09:16	<b>Accident Statement Addm. #1</b>							Load HTM			
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)						Thumbnail	Print			
1	17/01/19 19:08	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
2	17/01/19 19:08	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
3	17/01/19 19:08	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
4	17/01/19 19:08	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
5	17/01/19 19:08	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
6	17/01/19 19:08	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
7	17/01/19 19:08	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		

					<input checked="" type="checkbox"/>
8	17/01/19 19:08	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	17/01/19 19:08	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	19/01/19 08:43	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	19/01/19 09:11	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	19/01/19 09:11	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid gray; height: 40px;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120

**Our File No:** CC3/AIG19001542/ASD3N2

**Date:** 24/06/2019

#### REFERENCE

**Insured/Claimant:** ANG LI-HSIEN, SAMUEL      **Policy No:** 2100505869  
**Date of Loss:** 16/01/2019      **Nature of Claim:** OD      **Claim No:** 7723195490SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	SLM5745R	<b>Engine No:</b>	CHZ142518
<b>Make &amp; Model:</b>	AUDI A3, 999cc SEDAN TFSI (A)	<b>Chassis No:</b>	WAUZZZ8VXH1017120
<b>Reg. Date:</b>	31/03/2017 (Man. Year: 2016)	<b>Odometer:</b>	46993 km
<b>Colour:</b>	Black		
<b>Engine Capacity:</b>	999 cc		
<b>Market Value/New Car Price:</b>	S\$90,000.00		
<b>Sum Insured (S\$):</b>	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:**      **Steering (Serviceable):**      Yes      **Footbrake (Serviceable):**      Yes  
**Handbrake (Serviceable):**      Yes      **Engine Modification:**      No      **Pre-accident Condition:**

#### CONDITION OF TYRES

<b>Front Tyre Size:</b>	205/55R16	<b>Rear Tyre Size:</b>	205/55R16
<b>Front Left Side:</b>	Pirelli 6 mm	<b>Rear Left Side:</b>	Pirelli 6 mm
<b>Front Right Side:</b>	Pirelli 6 mm	<b>Rear Right Side:</b>	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,721.00	5,623.60	7,097.40	55.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,152.00	2,402.00	1,750.00	42.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,873.00</b>	<b>8,025.60</b>	<b>8,847.40</b>	<b>52.44</b>
<b>- Excess (S\$)</b>	<b>600.00</b>	<b>600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>16,273.00</b>	<b>7,425.60</b>	<b>8,847.40</b>	<b>54.37</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,139.11</b>	<b>519.79</b>	<b>619.32</b>	<b>54.37</b>
<b>Nett Amount (S\$)</b>	<b>17,412.11</b>	<b>7,945.39</b>	<b>9,466.72</b>	<b>54.37</b>

#### INSPECTION

**Date of Assignment:** 23/01/2019  
**Date Inspected:** 23/01/2019      **Inspected At:** Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

**Estimated Period of Repair:** 4.0 days

**Adjuster:** ADRIAN LING

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,830.00 FS	*1,464.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION-LH	Not Necessary	35.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Not Necessary	146.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	488.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	270.00 FS	*- FS
7	1		*FRONT BUMPER LOWER TRIM-LH	Not Necessary	148.00 FS	*- FS
8	1		*ADAPTER WHEEL HOUSING LINER-LH	Not Necessary	34.00 FS	*- FS
9	1		*RADIATOR GRILLE	Not Necessary	1,301.00 FS	*- FS
10	1		*CLOSING ELEMENT	Not Necessary	174.00 FS	*- FS
11	1		*AIR GUIDE GRILLE-LH	Cut	171.00 FS	*136.40 FS
12	1		*FRONT REINFORCEMENT	Not Necessary	660.00 FS	*- FS
13	1		*FOAM FILLER PIECE	Not Necessary	172.00 FS	*- FS
14	1		*FOAM FILLER PIECE COVER	Not Necessary	111.00 FS	*- FS
15	1		*COVER	Not Necessary	111.00 FS	*- FS
16	1		*CAUTION SIGN STICKER	Not Necessary	13.00 FS	*- FS
17	1		*FRONT FENDER-LH	Repair	778.00 FS	*- FS
18	1		*ATTACHMENT PARTS FOR FENDER	Not Necessary	65.00 FS	*- FS
19	1		*BRACKET FOR FENDER-LH	Not Necessary	35.00 FS	*- FS
20	1		*FENDER BRACE	Not Necessary	88.00 FS	*- FS
21	1		*WHEEL HOUSING LINER-LH	Not Necessary	158.00 FS	*- FS
22	1		*ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Not Necessary	81.00 FS	*- FS
23	1		*LED HEADLIGHT-LH	Cut	5,029.00 FS	*4,023.20 FS
24	1		*HEADLIGHT LIFT CYLINDER	Not Necessary	128.00 FS	*- FS
25	1		*FRONT NUMBER PLATE	Not Necessary	25.00 FS	*- FS
26	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>12,721.00</b>	<b>5,623.60</b>
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	750.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	1,500.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,152.00</b>	<b>2,402.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >