



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD	Ref : CC6/CTI19001547/Aea3s2
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909	Date : 20-04-2020
	Code : CTI



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GW 889Z	Veh. Inspected	SFR 1133C
Policy No.	DMCVSN3075891502	Coverage (\$)	0.00
Claim No.	SNM19D200465	Excess (\$)	0.00
Assign From		Assign Date	21/01/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 318I	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBA8E32030A020396	Colour	BLACK
Odometer	13243	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/40 R18	BRIDGESTONE	6 mm
L/H Front Tyre	255/40 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	255/40 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	255/40 R18	BRIDGESTONE	6 mm

4. Description of Damages

	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--	--

5. General Information

Accident Date	18/01/2019	Inspection Date	21/01/2019
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--

5b. Estimate Days of Repair

	ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
--	-------------------------------------	-----------------------