



ESTIMATE TO REPAIR

VEHICLE NO. : GBH 3588 Y
 MAKE : KIA
 MODEL : K2500 6MT
 YEAR : 2017
 CHASSIS NO : KNCSJX76LH7179965

SURVEYOR NAME	:
DATE OF SURVEY	: 19.02.2019
TIME OF SURVEY	:

DATE : 23-Jan-19
 DATE OF ACCIDENT : 18-Jan-19
 THIRD PARTY REF : SJX 9202 E / LONPAC

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	N/S Tail Lamp			<i>Wjcm</i> \$	304.00
1 pc	N/S Tail Lamp Bracket			<i>Buclad</i> \$	145.00
1 pc	Front Bumper			\$	339.00
1 pc	Front Panel			\$	326.00
1 pc	Front Panel Emblem			\$	86.00
1 pc	Front Grille			\$	250.00
				\$	1,450.00
	Less 10%			\$	145.00
				\$	1,305.00
1 pc	Rear Bumper	S.Nett		\$	450.00
1 pc	Tailgate KIA MOTOR Sticker	S.Nett		\$	120.00
1 pc	70km/h Sticker	S.Nett		\$	15.00
1 pc	13 PAX Sticker	S.Nett		\$	15.00
1 set	Number Plate	S.Nett		\$	85.00
				\$	400.00
	To putty and spray painting			\$	500.00
	Labour Chrages			\$	450.00
	<i>Not withain Resurvey After Paint 11 Day 8? 4 days</i>				
TG/RA-	Total				\$ 2,935.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0