

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

23 JAN 2019

Estimate No. : <b>b1 49859</b>	Page No. : 1 of 5
Date Estimated : <b>22/01/2019</b>	
Prepared By : <b>Kevin Leong Wai Kit</b>	

<b>- ESTIMATE REPAIR FOR -</b> Tan Sing Wei, Sean 25 Akyab Road #16-05  singapore 309979	<b>- ACCOUNT - 121</b> AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJY1314M	D829085	04/03/2016	520ia	0

DESCRIPTION	VALUE
To replace rear bumper, boot and all attachments cause by accident. To repair on rear end panel	<del>2,580.00</del> 2125
Painting on rear bumper, boot & end panel	<del>2,666.00</del> 2399
To check electrical wiring systems and lightings at the rear section for proper function.	<del>177.00</del> 1500
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	<del>531.00</del> 451
To carry out body cavity preservation. (Per panel) Boot	<del>118.00</del> 100
Sundries.	<del>150.00</del> ?
<b>Total Labour 1:</b>	<b>6,192.00</b>

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID <del>31</del>	1	1,642.45	1,642.45
SET MOUNTS PDC SENSOR REAR ?	1	58.60	58.60
RR BUMPER BOTTOM CENTRE GUIDE ?	1	60.45	60.45
RR BUMPER CARRIER ?	1	772.05	772.05
ADAPTOR ?	1	72.30	72.30
REAR BUMPER CENTRE GUIDE ?	1	61.55	61.55
RR LH MOUNT ?	1	192.15	192.15
RR RH MOUNT ?	1	198.30	198.30
REAR BUMPER PRIMED (PDC) <del>DE</del>	1	1,563.25	1,563.25
REAR BUMPER TOWING EYE COVER PRIMED ?	1	47.60	47.60
EMBLEM GROMMET <del>rec</del>	2	0.80	1.60
BMW EMBLEM <del>rec</del>	1	71.25	71.25
MODEL LETTERING 520i <del>rec</del>	1	64.10	64.10
REAR RIGHT COVERING ?	1	84.20	84.20
BOOTLID SEALING <del>cut</del>	1	115.25	115.25
REAR LH REFLECTOR ?	1	36.80	36.80

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : **b1 49859**  
Date Estimated : **22/01/2019**  
Prepared By : **Kevin Leong Wai Kit**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SJY1314M</b>	<b>D829085</b>	<b>04/03/2016</b>	<b>520iA</b>	<b>0</b>

DESCRIPTION	QTY	PRIC	VALUE
REAR RH REFLECTOR ?	1	36.80	36.80
DECOUPLING RING PDC TORQUE CONVERTE ?	4	5.05	20.20
BUMPER PDC SENSOR (300 ALPINWEISS) ?	2	368.80	737.60
Total Parts :			<b>5,836.50</b>

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date & Time 11/02/19 @ 1400hrs Excess S\$ \_\_\_\_\_

Surveyor's Name Pisul Sign \_\_\_\_\_

Surveyor's Tel 90010068 Authorised Yes / No \_\_\_\_\_

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No \_\_\_\_\_ PML Yes / No \_\_\_\_\_

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommend 5 days

Labour 1	:	6,192.00
Parts	:	5,836.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	842.00
<b>Grand Total</b>	:	<b>12,870.50</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*