

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5177A**AAD1901-209***Not Authored**Recovery B4pam**82469.27*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5177A

JTDKB3FU703078482

TOYOTA

PRIUS

22.1.2019

III

19/12/2018

PART**LIST**

1	1 FRONT DOOR LH	\$	<i>B</i> 1,227.00	<i>✓</i>
2	1 FRONT DOOR OUTER MOULDING LH	\$	<i>h</i> 188.60	<i>X</i>
3	1 FRONT DOOR GLASS LH	\$	<i>h</i> 780.50	<i>X</i>
4	1 PANEL, FRONT DOOR, OUTER LH	\$	<i>h</i> 361.00	<i>X</i>
5	1 PANEL, FRONT DOOR, OUTER RH	\$	<i>h</i> 289.80	<i>X</i>
6	1 HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	<i>h</i> 383.40	<i>X</i>
7	1 MOULDING ASSY, BODY ROCKER PANEL, LH	\$	<i>Ad / h</i> 583.30	<i>✓</i>

\$ 3,813.60**25% \$ 953.40**

\$ 2,860.20

Specical Nett

1	1 FRONT DOOR STICKER 'TRANS-CAB'	\$	<i>h</i> 80.00	<i>6052</i>
---	----------------------------------	----	----------------	-------------

TOTAL \$ 80.00

TOTAL PARTS \$ 2,940.20

LABOURPutty And Spray Painting Of The Affected Portion. \$ 3,000.00 *4401*Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same \$ 3,000.00 *2501*To Rust-Proofing Of The Affected Areas. \$ 170.00 *301*

Trans-cab Auto Services Pte Ltd**AAD1901-209**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5177A

To transfer of Door fittings, attachments and perform
water seepage test. \$ 170.00 *601*

To check steering geometry and computer wheel
alignment \$ *~ ~* 220.00 *X*

TOTAL \$ 6,560.00

Over All Total \$ 12,360.40

(PART-BY-PART) Repair Days**~~10~~ DAYS***2 1/2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: