



LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645
 No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
 Tel: 6453 4177 Fax: 6459 3724
 Email: limyewboo@singnet.com.sg
 Company Reg. No. : 200514/00L

QBE INSURANCE (INTERNATIONAL) LTD
 1 RAFFLES QUAY #29-10
 SOUTH TOWER SINGAPORE 048583

Attention : Motor Claim Department
 Contact : 62246633 Fax No. : 65333270

Estimate : TP19/001

Date : 18/01/2019
 Vehicle Num. : SGH 8016C
 Make/Model : TOYOTA VIOS E-2006
 Chassis/Eng#: MR053HY4204193509/1NZX44602
 Accident Date : 18/01/2019
 Claim No. : V0014300
 Reference : LYB/SGH8016C/QBE/tp/sl
 Policy No. :

*Not Authorized
 1/1/2019
 Resurvey After Paint*

7 days

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR LID	536.00	
2.	1	REAR LID RUBBER	159.10	
3.	2	REAR LID HINGES	52.10	
4.	1	REAR LID CABLE	104.20	
5.	1	REAR LID OUTER HANDLE	181.80	
6.	1	REAR LID LOCK (LOWER)	172.80	
7.	1	REAR LID LOCK (UPPER)	68.20	
8.	1	REAR EMBLEM 'TOYOTA' IN LOGO FONT	58.20	
9.	1	REAR EMBLEM 'VIOS'	67.80	
10.	1	REAR EMBLEM '1.5E'	35.46	
11.	1	REAR EMBLEM 'VVTI'	31.80	
12.	1	REAR NO PLATE (SMOOTH)	39.70	
13.	2	REAR NO PLATE LAMP	25.00	
14.	1	REAR TAILEND PANEL	101.80	
15.	1	REAR TAILEND PANEL INNER GARNISH	203.60	
16.	1 SET	REAR TAILEND PANEL INNER GARNISH CLIP	605.00	
17.	1	REAR SPARE TYRE FLOOR PANEL	210.00	
18.	1	REAR SPARE TYRE TRIM BOARD	12.00	
19.	1	REAR SPARE TYRE PANEL SEALANT	549.00	
20.	1	REAR BUMPER	219.00	
21.	2	REAR BUMPER RETAINER	54.20	
22.	2	REAR FENDER INNER TRIM	470.10	
23.	1	REAR FENDER INNER SHIELD/LH	98.00	
24.	1	REAR FENDER INNER SHIELD/RH	219.80	

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

All cheques should be crossed and made payable to
 Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.



LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645
 No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
 Tel: 6453 4177 Fax: 6459 3724
 Email: limyewboo@singnet.com.sg
 Company Reg. No. : 200514/00L

QBE INSURANCE (INTERNATIONAL) LTD
 1 RAFFLES QUAY #29-10
 SOUTH TOWER SINGAPORE 048583

Attention : Motor Claim Department
 Contact : 62246633 Fax No. : 65333270

Estimate : TP19/001

Date : 18/01/2019
 Vehicle Num. : SGH 8016C
 Make/Model : TOYOTA VIOS E-2006
 Chassis/Eng# : MR053HY4204193509/1NZX44602
 Accident Date : 18/01/2019
 Claim No. : V0014300
 Reference : LYB/SGH8016C/QBE/tp/si
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
25.		REAR SILENCER <i>2 x</i>		
		List Total S\$:		4,701.36
		25.00% Discount S\$:		1,175.34
				3,526.02
1.	2	SPECIAL NETT ITEMS :		
2.	1 set	REAR TAILEND PANEL TEROSTAT SEALANT	<i>na</i> 54.20	108.40
3.	1 set	REAR FENDER INNER SHIELD CLIPS	<i>nn</i>	12.00
		REAR REVERSE SENSOR	<i>short 200sm</i>	250.00
		Special Nett Total S\$:		370.40
		LABOUR :		
		TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS		120.00 <i>60l</i>
		TO CHECK REAR WIRING FUNCTION		35.00 <i>20l</i>
		LABOUR TO REPLACE THE SENSOR & CHECK SENSOR FUNCTIONS		80.00 <i>50l</i>
		TO RENEW & REPLACE REAR EXHAUST SILENCER		150.00 <i>nn</i>
		TO TRANSFER BOOT LID PARTS & FITTING TO NEW BOOT LID		120.00 <i>50l</i>
		TO CHECK WATER SEEPAGE		80.00 <i>2</i>

CONTINUE / ...

All cheques should be crossed and made payable to
 Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.



LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645
 No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
 Tel: 6453 4177 Fax: 6459 3724
 Email: limyewboo@singnet.com.sg
 Company Reg. No. : 200514/00L

QBE INSURANCE (INTERNATIONAL) LTD
 1 RAFFLES QUAY #29-10
 SOUTH TOWER SINGAPORE 048583

Attention : Motor Claim Department
 Contact : 62246633 Fax No. : 65333270


Estimate : TP19/001

Date : 18/01/2019
 Vehicle Num. : SGH 8016C
 Make/Model : TOYOTA VIOS E-2006
 Chassis/Eng# : MR053HY4204193509/1NZX44602
 Accident Date : 18/01/2019
 Claim No. : V0014300
 Reference : LYB/SGH8016C/QBE/tp/si
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		MOUNT VEHICLE ON JIG BENCH TO FACILIATE REPAIR JOB		350.00
		TO CUT, WELD ON REPLACED PANEL, TO STRAIGHTEN PANEL BEAT ON AFFECTED LEFT & RIGHT REAR FENDER, DOOR, LABOUR TO REPLACE THE ABOVE PARTS		2,000.00
		TO PUTTY, PRIMER & SPRAY PAINT ON REAR BOOT LID, TAIL END PANEL, BUMPER, SENSOR, SPARE TYRE FLOOR PANEL, AFFECTED REAR LEFT & RIGHT REAR FENDER USING 2K PAINT		1,800.00
		Labour Total S\$:		4,735.00

E. & O. E.

Total S\$: 8,631.42


 for LIM YEW BOO SPRAY PAINT CO.

All cheques should be crossed and made payable to
 Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.