

## Veron Chen (LKKAUTO)

---

**From:** glory.tan@premiumauto.com.sg  
**Sent:** Tuesday, 29 January 2019 6:10 PM  
**To:** SUR  
**Cc:** 'Claims'; Adrian Ling (LKKAUTO)  
**Subject:** Check item photos and before paint photos for SGG 8118 Y  
**Attachments:** WhatsApp Image 2019-01-29 at 4.44.13 PM.jpeg; WhatsApp Image 2019-01-29 at 4.44.14 PM (1).jpeg; WhatsApp Image 2019-01-29 at 4.44.14 PM.jpeg; WhatsApp Image 2019-01-29 at 4.44.15 PM (1).jpeg; WhatsApp Image 2019-01-29 at 4.44.15 PM.jpeg; WhatsApp Image 2019-01-29 at 4.44.16 PM (1).jpeg; WhatsApp Image 2019-01-29 at 4.44.16 PM.jpeg; WhatsApp Image 2019-01-29 at 4.48.37 PM.jpeg; WhatsApp Image 2019-01-29 at 4.55.34 PM.jpeg; WhatsApp Image 2019-01-29 at 4.55.35 PM.jpeg; WhatsApp Image 2019-01-29 at 4.55.36 PM.jpeg

Dear all,

Please refer to the attached for SGG 8118 Y check item photos and before paint photos.

Item number in marked estimate,  
3. Front bumper side reinforcement.  
16. Front bumper cover.  
24. Front main beam headlight mounting - LH

Thank you.

Glory Tan  
Bodyworks Department

**Premium Automobiles Pte Ltd** (Reg No 199902271W)  
55 Ubi Road 1 Road Singapore 408699  
**p.** +65 6388 2323 **f.** +65 6841 1183  
**e.** [glory.tan@premiumauto.com.sg](mailto:glory.tan@premiumauto.com.sg) **w.** [www.audi.com.sg](http://www.audi.com.sg)  
**Audi Showroom, Audi Centre** 281 Alexandra Road Singapore 159938 **p.** +65 6836 2223