

ASS. REC. BY:

REF: 08/MSG19001623/Btd321

Special Instruction:

Surveyor  
Meunier

Mr. Jim

ASSIGNMENT (Office)

From (Person):

Jasmine Juk

of

M81G

Date/Time:

24/1/19 @ 3:11pm

Estimated Cost:

Bill to:

OD  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDW 221K

Insured:

XE 204T

at Workshop m/s

Torque 5

Tel:

6452 4457

of

8 Kaki Bukit Ave 4 #01-49 Premier

Policy No:

P28647186MCC

Claim No:

583126

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/01/2019

CA / REV / REP. / REV 24 HRS <sup>up</sup>

H.O.D. Endorsement:

Date/Time:

3:23pm @ 24/1/19

Person Contacted:

Jueg

Vehicle  IN  OUT

Date/Time	Action/Instruction	Estimate
	SDW 221K - NA/AIG19001239/24	DUA: 18/01/19
	XE 204T - NA/AIG19001239/24	DUA: 18/1/2019
	Lump Sum \$6400 (Red: 17227.80; 72%)	

ASSIGNMENT

From: Date: 24/1/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SDW 221 K

at Workshop m/s TORQUE 5

of 8 KAKI BUKIT AVE 4 #01-50

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No SDW 221 K Yr Regn: 20/2/2012

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: AUDI A4 1.8TFSI C.C. 1798

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 219425 T/Radio: Insured / Std / NI / NA

Eng/No: CDH160206

C/No: WACZZZ8K5CA10782A

Gen. Cond: Good Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / Rim / STD A/Rim or

Tyre Size: F: 225/50/17 MIC

R: 225/50/17 P/R

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 18.1.19 D.O.I. 24/1/19

Survey held at TORQUE 5

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

See my remarks

RECEIVED 00 JAN 2019

*[Signature]*  
4/3

MV 61,000/=

PV 41,365/2

NY 19,635/2

Terim lin  
31/1/19

Date/Time, File Pass to?  : Preli. Report

1) 0/3 Typist  : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee

Transportation

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Photos

Others

TOTAL

Report Format :

Lum Sum / I.B.I. (\$) TP 64001-

200
10
210

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Jan 2019		24 Jan 2019 15:11 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>PIAGET CHEMICALS &amp; MANUFACTURING PTE LTD</b> , Co. Reg. No.: NA		
Main Claimant:	<b>WONG TECK FONG</b> , ID: S1524086E		
Vehicle Reg. No.:	<b>SDW221K</b>	Date of Loss:	18/01/2019 11:00 - :59 [82 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 583126</b>	Policy/Cover Note No.:	P28647186MKC (Comprehensive) Coverage: 26/12/2018 - 25/12/2019
Vehicle Reg. No. (Insured):	<b>XE204T</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Torque 5 Bodyworks Pte Ltd (Kaki Bukit)</b> 8 Kaki Bukit Ave 4,, #01-49/50/51/52/53/54 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 64524457		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jasmine Lok Kheng Kwei</b> - 6594 2550]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Imm.Advice due 25/01/2019]		
Driver/Custodian (Insured):	LOH YEE KUANG (), NRIC: F7668348N, Tel: +6583432114		
Adj Asg. Remarks:	SJE AGREED / LIABILITY UNCLEAR Please appoint MR MARCUS CHUA from LKK AUTO to conduct the survey . Kindly contact MR LUCAS CHOW @ 9131 6518 or 6452 4457 to arrange for survey .		

### ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

## Denise Tay (LKKAuto)

---

**From:** Torque 5 Assessment <assessment@torque5.com>  
**Sent:** Friday, 1 March 2019 4:31 PM  
**To:** Denise Tay (LKKAuto)  
**Cc:** 'Torque 5 Assessment'; claims@torque5.com; sam.chang@torque5.com  
**Subject:** RE: SDW 221K / TP / DOA: 18/01/2019 / MSIG

Dear Denise ,



We hereby confirm the COR \$6400 with 07 days .

Thank you .

*Warmest Regards,*  
*Lucas Chow*  
Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Mobile (65) 8131 6518

Email lucas.chow@torque5.com

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54  
Premier @ KB, Singapore 415875

[www.torque5.com](http://www.torque5.com)



> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4086E
Vehicle Details	
Vehicle No.:	SDW221K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 1.8 TFSI MU
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	CDH160206
Chassis No.:	WAUZZZ8K5CA107824
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$31,836.00
Original Registration Date:	20 Feb 2012
First Registration Date:	20 Feb 2012
Transfer Count:	0
Actual ARF Paid:	\$31,836.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Feb 2022
PARF Rebate Amount:	\$20,693.00
Intended COE Rebate Details	
COE Expiry Date:	19 Feb 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$67,101.00
COE Rebate Amount:	\$20,672.00
<b>Total Rebate Amount:</b>	<b>\$41,365.00</b>

The information contained herein is correct as at 22 Jan 2019

OK

Dep 14,430/yr

MV 61,000/2  
 PV 41,365/2  
 NV 19,635/2

*Wij*  
 25/1/19

**FREE VALUATION**  
 Let us tell you how much your car can sell for!  
**No obligations and it's FREE!**

**How much is my car worth?**



**Post an Advertisement**  
 Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

2007 Suzuki Swift 1.5A (COE Till 08/2022).



Car In Good Condition New Compressor And Coil Regular Scheduled Servicing. Direct Owner StarAd

**AutoInn**  
 An Inspiration For Car Buyers

click here to view our **PRISTINE USED CARS** at **GREAT PRICES**

Post an Ad Advertiser Login Ways of Selling

Browse by Category

Sort by Date Posted 40 results/page

3 vehicles

A4 1.8A TFSI MU

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	<b>A4 1.8A TFSI MU</b>		Any	Any	<b>2012</b>	Any	Any	Any	<b>Available</b>
	<b>Audi A4 1.8A TFSI MU</b>		<b>\$47,000</b>	\$10,410 /yr	17-Jan-2012	1,798 cc	106,000 km	Luxury	<b>Available</b>
6 Months New Renewed Rod Tax! 80% Loan Available! Selling At Export Value, Same Depreciation As A Civic Yet In Excellent Shape With Timely Maintenance With Full Service History. Major Servicing Done A...									
Bavarian Marques Pte Ltd Posted: 12-Jan-2019 Tags: 2012 Audi A4, 2012 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi									
	<b>Audi A4 1.8A TFSI MU</b>		<b>\$63,000</b>	\$14,430 /yr	29-Feb-2012	1,798 cc	109,000 km	Luxury	<b>Available</b>
Very Well Done Up And Maintained Audi A4! Rare One Of A Kind On The Road, Regularly Maintained And Serviced With Receipts To Prove. All Out On Aesthetics, Wide Body Kit, Upgraded Rims, Brembo Brake Kl...									
Bavarian Marques Pte Ltd Posted: 19-Jan-2019 Tags: 2012 Audi A4, 2012 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi									
	<b>Audi A4 1.8A TFSI MU Attraction</b>		<b>\$68,800</b>	\$14,840 /yr	19-Jun-2012	1,798 cc	105,000 km	Luxury	<b>Available</b>
Single Owner N Well Maintained, Face Lifted Model, Agent Unit, Serviced Regularly At Workshop, Original Factory Condition, Accident Free, Own Workshop/STA Evaluation Welcome, Optional Warranty Can Be ...									
Prem Roy Motoring Posted: 29-Nov-2018 Tags: 2012 Audi A4, 2012 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

40 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used A4 1.8A TFSI MU, A4 1.8A TFSI MU Singapore, used A4 1.8A TFSI MU Singapore, used A4 1.8A TFSI MU, used vehicles Singapore or even buy used A4 1.8A TFSI MU Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

**Follow sgCarMart.com**

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

Compare

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/01/2019 17:10
Date Of Accident	18/01/2019 11:05
Exact Location Of Accident	29 QUALITY RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDW221K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WONG TECK FONG
NRIC No	S1524086E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97481386
Alternative Phone No	OFFICE-97481386

### Vehicle Particulars

Manufacturer	AUDI
Model	A4 1.8 TFSI MU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100289171-06
Cover Note Number	

### Driver

Name of Driver	WONG JUNHENG BRENT
NRIC No	S9602845H
Date Of Birth	18/01/1996
Occupation	INDOOR
Date Of Driving Pass	28/06/2016
Driving Experience	2 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96917318
Fax Number	
Contact Number	OFFICE-96917318
Email Address	NOEMAIL

Address	BLK 205 PASIR RIS STREET 21 #07-386
Postcode	510205
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE204T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

#### DETAILS OF INJURED PERSON 1

Name	WONG JUNHENG BRENT
------	--------------------

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

SDW221K

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

## Accident Sketch Plan

### ACCIDENT PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud and claims; and
  - (ii) to relevant agencies which are lawfully and reasonably required for the purposes stated in (a) above.


Policyholder / Insured  
(Name):

Insurer Representative  
(Name):  
Date & Time:

Reporting Insurer Representative  
(Name):  
Date & Time:

Accident Sketch Plan

DESCRIPTION



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

In the stated date & time, I, vehicle A (SAW 201K) was stationary, preparing to turn right in to the building. (Independently) Vehicle B (XE 204T) overtook my vehicle on my right side & hit <sup>into</sup> my vehicle rear right portion.

DECLARATION

I hereby declare that the information provided in this report is true and correct to the best of my knowledge and belief.

Signature of Driver

Signature of Witness

Signature of Investigator



**ESTIMATION REPORT**

**Vehicle No** : SDW221K  
**Make & Model** : AUDI,A4 1.8 TFSI MU,WAUZZZ8K5CA107824  
**Year of Manufacture** : 2011

**Estimation No.** : E19010024  
**DOA** : 18/01/2019

No	Description	Qty	U/P	Amt
<b>Section: List Items</b>				
1	Rear bumper	1.00	1,104.00	✓ 1,104.00 CUT V
2	Rear bumper retainer (LH)	1.00	110.00	✓ 110.00 } NEC V
3	Rear bumper retainer (RH)	1.00	110.00	✓ 110.00 }
4	Rear bumper towing cap	1.00	0.00	0.00 NN X
5	Rear bumper lower garnish	1.00	176.00	176.00 NN X
6	Rear bumper undercover (RH)	1.00	0.00	0.00 NN X
7	Tail lamp (RH)	1.00	598.90	598.90 BR V
8	Tail lamp inner panel	1.00	1,650.00	1,650.00 R X
9	Bootlid	1.00	1,375.00	1,375.00 R X
10	Bootlid emblem - Logo	1.00	114.00	107.00 114.00 }
11	Bootlid emblem - A4	1.00	89.60	82.70 89.60 } NEC V
12	Bootlid emblem - 1.8T	1.00	84.30	60.00 84.30 }
13	Bootlid lock	1.00	0.00	0.00 }
14	Bootlid hinge (LH)	1.00	190.00	190.00 } NN X
15	Bootlid hinge (RH)	1.00	190.00	190.00 }
16	Rear fender (RH)	1.00	2,100.00	✓ 2,100.00 DD V
17	Rear fender inner shield (RH)	1.00	296.00	112.60 296.00 } ? IN V
18	Rear fender inner trim (RH)	1.00	965.00	965.00 } NN X
19	Rear bumper reinforcement	1.00	529.00	501.00 529.00 } ? BT V NN
20	Fuel lid	1.00	0.00	0.00 R X
21	Rear windscreen	1.00	0.00	0.00 NEC NN X
22	Rear fender QTR glass (RH)	1.00	0.00	0.00 NN X
23	Rear door (RH)	1.00	0.00	0.00 R X
24	Rear door outer handle	1.00	0.00	0.00 NN X
25	Rear wheel rim (RH)	1.00	1,680.00	250.00 SN 1,680.00 CUT V R? local Repair

Continue on next page...



# Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
 Co. & GST Reg. No.: 201313221G

## ESTIMATION REPORT

**Vehicle No** : SDW221K  
**Make & Model** : AUDI,A4 1.8 TFSI MU,WAUZZZ8K5CA107824  
**Year of Manufacture** : 2011

**Estimation No.** : E19010024  
**DOA** : 18/01/2019

No	Description	Qty	U/P	Amt
26	Rear wheel cap (RH)	1.00	0.00	0.00
27	Rear absorber (RH)	1.00	1,490.00	1,490.00
28	Rear knuckle arm (RH)	1.00	1,730.00	1,730.00
29	Rear knuckle bearing (RH)	1.00	980.00	980.00
30	Rear lower arm (RH)	1.00	1,190.00	1,190.00
31	Rear control arm (RH)	1.00	0.00	0.00
32	Rear trailing arm (RH)	1.00	580.00	580.00
33	Reverse sensor	1 pc 4.00	274.00	1,096.00
34	Reverse sensor harness wire	1.00	0.00	0.00
35	Rear door lock	1.00	0.00	0.00

**Amt** S\$ 18,427.80  
**Discount (0.00%)** S\$ 0.00  
**Subtotal** S\$ 18,427.80

### Section: Special Nett Items

36	Rear bumper clip set	1.00	50.00	50.00
37	Rear fender inner trim clip set	1.00	50.00	50.00
38	Rear fender inner shield clip set	1.00	50.00	50.00
39	Rear tyre (RH)	1.00	280.00	280.00
40	Rear windscreen tinted	1.00	200.00	200.00
41	Rear windscreen sealant	1.00	50.00	50.00
42	Rear fender QTR glass sealant	1.00	50.00	50.00
43	Rear fender QTR glass tinted	1.00	100.00	100.00

**Amt** S\$ 830.00  
**Discount (0.00%)** S\$ 0.00  
**Subtotal** S\$ 830.00

Continue on next page...

1188



**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
 Co. & GST Reg. No.: 201313221G

**ESTIMATION REPORT**

**Vehicle No** : SDW221K  
**Make & Model** : AUDI,A4 1.8 TFSI MU,WAUZZZ8K5CA107824  
**Year of Manufacture** : 2011

**Estimation No.** : E19010024  
**DOA** : 18/01/2019

No	Description	Qty	U/P	Amt
<b>Section: Labour Items</b>				
44	To R&R rear bumper reverse sensor	1.00	60.00	60.00 ✓
45	To check wiring & lighting system	1.00	80.00	<del>80.00</del> 50.00
46	To supply under-coating / putty on affected areas	1.00	80.00	<del>80.00</del> 60.00
47	To conduct all wheel alignment before and after	1.00	160.00	160.00 <del>160.00</del> 60.00
48	To R&R wheel rim, tyre and balancing	1.00	50.00	<del>50.00</del> 30.00
49	To R&R rear RH under-carriage damaged parts	1.00	400.00	<del>400.00</del> <del>200.00</del> 100.00
50	To R&R fuel tank to cut & weld	1.00	350.00	<del>350.00</del> 100.00 NN
51	To R&R rear windscreen	1.00	250.00	<del>250.00</del> 100.00
52	To R&R rear trims, garnish and seats assy	1.00	250.00	<del>250.00</del> 100.00
53	To diagnose erase fault code memories	1.00	120.00	<del>120.00</del> NN
54	To repair,replace & realign damaged areas	1.00	1,200.00	<del>1,200.00</del> <del>600.00</del> 600.00 li
55	To spray painting on affected areas	1.00	1,100.00	<del>1,100.00</del> 700.00
56	To perform water seepage test after repair	1.00	120.00	<del>120.00</del> <del>60.00</del> NN
57	To car wash & polish vehicle after repair	1.00	100.00	<del>100.00</del> NN
58	Sundries	1.00	50.00	<del>50.00</del> NN ✓

**Amt** S\$ 4,370.00  
**Discount (0.00%)** S\$ 0.00  
**Subtotal** S\$ 4,370.00

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*[Handwritten Signature]*  
 12/1/19  
 ? photo  
 TGI in line 24/1/19 1620  
 Lump sum repair  
 Repair days 7  
*[Handwritten Signature]*  
 28/2/19

**List Items Subtotal** S\$ 18,427.80  
**Special Nett Items Subtotal** S\$ 830.00  
**Labour Items Subtotal** S\$ 4,370.00  
**Total** S\$ 23,627.80

24207-80



## Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

### SUPPLEMENTARY REPORT

Vehicle No : SDW221K

Estimation No. : E19010038

Make & Model : AUDI,A4 1.8 TFSI MU,WAUZZZ8K5CA107824

DOA : 18/01/2019

Year of : 2011

Manufacture

No	Description	Qty	U/P	Amt
<b>Section: List Items</b>				
1	Fuel pump	1.00	580.00	580.00 X
				<b>Amt</b> S\$ 580.00
				<b>Discount (0.00%)</b> S\$ 0.00
				<b>Subtotal</b> S\$ 580.00

**List Items Subtotal** S\$ 580.00  
**Total** S\$ 580.00



**ESTIMATION REPORT**

**Vehicle No** : SDW221K  
**Make & Model** : AUDI,A4 1.8 TFSI MU,WAUZZZ8K5CA107824  
**Year of Manufacture** : 2011

**Estimation No.** : E19010024  
**DOA** : 18/01/2019

No	Description	Qty	U/P	Amt	
<b>Section: List Items</b>					
1	Rear bumper	1.00	1,104.00	1,104.00	CuTV
2	Rear bumper retainer (LH)	1.00	110.00	110.00	} NECV
3	Rear bumper retainer (RH)	1.00	110.00	110.00	
4	Rear bumper towing cap	1.00	0.00	0.00	NNX
5	Rear bumper lower garnish	1.00	176.00	176.00	NNX
6	Rear bumper undercover (RH)	1.00	0.00	0.00	NNX
7	Tail lamp (RH)	1.00	598.90	598.90	BRV
8	Tail lamp inner panel	1.00	1,650.00	1,650.00	RX
9	Bootlid	1.00	1,375.00	1,375.00	RX
10	Bootlid emblem - Logo	10709 1.00	114.00	114.00	} NECV
11	Bootlid emblem - A4	82.70 1.00	89.60	89.60	
12	Bootlid emblem - 1.8T	60 1.00	84.30	84.30	
13	Bootlid lock	1.00	0.00	0.00	} NNX
14	Bootlid hinge (LH)	1.00	190.00	190.00	
15	Bootlid hinge (RH)	1.00	190.00	190.00	
16	Rear fender (RH)	1.00	2,100.00	2,100.00	DDV
17	Rear fender inner shield (RH)	112.60 1.00	296.00	296.00	} X
18	Rear fender inner trim (RH)	1.00	965.00	965.00	
19	Rear bumper reinforcement	1.00	529.00	529.00	X BTV
20	Fuel lid	1.00	0.00	0.00	RX
21	Rear windscreen	1.00	0.00	0.00	NNX0.00 NECV
22	Rear fender QTR glass (RH)	1.00	0.00	0.00	NNX
23	Rear door (RH)	1.00	0.00	0.00	RX
24	Rear door outer handle	1.00	0.00	0.00	NNA
25	Rear wheel rim (RH)	1.00	1,680.00	1,680.00	CuTV LC 250

Continue on next page...



**ESTIMATION REPORT**

Vehicle No : SDW221K Estimation No. : E19010024  
 Make & Model : AUDI,A4 1.8 TFSI MU,WAUZZZ8K5CA107824 DOA : 18/01/2019  
 Year of : 2011  
 Manufacture :

No	Description	Qty	U/P	Amt	
26	Rear wheel cap (RH)	1.00	0.00	<del>0.00</del>	NNX
27	Rear absorber (RH)	1.00	1,490.00	1,490.00	BTV
28	Rear knuckle arm (RH)	1.00	1,730.00	1,730.00	DDV
29	Rear knuckle bearing (RH)	1.00	980.00	980.00	JMV
30	Rear lower arm (RH)	1.00	1,190.00	<del>1,190.00</del>	NNX
31	Rear control arm (RH)	1.00	0.00	0.00	X
32	Rear trailing arm (RH)	1.00	580.00	<del>580.00</del>	NNX
33	Reverse sensor	1pc	274.00	274.00	CUTV
34	Reverse sensor harness wire	1.00	0.00	0.00	NNX
35	Rear door lock	1.00	0.00	0.00	NNX

**Amt** S\$ 18,427.80  
**Discount (0.00%)** S\$ 0.00  
**Subtotal** S\$ 18,427.80

**Section: Special Nett Items**

36	Rear bumper clip set	1.00	50.00	50.00	NEC
37	Rear fender inner trim clip set	1.00	50.00	50.00	X
38	Rear fender inner shield clip set	1.00	50.00	50.00	X
39	Rear tyre (RH)	1.00	280.00	280.00	CUTV
40	Rear windscreen tinted	1.00	200.00	<del>200.00</del>	NNX
41	Rear windscreen sealant	1.00	50.00	50.00	NECV
42	Rear fender QTR glass sealant	1.00	50.00	50.00	
43	Rear fender QTR glass tinted	1.00	100.00	<del>100.00</del>	NNX

**Amt** S\$ 830.00  
**Discount (0.00%)** S\$ 0.00  
**Subtotal** S\$ 830.00

Continue on next page...



**ESTIMATION REPORT**

Vehicle No : SDW221K  
 Make & Model : AUDI,A4 1.8 TFSI MU,WAUZZZ8K5CA107824  
 Year of Manufacture : 2011

Estimation No. : E19010024  
 DOA : 18/01/2019

No	Description	Qty	U/P	Amt
<b>Section: Labour Items</b>				
44	To R&R rear bumper reverse sensor	1.00	60.00	60.00 ✓
45	To check wiring & lighting system	1.00	80.00	<del>80.00</del> 50.00
46	To supply under-coating / putty on affected areas	1.00	80.00	80.00 60.00
47	To conduct all wheel alignment before and after	1.00	160.00	160.00 100.00
48	To R&R wheel rim, tyre and balancing	1.00	50.00	50.00 ✓
49	To R&R rear RH under-carriage damaged parts	1.00	400.00	<del>400.00</del> 200.00
50	To R&R fuel tank to cut & weld	1.00	350.00	<del>350.00</del> 100.00
51	To R&R rear windscreen	1.00	250.00	<del>250.00</del> 100.00
52	To R&R rear trims, garnish and seats assy	1.00	250.00	250.00 120.00
53	To diagnose erase fault code memories	1.00	120.00	<del>120.00</del> NNX
54	To repair,replace & realign damaged areas	1.00	1,200.00	<del>1,200.00</del> 600.00
55	To spray painting on affected areas	1.00	1,100.00	<del>1,100.00</del> 700.00
56	To perform water seepage test after repair	1.00	120.00	<del>120.00</del> 60.00
57	To car wash & polish vehicle after repair	1.00	100.00	<del>100.00</del> NNX
58	Sundries	1.00	50.00	50.00 NECV ✓

Amt S\$ 4,370.00  
 Discount (0.00%) S\$ 0.00  
 Subtotal S\$ 4,370.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

? photo  
 TGT in air 24/1/19 16:20  
 Lump sum repair  
 Repair days 7

List Items Subtotal S\$ 18,427.80  
 Special Nett Items Subtotal S\$ 830.00  
 Labour Items Subtotal S\$ 4,370.00  
**Total** S\$ 23,627.80

**NO 8 KAKI BUKIT AVENUE 4  
PREMIER@KAKI BUKIT  
#01-07 SINGAPORE 415875  
TEL: 93261342  
FAX: 64524584**

**EMAIL: motorstopoffice@gmail.com**

**Order: R003558  
Case: SDW221K  
24.1.19 18:25**

**Audi : A4 : 2007-16 (B8 - 8K) : Standard Suspension (1BA) : Right-hand Drive  
4-Wheel Total Alignment**

**Front : Left**

**Front : Right**

Actual	Before	Specified Range
-1°14'	-1°14'	
3°57'	3°57'	
0°18'	0°18'	0°05' 0°15'
4°37'	4°37'	
3°23'	3°23'	
		-2°19' -1°19'

**Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.**

Actual	Before	Specified Range
-0°57'	-0°57'	
4°05'	4°05'	
0°19'	0°19'	0°05' 0°15'
5°29'	5°29'	
4°32'	4°32'	
		-2°19' -1°19'

**Front**

**Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.**

Actual	Before	Specified Range
-0°16'	-0°16'	-0°30' 0°30'
-0°08'	-0°08'	
-0°52'	-0°52'	
0°37'	0°37'	0°06' 0°34'

**Rear : Left**

**Rear : Right**

Actual	Before	Specified Range
-1°29'	-1°29'	-1°45' -0°55'
0°14'	0°14'	0°05' 0°15'

**Camber  
Toe**

Actual	Before	Specified Range
-1°46'	-1°46'	-1°45' -0°55'
0°17'	0°17'	0°05' 0°15'

**Rear**

**Cross Camber  
Total Toe  
Thrust Angle**

Actual	Before	Specified Range
0°17'	0°17'	-0°30' 0°30'
0°31'	0°31'	0°10' 0°30'
-0°02'	-0°01'	-0°10' 0°10'

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Jan 2019		24 Jan 2019 15:11 <a href="#">Edit Adj Rpt</a>	<b>S\$6,400.00</b> <a href="#">Edit Estimates</a>	<b>S\$6,400.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>PIAGET CHEMICALS &amp; MANUFACTURING PTE LTD</b> , Co. Reg. No.: NA								
Main Claimant:	<b>WONG TECK FONG</b> , ID: S1524086E								
Vehicle Reg. No.:	<b>SDW221K</b>	Date of Loss:	18/01/2019 11:00 - :59 [82 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 583126</b>	Policy/Cover Note No.:	P28647186MKC (Comprehensive) Coverage: 26/12/2018 - 25/12/2019						
Vehicle Reg. No. (Insured):	<b>XE204T</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Torque 5 Bodyworks Pte Ltd (Kaki Bukit)</b> 8 Kaki Bukit Ave 4,, #01-49/50/51/52/53/54 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 64524457								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jasmine Lok Kheng Kwel</b> - 6594 2550]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... [Imm.Advice due 25/01/2019]								
Driver/Custodian (Insured):	LOH YEE KUANG (), NRIC: F7668348N, Tel: +6583432114 Email:								
Adj Asg. Remarks:	SJE AGREED / LIABILITY UNCLEAR Please appoint MR MARCUS CHUA from LKK AUTO to conduct the survey . Kindly contact MR LUCAS CHOW @ 9131 6518 or 6452 4457 to arrange for survey .								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SDW221K (583126)  
[XE204T]

TP

WONG TECK FONG

Jan 18 2019 11:00AM

[PIAGET CHEMICALS & MANUFACTURING PTE LTD]

Torque 5 Bodyworks Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View <input type="button" value="View in Browser"/>		
<b>Assessment Reports</b>									1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print		
1	23/01/19 19:26	<b>Accident Statement</b> From:SC - Reg. No: XE204T, Claimant: PIAGET CHEMICALS & MANUFACTURING PTE LTD							Load HTM	<input type="checkbox"/>	
<b>Photos/Images</b>									3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
2	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
3	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
4	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
5	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
6	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
7	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
8	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
9	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
10	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
11	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
12	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
13	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
14	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
15	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
16	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
17	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
18	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
19	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
20	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
21	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
22	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
23	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
24	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
25	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
26	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
27	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
28	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
29	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
30	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
31	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
32	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
33	04/03/19 10:06	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	04/03/19 10:06	General View		<input checked="" type="checkbox"/>
35	04/03/19 10:06	General View		<input checked="" type="checkbox"/>
36	04/03/19 10:06	General View		<input checked="" type="checkbox"/>
37	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
38	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
39	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
40	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
41	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
42	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
43	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
44	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
45	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
46	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
47	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
48	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
49	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
50	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
51	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
52	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
53	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
54	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
55	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
56	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
57	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
58	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
59	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
60	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
61	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
62	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>
63	04/03/19 10:06	Reinspection Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/01/19 19:18	TP PRI		<input type="checkbox"/>
2	23/01/19 19:26	E-FILE REPORT (SDW221K) From:SC - Reg. No: XE204T, Claimant: PIAGET CHEMICALS & MANUFACTURING PTE LTD		<input type="checkbox"/>
3	24/01/19 10:11	Reply email from TP workshop & appoint MARCUS CHUA from LKK AUTO		<input type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG19001623/BTD3E2  
**Date:** 08/03/2019

#### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	P28647186MKC
<b>Claimant Vehicle No :</b> SDW221K	<b>Insured Vehicle No :</b>	XE204T
Date of Loss: 18/01/2019	Nature of Claim:	TP
		Claim No: 583126

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SDW221K</b>	Engine No:	CDH160206
Make & Model:	AUDI A4, 1.8 TFSI MU (EU6) (A)	Chassis No:	WAUZZZ8K5CA107824
Reg. Date:	20/02/2012 (Man. Year: 2011)	Odometer:	219425 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Pirelli 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,887.80	6,039.84	13,847.96	69.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,320.00	1,960.00	2,360.00	54.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>24,207.80</b>	<b>7,999.84</b>	<b>16,207.96</b>	<b>66.95</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,400.00</b>		
(S\$)	24,207.80	6,400.00	17,807.80	73.56
<b>+ GST 7.00/7.00% (S\$)</b>	1,694.55	448.00	1,246.55	73.56
<b>Nett Amount (S\$)</b>	<b>25,902.35</b>	<b>6,848.00</b>	<b>19,054.35</b>	<b>73.56</b>

#### INSPECTION

Date of Assignment:	24/01/2019	
Date Inspected:	24/01/2019 Inspected At:	Torque 5 Bodyworks Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4,, #01-49/50/51/52/53/54 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	7.0 days	

---

**Adjuster:** Lim Teow Guan

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2019)
<b>Parts:</b> 143	AUDI A4 1.8 TFSI MU (EU6) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SDW221K)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	1,104.00 F	*1,104.00 FL
2	1		*REAR BUMPER RETAINER (LH)	Necessary	110.00 F	*110.00 FL
3	1		*REAR BUMPER RETAINER (RH)	Necessary	110.00 F	*110.00 FL
4	1		*REAR BUMPER TOWING CAP (NPA)	Not Necessary	0.00 F	*-FL
5	1		*REAR BUMPER LOWER GARNISH	Not Necessary	176.00 F	*-FL
6	1		*REAR BUMPER UNDERCOVER (RH) (NPA)	Not Necessary	0.00 F	*-FL
7	1		*TAIL LAMP (RH)	Broken	598.90 F	*598.90 FL
8	1		*TAIL LAMP INNER PANEL	Repair	1,650.00 F	*-FL
9	1		*BOOTLID	Repair	1,375.00 F	*-FL
10	1		*BOOTLID EMBLEM - LOGO	Necessary	114.00 F	*107.00 FL
11	1		*BOOTLID EMBLEM - A4	Necessary	89.60 F	*82.70 FL
12	1		*BOOTLID EMBLEM - 1.8T	Necessary	84.30 F	*60.00 FL
13	1		*BOOTLID LOCK (NPA)	Not Necessary	0.00 F	*-FL
14	1		*BOOTLID HINGE (LH)	Not Necessary	190.00 F	*-FL
15	1		*BOOTLID HINGE (RH)	Not Necessary	190.00 F	*-FL
16	1		*REAR FENDER (RH)	Dented	2,100.00 F	*2,100.00 FL
17	1		*REAR FENDER INNER SHIELD (RH)	Torn	296.00 F	*112.60 FL
18	1		*REAR FENDER INNER TRIM (RH)	Not Necessary	965.00 F	*-FL
19	1		*REAR BUMPER REINFORCEMENT	Not Necessary	529.00 F	*-FL
20	1		*FUEL LID (NPA)	Repair	0.00 F	*-FL
21	1		*REAR WINDSCREEN (NPA)	Not Necessary	0.00 F	*-FL
22	1		*REAR FENDER QTR GLASS (RH) (NPA)	Not Necessary	0.00 F	*-FL
23	1		*REAR DOOR (RH) (NPA)	Repair	0.00 F	*-FL
24	1		*REAR DOOR OUTER HANDLE (NPA)	Not Necessary	0.00 F	*-FL
25	1		*REAR WHEEL RIM (RH)	Repair	1,680.00 F	*-FL
26	1		*REAR WHEEL CAP (RH) (NPA)	Not Necessary	0.00 F	*-FL
27	1		*REAR ABSORBER (RH)	Not Necessary	1,490.00 F	*-FL
28	1		*REAR KNUCKLE ARM (RH)	Distorted	1,730.00 F	*863.00 FL
29	1		*REAR KNUCKLE BEARING (RH)	Necessary	980.00 F	*300.00 FL
30	1		*REAR LOWER ARM (RH)	Bent	1,190.00 F	*325.00 FL
31	1		*REAR CONTROL ARM (RH) (NPA)	Not Necessary	0.00 F	*-FL
32	1		*REAR TRAILING ARM (RH)	Not Necessary	580.00 F	*-FL
33	1		*REVERSE SENSOR (4PCS)	Cut-1PC ONLY	1,096.00 F	*274.00 FL
34	1		*REVERSE SENSOR HARNESS WIRE (NPA)	Not Necessary	0.00 F	*-FL
35	1		*REAR DOOR LOCK (NPA)	Not Necessary	0.00 F	*-FL
36	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
38	1		*SET REAR FENDER INNER SHIELD CLIP	Necessary	50.00 FS	*50.00 FS
39	1		*REAR TYRE (RH)	Not Necessary	280.00 FS	*- FS
40	1		*REAR WINDSCREEN TINTED	Not Necessary	200.00 FS	*- FS
41	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
42	1		*REAR FENDER QTR GLASS SEALANT	Necessary	50.00 FS	*50.00 FS
43	1		*REAR FENDER QTR GLASS TINTED	Not Necessary	100.00 FS	*- FS
44	1		*SUNDRIES	Not Necessary	50.00 F	*- FL
45	1		*FUEL PUMP (DAMAGED)	Not Consistent With The Impact	580.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>19,887.80</b>	<b>6,347.20</b>
- List Item Discount on L Items 0.00/5.00% (S\$)	0.00	307.36
<b>Total Parts (S\$)</b>	<b>19,887.80</b>	<b>6,039.84</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO R&R REAR BUMPER REVERSE SENSOR	New	60.00	60.00
2	TO CHECK WIRING & LIGHTING SYSTEM	New	80.00	50.00
3	TO SUPPLY UNDER-COATING / PUTTY ON AFFECTED AREAS	New	80.00	60.00
4	TO CONDUCT ALL WHEEL ALIGNMENT BEFORE AND AFTER	New	160.00	60.00
5	TO R&R WHEEL RIM, TYRE AND BALANCING	New	50.00	30.00
6	TO R&R REAR RH UNDER-CARRIAGE DAMAGED PARTS	New	400.00	0.00
7	TO R&R FUEL TANK TO CUT & WELD	New	350.00	0.00
8	TO R&R REAR WINDSCREEN	New	250.00	100.00
9	TO R&R REAR TRIMS, GARNISH AND SEATS ASSY	New	250.00	100.00
10	TO DIAGNOSE ERASE FAULT CODE MEMORIES	New	120.00	0.00
11	TO REPAIR, REPLACE & REALIGN DAMAGED AREAS	New	1,200.00	800.00
12	TO SPRAY PAINTING ON AFFECTED AREAS	New	1,100.00	700.00
13	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	New	120.00	0.00
14	TO CAR WASH & POLISH VEHICLE AFTER REPAIR	New	100.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>4,320.00</b>	<b>1,960.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >