

REF:

ALB

CC3 / ALB 19001689 / Agd3se

ASSIGNMENT

From:

Date:

25/01/2019

Veh No:

SMH876T.

Yr Regn:

2019 Jan.

Estimated Cost:

Type: ☒ Car / ☐ Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No:

SMH 876T

Make:

Audi Q2

C.C. 1385

at Workshop m/s

Premium

Colour:

Grey.

A/C: Insured / Std / NI / NA

of

55 Ubi Rd 1

Sp Reading

974.

T/Radio: Insured / Std / NI / NA

Insured

Eng/No:

Policy No.

1900007552

C/No:

WAU222GA3JA107553.

Claims No.

736359555654

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

\$800.

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

(Client's Record)

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Make of Veh:

Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or

(Policy Condition)


11km

Tyre Size:

F: 235/40R19.

R: 235/40R19.

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

1401C.

Front

Rear

IDAC Accident Rpt:

Consistent?: Yes or No

R/Bal.

ob

mm

R/Bal.

ob

mm

GIA / PR Seen:

Consistent?: Yes or No

L/Bal.

ob

mm

L/Bal.

ob

mm

Est Repairs:

03 88 days

Res.: Yes or No

D.O.A.

D.O.I.

25/01/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

Premium.

CA / REV / REP. / 24 HRS

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD ALB.

25/1/19 @ 4:27pm report to Victor via Merimen.

28/1/2019 @ 16:45 - authorize repair by victor \$800

28/1/2019 @ 5:04pm inform claim authorize repair excess \$800.

08/4/19 @ 4:51pm 2nd report to Victor via Merimen.

08/5/19 @ 14:44pm Andy Kong informed claim at \$7398.28 via Merimen.

09/5/19 @ 12:03pm confirmed with Mr Bos final fig \$7398.28, 3 days

CRed \$8642.84, 54%

RECEIVED 6 JUN 2019

Date/Time, File Pass to?



Preli. Report

Days Of Repair:

3

11/06/16 14:44



Final Report

Resurvey No. of Trip:

1

Survey Fee:

200

Transportation

) 5 + RS 34

) Photos

) Other

) 5

TOTAL

Date/Time, File Return to?

(2)

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Invs (\$)



Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

11

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 9 May 2019 12:03 PM
To: Boo seng yak; SUR; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: RE: FINAL REVISION - SMH876T - OD AIG - SURVEYED 25 JAN 19

Dear Mr Boo,

WITHOUT PREJUDICE

Confirm final fig \$7,398.28 before excess \$800.00 & GST and 3 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Tuesday, 12 March 2019 4:49 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SMH876T - OD AIG - SURVEYED 25 JAN 19

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$7398.28 @ 3 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	22 Jan 2019 18:08	Clim Veh Model Changed		[I] Merimen Administrator
2	22 Jan 2019 18:08	Clim Created	Reg No: SMH876T, Policy No: 1900002552, Acct Date: 2019/01/22, Claim Type: S C, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA119010773	[I] Merimen Administrator
3	24 Jan 2019 14:21	Clim Registration Modified	Acct Time:08:40:00->08:00:00, Init.Est.->5,000 - 6,000.	[I] Chan, Yoke Shi
4	24 Jan 2019 14:21	Clim Veh Model Changed	(206145) AUDI Q2 1.4 (A).	[I] Chan, Yoke Shi
5	25 Jan 2019 14:54	Clim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[I] CATHERINE CHONG KAI LING
6	25 Jan 2019 14:54	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[I] CATHERINE CHONG KAI LING
7	25 Jan 2019 14:54	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
8	25 Jan 2019 14:54	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/02/07	[A] CATHERINE CHONG KAI LING
9	25 Jan 2019 14:54	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
10	25 Jan 2019 14:54	Clim Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
11	25 Jan 2019 14:54	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
12	25 Jan 2019 16:22	Adj Rpt Initiated		[A] SHIAU CHAN
13	25 Jan 2019 16:22	Clim Dtl Modified	JPJ Reg. Date: -> 2019/01/10.	[A] SHIAU CHAN
14	25 Jan 2019 16:22	Clim Details Notified		[A] SHIAU CHAN
15	25 Jan 2019 16:26	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/02/07	[A] SHIAU CHAN
16	25 Jan 2019 16:27	Adj Mandate Request	Cur.Reg:11733.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
17	25 Jan 2019 17:28	Clim Registration Modified	Excess: -> 800.00, 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Loo, Tong Shing
18	25 Jan 2019 17:28	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
19	28 Jan 2019 16:45	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/02/07, Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
20	28 Jan 2019 16:45	Adj Mandate Set	Approved:5841.00:Re-inspection to be done for damage check and supplementary items / labour, Reinsp:Yes.	[I] Koh, Victor-CK
21	15 Mar 2019 14:50	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/02/07	[A] SHIAU CHAN
22	15 Mar 2019 14:51	Adj Mandate Request	Cur.Reg:7398.28:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
23	08 Apr 2019 14:00	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/02/07. Mandate Remarks: Finalise marking?	[I] Koh, Victor-CK
24	08 Apr 2019 14:00	Adj Mandate Set	Maintained:Finalise marking?	[I] Koh, Victor-CK
25	08 Apr 2019 16:51	Adj Mandate Request	Cur.Reg:7398.28:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY, THE RELEVANT DOCUMENT UPLOADED.	[A] SHIAU CHAN
26	08 May 2019 13:44	Adj Mandate Set	Approved:7398.28.	[I] Fong, Andy-SY

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 15 Mar 2019

Preliminary Advice

Vehicle No	: SMH876T	Accident Date	: 22/01/2019
Make	: AUDI Q2	Policy No.	: 1900002552
Assignment Date	: 25/01/2019	Excess	: S\$800.00
Date of Inspection	: 25/01/2019	Est. Duration of Repair	: 3.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,041.12	(ESTIMATE \$14,500.00 + SUPPLEMENTARY \$1,541.12)
Revised Amount	:S\$	7,398.28	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	7,398.28	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	140,000.00
COE / PARF Rebate	:S\$	56,222.00
Salvage Value	:S\$	
Margin for Repair	:S\$	83,778.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 28 January 2019 5:04 PM
To: 'Claims'; SUR; Admin A
Cc: 'NORA '
Subject: RE: OD claim for SMH 876 T

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SMH 876T (Excess \$800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Wednesday, 23 January 2019 3:09 PM
To: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: Claims <claims@premiumauto.com.sg>
Subject: OD claim for SMH 876 T

Good afternoon all ,

Here is the attached estimate for your kind reference .

Note : There is a survey arranged on 25/01/2019 @ 11am (owner waiting) . Kindly assist for the survey .

Thank you .

Best Regards,
Phua
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

View Received Message

This mail is associated with :

***SMH876T (7363595556SG)**

OD

Jan 22 2019 8:00AM

[LEE WEE LEONG]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 28/01/2019 16:45 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$5841.00) - SMH876T - Claim Handler: Loo, Tong Shing

Approved:5841.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 25 Jan 2019

Preliminary Advice

Vehicle No	: SMH876T	Accident Date	: 22/01/2019
Make	: AUDI Q2	Policy No.	: 1900002552
Assignment Date	: 25/01/2019	Excess	: S\$0.00
Date of Inspection	: 25/01/2019	Est. Duration of Repair	: 3.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,500.00
Revised Amount	:S\$	5,841.00
Check Items (Estimated)	:S\$	5,892.00
Total	:S\$	11,733.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	140,000.00
COE / PARF Rebate	:S\$	56,222.00
Salvage Value	:S\$	
Margin for Repair	:S\$	83,778.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/01/2019 17:48
Date Of Accident	22/01/2019 08:40
Exact Location Of Accident	JUNCTION OF ROSYTH AND LEITH RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH876T
Insured/Policyholder	
Name Of Registered Owner	LEE WEE LEONG
NRIC No	S7911061B
Email Address	LEEWEELEONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98782995
Alternative Phone No	OFFICE-98782995

Vehicle Particulars

Manufacturer	AUDI
Model	Q2 1.4 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900002552
Cover Note Number	

Driver

Name of Driver	LEE WEE LEONG
NRIC No	S7911061B
Date Of Birth	15/04/1979
Occupation	INDOOR
Date Of Driving Pass	05/02/2013
Driving Experience	5 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98782995
Fax Number	
Contact Number	OFFICE-98782995
EMail Address	LEEWEELEONG@GMAIL.COM

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 22/01/2019
0957 hrs

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Tan, Gary
NRIC/FIN No.: 6201197A

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 1061B

Vehicle Details

Vehicle No.: SMH876T

Vehicle to be Exported: No

Intended Deregistration Date: 25 Jan 2019

Vehicle Make: AUDI

Vehicle Model: Q2 1.4 TFSI COD S TRONIC

Primary Colour: Grey

Manufacturing Year: 2018

Engine No.: CZE815190

Chassis No.: WAUZZZGA3JA107553

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$28,725.00

Original Registration Date: 10 Jan 2019

First Registration Date: 10 Jan 2019

Transfer Count: 0

Actual ARF Paid: \$32,215.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 09 Jan 2029

PARF Rebate Amount: \$24,161.00

Intended COE Rebate Details

COE Expiry Date: 09 Jan 2029

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$32,200.00

COE Rebate Amount: \$32,061.00

Total Rebate Amount: \$56,222.00

The information contained herein is correct as at 25 Jan 2019

OK

Accident Photo



Accident Photo





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LEE WEE LEONG (LI WEILIANG)
Period of Insurance : 10 Jan 2019 To 09 Jan 2020
Engine No. : CZE815190
Chassis No. : WAUZZZGA3JA107553

Vehicle No. : SMH876T
Policy No. : 1900002552
Endorsement No. :
Issued Date : 11 Jan 2019

ABOUT THE COVER

Make/Model : AUDI Q2/ Q2 Sport 1.4 TFSI COD S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2019
Insuring with COE/PAF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 5 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LEE WEE LEONG (LI WEILIANG) - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125220

PREMIUM LEASING - MH
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Cheng Cheng Chee

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number **S7911061B**

Name

**LEE WEE LEONG
(LI WEILIANG)**

Birth Date **15 Apr 1979**

Issue Date **05 Feb 2013**



002148588D

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) \leq 3000kg 05 Feb 2013
with \leq 7 passengers, exclusive of the driver; and
other motor vehicles without clutch pedals \leq 2500kg

NP 428A



Licence No: S7911061B

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0105/2019/PH
Date : 23-Jan-19

Vehicle NOT IN workshop. Kindly arrange for survey.

NTUC Income Insurance Co - Claims Department

73 Bras Basah Road

#05-01 NTUC Trade Union House

Singapore 189556

ALG.

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Mr Lee Wee Leong
Address : 69 Poh Huat Road
#02-03 Fontaine Parry
Singapore 546777
Telephone : HP +65 98782995
Type of Claim : Own Damage Claims
Policy No. : 1900002552
Vehicle No : **SMH 876 T**
Model Code : Q2 1.4 TFSI
Model / Year : Jan-19
Engine No : CZE 815190
Chassis No : WAUZZZGA3JA107553
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Jan-19
Place of Accident : Junction of Rosyth and Leith Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMH 876 T .

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper assy and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00 1,050 ✓	
3	To respray front bumper assy and lhs front fender.	\$ 1,600.00 1,000 550 ✓	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 3,552.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 25/01/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0105/2019/PH
Date	:	23-Jan-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

3 days - ok - jb - 12 Mar 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Lee Wee Leong
Address	:	69 Poh Huat Road #02-03 Fontaine Parry Singapore 546777
Telephone	:	HP +65 98782995
Type of Claim	:	Own Damage Claims
Policy No.	:	1900002552
Vehicle No	:	SMH 876 T
Model Code	:	Q2 1.4 TFSI
Model / Year	:	Jan-19
Engine No	:	CZE 815190
Chassis No	:	WAUZZZGA3JA107553
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	22-Jan-19
Place of Accident	:	Junction of Rosyth and Leith Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMH 876 T .

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	\$ 360.00
2	To dismantle and renew front bumper assy and lhs headlight. Re-organise crash management components. Reinstall all parts removed. <i>(Re align console, reinforcement replacement and off road kit \$500.00 added)</i>	\$ 1,400.00	\$ 1,000.00
3	To respray front bumper assy and lhs front fender. <i>(Frt bumper \$550.00 - LHS front fender \$550.00)</i>	\$ 1,600.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 3,552.00	\$ 2,652.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 876 T .

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remark</u>
1	FRONT BUMPER	\$ 1,706.00	\$ 1,364.00
2	FIXING PARTS FOR FRONT BUMPER	\$ 314.00	
3	GRILLE - CENTER	\$ 179.00	\$ 143.20
4	AIR GUIDE GRILLE - SELENITE SILVER - LH	\$ 154.00	\$ 122.80
5	FRONT BUMPER END CAP - LH	\$ 31.00	
6	FRONT BUMPER SPOILER ANTHRACITE	\$ 273.00	
7	FRONT BUMPER CLOSING ELEMENT	\$ 142.00	
8	WHEEL SPOILER - SATIN BLACK - LH	\$ 31.00	
9	ADAPTER - LH	\$ 32.00	
10	RADIATOR GRILLE COOLER GREY	\$ 1,301.00	\$ 1,040.80
11	STRIKER PLATE	\$ 114.00	
12	FOAM FILLER PIECE	\$ 71.00	
13	FRONT BUMPER CARRIER	\$ 625.00	\$ 499.60
14	BUMPER CARRIER COVER	\$ 91.00	
15	FRONT BUMPER GUIDE SECTION - LH	\$ 32.00	
16	"CAUTION" SIGN STICKER	\$ 13.00	\$ 9.76
17	LED HEADLIGHT - LH	\$ 4,491.00	
18	MOUNTING FOR MAIN BEAM HEADLIGHT - LH	\$ 107.00	
19	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM - LH	\$ 128.00	
20	WHEEL COVER ANTHRACITE - LH/RH FRONT	2 \$ 588.00	
SUB - TOTAL SPARE PARTS CHARGES		\$ 10,423.00	\$ 3,180.16

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 876 T .

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
		c/f	\$ 3,180.16
21	FRONT NUMBER PLATE	S/N \$ 25.00	\$ 25.00
22	<i>Added parts - see attached (Off road kit)</i>	\$ 1,926.40	\$ 1,541.12
23	SUNDRIES	\$ 500.00	
	TOTAL SPARE PARTS CHARGES	\$ 12,874.40	\$ 4,746.28
	TOTAL LABOUR CHARGES	\$ 3,552.00	\$ 2,652.00
	GRAND TOTAL	\$ 16,426.40	\$ 7,398.28

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0105/2019/PH 20-Feb-19 Glory Tan 1 of 1 SMH 876 T Q2 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Front Skirt Contains Underrun Bar (Off road kit) <i>LT</i>	\$ 762.00	\$ 609.60 <i>CB</i>
2	1 Set Wheel Arch Covers (Off road kit) <i>new</i>	\$ 762.40	\$ 609.92 <i>LT</i>
3	Trim Strips for Radiator Grille (Off road kit) <i>WT</i>	\$ 402.00	\$ 321.60 <i>CB</i>
		\$ 1,926.40	\$ 1,541.12
<u>LABORS</u>			
	TOTAL	\$ 1,926.40	

For Premium Automobiles Pte Ltd

Adrian LG
St.S.

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SMH 876 T

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0105/2019/MAS

31 May 2019

Dear Sir,

RE: INSURANCE CLAIM FOR SMH 876 T, Audi Q2 1.4 TFSI

With reference to the above-mentioned vehicle, no. **SMH 876 T**, claimant, **Mr. Lee Wee Leong**, please find the related document per attached:

1. A copy of the Original invoice no. 85013808 – S\$7,060.16
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SMH 876 T

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LEE WEE LEONG (LI WEILIANG)
Period of Insurance : 10 Jan 2019 To 09 Jan 2020
Engine No. : CZE815190
Chassis No. : WAUZZZGA3JA107553

Vehicle No. : SMH876T
Policy No. : 1900002552
Endorsement No. :
Issued Date : 11 Jan 2019

ABOUT THE COVER

Make/Model : AUDI Q2/ Q2 Sport 1.4 TFSI COD S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2019
Insuring with COE/PAF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 5 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)
LEE WEE LEONG (LI WEILIANG) - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125220

PREMIUM LEASING - MH
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938
Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE
Cheng Cheng Chee

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SMH 876 T

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0105/2019/SM
21 February 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

1

total pages

Make & Model : AUDI Q2 1.4 TFSI
Vehicle Chassis No. : WAUZZZGA3JA107553
Vehicle Regn No. : **SMH 876 T**
Vehicle Mileage : 40390 KM
Vehicle Owner : Mr. Lee Wee Leong
Certificate No : 1900002552
Own Damage Excess : S\$856.00 (Inclusive of 7% GST)
Accident Date : 22/01/2019
Place : JUNCTION OF ROSYTH AND LEITH RD
Repair Cost : \$ 7,060.16
WIP No. : 40387
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 21/2/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jan 2019		25 Jan 2019 14:54 Edit Adj Rpt	\$7,398.28 Edit Estimates	\$7,398.28 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured: **LEE WEE LEONG**, ID: S7911061B, Tel: +6598782995, Email: leeweeleong@gmail.com

Vehicle Reg. No.: **SMH876T**

Claim Type: **OD / 7363595556SG**

Date of Loss: 22/01/2019 08:00 - :59
[12 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.: 1900002552 (Comprehensive)
Coverage: 10/01/2019 - 09/01/2020

Excess: \$800.00

Repairer: **Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Loo, Tong Shing**] TongShing.Loo@aig.com

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... **[Final Rpt due 07/02/2019]**

Driver/Custodian: **LEE WEE LEONG (39 / Male)**, NRIC: S7911061B, Tel: +6598782995 Email: leeweeleong@gmail.com

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (08/05/2019): **Alert - Adj Mandate Approved (\$7398.28) - SMH876T - Claim Handler: Loo, Tong Sh...**
- AIG_SG (08/04/2019): **Alert - Adj Mandate Maintained - SMH876T - Claim Handler: Loo, Tong Shing**
- AIG_SG (28/01/2019): **Alert - Adj Mandate Approved (\$5841.00) - SMH876T - Claim Handler: Loo, Tong Sh...**
- AIG_SG (25/01/2019): **SMH876T / OD / 22/01/2019 / Coverage & Excess update**

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)



Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									






Claim Documents



***SMH876T (7363595556SG)**
OD
Jan 22 2019 8:00AM
[LEE WEE LEONG]
Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

[View](#)
[View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/01/19 16:26	Adjuster Immediate Advice	 Load HTM	<input checked="" type="checkbox"/>
2	15/03/19 14:50	Adjuster Immediate Advice	 Load HTM	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/01/19 16:20	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
14	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
15	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
16	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
17	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
18	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
19	25/01/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
20	15/03/19 09:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
21	15/03/19 09:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
22	15/03/19 09:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
23	15/03/19 09:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
24	15/03/19 09:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
25	15/03/19 09:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	15/03/19 09:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	15/03/19 09:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	15/03/19 09:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/01/19 16:20	Singapore Accident Statement	 Load PDF	<input checked="" type="checkbox"/>
2	25/01/19 16:20	Certificate of Insurance	 Load PDF	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
3	25/01/19 16:20	Driver's Driving License	Load PDF	
4	25/01/19 16:20	ESTIMATE	Load PDF	
5	15/03/19 14:47	SUPPLEMENTARY LIST	Load PDF	
6	08/04/19 16:50	REVISED ESTIMATE	Load PDF	
7	20/06/19 11:45	DISCHARGE VOUCHER	Load PDF	
8	20/06/19 11:45	WORKSHOP INVOICE	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/01/19 18:08	Accident Statement	Load HTM	

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/01/19 17:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	22/01/19 17:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	22/01/19 17:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	22/01/19 17:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	22/01/19 17:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	22/01/19 17:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	22/01/19 17:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	22/01/19 17:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	22/01/19 17:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	22/01/19 17:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	22/01/19 17:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/01/19 18:07	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	22/01/19 18:07	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19001689/AQD3S2

Date: 20/06/2019

REFERENCE

Insured/Claimant:	LEE WEE LEONG	Policy No:	1900002552	
Date of Loss:	22/01/2019	Nature of Claim:	OD	Claim No: 7363595556SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH876T		
Make & Model:	AUDI Q2, 1.4 (A)	Engine No:	CZE815190
Reg. Date:	10/01/2019 (Man. Year: 2018)	Chassis No:	WAUZZZGA3JA107553
Colour:	Grey	Odometer:	974 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$140,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/40 R19	Rear Tyre Size:	235/40 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,489.12	4,746.28	7,742.84	62.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,552.00	2,652.00	900.00	25.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,041.12	7,398.28	8,642.84	53.88
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	15,241.12	6,598.28	8,642.84	56.71
+ GST 7.00/7.00% (S\$)	1,066.88	461.88	605.00	56.71
Nett Amount (S\$)	16,308.00	7,060.16	9,247.84	56.71

INSPECTION

Date of Assignment:	25/01/2019		
Date Inspected:	25/01/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,706.00 FS	*1,364.00 FS
2	1		*FIXING PARTS FOR FRONT BUMPER	Not Necessary	314.00 FS	*- FS
3	1		*GRILLE - CENTER	Deformed	179.00 FS	*143.20 FS
4	1		*AIR GUIDE GRILLE - SELENITE SILVER - LH	Missing	154.00 FS	*122.80 FS
5	1		*FRONT BUMPER END CAP - LH	Not Necessary	31.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER ANTHRACITE	Not Necessary	273.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	142.00 FS	*- FS
8	1		*WHEEL SPOILER - SATIN BLACK - LH	Not Necessary	31.00 FS	*- FS
9	1		*ADAPTER - LH	Not Necessary	32.00 FS	*- FS
10	1		*RADIATOR GRILLE COOLER GREY	Cracked	1,301.00 FS	*1,040.80 FS
11	1		*STRIKER PLATE	Not Necessary	114.00 FS	*- FS
12	1		*FOAM FILLER PIECE	Not Necessary	71.00 FS	*- FS
13	1		*FRONT BUMPER CARRIER	Bent	625.00 FS	*499.60 FS
14	1		*BUMPER CARRIER COVER	Not Necessary	91.00 FS	*- FS
15	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	32.00 FS	*- FS
16	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*9.76 FS
17	1		*LED HEADLIGHT - LH	Not Necessary	4,491.00 FS	*- FS
18	1		*MOUNTING FOR MAIN BEAM HEADLIGHT - LH	Not Necessary	107.00 FS	*- FS
19	1		*LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM - LH	Not Necessary	128.00 FS	*- FS
20	1		*WHEEL COVER ANTHRACITE - LH/RH FRONT	Not Necessary	588.00 FS	*- FS
21	1		*FRONT NUMBER PLATE	Dented	25.00 FS	*25.00 FS
22	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS
23	1		*FRONT SKIRT CONTAINS UNDERRUN BAR (OFF ROAD KIT)	Cut	609.60 FS	*609.60 FS
24	1		*SET WHEEL ARCH COVERS (OFF ROAD KIT)	Necessary	609.92 FS	*609.92 FS
25	1		*TRIM STRIPS FOR RADIATOR GRILLE (OFF ROAD KIT)	Cut	321.60 FS	*321.60 FS
Total Parts (\$\$)					12,489.12	4,746.28

F=Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ASSY AND LHS HEADLIGHT. RE-ORGANIS CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,400.00	1,000.00
3	TO RESPRAY FRONT BUMPER ASSY AND LHS FRONT FENDER.	New	1,600.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			3,552.00	2,652.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >