

## TRANS EUROKARS PTE LTD NO:5 UBI CLOSE, SINGAPORE 408605



## **ESTIMATE COST OF REPAIRS**

EQ INSURANCE COMPANY LTD NAME: Mr Johari Bin Abdullah @Johari Bin Mahn WIP: 41535

5 Maxwell Road ADDRESS: 804 Chai Chee Road EXCESS:

#17-00 Tower Block #09-620 **DATE**: 24-Jan-19

MND Complex, Singapore 069110 Singapore 460804

ATTN.: MOTOR CLAIMS TEL: 96206477FADHIL

FAX:

 VEH NO:
 SLZ4130C
 DATE IN:
 CONTACT PERSON:
 Ronald 63957875

CHASSIS NO: JM6BN22A8J0201101 MILEAGE: TYPE OF CLAIM: THIRD PARTY CLAIM

MODEL: MAZDA3 DATE REG.: 30-Apr-18 POLICY NO.:

## NATURE OF WORKS

Parts Description							
NO	QТY			REVISED		PRICES  1,074.80  5.10  537.30  34.60  344.40  24.30  16.80  6.40  11.20  5.60	
1	REAR BUMPER		1	MBPD8-50-221ABB		\$	1,074.80
2	BRACKET CENTER	₹	1	MKD53-50-251		\$	5.10
3	REAR REINFORCE	MENT	1	MB45A-50-260		\$	537.30
4	RETAINER, CENTI	ER, SENSOR	2	MKD47-67-UC5A53		\$	34.60
5	SENSOR CENTER, ULTRASONIC 2 MGMK6-67-UC1 53			\$	344.40		
6	TAPE PROTECTO	R, SENSOR	3	MGS1D-50-EM1A		\$	24.30
7	RIVET, REAR BUN	/IPER	4	MBBM4-50-355		\$	16.80
8	CLIP, REAR BUMI	CLIP, REAR BUMPER 2 MGJ21-50-049			\$	6.40	
9	FASTENER, REAR BUMPER 4 MB45A-56-146A		MB45A-56-146A		\$	11.20	
10	GROMMET, REAF	R BUMPER	2	M9991-00-501		\$	5.60
11	GROMMET, REAF	R BUMPER	4	MBHN1-50-0Z1A		\$	10.00
12	GASKET LHS, TAII	LAMP	1	MB45A-51-3J8		\$	20.90
13	GASKET RHS, TAI	LLAMP	1	MB45A-51-3H8		\$	20.90
	TOTAL PARTS					\$	2,112.30
	LESS 10%					\$	211.23
	TOTAL PARTS COST				\$	1,901.07	
		<u> </u>	abour Descripti	<u>on</u>			
1	MZ-BR-REAR02 TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.				\$	1,980.00	
2	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND REAR END PANEL.				\$	1,890.00	
3	MZ-BR-REVSEN TO TRANSFER REVERSE SENSORS.			NETT	\$	330.00	
4	MZ-BR-CAVITY TO CARRY-OUT BODY CAVITY PRESERVATION.				\$	250.00	

5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.				\$ 350.00
7		TO SUPPLY BRILA PREMIUM COATING		NETT		\$ 800.00
8	MZ-BR-SUNDRI	SUNDRIES.		NETT		\$ 100.00
			TOTAL LABOUR	\$	-	\$ 5,950.00
			TOTAL PARTS	\$	-	\$ 1,901.07
			TOTAL	\$	-	\$ 7,851.07
			LESS EXCESS	\$	-	\$ -
			TOTAL AFTER EXCESS	\$	-	
			GST 7%	\$	-	\$ -
			GRAND TOTAL	\$	-	\$ -

## REMARKS

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

<b>TRANS</b>	<b>FUR</b>	OKARS	PTF	LTD

Aut	horised	d Sign	ature