

A: REC. BY:

REF:

CS/FWD 19001799/Ksd3

Special Instruction

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Josey Loh

of

FWD

Date/Time

28012019 1139am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDH 53H

Insured:

at Workshop m/s

Ah Lim Motor

Tel:

6456 3637

of

176 Sin Ming Dr #05-12

Policy No:

PNPV 2018-00012112

Claim No:

1201900003301

Sum Insured:

Excess:

\$600.00

Make of Veh:

D.O.A.

25012019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

28012019 237pm

Person Contacted:

Meili

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SDH 53H - NA / A2119001699/hu

DUA: 28012019

29/1/19 @ 235pm Mei Li said repair on part by part
 29/1/19 @ 309pm Ah Qiang said some of the parts, parts price need to check
 29/1/19 Revert via merimen - Some of the parts pending for parts prices
 29/1/19 @ 16:08 p.m. authorize repair approved by Lionel Tan via merimen.

ASS. REC. BY:

REF: FWP/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TR / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SDH 5314

Yr Regn:

09, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Picnic

c.c

1998

Colour:

M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

76919

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTEGH 23B 800026986

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Maxxis

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

25/1/19

D.O.I.

28/1/19

Survey held at

Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

30/01/19 Kenneth

30/01/19 @ 10:50 a.m. revert authorize repair to Meit. Cupam via email.

29/4 83483 Confirm

(\$ 115 \$ 1,130 Red - 25%)

RECEIVED 30 APR 2019

J. M. M. M.

30/4/2019

Date/Time, File Pass to?

30/04/19

☐

: Prel. Report

1)

Typist

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trlp:

1

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

3,483.00 p/p

200
50
50
10

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jan 2019 Sendback Est	28 Jan 2019 10:51 S\$4,413.00	28 Jan 2019 11:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	SIO WEE SYN, ID: S7715360H		
Vehicle Reg. No.:	SDH53H	Date of Loss:	25/01/2019 12:00 - :59 [112 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201900003301	Policy/Cover Note No.:	PNPV2018-00012112 (Comprehensive)
		Excess:	S\$600.00
Repairer:	Ah Lim Motor Company (Sin Ming) 176 Sin Ming Drive #05-12, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64563637		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/02/2019]		
Driver/Custodian:	YVONNE GOH HWEE PENG (41 / Female), NRIC: S7718936Z, Tel: +6597613730		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 30 January 2019 10:50 AM
To: meili@almsm.com.sg
Cc: SUR
Subject: RE: Limit Amount for repair - SDH 53H OD (FWD)- Toyota Picnic

Dear Meili,

As instructed by our client, please proceed at repair cost not exceeding \$ 4,200.00 (inclusive supplementary) to repair the insured vehicle **SDH 53H (Excess \$ 600/-)** on part by part basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: meili@almsm.com.sg [mailto:meili@almsm.com.sg]
Sent: Wednesday, 30 January 2019 9:41 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: Limit Amount for repair - SDH 53H OD (FWD)- Toyota Picnic

Dear Shirley,

OK. We accept the Limit Amt of \$4,200/- at P/P

Regards,

Meili Tan - (Sin Ming)
176 Sin Ming Drive
#05-12 Sin Ming Autocare
Singapore 575721
Tel : 6456 3637 Fax: 6456 3686
email : meili@almsm.com.sg

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, January 30, 2019 9:21 AM
To: meili@almsm.com.sg

Cc: SUR

Subject: SDH 53H OD (FWD)

Dear Meili/Ah Qiang,

As spoken, kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 4,200.00 on part by part basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SDH53H (1201900003301)

OD

Jan 25 2019 12:00PM

[SIO WEE SYN]

Ah Lim Motor Company

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 30/04/2019 12:06 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$3483.00) - SDH53H - Claim Handler: Josey Loh

Approved:3483.00.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SDH53H (1201900003301)

OD

Jan 25 2019 12:00PM

[SIO WEE SYN]

Ah Lim Motor Company

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 29/01/2019 16:08 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$3973.00) - SDH53H - Claim Handler: Josey Loh

Approved:3973.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 30 Apr 2019

Preliminary Advice

Vehicle No	: SDH53H	Accident Date	: 25/01/2019
Make	: TOYOTA PICNIC	Policy No.	: PNPV2018-00012112
Assignment Date	: 28/01/2019	Excess	: S\$600.00
Date of Inspection	: 28/01/2019	Est. Duration of Repair	: 6.00
Inspection At	: AH LIM MOTOR COMPANY (SIN MING) 176 SIN MING DRIVE #05-12, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,813.00
Revised Amount	:S\$	3,483.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,483.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	18,000.00
COE / PARF Rebate	:S\$	13,361.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,639.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 29 Jan 2019

Preliminary Advice

Vehicle No	: SDH53H	Accident Date	: 25/01/2019
Make	: TOYOTA PICNIC	Policy No.	: PNPV2018-00012112
Assignment Date	: 28/01/2019	Excess	: S\$600.00
Date of Inspection	: 28/01/2019	Est. Duration of Repair	: 6.00
Inspection At	: AH LIM MOTOR COMPANY (SIN MING) 176 SIN MING DRIVE #05-12, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,413.00
Revised Amount	:S\$	3,433.00
Check Items (Estimated)	:S\$	540.00
Total	:S\$	3,973.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	18,000.00
COE / PARF Rebate	:S\$	13,361.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,639.00

Remarks

☐ The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

☐ The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

☒ Other comments : Some of the parts pending for parts prices.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/01/2019 17:35
Date Of Accident	25/01/2019 12:40
Exact Location Of Accident	CTE TWDS AYE NEAR EXIT 14
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDH53H
Insured/Policyholder	
Name Of Registered Owner	SIO WEE SYN
NRIC No	S7715360H
Email Address	SIOELVIS@YAHOO.COM
Mobile Phone No	(LOCAL) +65-98626855
Alternative Phone No	OTHERS-97613730

Vehicle Particulars

Manufacturer	TOYOTA
Model	PICNIC-2.0 W/O ROOF RACK (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00012112
Cover Note Number	23/09/2018 TO 22/09/2019

Driver

Name of Driver	YVONNE GOH HWEE PENG
NRIC No	S7718936Z
Date Of Birth	15/07/1977
Occupation	INDOOR
Date Of Driving Pass	28/08/1998
Driving Experience	20 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97613730
Fax Number	
Contact Number	
Email Address	SIOELVIS@YAHOO.COM

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJX8402B
Vehicle Make/Model/Colour CAR C
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver JEGAMOHAN
NRIC/Passport Number
Contact Number 94324170
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SHC5136Z
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver MOK KOK KEONG
NRIC/Passport Number S1397851D
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)


DETAILS OF INJURED PERSON 1

Name JEGAMOHAN - DRIVER OF CAR C
Approximate Age
Injuries Sustain UNKNOWN
Injured person in which vehicle? SJX8402B
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

Sketch Plan Pg. 2

Date of accident: 25/01/2019 Time: 1240^{EST} Location: CTE toward AYE near Exit 14
 My Vehicle A: SDH53H Vehicle B: SKG607H Vehicle C: JX8402B
 SKETCH PLAN Vehicle D: SHC513LZ

1st
2nd
3rd
4th



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach Police Report

No: T/20190125/2075

dd: 25/01/2019

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my effie accident report to:

My workshop:

Email address:

& myself:

Email address: Siolins@yahoo.com

Note: Please take note that your Insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own Insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Vehicle: - SDH53H

Policyholder's Signature

Date & Time:

Driver's Signature


(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



Form SK Sketch Plan Form V3

Police Report Pg. 2



**SINGAPORE
POLICE FORCE**



T/20190125/2075

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

2 of 4

Report No. T/20190125/2075

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	YVONNE GOH HWEE PENG	ID No.	S7718936Z
Related Vehicle	SDH53H (Car)	Contact No.	97613730
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	Mok Kok Keong	ID No.	S1397851D
Related Vehicle	SHC5136Z (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	Loke Yuen Yuen	ID No.	S1230133B
Related Vehicle	SJX8402B (Car)	Contact No.	90297877
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20190125/2075

4 of 4

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

Report No. T/20190125/2075

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /
Sgt 2 JEREMY KHOO WEI LIANG

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
25/01/2019 14:58

Officer In Charge Of Case:
TP / GIT /
Sgt 3 RASHIDAH BINTE AZMAN
Contact No.: 65476216

Classification Of Case:

Authentication Stamp
NP168



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5360H
Vehicle Details	
Vehicle No.:	SDH53H
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PICNIC AUTO W/O ROOF RACK
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	1AZH365038
Chassis No.:	JTEGH23B800026986
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$24,216.00
Original Registration Date:	23 Sep 2009
First Registration Date:	23 Sep 2009
Transfer Count:	1
Actual ARF Paid:	\$24,216.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Sep 2019
PARF Rebate Amount:	\$12,108.00
Intended COE Rebate Details	
COE Expiry Date:	22 Sep 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$6,182.00
COE Rebate Amount:	\$1,253.00
Total Rebate Amount:	\$13,361.00

The information contained herein is correct as at 29 Jan 2019

OK

X

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 5360H

Vehicle Details

Vehicle No.: SDH53H

Vehicle to be Exported: Yes

Intended Deregistration Date: 30 Jan 2019

Vehicle Make: TOYOTA

Vehicle Model: PICNIC AUTO W/O ROOF RACK

Primary Colour: Blue

Manufacturing Year: 2009

Engine No.: 1AZH365038

Chassis No.: JTEGH23B800026986

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$24,216.00

Original Registration Date: 23 Sep 2009

First Registration Date: 23 Sep 2009

Transfer Count: 1

Actual ARF Paid: \$24,216.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 22 Sep 2019

PARF Rebate Amount: \$12,108.00

Intended COE Rebate Details

COE Expiry Date: 22 Sep 2019

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$6,182.00

COE Rebate Amount: \$1,248.00

Total Rebate Amount: \$13,356.00

The information contained herein is correct as at 25 Jan 2019

OK

Driver's Particulars Pg. 2

REPUBLIC OF SINGAPORE DRIVING LICENCE

Identity No: S7718936Z

YVONNE GOH HWEE PENG
(YVONNE WU HUIPING)

Birth Date: 15 Jul 1977
Valid Date: 05 Aug 2003

10007206198

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7718936Z

YVONNE GOH HWEE PENG
(WU HUIPING)

吴惠萍

Race: CHINESE
Date of birth: 15-07-1977
Country of birth: SINGAPORE

Sex: F

67718936Z

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 5 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: 28 Aug 1998

NP 428A



4141494

NPIC No: S7718936Z

Date of issue: 20-11-2007

APT BLK 138A LORONG 1A TDA PAYOH #13-40
SINGAPORE 311138

NPIC No: S7718936Z Date: 09/02/2018

AH LIM MOTOR COMPANY

176 SIN MING DRIVE #05-12
SIN MING AUTOCARE Singapore 575721
Tel: 64563637 Fax: Email:
GST Reg No: M9-0009639-E

SURVEYOR COPY

INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	MCS1900016
Policy No:	PNPV2018-00012112	Date of Loss:	25/01/2019
Vehicle Reg. No.:	SDH53H	Driveable?	
Driver Age/Info:	41 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	SIO WEE SYN		
Driver:	YVONNE GOH HWEE PENG		

Make/Model:	TOYOTA PICNIC, 2.0 W/O ROOF RACK (A)	Vehicle Reg. Date:	23/09/2009
Vehicle Colour:	BLUE	Chassis No:	JTEGH23B800026986
Engine No:	1AZH365038		
Odometer:	0 KM		

Paint Type:
Total Loss? NO

Est. Duration of Repair (day) 10-16 days

Fax: 62564315

Description of Accident/Loss: REFER TO ATTACH POLICE REPORT NO. T/20190125/2075 DD. 25/01/2019

Remarks: CAR IS IN OUR SIN MING WORKSHOP. PLS ARRANGE FOR SURVEY SOONES

Present Location: AH LIM MOTOR COMPANY (SIN MING)

COST OF CLAIMS

Parts
Miscellaneous Items
Labour
Paintwork Labour
Towing

Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged parts during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification is allowed - Supplementary (extra) must be resurveyed and is subject to final approval from Insurance Company	
Acknowledged by Repairer:	Amount
Signature:	2,413.00
Date:	0.00
	2,000.00
	0.00
	0.00

Gross Total (S\$)	4813	4,413.00
+ GST 7.00% (S\$)		308.91
Nett Amount (S\$)		4,721.91

This claim is handled by: KEE MUI HONG

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	200 30.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	100 120.00
3	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT SUPPORT PANEL ; TO REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	600 750.00
4	TO SPRAY BONNET; FRONT BUMPER; FRONT FENDER LH/RH; FRONT DOOR LH/RH AND FRONT SUPPORT PANEL	New	900 1,100.00
Gross Labour Cost (S\$)			2,000.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : FWD SINGAPORE PTE LTD
 6 TEMASEK BOULEVARD
 #18-01 SUNTEC TOWER 4
 SINGAPORE 038986

TEL: 67275700

FAX: 67275799

ATTN: Motor Claim Department

Your Ref No: SDH53H

Claim Type: Own Damage

Accident Date: 25/01/2019

Claim No: MCS1900016

Ref No: MFS1900056

Date: 27 Mar 2019

Policy No: PNPV2018-00012112

Veh Reg No: SDH53H

Make/Model: TOYOTA PICNIC

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SDH53H

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
SPARE PARTS				
1 FRONT BONNET		1 PC	210.00	
2 FRONT BUMPER		1 PC	180.00	
3 FRONT BUMPER CLIPS		20 PC	20.00	
4 FRONT BUMPER REINFORCEMENT		1 PC	95.00	
5 FRONT BUMPER SPONGE		1 PC	48.00	
6 FRONT FENDER RH		1 PC	175.00	
7 FRONT FENDER COWLING CLIPS		10 PC	10.00	
8 FRONT FENDER LOGO		1 PC	10.00	
9 RADIATOR GRILLE C/W GRILLE LOGO		1 PC	155.00	
10 BRACE PANEL		1 PC	40.00	
11 RADIATOR		1 PC	180.00	
12 AIR CON CONDENSER		1 PC	480.00	
13 HEADLAMP RH		1 PC	200.00	
				1,803.00
Special Nett				
14 RADIATOR COOLANT		1 PC	35.00	
15 NUMBER PLATE		1 PC	25.00	
				60.00
LABOUR				
16 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	20.00	
17 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	100.00	
18 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT SUPPORT PANEL, TO REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	600.00	
19 TO SPRAY BONNET, FRONT BUMPER, FRONT FENDER LH/RH, FRONT DOOR LH/RH AND FRONT SUPPORT PANEL		1 PC	900.00	
				1,620.00

AH LIM MOTOR COMPANY
 No 10 Ang Mo Kio Industrial Park 2A
 #01-09 AMK Autopoint Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4
SINGAPORE 038986

TEL: 67275700

FAX: 67275799

ATTN: Motor Claim Department

Your Ref No: SDH53H

Claim Type: Own Damage

Accident Date: 25/01/2019

Claim No: MCS1900016
Ref No: MFS1900056
Date: 27 Mar 2019
Policy No: PNPV2018-00012112
Veh Reg No: SDH53H
Make/Model: TOYOTA PICNIC

Repair Cost to Vehicle No (For Finalization):SDH53H

Amount Before Excess	S\$ 3,483.00
Less Excess	S\$ 600.00
Amount Before GST	S\$ 2,883.00
Add GST @ 7%	201.81
Total Amount payable	S\$ 3,084.81

TOTAL: SINGAPORE DOLLAR THREE THOUSAND EIGHTY FOUR AND CENTS EIGHTY ONE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 25/01/2019

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
AUTHORISED SIGNATURE 170

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jan 2019)

Parts: M1-MPV TOYOTA PICNIC 2.0 W/O ROOF RACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SDH53H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No. Qty Part No. Particulars

%Disc %Depr Amount

1	1	*RADIATOR COOLANT	0	0.00	*35.00 FS	✓
2	1	*NUMBER PLATE	0	0.00	*35.00 FS	25.00 ✓
3	1	*FRONT BONNET	0.00	0.00	*210.00 F	✓
4	2	*FRONT BONNET HINGE LH / RH	0.00	0.00	*50.00 F	✓
5	1	*FRONT BUMPER	0.00	0.00	*180.00 F	✓
6	2	*FRONT BUMPER SIDE RETAINER LH / RH	0.00	0.00	*80.00 F	✓
7	20	*FRONT BUMPER CLIPS	0.00	0.00	*20.00 F	✓
8	1	*FRONT BUMPER REINFORCEMENT	0.00	0.00	*95.00 F	✓
9	2	*FRONT BUMPER REINFORCEMENT BRACKET LH / RH	0.00	0.00	*60.00 F	✓
10	1	*FRONT BUMPER SPONGE	0.00	0.00	*48.00 F	✓
11	1	*FRONT FENDER RH	0.00	0.00	*175.00 F	✓
12	10	*FRONT FENDER COWLING CLIPS	0.00	0.00	*10.00 F	✓
13	1	*FRONT FENDER LOGO	0.00	0.00	*10.00 F	✓
14	1	*RADIATOR GRILLE C/W GRILLE LOGO	0.00	0.00	*165.00 F	✓
15	1	*RADIATOR SUPPORT PANEL	0.00	0.00	*240.00 F	✓
16	1	*BRACE PANEL	0.00	0.00	*40.00 F	✓
17	1	*RADIATOR	0.00	0.00	*480.00 F	✓
18	1	*AIR CON CONDENSER	0.00	0.00	*480.00 F	✓
19	1	*AIR CON CONDENSER HIGH PRESSURE PIPE - CHK PRICE	0.00	0.00	*F	✓
20	2	*HEADLAMP LH / RH - CHK PRICE	0.00	0.00	*F	✓
21	1	*FRONT BONNET LOCK - CHK PRICE	0.00	0.00	*F	✓

F=Franchise part, S=SpocNett.

Total Parts (S\$)

2,413.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			<i>201</i>
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	30.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	<i>1001</i> 120.00
3	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT SUPPORT PANEL ; TO REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	<i>6001</i> 750.00
4	TO SPRAY BONNET; FRONT BUMPER; FRONT FENDER LH/RH; FRONT DOOR LH/RH AND FRONT SUPPORT PANEL	New	<i>9001</i> 1,100.00
Gross Labour Cost (S\$)			2,000.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 9791 / 6745 9629



Dept Direct: 6417 9792

Dept Direct: 6417 9792

Dept Direct: 6417 9792

Dept Direct: 6417 9792

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY(SIN MING)
176 SIN MING AUTOCARE #05-12

SINGAPORE 575721
TEL : 6456 3637 FAX : 6456 3686
ATTN : KEONG

MCs1900016
SDH 53H
P.1

TAX INVOICE : AR201901-16128
DATE : 30/01/2019
CUSTOMER ID : AHL012
VEH REG. NO. : SDH53H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 2
CURR : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
3	T53301-44060 ACM21 IPSUM	FRT BONNET	CC CC12-B-08B	1	210.00	210.00
9	T52021-44010 ACM20 PICNIC	FRT BUMPER REINFORCEMENT	CC CC12-J-01B	1	95.00	95.00
12	T90467-07166 JB33/ACV30/31R	CLIP FOR SHIELD	CC CC12-N-03B7	10	1.00	10.00
13	T75443-06151 ALL MODEL	VVTI EMBLEM	CC CC12-N-01B1	1	10.00	10.00
18	T88460-44430/44510 ACM21 PICNIC	AIRCON CONDENSER	CC CC12-G-10C	1	480.00	480.00
PA	T52119-44909 ACM20 03-	FRT BUMPER ASSY	CC NEW	1	180.00	180.00
20	T52161-16010 ROC ALL MODEL	BUMPER CLIP	CC NEW	20	1.00	20.00

CONTINUE NEXT PAGE

[P] 30/01/2019 11:54:54AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[B] 30/01/2019 11:46:49AM

CP



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9781 / 6745 9889



Dept Direct: 6417 9794

Dept Direct: 6417 9793

Dept Direct: 6417 9796

Dept Direct: 6417 9799

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY(SIN MING)
176 SIN MING AUTOCARE #05-12

SINGAPORE 575721
TEL : 6456 3637 FAX : 6456 3686
ATTN : KEONG

MC51400016

P-2

TAX INVOICE : AR201901-16128
DATE : 30/01/2019
CUSTOMER ID : AHL012
VEH REG. NO. : SDH53H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 2
CURR : S\$

SO/STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
53811-44060 ACM20 (PICNIC)	FENDER-FRT-RH	CC NEW	1	175.00	175.00

SUB-TOTAL : 1,180.00
ADD GST 7.00 % 82.60

E. & O.E

TOTAL AMOUNT S\$: 1,262.60

[P] 30/01/2019 11:54:54AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 30/01/2019 11:46:49AM

JAE Auto Pte. Ltd.

Sales Executive: STEVEN

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

日美汽車私人有限公司

JAE AUTO PTE LTD

BLK 3018 UBI ROAD 1 #01-121 SINGAPORE 40871
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9330

Dept Direct: 6365 9610

Dept Direct: 6417 9794

Arrange By _____ Driver _____

Dept Direct: 6366 9611

Dept Direct: 6417 9792

Dept Direct: 6417 9795

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY (SIN MING)

176 SIN MING AUTO CARE #05-12

SINGAPORE 575721

TEL: 6456 3687 FAX: 6456 3686

ATTN: KEONG

MCE 1900016

P3

TAX INVOICE : AR201901-16159

DATE: 30/01/2019

CUSTOMER ID: AHL012

VEH REG NO: SDH53H

TERMS: 30 days

PO NO:

PAGE NO: Page 1 of 1

CURR: S\$

SO STOCK ID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1. T53208-44020	BRACE PANEL	UI	1	40.00	40.00
ACM20 IPSUM		SUPPLIER			
2. T52611-44020	FRT BUMPER ABSORBER	UI	1	48.00	48.00
ACM20 IPSUM		SUPPLIER			

SUB-TOTAL: 88.00
ADD GST 7.00%: 6.16

E. & O.E

TOTAL AMOUNT S\$: 94.16

[P] 30/01/2019 12:06:48PM

[E] 30/01/2019 12:06:10PM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on Over Due Account(s)

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive: STEVEN



* AR201901-16159 *

This is computer generated document.

No signature is required.

ORIGINAL: 1/1

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

AHLIM MOTOR COMPANY (SIN MING)

176 SIN MING ALTO CARE #05-12

SINGAPORE 575721

TEL: 6456 3637 FAX: 6456 3686

ATTN: KEONG



SQ STOCKID

88M30/4210

ACM20

20

DESCRIPTION

HEAD LAMP RH

Stk Loc

U

SUPPLIER

QTY

U/PRICE

AMOUNT

200.00

200.00

SUB-TOTAL:

200.00

ADD GST 7.00%

14.00

E & O E

TOTAL AMOUNT S\$:

214.00

[P] 30/01/2019 1:30:38PM

[E] 30/01/2019 1:30:04PM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on Over Due Account(s)

Goods Received in Good Order

JAE Auto Pte Ltd

Sales Executive MAE

This is computer generated document.

No signature is required.



* A R 2 0 1 9 0 1 - 1 6 2 3 4 *

ORIGINAL

Signature / Co Stamp / Date

WINDSCREEN GLASS
Dept Direct: 6417 8791 / 6746 9959



Wiper blade: NWB (Nippon Wiper blade), Sliiper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201901-16234

DATE : 30/01/2019

CUSTOMER ID : AHL012

VEH REG. NO. : SDH53H

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : S\$

MCC1900016

P-4

Handwritten signature



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO: M2-0119201-3 CO. REG. NO.: 199307741M

AH LIM MOTOR COMPANY(SIN MING)

176 SIN MING AUTOCARE #05-12

SINGAPORE 575721

TEL: 6456 3687 FAX: 6456 3686

ALLEN KEONG

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9808



Dept Direct: 6935 9610

Dept Direct: 6305 9811

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201901-16451

DATE : 30/01/2019

CUSTOMER ID : AHL012

VEH REG NO : SDH53H

TERMS : 30 days

PO NO :

PAGE NO : Page 1 of 1

CURR : S\$

NCS 1900016

RS

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1 716400-28290 ROC	RADIATOR (ROC)	UI	1	180.00	180.00
ACN020		SUPPLIER			

SUB-TOTAL : 180.00
ADD GST 7.00 % 12.60

E. & O.E

TOTAL AMOUNT S\$: 192.60

[E] 30/01/2019 4:15:37PM

[P] 30/01/2019 4:16:28PM

Goods Sold are non-refundable for Cash

Interest Rate of 1.5% per month will be imposed on Over Due Account(s)

Goods Received in Good Order

JAE Auto Pte Ltd

Sales Executive STEVEN



AR201901-16451

This is computer generated document.

No signature is required.

ORIGINAL

Signature / Co Stamp / Date



合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: AH LIM MOTOR CO - SIN MING

176, SIN MING DRIVE

#05-12 SIN MING AUTOCARE

SINGAPORE 575721

SDH53H

MCS 1900016

P-6

NO: DLI9213599

PAGE: 1

DATE: 30/01/2019

A/C CODE: LDAL002

TERMS: CR

P/O NO: sdh53h

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 T53101-44190-J0	14 GRILLE	DB11/22	1	155.00	155.00
TOTAL QUANTITY:			1	TOTAL	SIN 155.00
				ADD GST @ 7%	10.85
				GRAND TOTAL	<u>SIN 165.85</u>

Printed: CHAI / 30/01/2019 4:29:23 PM

SALESMAN: CHAI

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

GOODS RECEIVED BY



E. & O. F.



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jan 2019 Sendback Est	30 Apr 2019 09:20 S\$4,813.00	28 Jan 2019 11:39 Edit Adj Rpt	S\$3,483.00 Edit Estimates	S\$3,483.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SIO WEE SYN , ID: S7715360H		
Vehicle Reg. No.:	SDH53H	Date of Loss:	25/01/2019 12:00 - :59 [112 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201900003301	Policy/Cover Note No.:	PNPV2018-00012112 (Comprehensive)
		Excess:	S\$600.00
Repairer:	Ah Lim Motor Company (Sin Ming) 176 Sin Ming Drive #05-12, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64563637		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 08/02/2019]		
Driver/Custodian:	YVONNE GOH HWEE PENG (41 / Female), NRIC: S7718936Z, Tel: +6597613730 Email: sioelvis@yahoo.com		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- FWD_SG (30/04/2019): Alert - Adj Mandate Approved (S\$3483.00) - SDH53H - Claim Handler: Josey Loh
- FWD_SG (29/01/2019): Alert - Adj Mandate Approved (S\$3973.00) - SDH53H - Claim Handler: Josey Loh

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

SDH53H (1201900003301)
 OD
 Jan 25 2019 12:00PM
 [SIO WEE SYN]
 Ah Lim Motor Company

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
1	30/04/19 09:20	Repairer Estimates	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/01/19 15:11	Adjuster Immediate Advice	 Load HTM	☐
2	29/01/19 15:16	Adjuster Immediate Advice	 Load HTM	☐
3	30/04/19 09:13	Adjuster Immediate Advice	 Load HTM	☐
4	30/04/19 11:18	Adjuster Immediate Advice	 Load HTM	☐

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/01/19 14:35	General View	 Load JPG ☒	☒
2	29/01/19 14:35	General View	 Load JPG ☒	☒
3	29/01/19 14:35	General View	 Load JPG ☒	☒
4	29/01/19 14:35	General View	 Load JPG ☒	☒
5	29/01/19 14:35	General View	 Load JPG ☒	☒
6	29/01/19 14:35	General View	 Load JPG ☒	☒
7	29/01/19 14:35	General View	 Load JPG ☒	☒
8	29/01/19 14:35	General View	 Load JPG ☒	☒
9	29/01/19 14:35	General View	 Load JPG ☒	☒
10	29/01/19 14:35	General View	 Load JPG ☒	☒
11	29/01/19 14:35	General View	 Load JPG ☒	☒
12	29/01/19 14:35	General View	 Load JPG ☒	☒
13	29/01/19 14:35	General View	 Load JPG ☒	☒
14	29/01/19 14:35	General View	 Load JPG ☒	☒
15	29/01/19 14:35	General View	 Load JPG ☒	☒
16	29/01/19 14:35	General View	 Load JPG ☒	☒
17	29/01/19 14:35	General View	 Load JPG ☒	☒
18	29/01/19 14:35	General View	 Load JPG ☒	☒
19	29/01/19 14:35	General View	 Load JPG ☒	☒
20	29/01/19 14:35	General View	 Load JPG ☒	☒
21	29/01/19 14:35	General View	 Load JPG ☒	☒
22	29/01/19 14:35	General View	 Load JPG ☒	☒
23	29/01/19 14:35	General View	 Load JPG ☒	☒
24	29/01/19 14:35	General View	 Load JPG ☒	☒
25	30/04/19 09:24	Reinspection Photo	 Load JPG ☒	☒
26	30/04/19 09:24	Reinspection Photo	 Load JPG ☒	☒
27	30/04/19 09:24	Reinspection Photo	 Load JPG ☒	☒
28	30/04/19 09:24	Reinspection Photo	 Load JPG ☒	☒
29	30/04/19 09:24	Reinspection Photo	 Load JPG ☒	☒

Assessment Reports			1 per page	☒
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
Documentation			1 per page	☒
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
1	28/01/19 10:50	Certificate of Insurance	 Load PDF	
2	28/01/19 10:50	53-Driver's Particulars.pdf	 Load PDF	
3	28/01/19 10:50	E-filed GIA report	 Load PDF	
4	28/01/19 10:50	Log card (if available)	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/01/19 14:55	MARK ESTIMATE	 Load PDF	
2	30/04/19 11:25	ESTIMATE MARKED.pdf	 Load PDF	
3	02/05/19 09:51	PARTS INVOICE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
1	26/01/19 11:25	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
1	25/01/19 17:59	Accident Photo	 Load JPG	☒
2	25/01/19 17:59	Accident Photo	 Load JPG	☒
3	25/01/19 17:59	Accident Photo	 Load JPG	☒
4	25/01/19 17:59	Accident Photo	 Load JPG	☒
5	25/01/19 17:59	Accident Photo	 Load JPG	☒
6	25/01/19 17:59	Accident Photo	 Load JPG	☒
7	25/01/19 17:59	Accident Photo	 Load JPG	☒
8	25/01/19 17:59	Accident Photo	 Load JPG	☒
9	25/01/19 17:59	Accident Photo	 Load JPG	☒
10	25/01/19 17:59	Accident Photo	 Load JPG	☒
11	25/01/19 17:59	Accident Photo	 Load JPG	☒
12	25/01/19 17:59	Accident Photo	 Load JPG	☒
13	25/01/19 17:59	Accident Photo	 Load JPG	☒
14	25/01/19 17:59	Accident Photo	 Load JPG	☒
15	25/01/19 17:59	Accident Photo	 Load JPG	☒
16	25/01/19 17:59	Accident Photo	 Load JPG	☒
17	25/01/19 17:59	Accident Photo	 Load JPG	☒
18	25/01/19 17:59	Accident Photo	 Load JPG	☒
19	25/01/19 17:59	Accident Photo	 Load JPG	☒
20	25/01/19 17:59	Accident Photo	 Load JPG	☒
21	25/01/19 17:59	Accident Photo	 Load JPG	☒
22	25/01/19 17:59	Accident Photo	 Load JPG	☒
23	25/01/19 17:59	Accident Photo	 Load JPG	☒
24	25/01/19 17:59	Accident Photo	 Load JPG	☒
25	25/01/19 17:59	Accident Photo	 Load JPG	☒
26	25/01/19 17:59	Accident Photo	 Load JPG	☒
27	25/01/19 17:59	Accident Photo	 Load JPG	☒
28	25/01/19 17:59	Accident Photo	 Load JPG	☒
29	25/01/19 17:59	Accident Photo	 Load JPG	☒
30	25/01/19 17:59	Accident Photo	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☒ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD19001799/KSD3S2

Date: 02/05/2019

REFERENCE

Insured/Claimant: SIO WEE SYN Policy No: PNPV2018-00012112
Date of Loss: 25/01/2019 Nature of Claim: OD Claim No: 1201900003301

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDH53H
Make & Model: TOYOTA PICNIC, 2.0 W/O ROOF RACK (A) Engine No: 1AZH365038
Reg. Date: 23/09/2009 (Man. Year: 2009) Chassis No: JTEGH23B800026986
Colour: Metallic Blue Odometer: 76919 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$18,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R15 Rear Tyre Size: 205/60R15
Front Left Side: Maxxis 9 mm Rear Left Side: Maxxis 9 mm
Front Right Side: Maxxis 9 mm Rear Right Side: Maxxis 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,813.00	1,863.00	950.00	33.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,620.00	380.00	19.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,813.00	3,483.00	1,330.00	27.63
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	4,813.00	2,883.00	1,930.00	40.10
+ GST 7.00/7.00% (S\$)	336.91	201.81	135.10	40.10
Nett Amount (S\$)	5,149.91	3,084.81	2,065.10	40.10

INSPECTION

Date of Assignment: 28/01/2019 Present Location: Ah Lim Motor Company (Sin Ming)
Date Inspected: 28/01/2019 Inspected At: Ah Lim Motor Company (Sin Ming)
Estimated Period of Repair: 6.0 days 176 Sin Ming Drive #05-12, Sin Ming AutoCare
Singapore 575721

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 May 2019)

Parts: M1-MPV TOYOTA PICNIC 2.0 W/O ROOF RACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SDH53H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR COOLANT	Necessary	35.00 FS	*35.00 FS
2	1		*NUMBER PLATE	Cracked	35.00 FS	*25.00 FS
3	1		*FRONT BONNET	Bent	210.00 F	*210.00 F
4	2		*FRONT BONNET HINGE LH / RH	Repair	50.00 F	*- F
5	1		*FRONT BUMPER	Bent	180.00 F	*180.00 F
6	2		*FRONT BUMPER SIDE RETAINER LH / RH	Serviceable	80.00 F	*- F
7	20		*FRONT BUMPER CLIPS	Necessary	20.00 F	*20.00 F
8	1		*FRONT BUMPER REINFORCEMENT	Bent	95.00 F	*95.00 F
9	2		*FRONT BUMPER REINFORCEMENT BRACKET LH / RH	Repair	60.00 F	*- F
10	1		*FRONT BUMPER SPONGE	Cracked	48.00 F	*48.00 F
11	1		*FRONT FENDER RH	Buckled	175.00 F	*175.00 F
12	10		*FRONT FENDER COWLING CLIPS	Necessary	10.00 F	*10.00 F
13	1		*FRONT FENDER LOGO	Necessary	10.00 F	*10.00 F
14	1		*RADIATOR GRILLE C/W GRILLE LOGO	Cracked	165.00 F	*155.00 F
15	1		*RADIATOR SUPPORT PANEL	Repair	240.00 F	*- F
16	1		*BRACE PANEL	Bent	40.00 F	*40.00 F
17	1		*RADIATOR	Punctured	480.00 F	*180.00 FS
18	1		*AIR CON CONDENSER	Bent / Punctured	480.00 F	*480.00 F
19	1		*AIR CON CONDENSER HIGH PRESSURE PIPE - CHK PRICE (NPA)	Serviceable	0.00 F	*- F
20	1		*HEADLAMP LH / RH - CHK PRICE	N/s Mtg Cracked	400.00 F	*200.00 F
21	1		*FRONT BONNET LOCK - CHK PRICE (NPA)	Repair	0.00 F	*- F
F=Franchise part, S=SpcNett.						
					Total Parts (S\$)	2,813.00 1,863.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	30.00	20.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	120.00	100.00
3	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT SUPPORT PANEL ; TO REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	750.00	600.00
4	TO SPRAY BONNET; FRONT BUMPER; FRONT FENDER LH/RH; FRONT DOOR LH/RH AND FRONT SUPPORT PANEL	New	1,100.00	900.00
Gross Labour Cost (S\$)			2,000.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >