

JAS Auto Services

6D Mandai Estate #03-02 M-Space, Singapore 729938

Tel: 6453 1967 (5 lines). Fax: 6457 3091

53255447K

M/s EQ Insurance
5 Maxwell Rd #17-00 Tower Block MND Complex
Singapore 069110

Date : 30-Jan-19

No: 6223 9433

Attn: Motor Claim Dept

Re: Accident on 24/1/2019. Between SGH4038R. AND GBC6872X. (Your Insured)

Dear Sir;

We are pleased to submit herewith the estimate for repairs to the above mentioned accident damaged vehicle **Third Party Claim**.

Parts		Price
1pc	Rear bumper BVC	\$521.23 ✓
1pc	Rear bumper retainer Rh NN	\$45.30 X
1pc	Rear bumper reflector SCP	\$35.60 ✓
1pc	Rear boot NN	\$764.25 X
1pc	Rear fender Rh Repair	\$456.50 X
1pc	Taillamp RH CRA	\$250.80 ✓
1pc	Exhaust Repair	\$350.10 X
1pc	Clips S/N NEL	\$30.00 ✓

Total: \$2,453.78
Less: 25% \$613.45
\$1,840.34

Labour

To remove the affected parts, all relevant attachments, fittings to commence repairs, replace the damaged parts, reinstall & realign all necessary parts.

To putty & respray paint on the relevant repaired areas.

To rust proof affected areas where necessary.

450 \$800.00 ✓

400 \$800.00 ✓

30 \$90.00 ✓

Parts & Labour Total: \$3,530.34

Your Faithfully,

JAS Auto Services

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hwee Jiv - LKK

30/1/19

C/S 3 days

ays

Photo after paint