

✓
in 220419

Steve
83228813

With Prudence 22/4/19 2.30pm
P/P 4 days
Ry before spray

SERVICE ESTIMATE

99039 - C00001 SL: SERVICE SALES - PC
Mr Wong Kian Chong
Blk 117 Bedok North Road
#05-237

Singapore 460117

Closed by : Derek Oh Siong Wee
Svc Consultant :
Remarks : Mr Wong Kian Chong

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 29/01/2019
WIP No. . : 51240
Veh.In/Out: 28/01/2019
*Tel.No. . : Home: 91135380
Reg.No. . : SMF4458B
Reg.date . : 12/11/2018
Mileage .. : 0
Chassis No: YV1FS40LDJ2470561

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR RH FENDER, ETC ⁸⁰⁰	0	6400.00	0		6,400.00 S	7000 1200
800	TO PUTTY SPRAY PAINT ON REAR RH FENDER, REAR END PANEL, RH ROCKER PANEL, ETC ⁷⁰⁰	0	2800.00	0		2,800.00 S	2100 700
802	TO REPLACE REAR WINDSCREEN	0	800.00	0		800.00 S	X
802	TO REMOVE & INSTALL REAR BOOT COMPARTMENT PARTS	0	2400.00	0		2,400.00 S	1900 X
802	TO REMOVE & INSTALL INTERIOR PARTS	0	3200.00	0		3,200.00 S	4600 800
89994	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00 S	X
280	TO CHECK WIRING INCLUDE	0	450.00	0		450.00 S	/
RESETTING OF ALL ELECTRICAL MODULES							
	FENDER REAR RH S60 1 X ^{DBR}	1.0 EA	2032.70			2,032.70 S	
	D WINDSCREEN SEALA X ^{***}	2.0 EA	122.10			244.20 S	
	D PRIMER GLASS & P X ^{***}	1.0 EA	37.40			37.40 S	
	V001161436/*D* GLASS X ^{***}	1.0 EA	55.40			55.40 S	
	WINDSCREEN REAR S60 X ^{***}	1.0 EA	1288.90			1,288.90 S	

SERVICE ESTIMATE

99039 - C00001 SL: SERVICE SALES - PC

Mr Wong Kian Chong
Blk 117 Bedok North Road
#05-237

Singapore 460117

Closed by : Derek Oh Siong Wee
Svc Consultant :
Remarks : Mr Wong Kian Chong

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2
Inv.date. : 29/01/2019
WIP No. : 51240
Veh.In/Out: 28/01/2019
*Tel.No. : Home: 91135380
Reg.No. : SMF4458B
Reg.date. : 12/11/2018
Mileage : 0
Chassis No: YV1FS40LDJ2470561

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	SOUND DEADENING PAD X M/M	1.0 EA	250.00			250.00	S
--	---------------------------	--------	--------	--	--	--------	---

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour Total	16,330.00
Parts Total	3,908.60
Package Total	0.00

Gross Total.	20,238.60
Net.....	20,238.60
GST @ 7.0%	1,416.70
Total.....	21,655.30
Paid.....	0.00
Please Pay..	21,655.30

GST: S=StdRated; O=OutOfScope; Z=ZeroRated