

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 30/1/2019
VEHICLE NO: SLK5260H
MODEL: MAZDA 3
YEAR: 2017
ACCIDENT DATE: 30/1/2019
TYPE OF CLAIM: TP CLAIM
CLAIM ADVISOR: LOUIS ONG (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
REAR BUMPER <i>repair</i>	1	\$ 879.40
REAR BUMPER CLIPS <i>as</i>	10	\$ 30.00
LH REAR BUMPER RETAINER <i>X</i>	1	\$ 66.50
LH REAR BUMPER REFLECTOR <i>X</i>	1	\$ 188.60
REAR BUMPER DIFFUSER <i>X</i>	1	\$ 435.10
REAR REINFORCEMENT <i>X</i>	1	\$ 356.70
END PANEL	1	REPAIR

TOTAL: \$ 1,956.30
DISCOUNT 20%: \$ 391.26
\$ 1,565.04

S/NET	PRICE
REVERSE SENSOR <i>X</i>	\$ 220.00
	<u>\$ 220.00</u>

LABOUR	PRICE
LABOUR FOR FACILITATE REPAIR - REAR	\$ 800.00 <i>100</i>
TO RESPRAY AFFECTED AREAS - REAR BUMPER	\$ 300.00 <i>200</i>
TO RESPRAY AFFECTED AREAS - END PANEL	\$ 250.00 <i>X</i>
RUST PROOFING	\$ 80.00 <i>X</i>
SUNDARIES	\$ 50.00 <i>X</i>

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 30/1/2019
VEHICLE NO: SLK5260H
MODEL: MAZDA 3
YEAR: 2017
ACCIDENT DATE: 30/1/2019
TYPE OF CLAIM: TP CLAIM
CLAIM ADVISOR: LOUIS ONG (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR X
TO REMOVE AND REFIT REVERSE SENSOR ~~SP~~
TO CHECK AND RECONNECT ALL NECESSARY WIRING

\$	250.00	X
\$	100.00	60
\$	50.00	X
TOTAL: \$	1,880.00	

TOTAL: \$	3,665.04
7% GST: \$	256.55
\$	3,921.59

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue

Hp 90010068

2 days

01/03/19 @0945

Resurvey after repair