

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0130/2019/CL 25-Feb-19 1 of 1 SLN587H Audi A4 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	DOOR WIRE HARNESS <i>snapped</i>	\$ 531.50	<i>425.50</i>
GRAND TOTAL :		\$ 531.50	\$ -


For Premium Automobiles Pte Ltd

Adrian Ling
25/02/19
[Signature]



[Signature]
Authorised Signature

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:54

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice: 85014039	Account: A0006 (T 0)
		Date : 18/07/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
		Order : SLN0587H	
		Term : 30	

Regn No: SLN0587H (V 33344)	Regn Date: 20/04/2017	Mileage: 21140	WIP No.: 41044
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF45HA126031	Engine: CVN 033179	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER LHS FRONT DOOR,RHS FRONT AND REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES.	840.00	1.00	840.00
S	BODYWORK	M: TO DISMANTLE AND RENEW LHS FRONT DOOR,RHS FRONT AND REAR DOORS.TO REPAIR RHS SILL PANEL AND LHS REAR DOOR.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	2000.00	1.00	2,000.00
S	BODYWORK	M: TO RESPRAY RHS FRONT DOOR,RHS REAR DOOR, DOOR HANDLES,RHS SILL PANEL,LHS FRONT DOOR,LHS REAR DOOR AND LHS REAR FENDER	3540.00	1.00	3,540.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK	M: TO SUPPLY STONE CHIP TREATMENT	180.00	1.00	180.00
X	A8W0837210A	(A) (SK) PACKING 25/02	Less 020%	1.00	3.20
X	A8W0837278	(A) (SK) PACKING 25/02	Less 020%	1.00	3.20
X	A8W0971029BJ	(V) (SK) HARNESS 26/02	Less 020%	1.00	531.50
X	A8W0831051D	DOOR	Less 020%	1.00	2152.00
X	A8W5833052C	(A) (SK) DOOR 04/02/19	Less 020%	1.00	2152.00
X	A8W0831052D	(A) (G) DOOR 04/02/19	Less 020%	1.00	2152.00
X	A8K0837199	CLIP	Less 020%	15.00	0.70
X	A8W0837911A	(A) (SK) SEAL 04/02/19	Less 020%	1.00	184.50
X	A8W0837878	COVER	Less 020%	1.00	5.10
X	A8W0837912A	(A) (G) SEAL 04/02/19	Less 020%	1.00	184.50
X	A8W0837206	HANDLE	Less 020%	1.00	34.40
X	A8W5839912A	SEAL	Less 020%	1.00	184.50
X	A8W2837812A	(Ger) SUPPORT	Less 020%	1.00	148.50
X	A8W2837240 GRU	(A) (SK) TRIM 04/02/19	Less 020%	1.00	79.40

Customer Service

Service Appointment	6366 2323
24-hour Breakdown Service	9828 1233
Email	customer.care@premiumauto.com.sa

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLN 587 H

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0130/2019/KK
1 March 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1

total pages

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 1.4 TFSI
Vehicle Chassis No. : WAUZZZF45HA126031
Vehicle Regn No. : SLN 587 H
Vehicle Mileage : 18459 KM
Vehicle Owner : Mr. Wang Yi Li
Certificate No : 2100507480-01
Own Damage Excess : \$642.00 (Inclusive 7%GST)
Accident Date : 27/01/2019
Place : HDB Hub Car Park
Repair Cost : \$ 13,544.83
WIP No. : 41044
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

11:00 am

Date :

2/03/2019