

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 11 Feb 2019

Preliminary Advice

Vehicle No	: SKD3803D	Accident Date	: 28/01/2019
Make	: AUDI Q7	Policy No.	: 1700049946
Assignment Date	: 01/02/2019	Excess	: S\$500.00
Date of Inspection	: 31/01/2019	Est. Duration of Repair	: 10.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

RePAIRer's Estimate (Gross)	:S\$	51,585.00
Revised Amount	:S\$	35,159.00
Check Items (Estimated)	:S\$	9,430.00
Total	:S\$	44,589.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	215,000.00
COE / PARF Rebate	:S\$	96,629.00
Salvage Value	:S\$	
Margin for Repair	:S\$	118,371.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :