

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 07 Feb 2019

## **Preliminary Advice**

Insured Vehicle No	: SGN8660K		
TP Vehicle No	: SME5148U	Accident Date	: 31/01/2019
Make	: HONDA CIVIC	Assignment Date	: 31/01/2019
Date of Inspection	: 01/02/2019	Est. Duration of Repair	: 12 Days
Inspection At	: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,781.77
Revised Amount	:S\$	16,136.26
Check Items (Estimated)	:S\$	461.01
Total	:S\$	16,597.27
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : TP : WP