



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 13/03/2019

### Survey Details:

Date of loss	31-Jan-19
Date of appointment	1-Feb-19
Date of survey	18-Feb-19
Location of survey	RICO 60 AUTO SERVICES PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SJB 4325H
Make and Model	HONDA STREAM 1.8X A
Date of registration	11/1/2008
Excess	
Market Value	\$26,000
Parf Rebate	\$19,231
Nett Loss	\$6,769

### Repair details:

Initial Estimate	\$ 12,623.84
------------------	--------------

### Proposed/Revised repair cost:

Parts	\$ 2,461.10
Check items (estimate)	\$ -
Labour	\$ 2,080.00
<b>Total</b>	<b>\$ 4,541.10</b>
<b>Lump Sum(if applicable)</b>	<b>\$ 4,500.00</b>

Number of days for repair	<u>5DAYS</u>
---------------------------	--------------



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

*Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best.*

**Mandate:**

Liability(TP)		100%
Proposed repair cost	\$	4,815.00
Loss of use	\$	-
Loss of rental	\$	720.00
Loss of income	\$	-
LTA search fees	\$	36.45
Others	\$	-
<b>Proposed Total</b>	<b>\$</b>	<b>5,571.45</b>