

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Monday, 30 September 2019 8:25 AM  
**To:** Janet Tan  
**Cc:** Admin A  
**Subject:** <Seek Mandate>EQ ref : TBA \*LKK ref : CC4/EQI19002132/R1pb3q2 [ACCIDENT INVOLVING GBE2324C(EQ-OI) & SKM5207P(TP) ON 28/01/2019]  
**Attachments:** LKK Survey Report & Photos.pdf; TP LOD & Docs.pdf

EQ ref : **TBA**  
LKK ref : CC4/EQI19002132/R1pb3q2

Dear Sirs/Madam,

### **ACCIDENT INVOLVING GBE2324C(EQ-OI) & SKM5207P(TP) ON 28/01/2019**

We refer to the above matter.

It is a head-to-rear collision. Liability is down against our insured driver.

We seek your approval to offer Third Party repairer "**PROGRESSIVE CAR CARE PTE LTD**" at \$ (all-in).

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 16,673.28	\$10,091.49
2. Loss of Rental (36days)	\$ 3,700.00	\$ 1,100.00 (11days x \$100.00)
3. LTA/ GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 20,375.28	<b><u>\$11,193.49</u></b>

Surveyor recommended 6 days for repair + 2Sunday + 2PH + 1PRS = 11days.

Enclosed here with all the relevant documents for your perusal.

**Kindly let us have your approval/instruction.**

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)