

Juane

cc 6, LCR, 900 2134, Upay

LKR
TAG

MAYNUS

ASSIGNMENT

DGI

11/2/19

Date / Time:

11/2/19

Registered in Merimen:

11/2/19

Pre-assign / CCU / FTE



Insured Vehicle No.

SLB 4230 Z

Name of Insured

LCR PIC

Insured Tel No.

HP:

Excess Sec II:SS

D.O.A:

30/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L- YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Upper Sgrou Rd

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SLT800K



INSRS:

WSP:

Tel:

Liability:

RMKS:

Tan Lim

11986



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

DATE / PIC

STAGE

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call Of:

After call ltr to OI:

Documentation Check List: Handler: Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with Johnson

Email

Call

Final Liability:

%

(W)

(Agreed / Adjusted) BOLA S/N No.: 15.

Repair Cost:

S\$

3531.00

Loss of Rental (LOR):

S\$

-

(days)

Loss of Use (LOU):

S\$

400.00

(S)

100

x 4

(days)

Loss of Income (LOI):

S\$

-

(S)

-

x

(days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

7.49

Medical:

S\$

-

Disbursement:

S\$

-

Legal Cost

S\$

-

Total:

S\$

3930.49

Global Sum S\$: 3930.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee:

S\$

3930.00

Name 1:

Tan Lim Motor Pte Ltd

Payee 2: (Strike if N/A)

S\$

-

Name 2:

Payee 3: (Strike if N/A)

S\$

-

Name 3:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: S-LTBOOKat Workshop m/s Zurbin

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

OAC Accident Report: _____ Consistent? : Yes or No

GLS / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S-LTBOOK Yr Regn: 9/17Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: BMW 530i 5.0c.c 1998Colour: Black A/C: Insured / Std / NI / NASp. Reading: 13566 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAJA520X0G885470Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/45-R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MTC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 30/1/19

Survey held at _____

Rear

R/Bal. 7 mmL/Bal. 7 mmD.O.I. 1/2/19

Des. of Damages: Frl / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21.1.19 8:27g
US \$ 33w cred \$ 2676.19/456

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

____ \$ + RS ____ \$

Photos _____

Others _____

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$ _____)



陳林峰摩打有限公司

TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLB4230Z

Date of Accident : 30 January 2019

Messrs Eng Soon Auto Pte Ltd

Date : 14 February 2019

Estimate To Repair SLT800K - B.M.W 530i SE AUTO

Chassis No : WBAJA520X0G885470

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	rear bumper <i>Deep cut</i>	\$ 1,503.70 ✓
02	10 ps	rear bumper clip @ \$3.90 <i>all</i>	\$ 39.00 ✓
03	1 pc	rear bumper side retainer RH <i>11x</i>	\$ 98.50 X
04	1 pc	rear door RH <i>10/200</i>	\$ 1,863.50 ✓
05	1 pc	rear door outer moulding RH <i>11x</i>	\$ 124.40 X
Less 10 %			\$ 3,629.10
			\$ 362.91
			\$ 3,266.19
<u>SPECIAL NETT ITEMS</u>			
06	1 pc	rear tyre <i>SVC</i>	\$ 450.00 X
			\$ 450.00
<u>LABOUR & MISC. CHARGES</u>			
01		To transfer of tyre, rim and on wheel balancing.	\$ -80.00 X
02		To check steering geometry and computer wheel alignment.	\$ -80.00 X
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00 400 400
04		Putty and spray painting of rear bumper, rear fender RH, rear door RH and front door RH.	\$ 1,200.00 800 800
			\$ 2,260.00
Total			\$ 5,976.19
<p><i>parts - \$ 3466.20</i></p> <p><i>- 10%</i></p> <p><i>\$ 3065.58</i></p> <p><i>LB - \$ 1200.00</i></p> <p><i>\$ 4265.58</i></p>			<p><i>P-33089</i></p> <p><i>102</i></p> <p><i>2978.01</i></p> <p><i>4178.01</i></p> <p><i>3342.</i></p>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5198G
Vehicle Details	
Vehicle No.:	SLT800K
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Feb 2019
Vehicle Make:	B.M.W.
Vehicle Model:	530I SE
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	10539915B48B20B
Chassis No.:	WBAJA520X0G885470
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$53,103.00
Original Registration Date:	22 Sep 2017
First Registration Date:	22 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$62,586.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Sep 2027
PARF Rebate Amount:	\$46,939.00
Intended COE Rebate Details	
COE Expiry Date:	21 Sep 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$49,012.00
COE Rebate Amount:	\$42,340.00
Total Rebate Amount:	\$89,279.00

The information contained herein is correct as at 01 Feb 2019

OK

AlGAsia Insured's Veh No : SLB4230Z
Date of Accident : 30 January 2019



陳林峰摩私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs Eng Soon Auto Pte Ltd

Date : 01 February 2019

Marcus LKK 01/02/19

0936hrs

Estimate To Repair SLT800K - B.M.W 530i SE AUTO
Chassis No : WBAJA520X0G885470

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper <i>Deepan</i>	\$ 0.00
02	10 ps	rear bumper clip @ \$.00 <i>10</i>	\$ 0.00
03	1 pc	rear bumper side retainer RH <i>11 X</i>	\$ 0.00
04	1 pc	rear door RH <i>10/34</i>	\$ 0.00
05	1 pc	rear door outer moulding RH <i>11 X</i>	\$ 0.00
		Less 10 %	\$ 0.00
			\$ 0.00
		<u>SPECIAL NETT ITEMS</u>	
06	1 pc	rear tyre <i>800 X</i>	\$ 450.00
			\$ 450.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To transfer of tyre, rim and on wheel balancing.	\$ 17 80.00 <i>X</i>
02		To check steering geometry and computer wheel alignment.	\$ 17 80.00 <i>X</i>
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00 <i>400</i>
04		Putty and spray painting of rear bumper, rear fender RH, rear door RH and front door RH.	\$ 1,200.00 <i>800</i>
		<i>not Added</i>	\$ 2,260.00
		<i>1/5</i>	
		<i>3 day.</i>	
		<i>1/2/19</i>	
		<i>Whynb. Atty 14-</i>	
		Total	\$ 2,710.00



陳林摩打私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLB4230Z
Date of Accident : 30 January 2019

Messrs Eng Soon Auto Pte Ltd

Date : 01 February 2019

Marcus LKK

01/02/19

0936105

Estimate To Repair SLT800K - B.M.W 530I SE AUTO

Chassis No : WBAJA520X0G885470

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper <i>Deepan</i>	\$ 0.00
02	10 ps	rear bumper clip @ \$.00 <i>ren</i>	\$ 0.00
03	1 pc	rear bumper side retainer RH <i>11X</i>	\$ 0.00
04	1 pc	rear door RH <i>10/24</i>	\$ 0.00
05	1 pc	rear door outer moulding RH <i>11X</i>	\$ 0.00
		Less 10 %	\$ 0.00
			\$ 0.00
		<u>SPECIAL NETT ITEMS</u>	
06	1 pc	rear tyre <i>suc X</i>	\$ 450.00
			\$ 450.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To transfer of tyre, rim and on wheel balancing.	\$ 17 80.00 <i>X</i>
02		To check steering geometry and computer wheel alignment.	\$ 17 80.00 <i>X</i>
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00 <i>400</i>
04		Putty and spray painting of rear bumper, rear fender RH, rear door RH and front door RH.	\$ 1,200.00 <i>800</i>
		<i>not Afford</i>	\$ 2,260.00
		<i>ren</i>	
		Total	\$ 2,710.00

LKK Auto Consultants notice notify the Repairer of the following:

- To involve vehicle after spray painting
- To check damaged parts during resurvey
- Price prices are subject to confirmation
- To repair money is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4/58
327.
1/2/19
Whight. Affly

Hsiao Tong (LKKAUTO)

From: Boyogan, Joane <Joane.Boyogan@aig.com>
Sent: Monday, 4 March 2019 8:19 AM
To: Hsiao Tong (LKKAUTO)
Subject: RE: AIG Ref: 4621507384SG *LKK REF: CC6/LCR19002134/Upa3 [ACCIDENT INVOLVING SLB 4230Z(OI) & SLT 800K(TP) ON 30/01/2019]

Dear Hsiao Tong,

With reference to your email of 20 Feb 2019

In view of third party's video footage, please proceed to DS with third party's repairer


Thank you

Regards,

Joane Boyogan
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120

Tel +65 64191898
joane.boyogan@aig.com | www.aig.sg



AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.
[Click here to find out more](#)

Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Saturday, March 02, 2019 9:40 AM
To: Boyogan, Joane
Subject: RE: AIG Ref: 4621507384SG *LKK REF: CC6/LCR19002134/Upa3 [ACCIDENT INVOLVING SLB 4230Z(OI) & SLT 800K(TP) ON 30/01/2019]

Hi Joane,

We refer to our below email.

Kindly advise if we may proceed DS.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Wednesday, 20 February 2019 5:02 PM

To: Boyogan, Joane (Joane.Boyogan@aig.com) <Joane.Boyogan@aig.com>

Subject: AIG Ref: 4621507384SG *LKK REF: CC6/LCR19002134/Upa3 [ACCIDENT INVOLVING SLB 4230Z(OI) & SLT 800K(TP) ON 30/01/2019]

Hi Joane,

We refer to the above matter.

We have uploaded a copy of third party's video in Merimen for your easy reference.

From third party's video, it showed that our insured driver changed lane and collided with third party who was travelling straight within his lane at that point in time.

We are of the view that liability is not in our insured driver's favour. BOLA \$15 is applicable. We will proceed to settle the matter at best with third party.

Kindly let us have your comments/ instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into

which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 4 March 2019 8:23 AM
To: 'Caymen'; 'Johnson Chua'
Cc: Admin A; Joy Irene (LKKAuto); 'Wei Shong'
Subject: RE: Check Liability - TLM Ref: TP031012019; LKK REF: CC6/LCR19002134/Upa3; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Caymen <caymen@tlmotor.com.sg>
Sent: Saturday, 2 March 2019 9:56 AM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; 'Johnson Chua' <johnson.chua@tlmotor.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; 'Wei Shong' <wei.shong@tlmotor.com.sg>
Subject: Check Liability - TLM Ref: TP031012019; LKK REF: CC6/LCR19002134/Upa3; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Dear Hsiao Tong,

We refer to your email below.

Please reply to us on this matter.

Thank you.

Regards,



Caymen
caymen@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd
1 Defu Lane 6
Singapore 539365
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Motor Pte Ltd. Any use of the information (including but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]

Sent: 20, Feb, 2019 5:02 PM

To: Johnson Chua <johnson.chua@tlmotor.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; 'Caymen' <caymen@tlmotor.com.sg>; 'Wei Shong' <wei.shong@tlmotor.com.sg>; Joy Irene (LKKAuto) <joyirene@lkkauto.com>

Subject: RE: Check Liability - TLM Ref: TP031012019; LKK REF: CC6/LCR19002134/Upa3; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Without Prejudice

Dear Johnson,

Thank you for your video.

We will look into the matter and get back to you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Johnson Chua <johnson.chua@tlimotor.com.sg>

Sent: Wednesday, 20 February 2019 2:49 PM

To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; 'Caymen' <caymen@tlimotor.com.sg>; 'Wei Shong' <wei.shong@tlimotor.com.sg>

Subject: Check Liability - TLM Ref: TP031012019; LKK REF: CC6/LCR19002134/Upa3; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Importance: High

Dear Joy,

We refer to your email below.

We enclose a copy of the accident video footage for your attention.

From the accident video footage, it showed that your principal's insured cut lane and collided onto our client's vehicle while our client's driver was travelling straight within his lane at that point in time.

In view that your principal's insured is the proximate cause of the accident, please confirm within **FIVE** (5) days whether AIG is agreeable to direct settle with us at 100% liability for this accident.

Regards,



Johnson Chua
johnson.chua@tlimotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd
1 Defu Lane 6
Singapore 539365
<http://www.tlimotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Motor Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Joy Irene (LKKAuto) [<mailto:JoyIrene@lkkauto.com>]

Sent: Wednesday, 20 February 2019 9:05 AM

To: Caymen <caymen@tlimotor.com.sg>; Admin A <admin-a@lkkauto.com>

Cc: 'Johnson Chua' <johnson.chua@tlimotor.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Subject: RE: Check Liability - TLM Ref: TP031012019; AIG Ref: TBA; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019 *** LKK REF: CC6/LCR19002134/Upa3

WITHOUT PREJUDICE

LKK REF: CC6/LCR19002134/Upa3 – Hsiao Tong

Dear Caymen,

Liability unclear. Our insured driver's report below.

Kindly send us any available evidence you have for our review.

Thank you.

Upper Seayoon Rd.

SKETCH PLAN

(A) SLD4230E
(B) S4T800K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving slowly along Upper Seayoon Rd. I spent left from 2nd lane right following into the 3rd lane. A few seconds later suddenly vehicle B overtake me from the left and collides into my front left position then it immediately brake my car but after collision vehicle B still keep moving to stop diagonally to the right ahead of my car. Vehicle didn't brake and stop but continuing moving to increase the scratches of my car. Vehicle B has offer to provide settle at the point of accident, however today morning I received a call from Vehicle B and he informed me just proceed with insurance claim instant. Please I do report. I have a female passenger in the car during accident. When I stopped into 3rd lane I was the cars lane from Vehicle B.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Caymen [<mailto:caymen@tlmotor.com.sg>]
Sent: Wednesday, 20 February 2019 8:52 AM
To: Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Cc: 'Johnson Chua' <johnson.chua@tlmotor.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Subject: RE: Check Liability - TLM Ref: TP031012019; AIG Ref: TBA; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019 *** LKK REF: CC6/LCR19002134/Upa3

Dear Joy,

Please let us have your reply on the liability.

Thank you.

Regards,



Caymen

caymen@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte L

1 Defu Lane 6
Singapore 539365
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan L Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]

Sent: 18, Feb, 2019 3:59 PM

To: Caymen <caymen@tlmotor.com.sg>; Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

Cc: 'Johnson Chua' <johnson.chua@tlmotor.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Check Liability - TLM Ref: TP031012019; AIG Ref: TBA; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019 *** LKK REF: CC6/LCR19002134/Upa3

Dear Caymen,

Thank you for your email.

By copy to Joy

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Caymen <caymen@tlmotor.com.sg>

Sent: Monday, 18 February, 2019 2:47 PM

To: Admin A <admin-a@lkkauto.com>

Cc: 'Johnson Chua' <johnson.chua@tlmotor.com.sg>

Subject: Check Liability - TLM Ref: TP031012019; AIG Ref: TBA; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Dear Sir/Mdm,

We refer to the above matter.

Survey has been done on 01.02.2019.

Please reply within **five** (5) days whether AIG is agreeable to direct settle with us at 100% liability for this accident and advise on the PIC.

Thank you.

Regards,



Caymen
caymen@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte L
1 Defu Lane 6
Singapore 539365
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan L. Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

Hsiao Tong (LKKAUTO)

From: Johnson Chua <johnson.chua@tlmotor.com.sg>
Sent: Monday, 11 March 2019 5:15 PM
To: Hsiao Tong (LKKAUTO); Admin A; Joy Irene (LKKAUTO)
Cc: 'Wei Shong'
Subject: Letter of Demand - TLM Ref: TP031012019; LKK REF: CC6/LCR19002134/Upa3; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019
Attachments: LOD - SLT800K.pdf
Importance: High

Dear All,

We refer to the above matter.

We enclose a copy of our client's Letter of Demand together with the supporting documents for your attention.

Please acknowledge upon receipt and make your offer to us within the next fourteen (14) days.

Regards,



Johnson Chua
johnson.chua@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd
1 Defu Lane 6
Singapore 539365
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan L. Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place all programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Monday, 4 March 2019 8:23 AM
To: Caymen <caymen@tlmotor.com.sg>; 'Johnson Chua' <johnson.chua@tlmotor.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com>; 'Wei Shong' <wei.shong@tlmotor.com.sg>
Subject: RE: Check Liability - TLM Ref: TP031012019; LKK REF: CC6/LCR19002134/Upa3; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Caymen <caymen@tlmotor.com.sg>

Sent: Saturday, 2 March 2019 9:56 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; 'Johnson Chua' <johnson.chua@tlmotor.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; 'Wei Shong' <wei.shong@tlmotor.com.sg>

Subject: Check Liability - TLM Ref: TP031012019; LKK REF: CC6/LCR19002134/Upa3; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Dear Hsiao Tong,

We refer to your email below.

Please reply to us on this matter.

Thank you.

Regards,



Caymen

caymen@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd

1 Defu Lane 6
Singapore 539365
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Motor Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: 20, Feb, 2019 5:02 PM

To: Johnson Chua <johnson.chua@tlmotor.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; 'Caymen' <caymen@tlmotor.com.sg>; 'Wei Shong' <wei.shong@tlmotor.com.sg>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

Subject: RE: Check Liability - TLM Ref: TP031012019; LKK REF: CC6/LCR19002134/Upa3; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Without Prejudice

Dear Johnson,

Thank you for your video.

We will look into the matter and get back to you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Johnson Chua <johnson.chua@tlmotor.com.sg>

Sent: Wednesday, 20 February 2019 2:49 PM

To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; 'Caymen' <caymen@tlmotor.com.sg>; 'Wei Shong' <wei.shong@tlmotor.com.sg>

Subject: Check Liability - TLM Ref: TP031012019; LKK REF: CC6/LCR19002134/Upa3; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Importance: High

Dear Joy,

We refer to your email below.

We enclose a copy of the accident video footage for your attention.

From the accident video footage, it showed that your principal's insured cut lane and collided onto our client's vehicle while our client's driver was travelling straight within his lane at that point in time.

In view that your principal's insured is the proximate cause of the accident, please confirm within **FIVE** (5) days whether AIG is agreeable to direct settle with us at 100% liability for this accident.

Regards,



Johnson Chua
johnson.chua@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte L
1 Defu Lane 6
Singapore 539365
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Motor Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Joy Irene (LKKAUTO) [<mailto:JoyIrene@lkkauto.com>]
Sent: Wednesday, 20 February 2019 9:05 AM
To: Caymen <caymen@tlmotor.com.sg>; Admin A <admin-a@lkkauto.com>
Cc: 'Johnson Chua' <johnson.chua@tlmotor.com.sg>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Subject: RE: Check Liability - TLM Ref: TP031012019; AIG Ref: TBA; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019 *** LKK REF: CC6/LCR19002134/Upa3

WITHOUT PREJUDICE

LKK REF: CC6/LCR19002134/Upa3 – Hsiao Tong

Dear Caymen,

Liability unclear. Our insured driver's report below.


Kindly send us any available evidence you have for our review.

Thank you.

SKETCH PLAN

(A) SLB4230Z

(B) SLT800K



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving slowly along Upper Serangoon Rd. I signal left from 2nd lane before following into the 3rd lane. A few seconds later suddenly vehicle B overtake me from the left and collided into my front left position then it immediately brake my car but after collision vehicle B still keep moving to stop diagonally to the right in front of my car. Vehicle didn't brake and keep keep continuing moving to increase the damages of my car. Vehicle B has offer to provide CCTV at the point of accident. However today morning I received a call from vehicle B and he informed me just proceed with insurance claim without. Hence I do report to have a female passenger in the car during accident. When I followed into 3rd lane I was the cause from vehicle B.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Caymen [<mailto:caymen@tlmotor.com.sg>]

Sent: Wednesday, 20 February 2019 8:52 AM

To: Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <joyirene@lkkauto.com>

Cc: 'Johnson Chua' <johnson.chua@tlmotor.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Subject: RE: Check Liability - TLM Ref: TP031012019; AIG Ref: TBA; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019 *** LKK REF: CC6/LCR19002134/Upa3

Dear Joy,

Please let us have your reply on the liability.

Thank you.

Regards,



Caymen
caymen@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd
1 Defu Lane 6
Singapore 539365
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Motor Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]

Sent: 18, Feb, 2019 3:59 PM

To: Caymen <caymen@tlmotor.com.sg>; Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

Cc: 'Johnson Chua' <johnson.chua@tlmotor.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Check Liability - TLM Ref: TP031012019; AIG Ref: TBA; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019 *** LKK REF: CC6/LCR19002134/Upa3

Dear Caymen,

Thank you for your email.

By copy to Joy

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Caymen <caymen@tlmotor.com.sg>

Sent: Monday, 18 February, 2019 2:47 PM

To: Admin A <admin-a@lkkauto.com>

Cc: 'Johnson Chua' <johnson.chua@tlmotor.com.sg>

Subject: Check Liability - TLM Ref: TP031012019; AIG Ref: TBA; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Dear Sir/Mdm,

We refer to the above matter.

Survey has been done on 01.02.2019.

Please reply within **five** (5) days whether AIG is agreeable to direct settle with us at 100% liability for this accident and advise on the PIC.

Thank you.

Regards,



Caymen
caymen@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte L
1 Defu Lane 8
Singapore 539365
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan L. Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 1 Defu Lane 6 Singapore 539365

Tel: 6858 5151 Fax: 6858 0877

Our Ref : TP031012019
Your Ref : CCB/LCR19002134 / Upa3

Date : 01.03.2019

Claims Department - AIG ASIA PACIFIC
c/o LKK Auto Consultants

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING SLT800K & SLB4230Z ON 30.01.2019

We refer to the above accident.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

☐ Original survey report/ _____ copies of photographs

☒ Original Tax-invoice number

☐ Original rental invoice number

☒ SAS / AS & IS / police report

☐ police result

☐ Certificate Of Insurance

☒ Vehicle search result

☒ Authorisation To Act

☐ _____

*Survey under insurance instruction -

a)	Cost of repair (inclusive GST)	\$	3,531.00 ✓
b)	Survey fees / Photographs as per request	\$	
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$	7.49
d)	Loss of hire / use / rental / earnings / rental fees [4150 x 4 days]	\$	600.00 fw (4x14)
e)	Scene photographs	\$	
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$	
g)	Admin fee	\$	
Total		\$	4,138.49

* Driver's injury and other losses exclude in this claim.

Please acknowledge receipt of this letter within 14 days.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Johnson Chua

Email: johnson.chua@tlmotor.com.sg

Hsiao Tong (LKKAUTO)

From: Johnson Chua <johnson.chua@tlmotor.com.sg>
Sent: Monday, 6 May 2019 3:02 PM
To: Hsiao Tong (LKKAUTO); Admin A
Cc: 'Wei Shong'
Subject: TLM Ref: TP031012019; LKK REF: CC6/LCR19002134/Upa3; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Importance: High

Dear Hsiao Tong,

We refer to your email below.

Please forward the Discharge Voucher to us.

Regards,



Johnson Chua
johnson.chua@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd
1 Defu Lane 6
Singapore 539365
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Motor Pte Ltd. Any use of the information (including but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place a program, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Wednesday, 1 May 2019 1:57 PM
To: Johnson Chua <johnson.chua@tlmotor.com.sg>
Cc: 'Wei Shong' <wei.shong@tlmotor.com.sg>; Admin A <admin-a@lkkauto.com>
Subject: RE: Letter of Demand - TLM Ref: TP031012019; LKK REF: CC6/LCR19002134/Upa3; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We propose settlement at a global sum of \$3,930.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Johnson Chua <johnson.chua@tlimotor.com.sg>

Sent: Monday, 11 March 2019 5:15 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

Cc: 'Wei Shong' <wei.shong@tlimotor.com.sg>

Subject: Letter of Demand - TLM Ref: TP031012019; LKK REF: CC6/LCR19002134/Upa3; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Importance: High

Dear All,

We refer to the above matter.

We enclose a copy of our client's Letter of Demand together with the supporting documents for your attention.

Please acknowledge upon receipt and make your offer to us within the next fourteen (14) days.

Regards,



Johnson Chua
johnson.chua@tlimotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd
1 Defu Lane 6
Singapore 539365
<http://www.tlimotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Motor Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place a program, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]

Sent: Monday, 4 March 2019 8:23 AM

To: Caymen <caymen@tlimotor.com.sg>; 'Johnson Chua' <johnson.chua@tlimotor.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; 'Wei Shong' <wei.shong@tlimotor.com.sg>

Subject: RE: Check Liability - TLM Ref: TP031012019; LKK REF: CC6/LCR19002134/Upa3; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Caymen <caymen@tlmotor.com.sg>

Sent: Saturday, 2 March 2019 9:56 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; 'Johnson Chua' <johnson.chua@tlmotor.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; 'Wei Shong' <wei.shong@tlmotor.com.sg>

Subject: Check Liability - TLM Ref: TP031012019; LKK REF: CC6/LCR19002134/Upa3; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Dear Hsiao Tong,

We refer to your email below.

Please reply to us on this matter.

Thank you.

Regards,



Caymen
caymen@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd
1 Defu Lane 6
Singapore 539365
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Motor Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place a program, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]

Sent: 20, Feb, 2019 5:02 PM

To: Johnson Chua <johnson.chua@tlmotor.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; 'Caymen' <caymen@tlmotor.com.sg>; 'Wei Shong' <wei.shong@tlmotor.com.sg>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

Subject: RE: Check Liability - TLM Ref: TP031012019; LKK REF: CC6/LCR19002134/Upa3; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Without Prejudice

Dear Johnson,

Thank you for your video.

We will look into the matter and get back to you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Johnson Chua <johnson.chua@tlmotor.com.sg>

Sent: Wednesday, 20 February 2019 2:49 PM

To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; 'Caymen' <caymen@tlmotor.com.sg>; 'Wei Shong' <wei.shong@tlmotor.com.sg>

Subject: Check Liability - TLM Ref: TP031012019; LKK REF: CC6/LCR19002134/Upa3; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Importance: High

Dear Joy,

We refer to your email below.

We enclose a copy of the accident video footage for your attention.

From the accident video footage, it showed that your principal's insured cut lane and collided onto our client's vehicle while our client's driver was travelling straight within his lane at that point in time.

In view that your principal's insured is the proximate cause of the accident, please confirm within **FIVE (5) days** whether AIG is agreeable to direct settle with us at 100% liability for this accident.

Regards,



Johnson Chua
johnson.chua@tlimotor.com.sg

O: +65 6858 5151
F: +65 6858 0877

Tan Lim Motor Pte Ltd
1 Defu Lane 6
Singapore 539365
<http://www.tlimotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Motor Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place a program, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Joy Irene (LKKAuto) [<mailto:JoyIrene@lkkauto.com>]

Sent: Wednesday, 20 February 2019 9:05 AM

To: Caymen <caymen@tlimotor.com.sg>; Admin A <admin-a@lkkauto.com>

Cc: 'Johnson Chua' <johnson.chua@tlimotor.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Subject: RE: Check Liability - TLM Ref: TP031012019; AIG Ref: TBA; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019 *** LKK REF: CC6/LCR19002134/Upa3

WITHOUT PREJUDICE

LKK REF: CC6/LCR19002134/Upa3 – Hsiao Tong

Dear Caymen,


Liability unclear. Our insured driver's report below.

Kindly send us any available evidence you have for our review.

Thank you.

SKETCH PLAN

- (A) SLB4230Z
(B) SLT800K



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving slowly along Upper Seayoon Rd. I spent left from 2nd lane before following into the 3rd lane. A few seconds later suddenly vehicle B overtake me from the left and collided into my front left position then it immediately brake my car but with collision vehicle B still keep moving to stop diagonally to the right in front of my car. Vehicle B didn't brake and stop but continuing moving to increase the scratches of my car. Vehicle B has offer to private settle at the point of accident. However today morning I received a call from vehicle B and he informed me just proceed with insurance claim instant. Hence I do report & here a female passenger in the car during accident. When I follow into 3rd lane I was 100m away from vehicle B.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Caymen [<mailto:caymen@tlmotor.com.sg>]
Sent: Wednesday, 20 February 2019 8:52 AM
To: Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Cc: 'Johnson Chua' <johnson.chua@tlmotor.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Subject: RE: Check Liability - TLM Ref: TP031012019; AIG Ref: TBA; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019 *** LKK REF: CC6/LCR19002134/Upa3

Dear Joy,

Please let us have your reply on the liability.

Thank you.

Regards,



Caymen
caymen@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd
1 Defu Lane 6
Singapore 539365
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Motor Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place a program, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]
Sent: 18, Feb, 2019 3:59 PM
To: Caymen <caymen@tlmotor.com.sg>; Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Cc: 'Johnson Chua' <johnson.chua@tlmotor.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: RE: Check Liability - TLM Ref: TP031012019; AIG Ref: TBA; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019 *** LKK REF: CC6/LCR19002134/Upa3

Dear Caymen,

Thank you for your email.

By copy to Joy

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Caymen <caymen@tlmotor.com.sg>
Sent: Monday, 18 February, 2019 2:47 PM
To: Admin A <admin-a@lkkauto.com>
Cc: 'Johnson Chua' <johnson.chua@tlmotor.com.sg>
Subject: Check Liability - TLM Ref: TP031012019; AIG Ref: TBA; Accident involving SLT800K (TLM) & SLB4230Z (AIG) on 30.01.2019

Dear Sir/Mdm,

We refer to the above matter.

Survey has been done on 01.02.2019.

Please reply within **five** (5) days whether AIG is agreeable to direct settle with us at 100% liability for this accident and advise on the PIC.

Thank you.

Regards,



Caymen

caymen@tlmotor.com.sg

O. +85 6858 5151

F. +65 6858 0877

Tan Lim Motor Pte I

1 Defu Lane 6

Singapore 539365

<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan L Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place a programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Saturday, 2 March 2019 9:39 AM
To: 'Insurance LCR SG'; 'Eileen, May Hwee Yap'
Subject: ACCIDENT INVOLVING SLB 4230Z(AIG) AND SLT 800K ON 30/01/2019
Attachments: SLT800K 30.01.2019.mp4

Your Ref: **SLB 4230Z**
Our Ref: CC6/LCR19002134/Upa3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLB 4230Z(AIG) AND SLT 800K ON 30/01/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SLT 800K against your insurance policy.

We have reviewed the matter and based on all available information at hand for the accident, we are of the view that we do not have a good defense towards the claim submitted by the owner of SLT 800K. Kindly refer to the attached video footage from SKT 800K for your easy reference. As per video footage, we could observe that third party was driving straight on his own lane, your vehicle changed lane and collided with third party who was travelling straight within his lane at that point in time. As such, we are of the view that liability is not in your driver's favour and we shall proceed to negotiate for an amicable settlement of the third party claim at best to avoid further litigation, which would escalate to even more cost.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Note: This video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Eng Soon Auto Pte Ltd ("the third party claimant")
of 13 Koki Bukit Road 3 Eastpoint Terrace S417833 (address),
owner of SLT800k (vehicle no.) hereby authorize
Tan Lim Motor Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SLT800k that was
damaged pursuant to the accident which occurred on 30.01.2019 (date) along
Upper Serangoon Road (location)
involving vehicle no/s SLB4230Z ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 31st day of January (month) 20 19 (year)



Signed by "the third party claimant"



Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, TAN LIM MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3,930.00 (Global Sum) for vehicle no. SLT 800K that was damaged pursuant to the accident which occurred on 30/01/2019 (date) along UPPER SERANGOON ROAD involving vehicle no/s SLB 4230E.

This is pursuant to the inspection conducted on 01/02/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner ENG SOON AUTO PTE LTD (the third party claimant") of vehicle no. SLT 800K make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLT 800K (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 15th (day) of MAY (month) 2019 (year)



CCS

Signed by appointed surveyor



Johnson Chua

Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



TAX-INVOICE
NUMBER: TP0219/018

(Please quote our reference number: TP031012019 for payment)

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD


Eng Soon Auto Pte Ltd

Date: 27/02/2019

Vehicle No: SLT 800K
Model: B.M.W 530I

Description	Amount
To lump sum repair as recommended by surveyor.	\$3,300.00

Sub Total	\$3,300.00
Add 7% GST	\$231.00
Total	\$3,531.00


Tan Lim Motor Pte Ltd

No. 1 Defu Lane 6 Singapore 539365
~~No. 51 Defu Lane 10 Singapore 539216~~
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlmotor.com.sg www.tlmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

Enquire Vehicle & Owner Information (Vehicle No. SLB4230Z As At 30 Jan 2019 / 18:30:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: SR5TP.SLT800K.TLM

Current Owner Details

Owner ID Type: Company

Owner ID: 201624597K

Owner Name: LCRF PTE LTD

Registered Address Type: Private Residential (non-Condo Apt / non-House)

Registered Block/House No.: 29

Registered Street Name: PAYA LEBAR ROAD

Registered Unit No.: # 01 - Q3

Registered Building Name: -

Registered Postal Code: 409005

Current Vehicle Details

Vehicle No.: SLB4230Z

Make Description/Model: TOYOTA / COROLLA AXIO 1.5G A

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

































CLAIM SUBFOLDER TRACKING















Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Feb 2019 Edit Reg		01 Feb 2019 00:00 Edit Adj Rpt	\$53,300.00 Edit Estimates	\$53,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF Pte Ltd. Co. Reg. No.: 201624597K								
Main Claimant:	ENG SOON AUTO PTE LTD. Co. Reg. No.: 199705198G								
Vehicle Reg. No.:	SLT800K	Date of Loss:	30/01/2019 18:00 - :59 [16 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4621507384SG	Policy/Cover Note No.:	0999994764 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLB4230Z	Policy No. (Claimant):	1700055429-01						
		Excess:							
Repairer:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6, 539365 Defu Lane - Tel: 6858 5151								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/02/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (07/02/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT800K (4621507384SG)
[SLB4230Z]
TP
ENG SOON AUTO PTE LTD
Jan 30 2019 6:00PM
[LCRF Pte Ltd]
Tan Lim Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/02/19 16:56	SLT 800K vs SLB 4230Z - TP VIDEO	 Load MP4	
Letters/Correspondences				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit	
Photos/Images				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
2	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
3	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
4	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
5	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
6	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
7	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
8	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
9	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
10	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
11	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
12	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
13	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
14	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
15	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
16	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
17	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
18	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
19	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
20	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
21	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
22	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
23	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
24	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
25	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
26	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
27	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
28	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
29	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
30	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
32	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
33	01/02/19 15:21	General View	 Load JPG	<input checked="" type="checkbox"/>
34	01/02/19 15:22	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
35	01/02/19 15:22	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/02/19 18:32	TP GIA REPORT	 Load PDF	
2	16/02/19 18:32	TP ESTIMATE - MARKED	 Load PDF	
3	02/03/19 09:33	TP ESTIMATE_MARKED(FINAL)	 Load PDF	
4	28/05/19 09:09	WORKSHOP INVOICE	 Load PDF	
5	28/05/19 09:09	AUTHORISATION TO ACT FORM	 Load PDF	
6	28/05/19 09:09	Release Voucher	 Load PDF	
7	28/05/19 09:09	LTA SEARCH	 Load PDF	
8	28/05/19 09:09	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	07/02/19 13:50	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLB4230Z (Insd veh)	Model:	BMW 530I 2.0 SE (A)
	SLT800K (TP veh)		
Date of Accident:	30/01/2019		

Global Sum Settlement	: <input checked="" type="checkbox"/> [X] Yes	: <input type="checkbox"/> [] No	
Repair Estimate	: \$		6,394.52
Final Repair Cost	: \$		3,930.00
Loss of Use	: \$		4.00 days at \$100.00 per day
Rental (if any)	: \$		days
LTA / GIA Search Fee	: \$		
Others:	: \$		
	: \$		
Final Settlement Sum (Global Sum)	: \$		3,930.00

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	: \$	3,930.00
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

28 May
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No: 199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR19002134/UPA3Q2

Date: 28/05/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994764
Claimant Vehicle No : SLT800K **Insured Vehicle No :** SLB4230Z
 Date of Loss: 30/01/2019 Nature of Claim: TP Claim No: 4621507384SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT800K**
 Make & Model: BMW 530i, 2.0 SE (A) Engine No: 10539915B48B20B
 Reg. Date: 22/09/2017 (Man. Year: 2017) Chassis No: WBAJA520X0G885470
 Colour: Black Odometer: 13566 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,716.19	2,978.01	738.18	19.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,200.00	1,060.00	46.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,976.19	4,178.01	1,798.18	30.09
Approved Total (Overridden) (S\$)		3,300.00		
(S\$)	5,976.19	3,300.00	2,676.19	44.78
+ GST 7.00/7.00% (S\$)	418.33	231.00	187.33	44.78
Nett Amount (S\$)	6,394.52	3,531.00	2,863.52	44.78
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,938.49		
Global Sum Settlement (S\$)		3,930.00		

INSPECTION

Date of Assignment: 01/02/2019
 Date Inspected: 01/02/2019 Inspected At:

Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deep Cut	1,503.70 FL	*1,503.70 FL
2	10		*REAR BUMPER CLIP	Necessary	39.00 FL	*39.00 FL
3	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	98.50 FL	*- FL
4	1		*REAR DOOR RH	Dented / Bent	1,863.50 FL	*1,766.20 FL
5	1		*REAR DOOR OUTER MOULDING RH	Not Necessary	124.40 FL	*- FL
6	1		*REAR TYRE	Serviceable	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	4,079.10	3,308.90
- List Item Discount on L Items 10.00/10.00% (\$\$)	362.91	330.89
Total Parts (\$\$)	3,716.19	2,978.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TRANSFER OF TYRE ,RIM AND ON WHEEL BALANCING	New	80.00	0.00
2	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	80.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	900.00	400.00
4	PUTTY AND SPRAY PAINTING OF REAR BUMPER ,REAR FENDER RH ,REAR DOOR RH AND FRONT DOOR RH	New	1,200.00	800.00
Gross Labour Cost (\$\$)			2,260.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >