

mapus

ASSIGNMENT

DOI:

11/2/19

Date / Time:

31/1/2019

Registered in Meriten:

31/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJP 843 G

Name of Insured:

Low Wee Chia

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A: 30/01/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VL: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

YP 4572J



INSRS:

WSP:

Tel:

Liability:

RMKS:

Lin Bro.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

1372
A/GW

YP 4572J - X ; SJP 843 G - X

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call CE:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: (S)

Repair Cost: 45 S\$9,350

(5 days) Reduction: 45 %

Email ☒ Call ☐

FINAL SETTLEMENT Date/Time: 11.04.19

Confirm with Susan

Email ☒ Call ☐

Final Liability: % 100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost: S\$9,350.00

01: 117 STATIONARY VEHICLE.

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 90.00

(\$ 120 x 7 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☒

LOR + LOU ☐

LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow / Independent)

Legal Cost:

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: IF

3) Survey fee: 500

Total: S\$10,192.00

Global Sum S\$:

FINAL PAYMENT

Date/Time: 11.04.19

Confirm with: Susan

Email ☒ Call ☐

Payee 1: S\$10,192.00

Name 1:

LIA'S BROTHER AUTO ENGINEERING WORKSHOP

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

REF: FWD

ASSIGNMENT

From: Date 1/2/2019

Estimated Cost:

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: YP 4572J

at Workshop no: Liu's Brother

at 1 Kaki Bkt Ave 6 # 01-01

Insured:

Policy No:

Claims No:

Claim Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$90

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR: Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res: Yes or No

Lump Sum:

20 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

wup

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

ATA 3690

400 + 9,350 (350 + 7,900 + 400 + 450)

Veh No:

YP 4572J

Regn:

9 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

C/M

Make:

M.F. Fuso FK62

7545

Colour:

white

A/C

Insured / Std / NI / NA

Sp. Reading:

56976

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

FK62FM430169

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: STD / S/Rim / STD A/Rim or

Tyre Size:

F:

245/70 R19.5

R:

Austan

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Double coin

Front:

Rear:

R/Bal:

6

mm

R/Bal:

4/6

mm

L/Bal:

6/119

mm

L/Bal:

6/6

mm

D.O.A:

30/1/19

D.O.I:

1/2/19

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?

☐

Prel. Report

to

☐

Final Report

Date/Time: File Return to?

to

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format:

Lump Sum / LB: (\$) :

Add Fee:

☐

Site Insp (\$

☐

Interzone (\$

☐

Tech. Insp (\$

☐

Weekend (\$

Total:

Total:

Total:

Total:

Total:

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291791 | Tel: 6744-1730 / 731 | Fax: 6744-5746, Email: liusbros@gmail.com

Invoice/Ref No: YP4572190130

Estimate

Customer

Name: FWD Singapore Pte Ltd

Address: Motor Claims Department

6 Temasek Boulevard #18-01

Suntec Tower Four Singapore 038986

Date:

31-01-19

Vehicle No: YP45721

Model/Make: Mitsubishi Fuso

FK62FMZ1RDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Rh mudflap	\$ 655.40	
2	Front mudflap Bracket	\$ 299.20	
3	Air Cleaner Filter	\$ 488.50	
4	Air Cleaner Box	\$ 866.30	
5	Exhaust Pipe	\$ 953.00	
6	Rear Cargo Wooden Planks 02 pcs (@ S\$800.00 SN)	\$ 1,600.00	SN 9005 ~
7	Safety Bar & Bracket Rh 1 set	\$ 1,200.00	10005 ~
8	Air Tank Assy Small	\$ 1,500.00	12005 ~
9	Air Tank Assy Small Lower Bracket	\$ 420.00	3005 ~
10	Air Tank Assy Big	\$ 2,200.00	18005 ~
11	Air Tank Assy Big Lower Bracket	\$ 450.00	3005 ~
12	Fuse Relay Box Assy	\$ 850.00	
13	Air Tank Filter Assy	\$ 800.00	
14	Control Unit Assy	\$ 2,400.00	
15	Air Tank Assy Big Lower Rear Bracket	\$ 480.00	
	To check all wiring & replacing control unit	\$ 200.00	50
	To dismantle & refix rear cargo box for facilitate replace wooden plank	\$ 600.00	300
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	500
	To putty & spray painting & including touch up paint on accident affected	\$ 380.00	300

Total Parts & Labour of estimate for damaged vehicle

\$17,142.40

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

NOT AUTHORIZED

LHM

L/S 89350 / 500



M/s Liu's Brother Auto Engrg Wks

P-7195-20

252
5396.40

11746.4

9397.12

Customer's Representative hereby notify
the following:

- The vehicle is not to be repaired
- The vehicle is not to be repaired during recovery
- The vehicle is not to be repaired in a "Without Prejudice" basis
- The vehicle is not to be repaired in a "Without Prejudice" basis
- The vehicle is not to be repaired in a "Without Prejudice" basis
- The vehicle is not to be repaired in a "Without Prejudice" basis

Acknowledged by Receiver

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:Company

Owner ID:1196N

Vehicle Details

Vehicle No.:YP4572J

Vehicle to be Exported:No

Intended Deregistration Date:31 Jan 2019

Vehicle Make:MITSUBISHI

Vehicle Model:FUSO FK62FMZ1RDEB

Primary Colour:White

Manufacturing Year:2016

Engine No.:6M60216833

Chassis No.:FK62FMA30169

Maximum Power Output:-

Open Market Value:\$59,561.00

Original Registration Date:30 Sep 2016

First Registration Date:30 Sep 2016

Transfer Count:1

Actual ARF Paid:\$2,979.00

Intended PARF Rebate Details

PARF Eligibility:No

PARF Eligibility Expiry Date:-

PARF Rebate Amount:\$0.00

Intended COE Rebate Details

COE Expiry Date:29 Sep 2026

COE Category:C - Goods Vehicle & Bus

COE Period(Years):10

PQP Paid:\$4,816.00

COE Rebate Amount:\$3,690.00

Total Rebate Amount:\$3,690.00

The information contained herein is correct as at 31 Jan 2019

OK

[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Insurance](#)[Articles](#)[F](#)

AVIVA

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

2011 Volvo V60 T4 \$45,800



Accident Free, Low Mileage 78k.
White New Paintwork, Almost
New Interior!
Direct Owner StarAd



PRIME MORTGAGE

JICHENG YONG CREDIT ENTERPRISES

With over 200 units of veh
to choose from, ranging fr
all European to Japanese

Browse by Category ▼

Sort by Date Posted

1 vehicles

Mitsubishi fuso fk62

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	Mitsubishi fuso fk62		Any	Any	2016	Any	Any	

**Mitsubishi Fuso Fighter FK62****\$92,800****\$12,340 /yr****10-Aug-2016****7,545 cc****72,000 km****Fuel Type:** Diesel

High Cargo Canopy With Canvas. Easy Access To Load Pallet. High Railing. Condition Is As Good As New. See Photo To Be Convinced. L
Provided. Hurry Make Appointment For Viewing.

QiFei Auto Pte Ltd

Posted: 02-Jan-2019

Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso,
Used Mitsubishi

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
--	------	-------	-------	--------------	----------	---------	---------	---

For old advertisements, view [Expired ads](#)
[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resoun](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars insurance. Find buy used Mitsubishi fuso fk62, Mitsubishi fuso fk62 Singapore, used Mitsubishi fuso fk62 Singapore, used Mitsubishi fuso fk62, used vehicles Mitsubishi fuso fk62 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, for leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy.

Follow sgCarMart.com
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

[Compare](#)

Our Ref: YP4572J190130

Date: 12/03/2019

Your Ref:

FWD Singapore Pte Ltd
6 Temasek Boulevard #18-01
Suntec Tower Four
Singapore 038986

Attn: Motor Claims Department

Dear Sir / Madam

**TRAFFIC ACCIDENT ALONG JUNCTION OF ENTERPRISE ROAD AND JALAN BOON LAY
INVOLVING YP4572J AND SJP843G ON 30/01/2019**

We/I, **Messers Goldbell Leasing Pte Ltd** (Nric / ROC No: **199001196N**), the registered owners of m/vehicle – **YP4572J** at all material times of the above accident. Our/my vehicle was surveyed by "FWD" authorized appraiser and we/I based our/my claims on his recommendation for **S\$9,350-00** being the repair for **05 Days** (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle **SJP843G** when the same was involved in the aforesaid accident with our/my m/vehicle – **YP4572J**.

We/I whereby you are the insurers of m/vehicle **SJP843G** and the driver / owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle – **YP4572J** has suffered loss and damage as follows:

(a) Cost of repairs	S\$	9,350-00
(b) LOU for pre-repair notice 02 days @\$120-00 (7545 cc Truck)		240-00
(c) LOU Fee for 05 days @\$120-00		600-00
(d) GIA / LTA search fee		2-00

Total Amount	S\$	10,192-00
---------------------	------------	------------------

We/I enclose herewith copies of the supporting documents for vehicle no. **YP4572J** as follows:-

- (i) Motor Accident Report;
- (ii) Repair Invoices;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu's Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,



The owner of m/vehicle **YP4572J**
Messers Goldbell Leasing Pte Ltd
cc. Liu's Bro Auto Engrg Ws

Authorization To Act

Attn: Motor Claims Department

FWD Singapore Pte Ltd
6 Temasek Boulevard #18-01
Suntec Tower Four
Singapore 038986

I / We, Messers Goldbell Leasing Pte Ltd ("the third party claimant") of No. 18 Tuas Avenue 10 Singapore 639142 (address), owner of YP4572J (vehicle no.) hereby authorize Liu's Brother Auto Engineering Workshop ("the workshop") to act for me / us with respect to my / our claim for repair costs and / or rental and / or loss of use ("claim") for my / our vehicle no. YP4572J that was damaged pursuant to the accident which occurred on 30/01/2019 (date) along Junction Of Enterprise Road And Jalan Boon Lay (location) involving SJP843G ("the accident").

I / We further authorize the workshop to settle my / our above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my / our claim with payment cheque / s being made in favour of the workshop.

I / We further acknowledge that any settlement the workshop may reach on my / our behalf is on a without prejudice and without admission of liability basis insofar as the driver / owner / insurers of the other vehicle / s is concerned.

Dated this 23rd day of April (month) 20 19 (year)

3rd Party Claimant:

Signature: 

Name: Goldbell Leasing Pte Ltd

Address: No. 18 Tuas Avenue 10

Singapore 639142

Nric/ROC No: 199001196N

Workshop:

Signature: 

Name: Liu's Brother Auto Engrg Workshop

Address: 1 Kaki Bukit Avenue 6 #01-01

AutoBay @ Kaki Bukit

Singapore 417883

ROB No: 53291793J

RELEASE

Claim Reference:	1201900003668
Surveyor's Reference:	CC4/FWD19002145/Uea3
TP Reference:	YP4572J190130

We, LIU'S BROTHER AUTO ENGINEERING WORKSHOP ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle YP 4572J ("Vehicle") to accept the sum of \$10,192.00, being the amount claimed for \$9,350.00 (repair costs), \$840.00 (loss of rental/ use), \$ - (loss of income), \$2.00 (disbursement) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on 30/01/2019 (date of accident) at / along JUNC OF ENTERPRISE ROAD AND JLN BOON LAY (location) involving vehicle no/s. YP 4572J and SJP 843G.

This is pursuant to the inspection conducted on 01/02/2019 (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of SJP 843G be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 23 day of 04 2019

CLAIMANT



[Signed by the "Workshop" with Co. Stamp]
For and on behalf of the "Claimant"



CKS

[FWD's appointed surveyor with Co. Stamp]
For and on behalf of FWD Singapore Pte. Ltd.

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 | Tel: 6744-1730 / 731 | Fax: 6744-5746. Email: liusbro@yahoo.com

Invoice/Ref No: YP4572/190130

Final Bill

Customer

Name: FWD Singapore Pte Ltd

Date: 11-03-19

Address Motor Claims Department

Vehicle No: YP4572

6 Temasek Boulevard #18-01

Model/Make: Mitsubishi Fuso

Suntec Tower Four

Singapore 038986

FK62FMZ1RDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Rh Fender	\$ 655.40	\$ -
2	Fender Bracket	\$ 299.20	\$ -
3	Air Cleaner Filter	\$ 488.50	\$ -
4	Air Cleaner Box	\$ 866.30	\$ -
5	Exhaust Pipe	\$ 953.00	\$ -
6	Rear Cargo Wooden Planks 02 pcs (@ S\$800.00 SN)	\$ 1,600.00	\$ -
7	Safety Bar & Bracket Rh 1 set	\$ 1,200.00	\$ -
8	Air Tank Assy Small	\$ 1,500.00	\$ -
9	Air Tank Assy Small Lower Bracket	\$ 420.00	\$ -
10	Air Tank Assy Big	\$ 2,200.00	\$ -
11	Air Tank Assy Big Lower Bracket	\$ 450.00	\$ -
12	Fuse Relay Box Assy	\$ 850.00	\$ -
13	Air Tank Filter Assy	\$ 800.00	\$ -
14	Control Unit Assy	\$ 2,400.00	\$ -
15	Air Tank Assy Big Lower Rear Bracket	\$ 480.00	\$ -
	To check all wiring & replacing control unit	\$ 200.00	\$ -
	To dismantle & refix rear cargo box for facilitate replace wooden plank	\$ 600.00	\$ -
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	\$ -
	To putty & spray painting & including touch up paint on accident affected	\$ 380.00	\$ -

Total Parts & Labour of estimate for damaged vehicle

\$17,142.40

Total amount in Lump Sum Basis for repaired vehicle

\$ 9,350.00

SDLS: Nine Thousand Three Hundred Fifty Only



M/s Liu's Brother Auto Engrg Wks



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-017956

Date of Request: 31/01/2019

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 31/01/2019
Enquiry By: Susan Low Siew Yian
TP Vehicle No: SJP843G
Accident Date: 31/01/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Feb 2019 Edit Reg		31 Jan 2019 00:00 Edit Adj Rpt	S\$9,350.00 Edit Estimates	S\$9,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Low Wee Chiat, ID: S8417031C								
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N								
Vehicle Reg. No.:	YP4572J	Date of Loss:	30/01/2019 14:00 - :59 [28 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900003668	Policy/Cover Note No.:	PNPV2017-00007362-01 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJP843G	Policy No. (Claimant):	D-17087422MFCV						
		Excess:							
Repairer:	Liu's Brother Auto Engineering Workshop (Kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/02/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> FWD_SG (12/04/2019): Alert - Adj Mandate Approved (S\$10192.00) - YP4572J - Claim Handler: Josey Loh 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*YP4572J (1201900003668)

[SJP843G]

TP


















































GOLDBELL LEASING PTE LTD



















































Jan 30 2019 2:00PM


















[Low Wee Chiat]

Liu's Brother Auto Engineering Workshop (kaki Bukit)

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Letters/Correspondences									1 per page					
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown							1		Edit			
Photos/Images									3 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print			
1	12/04/19 16:12	Odometer Reading							1		Load JPG		<input checked="" type="checkbox"/>	
2	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
3	12/04/19 16:12	Chassis Number							1		Load JPG		<input checked="" type="checkbox"/>	
4	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
5	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
6	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
7	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
8	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
9	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
10	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
11	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
12	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
13	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
14	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
15	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
16	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
17	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
18	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
19	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
20	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
21	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
22	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
23	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
24	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
25	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
26	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
27	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
28	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
29	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
30	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
31	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
32	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
33	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	
34	12/04/19 16:12	General View							1		Load JPG		<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
38	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
41	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
43	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
44	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
45	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
46	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
47	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
48	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
49	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
50	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
51	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
52	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
53	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
54	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
55	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
56	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
57	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
58	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
59	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
60	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
61	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
62	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
63	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
64	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
65	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
66	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
67	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
68	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
69	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
70	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
71	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
72	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
73	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
74	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
75	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
76	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
77	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
78	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
79	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
80	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
81	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
82	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
83	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
85	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
86	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
87	12/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
88	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
134	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	12/04/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/02/19 16:38	ACKNOWLEDGEMENT EMAIL TO FWD DD 01.02.19	 Load PDF	
2	01/02/19 16:38	TP GIA REPORT	 Load PDF	
3	01/02/19 16:38	GIA Search	 Load PDF	
4	13/02/19 10:57	EMAIL - FWD TO OI DD 12.02.2019	 Load PDF	
5	08/04/19 16:24	WORKSHOP INVOICE	 Load PDF	
6	08/04/19 16:24	LOD	 Load PDF	
7	08/04/19 16:24	GIA SEARCH	 Load PDF	
8	30/04/19 08:44	Release Voucher	 Load PDF	
9	30/04/19 08:44	AUTHORISATION TO ACT FORM	 Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	12/02/19 11:15	OI GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJP843G (Insd veh)	Model:	MITSUBISHI FUSO FIGHTER
	YP4572J (TP veh)		7.5 D FK62 SERIES
Date of Accident:	30/01/2019		(FK62FMZ1RDEB) (M)

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	17,142.40
Final Repair Cost	:	\$	9,350.00
Loss of Use	:	\$	840.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	10,192.00

7.00 days at \$120.00 per day

days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____100____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Liu's Brother Auto Engineering Workshop	:	\$ 10,192.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

30 Apr
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No:199607188R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19002145/UEA3Q2

Date: 30/04/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00007362-01

Claimant Vehicle No : YP4572J Insured Vehicle No : SJP843G

Date of Loss: 30/01/2019 Nature of Claim: TP Claim No: 1201900003668

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP4572J**

Make & Model: MITSUBISHI FUSO FIGHTER, 7.5 D FK62 Series (FK62FMZ1RDEB) (M) Engine No: 6M60216833

Reg. Date: 30/09/2016 (Man. Year: 2016) Chassis No: FK62FMA30169

Colour: White Odometer: 56976 km

Engine Capacity: 7545 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/70 R19.50 Rear Tyre Size: 245/70 R19.50 (D)

Front Left Side: Double Coin 6 mm Rear Left Side: Austone 6/6 mm

Front Right Side: Double Coin 6 mm Rear Right Side: Austone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,162.40	10,596.40	4,566.00	30.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,150.00	830.00	41.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,142.40	11,746.40	5,396.00	31.48
Approved Total (Overridden) (S\$)		9,350.00		
Nett Amount (S\$)	17,142.40	9,350.00	7,792.40	45.46
+ Loss of Use (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,192.00		

INSPECTION

Date of Assignment: 31/01/2019

Date Inspected: 01/02/2019 Inspected At:

Liu's Brother Auto Engineering Workshop
(kaki Bukit) (HQ)
Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @
Kaki Bt Singapore 417883, Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Apr 2019)	
Parts:	N/A	mitsubishi fuso fighter 7.5 D FK62 Series (FK62FMZ1RDEB) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP4572J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH MUDFLAP	Torn	655.40 F	*655.40 FL
2	1		*FRONT MUDFLAP BRACKET	Repair	299.20 F	*- FL
3	1		*FRONT RH AIR CLEANER FILTER	Cut	488.50 F	*488.50 FL
4	1		*FRONT RH AIR CLEANER BOX	Cracked	866.30 F	*866.30 FL
5	1		*FRONT EXHAUST PIPE	Bent	953.00 F	*655.00 FL
6	2		*REAR CARGO WOODEN PLANKS (FRONT)	Cracked	1,600.00 FS	*900.00 FS
7	1		*SET REAR SAFETY BAR & BRACKET RH	Bent / Distorted	1,200.00 FS	*1,000.00 FS
8	1		*REAR AIR TANK ASSY SMALL	Dented	1,500.00 FS	*1,200.00 FS
9	1		*REAR AIR TANK ASSY SMALL LOWER BRACKET	Bent	420.00 FS	*300.00 FS
10	1		*REAR AIR TANK ASSY BIG	Dented	2,200.00 FS	*1,500.00 FS
11	1		*REAR AIR TANK ASSY BIG LOWER BRACKET	Bent	450.00 FS	*300.00 FS
12	1		*REAR FUSE RELAY BOX ASSY	Cracked	850.00 F	*850.00 FL
13	1		*REAR AIR TANK FILTER ASSY	Cracked	800.00 F	*800.00 FL
14	1		*REAR CONTROL UNIT ASSY	Cracked	2,400.00 F	*2,400.00 FL
15	1		*REAR AIR TANK ASSY BIG LOWER BAR BRACKET	Bent	480.00 F	*480.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	15,162.40	12,395.20
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,798.80
Total Parts (\$\$)	15,162.40	10,596.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL WIRING & REPLACING CONTROL UNIT	New	200.00	50.00
2	TO DISMANTLE & REFIX REAR CARGO BOX FOR FACILATE REPLACE WOODEN PLANK	New	600.00	300.00
3	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	800.00	500.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	380.00	300.00
Gross Labour Cost (S\$)			1,980.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >