

































PAR Automotive Consultancy

110 Thomson Rd, 11th Floor, #11-01, Singapore 307611 | Tel: 65 6339 1111 | Fax: 65 6339 8011

Report No: 0753-18-N51

24 December 2018

ACCIDENT VEHICLE SURVEY REPORT

Darwin-51 Car Rental Pte Ltd
c/o N-51 Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-18
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

<i>Vehicle Reg No</i>	SLS2046M	<i>Odometer</i>	75552km
<i>Make & Model</i>	Toyota Prius Alpha 1.8S	<i>Colour</i>	Grey
<i>Chassis number</i>	ZVW400025897	<i>Date of accident</i>	26/05/2018
<i>Year of Regn</i>	13/09/2017	<i>Date inspected</i>	01/06/2018
<i>Repairer at</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair)</i>	11/06/2018

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.





















