



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19002340/Ega3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 10-09-2020



ATTN: PETER WANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 612C	Veh. Inspected	SKZ 3370U
Policy No.	GA243047/1	Coverage (\$)	0.00
Claim No.	S9M01D5D	Excess (\$)	0.00
Assign From	PETER WANG	Assign Date	11/02/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104546554	Colour	WHITE
Odometer	295843	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	KAPSEN	5 mm
L/H Front Tyre	205/55 R16	KAPSEN	5 mm
R/H Rear Tyre	205/55 R16	KAPSEN	5 mm
L/H Rear Tyre	205/55 R16	KAPSEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/02/2019	Inspection Date	12/02/2019
Survey held at	ALLSWELL MOTOR TRADERS 100 JALAN SULTAN #02-41 SULTAN PLAZA SINGAPORE 199001		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**