

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

# Ailsweil Motor Traders

25 Jerni Lane Singapore 539266  
 Email: ben@ailsweilmotor.com.sg

Steve (LKK)

12/2/19

lets P/P A3228813

Mr Lim

LKK - old man (Van)

13/2/19 (dusmanthi)

Acknowledged by Repairer

Signature:

Date:

(3rd party claim against

AXA insured

SL2612C

P- 218-S1

Supp- 3054.75

N1- 95

7168.26

L-

Submitted by

Ben

COE expiry

18-01-2028

Engine No.

Estimate repair

Vehicle No. :

SKZ3370U

Make & Model :

Toyota Auris 1.6 CVT

Chassis No. :

Date of survey :

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01A	RH / LH fender (near) X R	01A01	#1,200.00	X	X Repair
01	Rear bumper / DD	01	#1,027.00	557 /	
02	Rear sunbar #150x2 pc. / GR	01	#300.00	/	
03	End panel / DD	01	#525.00	/	
04	Rear boot X R	01	#986.00	X	
05	Boot lock c/w casing / BT	01	#379.00	/	
06	Rear bumper / GR	01	#1,171.00	500.50 /	2874.69
07	Front chrome grille / GR	01	#515.00	439.19	-25%
08	LH rear retainer / GR	01	#62.00	/	2118.51
09	RH rear retainer / GR	01	#62.00	/	
Special note					
01	Clips / retainers studs for front rear bumper @ #72 / pict	MC 01	#72.00	60 / (N/A)	
Labour Description					
01	Dismantle / Assembly of all affected parts	01	#800.00	X	
02	Panel beating / welding / repair / replace end panel & 02 fenders	01	#1,200.00	900	
03	Respray including puffy, sandpaper polish & wash of all affected parts	01	#1,800.00	1000	1900
Supplementary					
01	License plate c/w casing front / BT	01	#65.00	35 / (N/A)	
02	front bonnet / DD	01	#1,001.00	/	
03	End panel trim / CRU	01	#187.30	/	
04	Reinforcement bar (rear) / DD	01	#496.70	/	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

05 LH headlamp / GR

01 #969.00 /

4973

06 RH headlamp / GR

01 #969.00 /

-25%

07. Condenser / BT

01 #450.00 /

3054.75