

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SLW3108R
Chassis No : JHMGK5850JX203900
Model : JAZZ 1.5VTIR CVT 18YM (EURO 6)
Owner's Name : KUA CHI KIONG
Ins Policy No. :
Date of Accident : 4/2/2019

Document No. : SQT19000601
Date : 8. Feb 2019
Customer No. : WZ1007
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B33111699
Date | Time : 8. Feb 2019 3:46:33 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------|---|-----|------------|--------|---------|---------------|------------------|
| | TP DIRECT SETTLEMENT (J/NO:) OWNER: KUA CHI KIONG OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 4/2/19 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INTL. INSURANCE TP VEH: SHC8855L | | | | | | |
| BOSUN | SUNDRIES | 11 | 30.00 | X | 30.00 | 2.10 | 32.10 |
| BKDR11K | STRAIGHTEN ALIGN FR L & RR DOOR. | 1 | 1120.00 | 560 | 1120.00 | 78.40 | 1198.40 |
| BP02R | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P) | 1 | 1350.00 | 900 | 1350.00 | 94.50 | 1444.50 |
| Sum Labor | | | | | 2500.00 | 175.00 | 2,675.00 |

Survey By

Date & Time

Excess

Status

Signature

Total Amount 2,500.00 175.00 2,675.00

Total (Inclusive of GST) 2,675.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 9/2/2019 9:17:10 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)