

Stacey Ng

CC 4, ASM, 9002494

Agg 03⁵²

LKK: 97730
IDAC:

Surveyor:

UMP

DOI:

ASSIGNMENT
12/1/19

Date / Time:

11/2/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : 56X4214 P
Name of Insured : Ong Keng Soon
Insured Tel No. : HP:
Excess Sec II :SS D.O.A : 2/2/19
Is driver the owner? (YES / NO) Nature of Accident :

Claim No. : S9m010cb
Policy No. :
Make / Model :
Place of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(VL: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO


Insured Liability : % Final ? Yes / No

SKL692J



INSRS:
WSP:
Tel:
Liability:
RMKS:

700005



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

18/1/19
20/1/19

SKL692J - X;
56X4214P - 66181614008352/mppyt : 009-284411
20/1/19 - Email LOI.
TO seek Mandate.
21/1/19 - Rec LOR to TP (Pending LOD).
Pending mandate approval.
18/1/19 - Pending mandate approval. (approved)
20/1/19 - settle @ \$7145 as per TP LOD, DV send
(Pending DV)
21/1/19 - DV in (File pass Admin to close)

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	
Documentation Check List: Handler Typist	
Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
After call ltr to OI:	<input checked="" type="checkbox"/>
Authorisation To Act:	<input checked="" type="checkbox"/>
Release Voucher:	<input checked="" type="checkbox"/>
Final Repair Bill:	<input checked="" type="checkbox"/>
Car Rental Invoice:	<input checked="" type="checkbox"/>
Towing Invoice	<input checked="" type="checkbox"/>
LTA / GIA :	<input checked="" type="checkbox"/>
Medical Bill:	<input checked="" type="checkbox"/>
PIR:	<input checked="" type="checkbox"/>
Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
LOD	<input checked="" type="checkbox"/>
Payment Breakdown Form:	<input checked="" type="checkbox"/>
Post-Repair Photos:	<input checked="" type="checkbox"/>
Others:	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By: Confirm by: Advrain

FINALIZATION Date/Time: Confirm with: Repair Cost: 45 \$6700.00 (5 days) Reduction: \$12,512.89 % 67

FINAL SETTLEMENT Date/Time: 20/1/19/19 Confirm with: Rachel. Email: Call:

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27
Repair Cost: (w/loss) \$634.00
Loss of Rental (LOR): \$ (days)
Loss of Use (LOU): \$480.00 (\$60 x 8 days)
Loss of Income (LOI): \$ (\$ x days)
LOR only LOU only LOR + LOU LOR + LOI [Tick only one]
GIA/LTA Search: \$31.00
Medical: \$-
Disbursement: \$- (e.g. Tow/Independent)
Legal Cost: \$-
Total: \$7145.00 Global Sum \$:
1) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: \$350-

COPY SENT

FINAL PAYMENT Date/Time: Confirm with: Email: Call:


Payee 1: \$7145.00 Name 1: TORQUE 5 Pte Ltd
Payee 2: (Strike if N.A.) \$ Name 2:
Payee 3: (Strike if N.A.) \$ Name 3:

REF: AXA

ASSIGNMENT

From: Date: 12/2/19
 Estimated cost:
 OD: WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SKL 692J
 at Work-shop no: Torque 5
 of: 8 kaki Bukit Ave 4 # 01-49 premier
 Insured:
 Policy No:
 Claim No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:

Veh No: SKL692J Regd: 2013 Sept.
 Type: Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mercedes Benz B200 cc: 1595
 Colour: Silver. AC: Insured / Std / Nil / NA
 Sp Reading: 131225. T/Radio: Insured / Std / Nil / NA
 Eng No:
 C/No: WDD2462432J196725
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R16.
 R: 205/55R16.
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO/YOKO or Continental.



Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value:
 IDAC Accident Report: Consistent? Yes or No
 GIA / PR Seen: Consistent? Yes or No
 Est. Repairs: 5 days Res: Yes or No
 Lum Sum: 90 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS ^{lup}
 Date: Person Contacted: Vehicle: IN / OUT

Front: Rear:
 R/Bal: 06 mm R/Bal: 06 mm
 L/Bal: 06 mm L/Bal: 06 mm
 D.O.A.: D.O.I: 12/02/19
 Survey held at: Torque 5.
 Des. of Damages: Frt: Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time: Action / Instruction
 TP AXA.
 Repairer agreed Admin to survey.
 MV: 65K - 45 \$6200/- (Net = \$12512.89 / 67%)
 PV: 76.4K
 Nett: 18.6K.

★ to repair days + 2 PRS + 1 Sunday = 9 days.

Date/Time, File Pass to: : Preli. Report
 : Final Report
 Days Of Repair:
 Resurvey No. of Trip:
 Survey Fee:
 Transportation:
 1. ...
 2. ...
 3. ...
 4. ...
 TOTAL:

Add Fee: Site Insp. 1\$
 Interview 1\$
 Techn. Insp. 1\$
 Weekend 1\$

Report Format:
 Lump Sum / LB. 1: 1\$



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

TO AXA.
 Joy.

ESTIMATION REPORT

Vehicle No : SKL692J
 Make & Model : MERCEDES BENZ,B 200 AT ABS AIRBAGS HID
 2WD 5DR(CHROME),WDD2462432J196725
 Year of Manufacture : 2013

Estimation No. : E19020004
 DOA : 07/02/2019

No	Description	Qty	U/P	Amt
<u>Section: List Items</u>				
1	Rear bumper <i>Deland</i>	1.00	0.00 1458.00	0.00 -1458
2	Rear bumper side core (LH) <i>3pc</i>	1.00	0.00 68.00	0.00 -68
3	Rear bumper side core (RH)	1.00	0.00 68.00	0.00 -68
4	Rear bumper centre bracket <i>Brand</i>	1.00	0.00 230.00	0.00 230
5	Rear bumper chrome moulding (LH) <i>3pc</i>	1.00	0.00 129.00	0.00 -129
6	Rear bumper chrome moulding (RH)	1.00	0.00 129.00	0.00 -129
7	Reverse sensor <i>3 pieces</i>	4.00 567.00	0.00 2248.00	0.00 -2250
8	Rear bumper lower garnish <i>Deland</i>	1.00	0.00 60.00	0.00 60
9	Rear bumper reinforcement <i>But</i>	1.00	0.00 525.00	0.00 525
10	Rear bumper towing cap <i>me on</i>	1.00	0.00 92.00	0.00 +
11	Rear bumper bracket (LH) <i>3pc</i>	1.00	0.00 116.00	0.00 +
12	Rear bumper bracket (RH)	1.00	0.00 116.00	0.00 +
13	Reverse sensor wiring set <i>Me on</i>	1.00	0.00 725.00	0.00 +
14	Tailgate <i>Deland</i>	1.00	0.00 1230.00	0.00 -
15	Tailgate lock <i>3pc</i>	1.00	0.00 360.00	0.00 -
16	Tailgate lock switch <i>3pc</i>	1.00	0.00 2280.00	0.00 +
17	Tailgate lock sensor <i>3pc</i>	1.00	0.00 180.00	0.00 +
18	Tailgate lock catch	1.00	0.00 75.00	0.00 +
19	Tailgate emblem - Logo <i>3pc</i>	1.00	0.00 54.00	0.00 -
20	Tailgate emblem - B200 <i>3pc</i>	1.00	0.00 97.00	0.00 -
21	Tailgate chrome garnish <i>me on</i>	1.00	0.00 335.00	0.00 +
22	License lamp (LH)	1.00	0.00 98.00	0.00 +
23	License lamp (RH)	1.00	0.00 98.00	0.00 +
24	Tailgate lamp (LH) <i>Not</i>	1.00	0.00	0.00 +
25	Tailgate lamp (RH) <i>Not</i>	1.00	0.00	0.00 +
26	Tailgate inner trim board	1.00	0.00	0.00 +

parts = 8151 - 10% ARA
 = 7335.90

S/N = 360
 Labour = 1590

p+s+l = 9285.90 - 20% 4/s
 = 7400

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKL692J
 Make & Model : MERCEDES BENZ,B 200 AT ABS AIRBAGS HID 2WD 5DR(CHROME),WDD246243J196725
 Year of Manufacture : 2013
 Estimation No. : E19020004
 DOA : 07/02/2019

No	Description	Qty	U/P	Amt
27	Tailgate inner side garnish (LH)	1.00	0.00 113.00	0.00 *
28	Tailgate inner side garnish (RH)	1.00	0.00 113.00	0.00 *
29	Tailgate inner centre garnish	1.00	0.00 106.50	0.00 *
30	Tailgate wiper motor	1.00	0.00 652.00	0.00 *
31	Tailgate wiper arm	1.00	0.00 170.00	0.00 *
32	Tailgate rubber beading	1.00	0.00 239.60	0.00 *
33	Tailgate rubber stopper (LH)	1.00	0.00 42.00	0.00 *
34	Tailgate rubber stopper (RH)	1.00	0.00 42.00	0.00 *
35	Tailgate damper (LH)	1.00	0.00 330.00	0.00 *
36	Tailgate damper (RH)	1.00	0.00 330.00	0.00 *
37	Tailgate hinge (LH)	1.00	0.00 126.00	0.00 *
38	Tailgate hinge (RH)	1.00	0.00 126.00	0.00 *
39	Rear windscreen	1.00	0.00	0.00 ✓ 1264.00
40	Tail lamp (LH)	1.00	0.00	0.00 *
41	Tail lamp (RH)	1.00	0.00	0.00 *
42	End panel	1.00	0.00	0.00 *
43	End panel top garnish	1.00	0.00 323.00	0.00 *
44	Rear floor panel top board	1.00	0.00 428.00	0.00 *
45	Rear floor panel	1.00	0.00	0.00 *
46	Rear exhaust muffler	1.00	0.00 1765.00	0.00 *
47	Rear exhaust mounting	5.00	90.00 0.00	450.00 0.00 *

6437
5793.30

Amt \$4 0.00
 Discount (0.00%) \$5 0.00
 Subtotal \$5 0.00 1630.10

Section: Special Nett Items

48	Reverse camera	1.00	500.00	500.00 *
49	Rear number plate & casing	1.00	45.00	45.00 *

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No: 201313221G

ESTIMATION REPORT

Vehicle No : SKL692J
 Make & Model : MERCEDES BENZ, B 200 AT ABS AIRBAGS HID
 2WD 5DR(CHROME), WDD2462432J196725
 Year of Manufacture : 2013

Estimation No. : E19020004
 DOA : 07/02/2019

No	Description	Qty	U/P	Amt
50	Rear bumper chrome protector <i>Re-l-d</i>	1.00	280.00	280.00 ✓
51	Rear bumper clip set <i>new</i>	1.00	50.00	50.00-30
52	Tailgate C&C emblem <i>new</i>	1.00	90.00	90.00 50.
53	Tailgate inner trim board clip set <i>new</i>	1.00	50.00	50.00 ✓
54	End panel top garnish clip set <i>new</i> 410	1.00	30.00	30.00 ✓
55	Rear windscreen sealant <i>new</i>	1.00	50.00	50.00 ✓
56	End panel sealant <i>new</i>	1.00	50.00	50.00 ✓
				Amt S\$ 1,145.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 1,145.00

Section: Labour Items

57	To R&R rear bumper reverse sensor	1.00	80.00	80.00-50
58	To check wiring & lighting system	1.00	100.00	100.00 30.
59	To respray undercoating / putty on affected areas	1.00	80.00	80.00 ✓
60	To supply anti rust treatment on affected areas	1.00	60.00	60.00-250
61	To R&R tailgate mechanism	1.00	280.00	280.00 80
62	To R&R rear windscreen	1.00	200.00	200.00 120
63	To R&R rear exhaust assy	1.00	250.00	250.00 ✓
64	To R&R rear trims, garnish and seats 1550	1.00	250.00	250.00 60.
65	To R&R fuel tank to cut & weld	1.00	300.00	300.00 ✓
66	To diagnostic erase fault code memories	1.00	160.00	160.00 ✓
67	To repair, replace and realign damaged areas	1.00	1,400.00	1,400.00 800.
68	To spray painting on affected areas	1.00	1,000.00	1,000.00 600
69	Sundries	1.00	50.00	50.00 ✓
				Amt S\$ 4,210.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 4,210.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King
 1/2 12/02/19

OS Rep

Total: 7793.30

h/s: 6.2K.

List Items Subtotal	S\$ 0.00
Special Nett Items Subtotal	S\$ 1,145.00
Labour Items Subtotal	S\$ 4,210.00
Total	S\$ 5,355.00


419712.89

SATISFACTION VOUCHER

I / We, Tang Yew Hong hereby confirm that repairs to my / our
vehicle no. SKL 692J have been completed to my / our satisfaction and
that I / we have collected my / our said vehicle on the under-mentioned date.

Date in: 08/02/2019

Date out: 14/02/2019



Owner's Signature

Name: Tang Yew Hong

NRIC No.: S 1483017D

Date: 20/02/2019

Time: 10:35 am

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3017J
Vehicle Details	
Vehicle No.:	SKL692J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Feb 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	B 200 AT ABS AIRBAGS HID 2WD 5DR(CHROME)
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	27091030241792
Chassis No.:	WDD2462432J196725
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$25,714.00
Original Registration Date:	26 Sep 2013
First Registration Date:	26 Sep 2013
Transfer Count:	0
Actual ARF Paid:	\$18,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Sep 2023
PARF Rebate Amount:	\$12,600.00
Intended COE Rebate Details	
COE Expiry Date:	25 Sep 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$73,100.00
COE Rebate Amount:	\$33,747.00
Total Rebate Amount:	\$46,347.00

The information contained herein is correct as at 13 Feb 2019

OK

6303

Wide selection of Inchcape Certified Pre-owned LEXUS & TOYOTA

Interest Rate **1.98%** till 31 Jan 2019

Extended Warranty **1yr**

Free Tyre & Service Credits up to **\$3,000**

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Porsche Cayman GT4, Year Of Reg 01 Aug 2016, 2 Owners

Dying Breed Of A Naturally Aspirated Mid-engined And Well Balanced Sports Car!
Direct Owner - StarAd

SKY AD

AutoInn
An Inspiration For Car Buyers

click here to view our **PRISTINE USED CARS** at **GREAT PRICES**

Browse by Category Sort by Date Posted | 20 results/page

[Save Search](#) [Print](#)

9 vehicles | **Search** B-Class B200 [Advanced Search](#) [Search](#) [View All](#)

Search Selection	B-Class B200	Any	Any	2013	Any	Any	Any	Available
	<input type="checkbox"/> Mercedes-Benz B-Class B200 Chrome	\$53,800	\$11,390 /yr	28-Feb-2013	1,595 cc	109,000 km	Hatchback	Available
Schedule A Test Drive Today. Viewing Is Strictly By Appointment Only.								
Carro COMBINATION								
★ Posted: 24-Jan-2019 <small>Tags: 2013 Mercedes-Benz B200, 2013 mercedes-benz b200, Mercedes-Benz B200, mercedes-benz b200, Mercedes-Benz, B200, b200, Used Mercedes-Benz</small>								
	<input type="checkbox"/> Mercedes-Benz B-Class B200	\$63,800	\$12,080 /yr	25-Apr-2013	1,595 cc	65,000 km	Hatchback	Available
C&C Unit, Regularly Groomed, Service And Maintained. 90% Loan Available, High Trade In Are Welcome, Call For Viewing Or Test Drive.								
★ Posted: 07-Feb-2019 <small>Tags: 2013 Mercedes-Benz B200, 2013 mercedes-benz b200, Mercedes-Benz B200, mercedes-benz b200, Mercedes-Benz, B200, b200, Used Mercedes-Benz</small>								
	<input type="checkbox"/> Mercedes-Benz B-Class B200 Chrome	\$61,000	\$12,290 /yr	13-Jun-2013	1,595 cc	54,100 km	Hatchback	Available
Well Taken Care By 1 Owner. Low Mileage And Service With Agent Cycle And Carriage. Luxury, Spacious And Comfortable Ride For You And Your Family. Bank And In House Loan Available! Trade In Welcome. Ca...								
★ Posted: 11-Dec-2018 <small>Tags: 2013 Mercedes-Benz B200, 2013 mercedes-benz b200, Mercedes-Benz B200, mercedes-benz b200, Mercedes-Benz, B200, b200, Used Mercedes-Benz</small>								
	<input type="checkbox"/> Mercedes-Benz B-Class B200 Chrome	\$57,800	\$11,510 /yr	19-Jun-2013	1,595 cc	122,000 km	Hatchback	Available
Purchase From Case Trust & SVTA Accredited Company With A Peace Of Mind! 1 Careful Owner! Immaculate Condition! No Repair Needed! View To Believe! Very Well Maintained By Previous Owner Regular Serv...								
★ Posted: 25-Jan-2019 <small>Tags: 2013 Mercedes-Benz B200, 2013 mercedes-benz b200, Mercedes-Benz B200, mercedes-benz b200, Mercedes-Benz, B200, b200, Used Mercedes-Benz</small>								
	Mercedes B-Class keeps up with the pack							
To keep up with the evolving market, Mercedes has injected some new life into the B-Class with an update that concerns fresh looks and new technology.								
Read this article								
	<input type="checkbox"/> Mercedes-Benz B-Class B200 Chrome	\$65,800	\$13,020 /yr	25-Jun-2013	1,595 cc	70,000 km	Hatchback	Available
One Meticulous Owner. No Gimmicks Low Mileage Done! Excellent Condition Almost Brand New. Owner's 4th Car. Fully Agent C&C Serviced. Well Maintained Interior And Exterior With Original Paintwork Since...								
Car Empire Automobiles Pte Ltd								
★ Posted: 14-Dec-2018 <small>Tags: 2013 Mercedes-Benz B200, 2013 mercedes-benz b200, Mercedes-Benz B200, mercedes-benz b200, Mercedes-Benz, B200, b200, Used Mercedes-Benz</small>								
	<input type="checkbox"/> Mercedes-Benz B-Class B200 Chrome	\$66,800	\$12,690 /yr	03-Sep-2013	1,595 cc	76,000 km	Hatchback	Available
Excellent And Original Condition, Well Maintained, Smooth Driving, Low Mileage. Serviced And Maintained By C&C. 2.28% Promo For Limited Time Only! Flexible Finance Packages With Low Interest Rates! Bu...								
Hua Yang Credit Pte Ltd PREMIUM AD								
★ Posted: 17-Dec-2018 <small>Tags: 2013 Mercedes-Benz B200, 2013 mercedes-benz b200, Mercedes-Benz B200, mercedes-benz b200, Mercedes-Benz, B200, b200, Used Mercedes-Benz</small>								

SHORTLISTED HISTORY

[Compare](#)

<input type="checkbox"/> Mercedes-Benz B-Class B200 Chrome	\$68,000	\$12,740 /yr	02-Oct-2013	1,595 cc	76,000 km	Hatchback	Available
--	----------	--------------	-------------	----------	-----------	-----------	-----------



Additional Info: Magnetic Sunshade, Built In GPS, Both Batt Replaced 6 Months Ago. Rubber Mount And Transmission Oil Replace 3 Weeks Ago With Receipt. Perfectly Good Working Condition. Schedule A Test...

COFINMENT

Carro

☆ Posted: 29-Dec-2018 Tags: 2013 Mercedes-Benz B200, 2013 mercedes-benz b200, Mercedes-Benz B200, mercedes-benz b200, Mercedes-Benz, B200, b200, Used Mercedes-Benz



Mercedes-Benz B-Class B200 Chrome \$69,500 \$12,670 /yr 24-Oct-2013 1,595 cc 59,900 km Hatchback Available

Fully Maintained With C&C Since Day One. High Specification With Twin Panoramic Moonroof. Spacious, Commodious Interior Perfect For Your Family With Kids. Drive A Premium Crossover With Merely \$11k De...

Car Buyers Automotive Pte Ltd

PREMIUM AD

☆ Posted: 02-Feb-2019 Tags: 2013 Mercedes-Benz B200, 2013 mercedes-benz b200, Mercedes-Benz B200, mercedes-benz b200, Mercedes-Benz, B200, b200, Used Mercedes-Benz



Mercedes-Benz B-Class B200 Chrome \$71,000 \$12,970 /yr 25-Nov-2013 1,595 cc 56,374 km Hatchback Available

Priced Dropped To \$71,000 (3/11/18)! Reluctant Sale By Fussy Owner. Under Utilized 3rd Car. Extremely Low Mileage. Superb Interior And Exterior. Engine Purring In Prime Condition. Engine And Gearbox N...

☆ Posted: 26-Dec-2018 Tags: 2013 Mercedes-Benz B200, 2013 mercedes-benz b200, Mercedes-Benz B200, mercedes-benz b200, Mercedes-Benz, B200, b200, Used Mercedes-Benz

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used B-Class B200, B-Class B200 Singapore, used B-Class B200 Singapore, used B-Class B200, used vehicles Singapore or even buy used B-Class B200 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

SHORTLISTED HISTORY
Compare

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Monday, 11 February 2019 5:58 PM
To: assignments
Subject: FW: Accident involving SKL692J & SGX4214P on 07/02/2019 (PRE-REPAIR SURVEY REQUEST)
Attachments: image001.emz; image012.wmz; SKL692J - GIA REPORT.pdf

Hi nivitha,

Tp smart claim – plz check whether wksp want to do ds.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

9.20am @ 12/2/2019
person @ lee yi
vehicle in

From: Torque 5 Assessment <assessment@torque5.com>
Sent: Monday, 11 February, 2019 11:08 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Cc: assessment@torque5.com; sam.chang@torque5.com; claims@torque5.com
Subject: Accident involving SKL692J & SGX4214P on 07/02/2019 (PRE-REPAIR SURVEY REQUEST)

Without Prejudice

Dear Sir/ Mdm,

We refer to the above matter.

We represent our client, Tang Yew Hong, to notify you of the aforesaid accident involving our client's vehicle SKL 692 J and your insured's vehicle SGX 4214 P on 07/02/2019.

Please find enclose our client's GIA report for your necessary action.

This serves as a **NOTICE** that we are claiming against SGX 4214 P for damages, costs and disbursements.

Please let us know within **2 working days** from today, your client's and your intention to conduct a pre-repair survey of our client's vehicle, along with your list of at least **ten (10) motor surveyors**.

If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you.

Premises for the Pre-repair inspection: 8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Contact Person: Stephanie Teo (9147 8841)
Contact Email: assessment@torque5.com

VEH IN (Date & Time) : 08/02/2019

PRS ARRANGEMENT (Date & Time) : 11/02/2019 11.07AM

PRS ACKNOWLEDGEMENT

Appointed Surveyor
(Name & Signature) :

Date & Time of Inspection :

Kindly cc a copy of this letter to your insured for his/her acknowledgement.

We look forward to hearing from you soon.

To avoid incurrence of any unnecessary cost on both our end, kindly confirm liability status within 7 days from this to minimize time wastage and incurrence of any unnecessary cost(s) on both our end, we seek your kind advice, within 7 days working days, on liability status for subject claim. If we do not hear from you within the stipulated period, we shall proceed with the purchase of your insured GIA



report and this cost or any other cost incurred for confirmation of liability status shall be included in our LOD for reimbursement purpose.

Warmest Regards,

Heng Lee Yi

Administrative Assistant | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com





Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/09/2019

Survey Details:

Date of loss	7-Feb-19
Date of appointment	11-Feb-19
Date of survey	12-Feb-19
Location of survey	TORQUE 5 PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKL 692J
Make and Model	MERCEDES BENZ B200
Date of registration	26/9/2013
Excess	
Market Value	\$65,000
Parf Rebate	\$46,400
Nett Loss	\$18,600

Repair details:

Initial Estimate	\$ 5,355.00
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 6,203.30
Check items (estimate)	\$ -
Labour	\$ 1,590.00
Total	\$ 7,793.30
Lump Sum(if applicable)	\$ 6,200.00

Number of days for repair	5
---------------------------	---



Remarks:

05 RECOMMENDED REPAIR DAYS + 1SUNDAY + 2PRS = 08 DAYS

Mandate:

Liability(TP)		100%	
Proposed repair cost (W/GST)	\$	6,634.00	W/GST
Loss of use	\$	480.00	8days x \$60
Loss of rental		-	
Loss of income		-	
LTA search fees	\$	31.00	
Others		-	
Proposed Total	\$	7,145.00	



<MANDATE IA> - S9M01DC6 {ACCIDENT INVOLVING SGX 4214P(OI) & SKL 692J(TP) ON 07/02/2019}

Type

🔔 Question

Message

LIABILITY: 100% BOLAS 27: INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$7,145.00 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CECILIA

Reply



Re:<MANDATE IA> - S9M01DC6 {ACCIDENT INVOLVING SGX 4214P(OI) & SKL 692J(TP) ON 07/02/2019}

Type

 Question

Message

PLS PROCEED

Reply

Claim amount as per below:-

1. Repair Cost	\$ 6,634.00
2. Loss of Use for 08 Days x \$60/- per day	\$ 480.00
3. LTA/GIA fee	\$ 31.00
TOTAL:	\$ 7,145.00

The above settlement is in respect of our client's claim for damages pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation of his personal injuries.

Kindly acknowledge by replying to this email and let us have your offer soon.

Your assistance is greatly appreciated.



Thank you.

Warmest Regards,

Rachel Wu

Claims Officer | Motor Claims Department

Hotline (65) 6452 4457 EXT 112 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19002494/Aga3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 01-10-2019



ATTN: STACEY NG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGX 4214P	Veh. Inspected	SKL 692J
Policy No.	GA386619/1	Coverage (\$)	0.00
Claim No.	S9M01DC6	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	11/02/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ B 200	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WDD2462432J196725	Colour	SILVER
Odometer	131225	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/02/2019	Inspection Date	12/02/2019
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 692J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,700.00	1,458.00
1	REAR BUMPER SIDE CORE (LH) (CONSISTENT)	NECESSARY	180.00	68.00
1	REAR BUMPER SIDE CORE (RH) (CONSISTENT)	NECESSARY	180.00	68.00
1	REAR BUMPER CENTRE BRACKET (CONSISTENT)	CRACKED	230.00	230.00
1	REAR BUMPER CHROME MOULDING (LH) (CONSISTENT)	NECESSARY	285.00	129.00
1	REAR BUMPER CHROME MOULDING (RH) (CONSISTENT)	NECESSARY	285.00	129.00
4	REVERSE SENSOR @ \$562.00 (CONSISTENT)	DAMAGED 3PCS ONLY	2,248.00	750.00
1	REAR BUMPER LOWER GARNISH (CONSISTENT)	DEFORMED	60.00	60.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	525.00	525.00
1	REAR BUMPER TOWING CAP (CONSISTENT)	NOT NECESSARY	92.00	-
1	REAR BUMPER BRACKET (LH) (CONSISTENT)	NOT NECESSARY	116.00	-
1	REAR BUMPER BRACKET (RH) (CONSISTENT)	NOT NECESSARY	116.00	-
1	SET REVERSE SENSOR WIRING (CONSISTENT)	NOT NECESSARY	723.00	-
1	TAILGATE (CONSISTENT)	DENTED	1,230.00	1,230.00
1	TAILGATE LOCK (CONSISTENT)	DAMAGED	360.00	360.00
1	TAILGATE LOCK SWITCH (CONSISTENT)	NOT NECESSARY	228.00	-
1	TAILGATE LOCK SENSOR (CONSISTENT)	NOT NECESSARY	180.00	-
1	TAILGATE LOCK CATCH (CONSISTENT)	NOT NECESSARY	75.00	-
1	TAILGATE EMBLEM - LOGO (CONSISTENT)	NECESSARY	54.00	54.00
1	TAILGATE CHROME GARNISH (CONSISTENT)	NOT NECESSARY	335.00	-
1	LICENSE LAMP (LH) (CONSISTENT)	NOT NECESSARY	98.00	-
1	LICENSE LAMP (RH) (CONSISTENT)	NOT NECESSARY	98.00	-
1	TAILGATE LAMP (LH) (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	TAILGATE LAMP (RH) (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	TAILGATE INNER TRIM BOARD (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	TAILGATE INNER SIDE GARNISH (LH) (CONSISTENT)	NOT NECESSARY	113.00	-
1	TAILGATE INNER SIDE GARNISH (RH) (CONSISTENT)	NOT NECESSARY	113.00	-
1	TAILGATE INNER CENTRE GARNISH (CONSISTENT)	NOT NECESSARY	106.50	-
1	TAILGATE WIPER MOTOR (CONSISTENT)	NOT NECESSARY	652.00	-
1	TAILGATE WIPER ARM (CONSISTENT)	NOT NECESSARY	170.00	-

Report Ref No. CC4/ASM19002494/Aga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE RUBBER BEADING (CONSISTENT)	NOT NECESSARY	239.60	-
1	TAILGATE RUBBER STOPPER (LH) (CONSISTENT)	NOT NECESSARY	42.00	-
1	TAILGATE RUBBER STOPPER (RH) (CONSISTENT)	NOT NECESSARY	42.00	-
1	TAILGATE DAMPER (LH) (CONSISTENT)	NOT NECESSARY	330.00	-
1	TAILGATE DAMPER (RH) (CONSISTENT)	NOT NECESSARY	330.00	-
1	TAILGATE HINGE (LH) (CONSISTENT)	NOT NECESSARY	126.00	-
1	TAILGATE HINGE (RH) (CONSISTENT)	NOT NECESSARY	126.00	-
1	REAR WINDSCREEN (CONSISTENT)	NECESSARY	1,284.00	1,284.00
1	TAIL LAMP (LH) (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	TAIL LAMP (RH) (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	END PANEL (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	323.00	-
1	REAR FLOOR PANEL TOP BOARD (CONSISTENT)	NOT NECESSARY	428.00	-
1	REAR FLOOR PANEL (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR EXHAUST MUFFLER (CONSISTENT)	NOT NECESSARY	1,765.00	-
5	REAR EXHAUST MOUNTING @\$90.00 (CONSISTENT)	NOT NECESSARY	450.00	-
1	TAILGATE EMBLEM - B200 (CONSISTENT)	NECESSARY	92.00	92.00
	LESS 10% DISCOUNT		-	-643.70
			16,130.10	5,793.30
SPECIAL NETT ITEMS				
1	REVERSE CAMERA (SN) (CONSISTENT)	NOT NECESSARY	500.00	-
1	REAR NUMBER PLATE & CASING (SN) (CONSISTENT)	NOT NECESSARY	45.00	-
1	REAR BUMPER CHROME PROTECTOR (SN) (CONSISTENT)	DEFORMED	280.00	280.00
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	TAILGATE C&C EMBLEM (SN) (CONSISTENT)	NECESSARY	90.00	50.00
1	SET TAILGATE INNER TRIM BOARD CLIP (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	SET END PANEL TOP GARNISH CLIP (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	END PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	50.00	-

Report Ref No. CC4/ASM19002494/Aga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDRIES (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
			1,195.00	410.00
	LABOUR			
	TO R&R REAR BUMPER REVERSE SENSOR.		80.00	50.00
	TO CHECK WIRING & LIGHTING SYSTEM.		100.00	30.00
	TO RESPRAY UNDERCOATING / PUTTY ON AFFECTED AREAS.	NOT NECESSARY	80.00	-
	TO SUPPLY ANTI RUST TREATMENT ON AFFECTED AREAS.		60.00	50.00
	TO R&R TAILGATE MECHANISM.		280.00	80.00
	TO R&R REAR WINDSCREEN.		200.00	120.00
	TO R&R REAR EXHAUST ASSY.	NOT NECESSARY	250.00	-
	TO R&R REAR TRIMS, GARNISH AND SEATS.		250.00	60.00
	TO R&R FUEL TANK TO CUT & WELD.	NOT NECESSARY	300.00	-
	TO DIAGNOSTIC ERASE FAULT CODE MEMORIES.	NOT NECESSARY	160.00	-
	TO REPAIR, REPLACE AND REALIGN DAMAGED AREAS. INCLUSIVE OF THE REPAIR OF END PANEL.		1,400.00	600.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	600.00
			4,160.00	1,590.00
	GRAND TOTAL		21,485.10	7,793.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,200.00

Report Ref No. CC4/ASM19002494/Aga3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.