



ESTIMATE TO REPAIR

VEHICLE NO. : SKA 3127 M
 MAKE : B.M.W
 MODEL : X6 3.0 A
 YEAR : 2011
 CHASSIS NO : WBAFG22070LL80464

SURVEYOR NAME :
DATE OF SURVEY :
TIME OF SURVEY :

DATE : 12-Feb-19
 DATE OF ACCIDENT : 28-Jan-19
 THIRD PARTY REF : SHB 9981 D / AXA

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper				\$ 1,273.80
1 pc	O/S Front Fender Arch Garnish				\$ 205.75
16 pcs	O/S Front Fender Arch Garnish Clips		\$ 5.00		\$ 80.00
	To putty and spray painting				\$ 1,559.55
	Labour Charges				\$ 450.00
					\$ 350.00
TG/RA-	Total				\$ 2,359.55

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg

Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd