Surveyor Guociano Ass Memon From (Person): Jany Tay of		iqdsez		1/2/190	el moon
Lodina Cost	Bill to:	Day	c/Inne	11121196	4 USPI
OD (TP) WS/TP RES/OD RES/EVA/IN	//MV/CS				-
To Inspect Vehicle No: SCK	622A	Insured:	YP 8	3414	
at Workshop m/s Char	u Motor	Tel	674	79241	
BIK () Kaki £	31C+ NR 6 # 01	-43			
Policy No: B29083968 MKC	Claim No:	58 42	80		
Sum Insured:	Excess:				
Make of Vehr (Client's Record)		D.0	.A. 06	2/02/20	19
CA / REV / REP. / REV 24 HRS			O.D. Endorses	meat:	
Date/Time: 10:37an 012 2 19 Person Co	mtacted Jukys	Vehic	le(IN)OU	T	
Date/Time Action/Instruction () Es	timate				-
8CR 622A-NA/MSG			Dun!	2/2/19	
128341 H- NA/MS	5019002242/1	3	AVA: 2	12/2019	
12120 11111 000 00 01	when compage	man) 1	priding	alstima	fo
1312 MAINT SEVA VIA MEN	THE PARTY OF THE P				-
1312@ 11:41 am- SENT VIA MEN 03/5/19@ 253pm NUISED TO JU	owen Tay Via	Meanin		,	

...CLAIM SUBFOLDER...(New Assignment)

LAIM SUBF	OLDER TRA	CKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adi Sut	mitted	Ins Authled	Status	
Main	11 Feb 2019		11 Feb 2019 16:03 Assign					New Assi Cancel Ca	The state of the s
	Main	Re	ference		Claim Details		Documen	ts	Show All
CLAIM SU	BFOLDER DE	TAILS		- The second second		[Creat	ed by insurer1		The second second
Insured:	UNI-TAT	ICE & MARKETIN	G PTE LTD, C	o. Reg. No.:	199406736C	Lordat	ed by madrer]		
Main Claimant:		G MENG, ID: S1							
Vehicle Reg. No.:	SCR622	A			Date of Loss:		2019 20:00 - :59	om LTA Rea D	ate (Man Yr)]
Claim Type:	TP / 584	280			Policy/Cover Note No.:	[96 Months and 9 Days From LTA Reg Date (Man B29083968MKC (Comprehensive) Coverage: 11/05/2018 - 10/05/2019			
Vehicle Reg. No. (Insured):	YP8341H				Policy No. (Claimant):		,	0,00,2013	
					Excess:	S\$800.0			
Repairer:	Chew Mot	or Pte Ltd (HQ)	BLOCK 1 KAKI B	UKIT AVE 6,	#01-43, 41788	3 Kaki Bu	kit - Tel: 67479241	4	
Handling Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (H	IQ) - Tel: +6	5 6827 7888	[Handled	by Jowyn Tay Me	el Ling - 6643	3 1307]
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Imm.Adv	ice due	12/02/20191		
Driver/Custo dian (Insured):)	N ELAIYARAJA (27							
Adj Asg. Remarks:	on WP. SJE	: AGREED / LIABI	LITY 100% Plea	se contact SL	JKYI CHONG @	6747 924	11 to arrange for su	rvey .	
ASSOCIAT	ED MAIL RE	CEIVED					Г	View All Co	mpose Case Mail
There are no	mail for this	case.						TOWN AND THE	mpose case Mail
ALL ASSO	CIATED TAS					View A		Create New	Task Complete
No results.	Priority	Type Task (Group Subj	ect Hand	ler Assign	ed By	Completed On	Create	d On Done?

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Jowyn Tay Mei Ling

Date: 03 May 2019

Preliminary Advice

Insured Vehicle No : YP8341H

TP Vehicle No

: SCR622A

Accident Date

: 02/02/2019

Make

: MERCEDES-BENZ E250

Assignment Date

: 11/02/2019

Est. Duration of Repair

: 11.00

Date of Inspection : 11/02/2019

Inspection At

: CHEW MOTOR PTE LTD (HQ)

NO 1 KAKI BUKIT AVE 6, #01-11/41, AUTOBAY@KAKI BUKIT

SINGAPORE 417883

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,673.20
Revised Amount	:S\$	20,394.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	20,394.90
Lump Sum Repair	:S\$	16,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle	is economical/not	economical	for repair
---	---	-------------	-------------------	------------	------------

(X) The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with:

*SCR622A (584280) [YP8341H] TP

GOH TONG MENG Feb 2 2019 8:00PM [UNI-TAT ICE & MARKETING PTE LTD] Chew Motor Pte Ltd

Resend	View Recipients Print Messa	e Delete Message	Forward	
From	LKK Auto Consultants Pte	td (LKK HO), sent	t on 13/02/2019 11:41 AM.	
То	SGSGJTML			
Cubiact	*CCD622A (594290) [VD9	24111		

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SCR 622A on 11/2/2019 We are pending estimate from repairer.

Regards, Denise

LKK Auto Consultants Pte.Ltd.

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC	
Owner ID:	5145A	
Vehicle Details		
Vehicle No.:	SCR622A	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	12 Feb 2019	
Vehicle Make:	MERCEDES BENZ	
Vehicle Model:	E 250CGI	
Primary Colour:	Silver	
Manufacturing Year:	2010	
Engine No.:	27186030166454	
Chassis No.:	WDD2120472A358760	
Maximum Power Output:	150.0 kW (201 bhp)	
Open Market Value:	\$55,808.00	
Original Registration Date:	24 Jan 2011	
First Registration Date:	24 Jan 2011	
Transfer Count:	1	
Actual ARF Paid:	\$55,808.00	
Intended PARF Rebate Details		
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	23 Jan 2021	
PARF Rebate Amount:	\$30,694.00	
Intended COE Rebate Details		
COE Expiry Date:	23 Jan 2021	
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	10	
QP Paid:	\$69,000.00	
COE Rebate Amount:	\$13,429.00	
Total Rebate Amount:	\$44,123.00	


The information contained herein is correct as at 12 Feb 2019

RENEW




%*P.A ONLY

MONEYBMAX MEMBER OF MONEYMAX FINANCIAL SERVICES LTD.







view our cars

Low prices guaranteedSpecialist in Japanese cars





High Loan Available, Price Stated Above Is Actual Selling Price, Low Mileages, Good For Further COE Renewal, Accident-Free, STA Evaluation Are Welcome, Purchase Comes With Official Warranty Certificat...

Posted: 11-Feb-2019 Tags: 2011 Mercedes-Benz E250, 2011 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz E250, e250, Used Mercedes-Benz e250, mercedes-benz e250,

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Mercedes-Benz E-Class E250 **CGI Coupe AMG**

\$62,800

\$16,620 /yr

21-Mar-2011

1,796 cc

99,000 km

Sports

Available

Newly Arrived! E250 Coupe With Full AMG Bodykits. Low Mileage Done. Flexible In House Loan, Excellent Interior Condition! Black Leather Sport Seats, New Paintwork Done. 100% Accident Free, High Trade ...

Posted: 01-Jan-2019 Tags: 2011 Mercedes-Benz E250, 2011 mercedes-benz e250, Mercedes-B



Mercedes-Benz E-Class E250 CGI Avantgarde

\$57,800

\$13,960 /yr

31-Mar-2011

1,796 cc

78,000 km

Luxury

Available

Rare High Specification Option Unit With Only 1 Careful Owner, Exterior And Interior Well Groomed By Prestige Retailer, 100% Major And Minor Accident Free With, 6 Months Road Tax And Servicing Done Bu...





6



Posted: 08-Feb-2019 Tags: 2011 Mercedes-Benz E250, 2011 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz E250, e250, Used Mercedes-Benz e250, mercedes-benz e250,

	Mercedes-Benz E-Class E250	\$66,900	\$16,450 /yr	29-Apr-2011	1,796 cc	118,698 km	Sports	Available
EN	(We Assure 100% Genuine Mileage,) Orig Attractive And Charming Look, Very Well I	inal Condition, Be Maintained. Accid	eautiful White Cabri	olet Mercedes Benz	E250 AMG. This	Sporty Car Always	Give You An	
	C Briefwer DC Sain 2010 Tags: 2011 Me		2011 mercedes-benz	r e250, Mercedes-Ber	z E250, mercedes	benz e250,		
	Mercedes-Benz E-Class E250 CGI	\$62,000	\$14,680 /yr	10-Jun-2011	1,796 cc	1 :	Luxury	Available
	Major Servicing Done With Many Wear An Always Parked Under Shelter, Immaculate	d Tear Parts Rep Condition. Comf	laced, Oil Change R for	legularly Every 7k K	M, All With Rece	ipt To Prove. PPS D	one For 1 Year,	PREMIUM AD
	Posteg: 13-Jan-2019 Tags: 2011 Mer Mercedes-Benz,	rcedes-Benz E250, E250, e250, Used	2011 mercedes-benz Mercedes-Benz	e250, Mércedes-Ben	z EZ50, mercedes-	benz e250,		
7	Mercedes-Benz E-Class E250 CGI Avantgarde	\$57,800	\$13,890 /yr	20-Jun-2011	1,796 cc		Luxury	Available
	Just Arrived, Very Well Maintained And Pro Condition, Extra 1 Year Pre-Owned Compri	oblem Free, No R ehesive Warranty	epairs Needed, 100 Wi	Points Checked By	Reputable Work	shop To Prove The	Car Outstanding	PERMITM XX
	Posted: 27-Jan-2019 Tags: 2011 Mercedes-Benz.	rcedes-Benz E250, E250, e250, Lised	2011 mercedes-benz Mercedes-Benz	e250, Mercedes-Ben	z E250, mercedes-	benz e250,		
*	Mercedes-Benz E-Class E250 CGI Coupe	\$64,300	\$15,280 /yr	12-Aug-2011	1,796 cc	135,000 km	Sports	Available
	Very Well Maintained, Regularly Serviced! Available! Call Now To View!	Classy Sporty Loc	oking Coupe! Suitab	ole For Short Term (Orive! Flexible In	House Financing Ar	nd High Trade In	1
	Hui Hua Credit Pte Ltd	cedes-Benz E250	2011 mercedes-benz	n350 Mercadas Bon	ESSA mismodur.	have also		
	Posted: 14-Jan-2019 1493: 2011 Mer Mercedes-Benz,	E250, e250, Used	Mercedes-Benz	stativy Prosteurinoens	EZBU, mercedes-	Denz ezau,		
D CANCE	Insurance renewal at cheaper pric	e!						
CAR MEURANCE	We'll find you the cheapest car insurance of comfort of your own home. Roadside assist	uotes from over tance & claims su	10 insurers. Make y	our choice on zero	excess and own	workshop, Everythi	ng done at the	
	Find out more!							
FA	Mercedes-Benz E-Class E250	\$59,800	\$13,020 /yr	05-Sep-2011	1,796 cc	145,000 km	Luxury	Available
	Know Who You Buying From Otherwise End	d Up Buying A Ex	-Grab Car! C&C Uni	it. Regularly Servici	ng, Always Parke	d Under Shelter, Im	maculate	
	Posteri 01-Feb-2019 Tags: 2011 Merc	edes-Benz E250, 2	Kepair K 2011 mercedes-benz					CHRECT OWNER
	Mercedes-Benz, E	E250, e250, Used N	dercedes-Benz		MARKET TITLESCHOOL S			
1300	Mercedes-Benz E-Class E250 CGI Avantgarde	\$59,999	\$14,100 /yr	28-Sep-2011	1,796 cc	81,888 km	Luxury	Available
	PI, Well Maintenance, Low Mileage, 1 Owner	er.						DIFFECT OWNER
1	Posted 29-Dec-2018 Tags: 2011 Mero Meroedes-Benz, B	edes-Bonz E250, 2 E250, e250, Used N	011 mercedes-benz o Mercedes-Benz	1250, Mercedes-Benz	E250, mercedes-b	enz e250,		
	Mercedes-Benz E-Class E250 CGI Cabriolet	\$77,800	\$18,470 /yr	07-Oct-2011	1,796 cc	75,000 km	Sports	Available
	New Tyres, Sexy Black With Sporty Red Lea Utilized Car. Please Make Appointment For Y	ther, Excellent C	ondition. 100% Acc	ident Free And Wel	Maintained, In	Great Condition For	Its Age. Under	
	Poster: 25-Jan-2019 Tags: 2011 Merc	edes-Benz E250, 2	011 mercedes-benz e	250, Mercedes-Benz	E250, mercedes-b	enz e250.		
	Mercedes-Benz, E	250, e250, Lised M	fercedes-Benz					
1	Mercedes-Benz E-Class E250 CGI	\$73,888	\$17,370 /yr	27-Oct-2011	1,796 cc	148,200 km	Luxury	Available
	Well Maintaned By Owner. E-Class Blends P	erfectly For Busin	ness And Leisure, Pl	ease Contact, View	ing By Appointme	ent Only, Venue To	Be Advised.	
	Posteri 74-199-2010 Tags: 2011 Mero		011 mercedes-benz e					PREMIUM AD
	Save this search criteria	a, to get email ale	erts whenever a ma	itch is found.	Save Seam	h		
	Make ▼ Model ▼ ‡	Price ▼ 🗧 [Depreciation ▼	Reg Date ▼ 🔮	Eng Cap ▼	Mileage ▼ 🗐 \	/eh Type ▼	Status 🔻 🕏
For old advertisements,	view Expired ads						20 ▼	results/page
	Home New Cars Used Cars 5	Sell My Car I	Directory Prod	ucts Insurance	Article F	forum Resource	es	

SQCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, fuxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car dealers. Singapore, used e250 Singapore, used e250 Singapore, used e250 Singapore, used e250 Singapore. We have new car dealers comprising parallel dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Oriver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

A A

Beaok worth Ra

×

beaute nowth the 3

B

A SCR67210

B: YPB341H

(FBN3783G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

rieure	THEY TO	police rej	DOVA 1/2	20190202/21	65.
			3,777		
				7	
				/	
			-/-	5,	
			/		
		/			
		/			A
	/	\sim		THE PARTY	8
				A SAP TO	
	/				

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time: Oriver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:





police Station Of Origin: Changi N.P.C

9 Simei Street 2 SINGAPORE 529914

Tel No. 1800-5872999

1 of 4

Report No T/20190202/2165

PEPORT	OF A	TRAFFIC	ACCIDENT

	Date/Time Report Made : 02/02/2019 21:09		Vide Report No	Station Diary No 41	
-					
	Informant: NG MENG		Address: 1 FLORA DRIVE #01-04 SIN	GAPORE 507009	
ID Type / ID No.: NRIC NO / S1275145A			Contact No: Home/Office: Mobile: 96669280		
Nationali SINGAP	ty: ORE CITIZ	EN	Email:		
Sex: Male	Age: 61	Date of Birth: 30/08/1957	Type of Informant:		
Race: Chinese			Language: Institution / School National English		
Occupation: COMPANTY DIRECTOR			Driving Licence Information: Class: 3	Date of Expiry	

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 02/02/2019 20:05	Type of Location	
Location: Along Road 1 BEDOK NOR BEDOK NOR					
Weather:		Road Surface:		Road Speed Limit	
Traffic Flow:		Traffic Control: Traffic Light - Wo	rking	Traffic Volume Moderate	
Type of Collision 3 way collision				Anyone conveyed by ambulance No	

FBN3783G	Motorcycle	Control consequence	The second second second			
					Seriously Damaged	1
SCR622A	Car	MERCEDES BENZ	E 250CGI	Silver	Seriously	0
WP8341H	Lorry	pl S	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Damaged	0





POLICE FORCE

Police Station Of Origin Changi N.P.C

9 Simei Street 2 SINGAPORE 529914

Tel No: 1800-5872999

CONTINUATION OF REPORT

2 of 4

Report No T/20190202/2165

SCR622A	AIG ASIA PACIFIC INSURANCE PTE	2100328369-06	24/01/2019	23/01/2020
	LTD.			

	volved: No			5 0102		
No. of Pedestrian	s Injured: NIL		Use of Ped	destria	n Cross	sing: NA
				4		
Name	Yeo Beng Koon			ID No).	S8713040A
Related Vehicle	FBN3783G (Motorcy	cle)		Conta	ect No	96234497
Hospital/Clinic	NIL			Class Drivin Licen- Expin	g	Class: NIL Date of Expiry NIL
Date Treatment	NIL		Date Disci			
	ted Medical Leave	NIL	Degree of			
Name	GOH TONG MENG			ID No		S1275145A
Related Vehicle	SCR622A (Car)			Conta	ect No.	96669280
Hospital/Clinic	NIL			Class Drivin Licen Expir	ng .	Class 3 Date of Expiry NIL
Date Treatment	NIL		Date Disc	harge	NII	
	ted Medical Leave	NIL	Degree of			
Name	Divar Veerappan Ela	iyraja		ID No) .	G2158393L
Related Vehicle	YP8341H (Lorry)			Conta	act No.	90080662
Hal/Clinic	NIL			Class Drivin Licen Expir	ng	Clase: NIL Date of Explry: NIL
ment	NIL		Date Disc			
Test Contract	ted Medical Leave	NIL	Degree of			The state of the s





3 of 4

Report No. T/20190202/2165

Police Station Of Origin: Changi N.P.C

9 Simei Street 2 SINGAPORE 529914

Tel No: 1800-5872999

CONTINUATION OF REPORT

Brief Details.

On the above stated date and time, I was travelling along the said road. I was on the right side of the road wanting to proceed towards PIE. After the junction, the motorcycle was in front of me and it had brake as the vehicle in front of it has stopped as well. Thus I followed and stopped my vehicle. Out of a sudden, the below mentioned lorry, hit the rear of my vehicle and due to the hit from the lorry, my vehicle was pushed in front and I hit the motorcycle due to the force.

All the drivers and rider exchanged particulars and no one was injured.



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk C #01-41 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com Registration No.: 201718369R

11/02/2019

Blk 1 Kaki Bukit Ave 6

01-43

WDD2120472A358760.

Singapore 417883

Accident date: 02/02/2019

Estimated repair cost for vehicle no: SCR622A MERCEDES E250 1.8 A '11

		CHASSIS: WDD2120472A358760		
S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet Devoted		\$2,536.00
2	2	Front Bonnet Hinge	\$145.00	\$290.00
3	2	Front Bonnet Shock Absorber	\$160.00	\$320.00 +
3 4	1	Front Bonnet Emblem Logo		\$157.00
5	1	Front Bonnet Center Lock 2 MP		\$166.00
6	2	Front Bonnet Side Lock	\$85.00	\$170.00 +.
7	1	Front Grille Could		\$1,248.00
8	6	Front Grille Clip New	\$8.00	\$48.00 3
9	2	Front Head Lamp RH crucked	\$1,205.00	\$2,410.00 /2
10	2	Front Head Lamp Lower Bracket > We Mee	\$68.00	\$136.00 💥
11	1	Front Bumper Dehand		\$1,560.00
12	10	Front Bumper Clip	\$6.50	\$65.00 3~
13	2	Front Bumper Side Retainer	\$70.00	\$140.00
14	2	Front Bumper Side Chrome RH wt	\$186.00	\$372.00 /
15	2	Front Bumper Fog Lamp RH could	\$256.00	\$512.00-2
16	2	Front Bumper Fog Lamp Cover Kirl Nile	\$53.00	\$106.00
17	1	Front Bumper Lower Garnish Couled		\$155.00
18	2	Front Bumper Inner Sponge RH crucled	\$111.00	\$222.00
19	1	Front Bumper Reinforcement AR Nec		\$575.00 \chi
20	1	Front Bumper Number Plate Best		\$50.00
21	1	Front Bumper Number Plate Garnish Deliand		\$165.00
22	4	Front Bumper Sensor Piles dund	\$285.00	\$1,140.00
23	2	Front Head Rest	\$982.00	\$1,964.00
24	1	Rear Boot Lid Devted		\$2,945.00
25	2	Rear Boot Lid Hinge	\$143.00	\$286.00
26	1	Rear Boot Lid Emblem Logo 🤈		\$58.00
27	1	Rear Boot Lid E250 Logo		\$75.00
28	1	Rear Boot Lid Cc Logo		\$65.00
29	1	Rear Boot Lid Cgi Logo		\$73.00

30	1	Rear Boot Lid Center Chrome ** Chrome		\$128.00 🗡
31	2	Rear Boot Lid Side Reflector Lat	\$475.00	\$950.00
32	1	Rear Boot Lid Inner Lock		\$370.00
33	1	Rear Boot Lid Inner Rubber at		\$165.00
34	1	Rear Boot Lid Inner Trim Board XM M		\$329.00
35	1	Rear Boot Lid Number Plate 147		\$50.00 ×
36	1	Rear Boot Lid Camera HM M		\$680.00 ×
37	2	Rear Tail Lamp Cacked	\$657.00	\$1,314.00
38	4	Rear Tail Lamp Clip New	\$8.00	\$32.00
39	1	Rear Bumper De horad		\$1,725.00
40	10	Rear Bumper Clip Mer	\$6.50	\$65.00 30
41	2	Rear Bumper Side Retainer	\$48.00	\$96.00
42	1	Rear Bumper Lower Lid 🔀 🗫 🦰		\$494.00
43	1	Rear Bumper Towing Cover ************************************		\$57.00
44	1	Rear Bumper Center Chrome		\$202.00
45	2	Rear Bumper Side Chrome	\$188.00	\$376.00
46	1	Rear Bumper Reinforcement Best.		\$862.00
47	4	Rear Bumper Reverse Sensor 2 pieces dend	\$296.00	\$1,184.00 500
48	1	Rear End Panel Dovice		\$387.00
49	1	Rear End Panel Top Garnish etucked		\$178.00
50	1	Rear Spare Tyre Panel Repr		\$306.00 *
51	1	Rear Spare Tyre Panel Top Cover		\$412.00 +
52	2	Rear Fender Inner Trim Board 2 M	\$335.00	\$670.00 *
53	16	Rear Fender Inner Trim Board Clip	\$6.50	\$104.00 7
54	1	Rear Exhaust		\$1,995.00
55	1	Rear Exhaust Chrome Pipe		\$206.00
56	2	Rear Exhaust Mounting KM W	\$39.60	\$79.20 🗶
57	1	Rear Exhaust Aluminium Cover M M		\$125.00
58	1	Rear Center Exhaust		\$1,363.00

18261 Subtotal:- \$32,913.20

Labour charges

Panel beating		\$2,400.00 600
Tuff kote	3960	\$150.00 50
To check wiring		\$100.00 ()
To reset computer		\$450.00 (3)
To reset front head rest		\$380.00 200
To remove & refit rear camera		\$180.00 50
To remove & refit rear & center exhaust		\$380,00 100
To remove & refit reverse sensor		\$120.00 60
To remove & refit front sensor		\$120.00 6 0
To remove & refit cushion & trim board		\$280.00 80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :-\$6,760.00

\$39,673.20

tolal. 20394.90 1/5: 16K (Nett Value)

Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBI	FOLDER TRA	1		Transferre	1	N1000 1000 1000	Turner than the purpose	Tax		
Case	Notified 11 Feb 2019	Est Submitted	Adj Assigned 11 Feb 2019 16:03 Edit Adj Rpt	S\$16,000.00 Edit Estimates	S\$16,0 View I	200	Ins Auth'ed	Pending for Su Report Cancel Case		4
	Main	R	eference	Claim De	ails		Documen	ts		Show All
CLAIM SU	BFOLDER DE	TAILS	THE RESERVE TO SERVE THE PARTY OF THE PARTY		[[Created	by insurer]			
Insured:	UNI-TAT	ICE & MARKETI	NG PTE LTD, Co. R	eg. No.: 19940673	C					
Main Claimant:	GOH TON	GOH TONG MENG, ID: S1275145A								
Vehicle Reg No.:	SCR622	Α		Date of			9 20:00 - :59 s and 9 Days Fro	om LTA F	Reg Date (N	lan Yr)]
Claim Type	TP / 584	280		Policy/O Note No		329083968MKC (Comprehensive) Coverage: 11/05/2018 - 10/05/2019				
Vehicle Reg No. (Insured):	YP8341H			Policy N (Claima						
				Excess:	S	\$800.00				
Repairer:	Chew Mo	tor Pte Ltd (HQ)	No 1 Kaki Bukit Ave	6, #01-11/41, Aut	bay@Kal	ki Bukit, 4	17883 Kaki Buk	cit - Tel:	67479241	6509554
Handling Insurer:		2 5 6	ore) Pte. Ltd. (HQ)				100 55	100		
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Handle	by XIN	G GUO Q	IANG] [Fin	al Rpt	due 13/0	3/2019]
Driver/Cust dian (Insured):		N ELAIYARAJA (2	7 / Male) , NRIC: 0	52158393L, Tel: +	6590080	662 Emai	1:			
Adj Asg. Remarks:	on WP. SJ	E : AGREED / LIA	BILITY 100% Please	contact SUKYI CHO	NG @ 674	17 9241 to	o arrange for su	rvey .		
ASSOCIAT	TED MAIL RE	CEIVED					V	iew All	Compos	e Case Mai
There are n	o mail for this	case.								
ALL ASSO	CIATED TAS	sks⊟			Viev	w All	Search Tasks	Create N	New Task	Complete
Due Date	e Priority	Type Task	Group Subjec	t Handler	ssigned	Ву	Completed Or	1 0	reated On	Done

Claim Documents

*SCR622A (584280)

[YP8341H]

TP

GOH TONG MENG

Feb 2 2019 8:00PM

[UNI-TAT ICE & MARKETING PTE LTD]

Chew Motor Pte Ltd

Ass	essment Reports		1 per page	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnai	Print
1	11/02/19 08:47	Accident Statement From:SC - Reg. No: YP8341H, Claimant: UNI-TAT ICE & MARKETING PTE LTD	1 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnai	Print
1	03/05/19 14:53	Adjuster Immediate Advice	1 Load HTM	
Pho	otos/Images		3 per page 🔍	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnai	Print
1	03/05/19 14:42	General View	Load JPG	✓
2	03/05/19 14:42	General View	■ Load JPG	V
3	03/05/19 14:42	General View	Load JPG	V
4	03/05/19 14:42	General View	Load JPG	V
5	03/05/19 14:42	General View	■ Load JPG	V
6	03/05/19 14:42	General View	Load JPG	V
7	03/05/19 14:42	General View	Load JPG	~
8	03/05/19 14:42	General View	Load JPG	V
9	03/05/19 14:42	General View	♠ Load JPG	V
10	03/05/19 14:42	General View	Load JPG	V
11	03/05/19 14:42	General View	Load JPG	V
12	03/05/19 14:42	General View	₫ Load JPG	V
13	03/05/19 14:42	General View	1 Load JPG	V
14	03/05/19 14:42	General View	♠ Load JPG	~
15	03/05/19 14:42	General View	Load JPG	V
16	03/05/19 14:42	General View	Load JPG	V
17	03/05/19 14:42	General View	⑥ Load JPG	V
18	03/05/19 14:42	General View	Load JPG	V
19	03/05/19 14:42	General View	♠ Load JPG	~
20	03/05/19 14:42	General View	1 Load JPG	V
21	03/05/19 14:42	General View	■ Load JPG	V
22	03/05/19 14:42	General View	1 Load JPG	V
23	03/05/19 14:42	General View	6 Load JPG	~
24	03/05/19 14:42	General View	Load JPG	V
25	03/05/19 14:42	General View	1 Load JPG	V
26	03/05/19 14:42	General View	Load JPG	~
27	03/05/19 14:42	General View	£ Load JPG	V
28	03/05/19 14:42	General View	1 Load JPG	✓
29	03/05/19 14:42	General View	Load JPG	V
30	03/05/19 14:42	General View	Load JPG	V
31	03/05/19 14:42	General View	■ Load JPG	V

Ass	essment Reports		1 per page V	-
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbna	Il Print
33	03/05/19 14:42	General View	■ Load JPG	1
34	03/05/19 14:42	General View	1 Load JPG	_
35	03/05/19 14:42	General View	1 Load JPG	-
36	03/05/19 14:42	General View	1 Load JPG	-
37	03/05/19 14:42	General View	1 Load JPG	1-
		General View	1 Load JPG	-
38	03/05/19 14:42	General View	1 Load JPG	_
39 40	03/05/19 14:42	General View	1 Load JPG	-
		General View	1 Load JPG	_
41	03/05/19 14:42		1 Load JPG	
42	03/05/19 14:42	General View	1 Load JPG	
43	03/05/19 14:42	General View	1 Load JPG	
44	03/05/19 14:42	General View		-
45	03/05/19 14:42	General View	1 Load JPG	_
46	03/05/19 14:42	General View	1 Load JPG	
47	03/05/19 14:42	General View	Load JPG	-
48	03/05/19 14:42	General View	1 Load JPG	_
49	03/05/19 14:42	General View	1 Load JPG	
50	03/05/19 14:42	General View	1 Load JPG	_
51	03/05/19 14:42	General View	1 Load JPG	-
52	03/05/19 14:42	General View	1 Load JPG	
53	03/05/19 14:42	General View	1 Load JPG	
54	03/05/19 14:42	General View	1 Load JPG	-
55	03/05/19 14:42	General View	1 Load JPG	_
56	03/05/19 14:42	General View	Load JPG	∀
57	03/05/19 14:43	Reinspection Photo	1 Load JPG	V
58	03/05/19 14:43	Reinspection Photo	1 Load JPG	☑
59	03/05/19 14:43	Reinspection Photo	■ Load JPG	✓
60	03/05/19 14:43	Reinspection Photo	Load JPG	
61	03/05/19 14:43	Reinspection Photo	■ Load JPG	
62	03/05/19 14:43	Reinspection Photo	1 Load JPG	V
63	03/05/19 14:43	Reinspection Photo	€ Load JPG	V
64	03/05/19 14:43	Reinspection Photo	1 Load JPG	Z
65	03/05/19 14:43	Reinspection Photo	■ Load JPG	
66	03/05/19 14:43	Reinspection Photo	€ Load JPG	∀
67	03/05/19 14:43	Reinspection Photo	1 Load JPG	V
68	03/05/19 14:43	Reinspection Photo	1 Load JPG	V
69	03/05/19 14:43	Reinspection Photo	■ Load JPG	V
70	03/05/19 14:43	Reinspection Photo	1 Load JPG	V
71	03/05/19 14:43	Reinspection Photo	1 Load JPG	· •
72	03/05/19 14:43	Reinspection Photo	1 Load JPG	-
73	03/05/19 14:43	Reinspection Photo	1 Load JPG	
74	03/05/19 14:43	Reinspection Photo	1 Load JPG	-
75	03/05/19 14:43	Reinspection Photo	1 Load JPG	_
76	03/05/19 14:43	Reinspection Photo	1 Load JPG	
77	03/05/19 14:43	Reinspection Photo	1 Load JPG	
78	03/05/19 14:43	Reinspection Photo	1 Load JPG	
			1 Load JPG	_
79	03/05/19 14:43	Reinspection Photo	1 Load JPC	
80	03/05/19 14:43	Reinspection Photo Reinspection Photo	1 Load JPG	

Ass	essment Reports		1 per page	√
No 82	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Reinspection Photo	Thumbna D Load JPC	
	03/05/19 14:43	•		1.4
3	03/05/19 14:43	Reinspection Photo	1 Load JPC	-
4	03/05/19 14:43	Reinspection Photo	1 Load JPC	-
5	03/05/19 14:43	Reinspection Photo	1 Load JPC	-
6	03/05/19 14:43	Reinspection Photo	1 Load JPC	_
7	03/05/19 14:43	Reinspection Photo	1 Load JPC	-
88	03/05/19 14:43	Reinspection Photo	1 Load JPC	G 🔽
39	03/05/19 14:43	Reinspection Photo	1 Load JPC	_
90	03/05/19 14:43	Reinspection Photo	1 Load JPC	3 🛂
91	03/05/19 14:43	Reinspection Photo	1 Load JPC	3 🛂
2	03/05/19 14:43	Reinspection Photo	1 Load JPC	3 🔽
93	03/05/19 14:43	Reinspection Photo	1 Load JPC	3 •
94	03/05/19 14:43	Reinspection Photo	1 Load JPC	3 🗸
95	03/05/19 14:43	Reinspection Photo	1 Load JPC	3 •
96	03/05/19 14:43	Reinspection Photo	1 Load JPC	3 🔽
7	03/05/19 14:43	Reinspection Photo	1 Load JPC	
98	03/05/19 14:43	Reinspection Photo	1 Load JPG	-
99	03/05/19 14:43	Reinspection Photo	1 Load JPC	
100	03/05/19 14:43	Reinspection Photo	1 Load JPG	-
01	03/05/19 14:43	Reinspection Photo	1 Load JPG	
102	03/05/19 14:43	Reinspection Photo	€ Load JPC	
03	I Company of the Company	Reinspection Photo	1 Load JPG	-
	03/05/19 14:43		1 Load JPC	
104	03/05/19 14:43	Reinspection Photo		_
105		Reinspection Photo	Load JPC	_
106	03/05/19 14:43	Reinspection Photo	① Load JPC	_
107	03/05/19 14:43	Reinspection Photo	■ Load JPC	
108		Reinspection Photo	① Load JPC	
109	03/05/19 14:43	Reinspection Photo	1 Load JPC	_
110	03/05/19 14:43	Reinspection Photo	1 Load JPC	
111	03/05/19 14:43	Reinspection Photo	1 Load JPC	_
112	03/05/19 14:43	Reinspection Photo	1 Load JPC	-
113	03/05/19 14:43	Reinspection Photo	Load JP6	G ▼
114	03/05/19 14:43	Reinspection Photo	1 Load JPC	G 🖳
115	03/05/19 14:43	Reinspection Photo	1 Load JPC	G 🔽
116	03/05/19 14:43	Reinspection Photo	■ Load JPC	G 🔽
117	03/05/19 14:43	Reinspection Photo	1 Load JPC	G 🛂
118	03/05/19 14:43	Reinspection Photo	Load JPG	g 🔽
19	03/05/19 14:43	Reinspection Photo	1 Load JPG	G ⋤
120	03/05/19 14:43	Reinspection Photo	1 Load JPC	g ⋤
121	03/05/19 14:43	Reinspection Photo	1 Load JPG	
122	I DOWN THE STREET	Reinspection Photo	■ Load JPC	
123		Reinspection Photo	D Load JPC	
124	Control of the Contro	Reinspection Photo	■ Load JPC	
125		Reinspection Photo	1 Load JPG	
126		Reinspection Photo	1 Load JPG	-
27	B = 1.2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Reinspection Photo	1 Load JPG	
_		Reinspection Photo	1 Load JPC	-
	03/05/19 14:43		1 Load JPC	
129		Reinspection Photo		-
130		Reinspection Photo		
131	03/05/19 14:43	Reinspection Photo	1 Load JP6	3

Asse	essment Reports		1 per	page 🗸	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	
132	03/05/19 14:43	Reinspection Photo	Ō	Load JPG	V
133	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
134	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
135	03/05/19 14:43	Reinspection Photo	Ð	Load JPG	~
136	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
137	03/05/19 14:43	Reinspection Photo	0	Load JPG	~
138	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
139	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
140	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
141	03/05/19 14:43	Reinspection Photo	Ð	Load JPG	V
142	03/05/19 14:43	Reinspection Photo	0	Load JPG	✓
143	03/05/19 14:43	Reinspection Photo	Ð	Load JPG	V
144	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
145	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
146	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
147	03/05/19 14:43	Reinspection Photo	0	Load JPG	~
148	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
149	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
150	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
151	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
152	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
153	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
154	03/05/19 14:43	Reinspection Photo	0	Load JPG	~
155	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
156	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
157	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
158	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
159	03/05/19 14:43	Reinspection Photo	0	Load JPG	~
160	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
161	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
162	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
163	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
164	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
165	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
166	03/05/19 14:43	Reinspection Photo	0	Load JPG	~
167	03/05/19 14:43	Reinspection Photo	0	Load JPG	✓
168	03/05/19 14:43	Reinspection Photo	0	Load JPG	V
Doc	umentation		1 per	The state of the s	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	A	Thumbnail	Print
1	11/02/19 08:47	TPD SCR622A - PRI	0	Load PDF	
2	11/02/19 13:07	Reply email to TP Workshop & appoint LKK AUTO	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Merimen e-Claims Page 5 of 5

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19002520/AGQD3E2

Date:

08/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

B29083968MKC

Claimant Vehicle

SCR622A

Insured Vehicle No:

YP8341H

Date of Loss:

02/02/2019

Nature of Claim:

TP

Claim No: 584280

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

No:

SCR622A

Make & Model:

MERCEDES-BENZ E250, 1.8 CGI (A)

Engine No:

27186030166454

207736 km

Reg. Date: Colour:

Silver

24/01/2011 (Man. Year: 2010)

Chassis No: Odometer:

WDD2120472A358760

Engine Capacity:

1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

245/45 R17

Rear Tyre Size:

245/45 R17

Front Left Side:

Michelin 6 mm

Rear Left Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

Front Right Side: Michelin 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,913.20	16,434.90	16,478.30	50.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,760.00	3,960.00	2,800.00	41.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,673.20	20,394.90	19,278.30	48.59
Approved Total (Overridden) (S\$)		16,000.00		
(S\$)	39,673.20	16,000.00	23,673.20	59.67
+ GST 7.00/7.00% (S\$)	2,777.12	1,120.00	1,657.12	59.67
Nett Amount (S\$)	42,450.32	17,120.00	25,330.32	59.67

INSPECTION

Date of Assignment:

11/02/2019

Date Inspected:

11/02/2019 Inspected At:

Chew Motor Pte Ltd (HQ)

No 1 Kaki Bukit Ave 6, #01-11/41,

Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair:

11.0 days

Adjuster: XING GUO QIANG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	ce		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2019)	
Parts:	143	MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SCR622A)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info	Items/values	not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BONNET	Dented	2,536.00 F	*2,067.00 FL
2	2	*FRONT BONNET HINGE @\$145.00	Not Necessary	290.00 F	*-FL
3	2	*FRONT BONNET SHOCK ABSORBER @\$160.00	Not Necessary	320.00 F	*-FL
4	1	*FRONT BONNET EMBLEM LOGO	Necessary	157.00 F	*157.00 FL
5	1	*FRONT BONNET CENTER LOCK	Not Necessary	166.00 F	*- FL
6	2	*FRONT BONNET SIDE LOCK @\$85.00	Not Necessary	170.00 F	*- FL
7	1	*FRONT GRILLE	Cracked	1,248.00 F	*895.00 FL
8	6	*FRONT GRILLE CLIP @\$8.00	Necessary	48.00 F	*30.00 FL
9	2	*FRONT HEAD LAMP @\$1205.00	O/S Cracked	2,410.00 F	*1,205.00 FL
10	2	*FRONT HEAD LAMP LOWER BRACKET @\$68.00	Not Necessary	136.00 F	*-FL
11	1	*FRONT BUMPER	Deformed	1,560.00 F	*1,381.00 FL
12	10	*FRONT BUMPER CLIP @\$6.50	Necessary	65.00 F	*30.00 FL
13	2	*FRONT BUMPER SIDE RETAINER @\$70.00	Necessary	140.00 F	*140.00 FL
14	2	*FRONT BUMPER SIDE CHROME @\$186.00	O/S Cut	372.00 F	*186.00 FL
15	2	*FRONT BUMPER FOG LAMP @\$256.00	O/S Cracked	512.00 F	*256.00 FL
16	2	*FRONT BUMPER FOG LAMP COVER @\$53.00	Not Necessary	106.00 F	*- FL
17	1	*FRONT BUMPER LOWER GARNISH	Cracked	155.00 F	*155.00 FL
18	2	*FRONT BUMPER INNER SPONGE @\$111.00	O/S Cracked	222.00 F	*111.00 FL
19	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	575.00 F	*- FL
20	1	*FRONT BUMPER NUMBER PLATE	Bent	50.00 F	*50.00 FL
21	1	*FRONT BUMPER NUMBER PLATE GARNISH	Deformed	165.00 F	*165.00 FL
22	4	*FRONT BUMPER SENSOR @\$285.00	Damaged-1PC ONLY	1,140.00 F	*250.00 FL
23	2	*FRONT HEAD REST @\$982.00	Repair	1,964.00 F	*- FL
24	1	*REAR BOOT LID	Dented	2,945.00 F	*2,066.00 FL
25	2	*REAR BOOT LID HINGE @\$143.00	Not Necessary	286.00 F	*- FL
26	1	*REAR BOOT LID EMBLEM LOGO	Necessary	58.00 F	*58.00 FL
27	1	*REAR BOOT LID E250 LOGO	Necessary	75.00 F	*75.00 FL
28	1	*REAR BOOT LID CC LOGO	Necessary	65.00 F	*65.00 FL
29	1	*REAR BOOT LID CGI LOGO	Necessary	73.00 F	*73.00 FL
30	1	*REAR BOOT LID CENTER CHROME	Not Necessary	128.00 F	*- FL
31	2	*REAR BOOT LID SIDE REFLECTOR @\$475.00	Cut	950.00 F	*950.00 FL
32	1	*REAR BOOT LID INNER LOCK	Damaged	370.00 F	*370.00 FL
33	1	*REAR BOOT LID INNER RUBBER	Cut	165.00 F	*165.00 FL
34	1	*REAR BOOT LID INNER TRIM BOARD	Not Necessary	329.00 F	*-FL
35	1	*REAR BOOT LID INNER NUMBER PLATE	Not Necessary	50.00 F	*- FL
36	1	*REAR BOOT LID CAMERA	Not Necessary	680.00 F	*- FL
37	2	*REAR TAIL LAMP @\$657.00	Cracked		*1,314.00 FL
38	4	*REAR TAIL LAMP CLIP @\$8.00	Necessary	32.00 F	*32.00 FL
39	1	*REAR BUMPER	Deformed	1,725.00 F	*1,235.00 FL
		Report was unsubmitted during th	is print-out.		

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
40	10	*REAR BUMPER CLIP @\$6.50	Necessary	65.00 F	*30.00 FL
41	2	*REAR BUMPER SIDE RETAINER @\$48.00	Necessary	96.00 F	*96.00 FL
42	1	*REAR BUMPER LOWER LID	Deformed	494.00 F	*494.00 FL
43	1	*REAR BUMPER TOWING COVER	Not Necessary	57.00 F	*- FL
44	1	*REAR BUMPER CENTER CHROME	Necessary	202.00 F	*202.00 FL
45	2	*REAR BUMPER SIDE CHROME @\$188.00	Necessary	376.00 F	*376.00 FL
46	1	*REAR BUMPER REINFORCEMENT	Bent	862.00 F	*715.00 FL
47	4	*REAR BUMPER REVERSE SENSOR @\$296.00	Damaged-2PCS ONLY	1,184.00 F	*500.00 FL
48	1	*REAR END PANEL	Dented	387.00 F	*387.00 FL
49	1	*REAR END PANEL TOP GARNISH	Cracked	178.00 F	*178.00 FL
50	1	*REAR SPARE TYRE PANEL	Repair	306.00 F	*- FL
51	1	*REAR SPARE TYRE PANEL TOP COVER	Not Necessary	412.00 F	*- FL
52	2	*REAR FENDER INNER TRIM BOARD @\$335.00	Not Necessary	670.00 F	*- FL
53	16	*REAR FENDER INNER TRIM BOARD CLIP @\$6.50	Not Necessary	104.00 F	*- FL
54	1	*REAR EXHAUST	Bent	1,995.00 F	*1,596.00 FL
55	1.	*REAR EXHAUST CHROME PIPE	Bent	206.00 F	*206.00 FL
56	2	*REAR EXHAUST MOUNTING @\$39.60	Not Necessary	79.20 F	*- FL
57	1	*REAR EXHAUST ALUMINIUM COVER	Not Necessary	125.00 F	*- FL
58	1	*REAR CENTER EXHAUST	Not Necessary	1,363.00 F	*- FL
F=Fra	anchise	e part. L=ListItemDisc.	Sub Tatal (SS)	22.042.20	10 261 00

Sub Total (S\$) 32,913.20 18,261.00 - List Item Discount on L Items 0.00/10.00% (S\$) 0.00 1,826.10

> Total Parts (S\$) 32,913.20 16,434.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO REMOVE & REFIT CUSHION & TRIM BOARD.	New	280.00	80.00
TO REMOVE & REFIT FRONT SENSOR.	New	120.00	60.00
TO REMOVE & REFIT REVERSE SENSOR.	New	120.00	60.00
TO REMOVE & REFIT REAR & CENTER EXHAUST.	New	380.00	100.00
TO REMOVE & REFIT REAR CAMERA.	New	180.00	50.00
TO RESET FRONT HEAD REST.	New	380.00	200.00
TO RESET COMPUTER.	New	450.00	100.00
TO CHECK WIRING.	New	100.00	60.00
TUFF KOTE.	New	150.00	50.00
PANEL BEATING.	New	2,400.00	1,600.00
SPRAY PAINTING.	New	2,200.00	1,600.00
Gross	Labour Cost (S\$)	6,760.00	3,960.00
	TO REMOVE & REFIT CUSHION & TRIM BOARD. TO REMOVE & REFIT FRONT SENSOR. TO REMOVE & REFIT REVERSE SENSOR. TO REMOVE & REFIT REAR & CENTER EXHAUST. TO REMOVE & REFIT REAR CAMERA. TO RESET FRONT HEAD REST. TO RESET COMPUTER. TO CHECK WIRING. TUFF KOTE. PANEL BEATING. SPRAY PAINTING.	TO REMOVE & REFIT CUSHION & TRIM BOARD. TO REMOVE & REFIT FRONT SENSOR. New TO REMOVE & REFIT REVERSE SENSOR. TO REMOVE & REFIT REAR & CENTER EXHAUST. New TO REMOVE & REFIT REAR CAMERA. New TO RESET FRONT HEAD REST. New TO RESET COMPUTER. New TO CHECK WIRING. New TUFF KOTE. New PANEL BEATING.	TO REMOVE & REFIT CUSHION & TRIM BOARD. New 280.00 TO REMOVE & REFIT FRONT SENSOR. New 120.00 TO REMOVE & REFIT REVERSE SENSOR. New 120.00 TO REMOVE & REFIT REAR & CENTER EXHAUST. New 380.00 TO REMOVE & REFIT REAR CAMERA. New 180.00 TO RESET FRONT HEAD REST. New 380.00 TO RESET COMPUTER. New 450.00 TO CHECK WIRING. New 100.00 TUFF KOTE. New 150.00 PANEL BEATING. New 2,400.00 SPRAY PAINTING. New 2,200.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.