



萬 春 摩 哆  
**BAN CHOON MOTOR WORKS**

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GSTReg. No. 351915/00A

**GST Regn No. 35191500A**

11/02/2019

Lonpac Insurance Berhad  
100 Beach Road  
#19-00 Shaw Tower  
Singapore 189702

Attn: Motor Claims Dept.

Dear Sir/Madam

QUOTATION FOR REPAIRS OF VEHICLE NO. SFT 6119 B

MODEL: BMW 523I

DATE OF ACCIDENT: 01/02/2019

YOUR INSURED VEHICLE NO. SJX 9279 J

|      |                     |    |             |
|------|---------------------|----|-------------|
| 1 pc | LH rear door        | \$ | 1,615.00    |
| 1 pc | LH rear door rubber |    | 175.75      |
| 1 pc | LH rocker panel     |    | 389.50      |
| 1 pc | LH sport rim        |    | 800.00      |
|      |                     |    | <hr/>       |
|      |                     |    | \$ 2,980.25 |

LABOUR CHARGES:

To knocking and straightening of all necessary damaged parts.

To changing of above part.

To putty and spray painting on accident damaged parts.

|             |
|-------------|
| 1,200.00    |
| 1,000.00    |
| <hr/>       |
| \$ 5,180.25 |

Yours faithfully,

*Peelinday*