

ASS. REC. BY:

REF:

CS/FCI19002538/49d3/72

Special Instruction:

Surveyor:

Markus

ASSIGNMENT (Office)

From (Person):

CWS
Karen Tan

of

FCI

Date/Time:

3:53pm 12/2/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SFE 2646B

Insured:

8HD6856S

at Workshop m/s

Yew Tee Automobile

Tel:

67023113/9743 2262

of

25 Kaki Blk Rd 4 # 01-60

Policy No.:

Claim No.:

D190006804MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/1/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

'0s'

H.O.D. Endorsement:

Date/Time:

10:30pm 12/2/19

Person Contacted:

Shaun

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SFE 2646B-X

8HD 6856S-X

13/2 @ 11:49am - sent email pending estimate.

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

7c.1

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SFE 26463

at Workshop m/s

Yew Tee

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

24

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

23/4/2013

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SFE 26463

Yr Regn:

41 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Toyo con/16 AHJ.c 1598

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

125333

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR0532EE106 105751

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

28/1/19

D.O.I.

12/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

33063

LTA 16214

21/2/19 confirmed d/s \$ 2500 with May (Red \$ 2673.75, 57%)

RECEIVED 21 FEB 2019

(EST)

MV: \$24,000 - LTA: \$16,214 = Net Value: \$7786

Date/Time, File Pass to?



Preli. Report

1) 21/2/19



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

7P

Lump Sum / I.B.I: (\$

2500

135

50

50+50

60

345



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000804MFSH

Date: 21 February 2019

Our Ref: CS/FCI19002538/Uqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SFE 2646B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/02/2019 at the premises of M/s YEW TEE AUTOMOBILE. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,173.25</u> .
Revised Estimate Amount	: S\$ <u>2,500.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	30-01-2019	Our Ref No. D19000804MFSH
Accident Date	28-01-2019	Claim Type. Third Party
Insured Vehicle	SHD6856S	Third Party Vehicle. SFE2646B
Survey Location	SYNERGY@KB, 25 KAKI BUKIT ROAD 4 UNIT NO #01-60/61	
Contact Person.	SHAUN TOH L M	
Contact No.	67023113/ 97432262	Fax No. 67023773
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	YEW TEE AUTOMOBILE TECH PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 21 February 2019 3:46 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000804MFSH/1
Attachments: CSFCI19002538Uqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SFE 2646B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 13 February 2019 11:49 AM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000804MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SFE 2646B on 12/2/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 12 February 2019 5:42 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000804MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 13 February 2019 11:49 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000804MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SFE 2646B on 12/2/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 12 February 2019 5:42 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000804MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



AVIVA

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Wish 1.8A



2.38%p.a Lowest Interest@GV
Cars Financing \$2800
Downpayment Monthly From
\$738
GV Credit Pte Ltd StarAd



Browse by Category ▼

« Back (1 2 3 4 5 6 7) Next »

Sort by Date Posted

136 vehicles

corolla altis

Advanced Search

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

V

Search Selection

corolla altis

Any

Any

> 10 year(s)
old

Any

Any



Toyota Corolla Altis 1.6A (New 5-yr COE)

\$27,800

\$5,560 /yr

11-Feb-2009

1,598 cc

-

2.38%p.a Lowest Interest At \$568 Monthly For Toyota Altis. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gear Available.

2.38%p.a Lowest Interest@Gv Cars Financing \$1800 Downpayment Monthly From \$568
GV Credit Pte Ltd

Posted: 13-Feb-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 10/2023)

\$31,800

\$6,750 /yr

30-Oct-2008

1,598 cc

86,939 km

Original Condition, Very Low Mileage, Road Tax Left For 2 Months Plus, Call For Appointment.

Call For Appointment To Find Out More Details.

Posted: 13-Feb-2019

Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 01/2024)

\$27,800

\$5,650 /yr

16-Jan-2009

1,598 cc

-

2.38%p.a Lowest Interest At \$568 Monthly For Toyota Altis. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gear Available.

2.38%p.a Lowest Interest@Gv Cars Financing \$1800 Downpayment Monthly From \$568
GV Credit Pte Ltd

Posted: 13-Feb-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 06/2021)

\$16,899

\$7,150 /yr

26-Jun-2006

1,598 cc

128,000 km

Low Mileage, Popular Choice For Daily Use! Excellent Fuel Efficiency With Ample Space For Passengers And Boot Storage. Well Maintained Owner. Clean And Neat Interior! Buy With Trust And Co...

Ken Garage Pte Ltd

Posted: 13-Feb-2019

Tags: 2006 Toyota Corolla, 2006 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

GET YOUR
COE
PEN

Compare

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town 12 days without effort! Enquire today.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

RENEW
YOUR COE1.99%*P.A
ONLY

MEMBER

corolla altis

Price Range

Depreciation

> 10 year(s)

Vehicle Type

Home » Used Cars » Thong Lee Trading Pte Ltd » Toyota Corolla Altis 1.6A (COE till 03/2023)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



Toyota Corolla Altis 1.6A (COE till 03/2023)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$27,800	
Depreciation	\$6,730 /yr	?
Reg Date	01-Apr-2008 (4yrs 1mth 18days COE left)	
Manufactured	2008	?
Mileage	128,000 km (11.8k /yr)	
Transmission	Auto	
Engine Cap	1,598 cc	
Road Tax	\$816 /yr	?
Power	80.0 kW (107 bhp) View specs of the Toyota Corolla Altis (2008-2013)	
Curb Weight	1,195 kg	?
Features	Fuel Efficient And Powerful 1.6L 16 Valve DOHC VVTI Engine, Smooth Auto Transmission With Ect, Dual SRS Airbags, ABS, Digital Climate Control Aircon.	
Accessories	Factory Fitted Audio System, Luxurious Beige Original Leather Seats Upholstery, Multi Steering Control And Retractable Side Mirrors With Indicators.	
Description	1 Owner, High OMV \$16994. Low Mileage. Brand New Paintwork Done. Tip Top Condition, Low Depreciation. Well Maintained By A Retired Owner, Shelter Parked. Accident-Free, 90% Flexible Loan Available, High Trade. Call For Viewing.	
COE	\$19,637	?
OMV	\$16,994	?
ARF	\$16,994	?
Dereg Value	\$16,215 as of today (change)	?
No. of Owners	1	?
Type of Veh	Mid-Sized Sedan	
Category	COE Car	



Location Map

Seller Information

Company	Thong Lee Trading Pte Ltd
Address	61 Ubi Avenue 1, #01-108
Location	Automotive
Office No	64444
Contact Person(s)	Gary Lim, Eric Lim

Useful Services

Afraid of letting this car evaluate?

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3306J
Vehicle Details	
Vehicle No.:	SFE2646B
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	3ZZ4756039
Chassis No.:	MR053ZEE106105751
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,994.00
Original Registration Date:	24 Apr 2008
First Registration Date:	24 Apr 2008
Transfer Count:	2
Actual ARF Paid:	\$16,994.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Apr 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$19,328.00
COE Rebate Amount:	\$16,214.00
Total Rebate Amount:	\$16,214.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Feb 2019

OK

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61

Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : FIRST CAPITAL INSURANCE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTKB/TP/1901/015
Policy No:	PNPV2018-00006139	Date of Loss:	28/01/2019
Vehicle Reg. No.:	SFE2646B	Driveable?	yes
Driver Age:	08/06/1987	Third Party Vehicle No.:	SHD6856S
Any Injuries?	no	Contact No:	91062682
Insured/Claimant:	HUI WAI KIONG	Driver:	HUI WAI KIONG

Make/Model:	Toyota, Altis - MR053ZEE106	Vehicle Reg. Date:	24/04/2008
Vehicle Colour:	SILVER	Engine Number:	3ZZ4756039
Chassis No:	MR053ZEE106105751	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss HEAD TO REAR

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	3,386.25
Miscellaneous Items	252.00
Labour	860.00
Paintwork Labour	675.00
Towing	0.00

Gross Total(S\$):	5,173.25
GST 7.00%(S\$):	362.13
Nett Amount(S\$):	5,535.38

This claim is handled by: Shaun Toh L M

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

rest Amount
also
1/5 \$2500 confirmed
12/2/19
the phs After 10pm

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER <i>De/roin</i>	0.00	485.00	-25.00	363.75
2	1	REAR BUMPER BRACKET LH <i>34</i>	0.00	45.00	-10.00	40.50
3	1	REAR BUMPER BRACKET RH <i>34</i>	0.00	45.00	-10.00	40.50
4	1	REAR BUMPER INNER SPONGE <i>34</i>	0.00	90.00	-10.00	81.00
5	1	REAR BUMPER REFLECTOR LH <i>11</i>	0.00	55.00	-10.00	49.50
6	1	REAR BUMPER RELECTOR RH <i>11</i>	0.00	55.00	-10.00	49.50
7	1	REAR BUMPER REINFORCEMENT <i>11</i>	0.00	155.00	-25.00	116.25
8	1	REAR BUMPER SIDE RETAINER LH <i>34</i>	0.00	35.00	-10.00	31.50
9	1	REAR BUMPER SIDE RETAINER RH <i>34</i>	0.00	35.00	-10.00	31.50
10	1	REAR END PANEL <i>20</i>	0.00	635.00	-25.00	476.25
11	1	REAR END PANEL INNER GARNISH <i>11</i>	0.00	180.00	-10.00	162.00
12	1	BOOT LID <i>11</i>	0.00	780.00	-25.00	585.00
13	1	BOOT LID HINGE LH <i>11</i>	0.00	90.00	-10.00	81.00
14	1	BOOT LID HINGE RH <i>11</i>	0.00	90.00	-10.00	81.00
15	1	BOOT LID LOCK <i>11</i>	0.00	85.00	-10.00	76.50
16	1	BOOT LID RUBBER <i>11</i>	0.00	180.00	-10.00	162.00
17	1	BOOT LID REFLECTOR LH <i>11</i>	0.00	380.00	-10.00	342.00
18	1	BOOT LID REFLECTOR RH <i>11</i>	0.00	380.00	-10.00	342.00
19	1	BOOT LID LOGO <i>11</i>	0.00	70.00	-10.00	63.00
20	1	BOOT LID SPOILER THIRD BRAKE LAMP <i>11</i>	0.00	130.00	-10.00	117.00
21	1	BOOT LID 1.6 EMBLEM <i>11</i>	0.00	35.00	-10.00	31.50
22	1	BOOT LID COROLLA EMBLEM <i>11</i>	0.00	35.00	-10.00	31.50
23	1	BOOT LID ALTIS EMBLEM <i>11</i>	0.00	35.00	-10.00	31.50

Total Parts (\$\$) 3,386.25

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIP <i>11</i>	0.00	30.00	0.00	30.00
2	1	REAR END PANEL INNER GARNISH CLIP <i>11</i>	0.00	22.00	0.00	22.00
3	1	REAR REVERSE SENSOR <i>11</i>	0.00	200.00	0.00	200.00

Sub Total (\$\$) 252.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	100.00	0.00	100.00
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00
3	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	650.00	650.00	0.00	650.00

Gross Labour Cost (\$\$) 860.00

P- 2000
 257
 1500
 P- 1500
 S.N- 200
 10km- 1430
 7/13/11

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	30.00	30.00	0.00	30.00 ✓
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	45.00 30
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	600.00	600.00	0.00	600.00 ✓

Gross Labour Cost (S\$) 675.00

< END OF ESTIMATES >

3110

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19002538/Uqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 22-02-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6856S	Veh. Inspected	SFE 2646B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000804MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	12/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053ZEE106105751	Colour	GREY	
Odometer	125555	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GOODYEAR	7 mm	
L/H Front Tyre	195/65 R15	GOODYEAR	7 mm	
R/H Rear Tyre	195/65 R15	GOODYEAR	7 mm	
L/H Rear Tyre	195/65 R15	GOODYEAR	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/01/2019	Inspection Date	12/02/2019	
Survey held at	YEW TEE AUTOMOBILE TECH PL BLK 25 KAKI BUKIT ROAD 4 #01-61 SYNERGY @ KAKI BUKIT SINGAPORE 417800			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFE 2646B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED / TORN	485.00	485.00
1	REAR BUMPER BRACKET LH	BENT	45.00	45.00
1	REAR BUMPER BRACKET RH	BENT	45.00	45.00
1	REAR BUMPER INNER SPONGE	CRACKED	90.00	90.00
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	55.00	-
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	55.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	155.00	-
1	REAR BUMPER SIDE RETAINER LH	BENT	35.00	35.00
1	REAR BUMPER SIDE RETAINER RH	BENT	35.00	35.00
1	REAR END PANEL	DENTED	635.00	635.00
1	REAR END PANEL INNER GARNISH	TWISTED	180.00	180.00
1	BOOT LID	TO REPAIR SEE LABOUR	780.00	-
1	BOOT LID HINGE LH	NOT NECESSARY	90.00	-
1	BOOT LID HINGE RH	NOT NECESSARY	90.00	-
1	BOOT LID LOCK	NOT NECESSARY	85.00	-
1	BOOT LID RUBBER	TWISTED	180.00	180.00
1	BOOT LID REFLECTOR LH	NOT NECESSARY	380.00	-
1	BOOT LID REFLECTOR RH	SCRATCHED	380.00	165.00
1	BOOT LID LOGO	NOT NECESSARY	70.00	-
1	BOOT LID SPOILER THIRD BRAKE LAMP	NOT NECESSARY	130.00	-
1	BOOT LID 1.6 EMBLEM	NECESSARY	35.00	35.00
1	BOOT LID COROLLA EMBLEM	NECESSARY	35.00	35.00
1	BOOT LID ALTIS EMBLEM	NECESSARY	35.00	35.00
	LESS 25% DISCOUNT		-1,026.25	-500.00
			3,078.75	1,500.00
SPECIAL NETT ITEMS				
1	REAR BUMPER CLIP (SN)	NOT NECESSARY	30.00	-
1	REAR END PANEL INNER GARNISH CLIP (SN)	NOT NECESSARY	22.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			252.00	200.00
	LABOUR			
	TO REMOVE AND REFIT CARPET AND TRIMS ON THE REAR SECTION TO GAVE WAY TO THE REPAIR ON THE REAR SECTION.		100.00	80.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		80.00	50.00
	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS.		30.00	20.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF BOOT LID.		650.00	620.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		30.00	30.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.		45.00	30.00
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		600.00	600.00
			1,535.00	1,430.00
GRAND TOTAL			4,865.75	3,130.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CS/FCI19002538/Uqd3n2

MARKET VALUE: \$24,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$16,214.00=NETT VALUE: \$7,786.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.