

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX8858C
ONG CHONG WEN
BLK 182 BEDOK NORTH ROAD
13-38
SINGAPORE 460182
TEL : FAX :
PH : 94472939
ATTN :

ESTIMATE BILL

Number : EB00005076
Date : 12/02/2019
Case No : AD00010226
Vehicle No : SLV6235S
Chassis : JHMFD46208S200528
Year of Mfr : 2007
Policy No : 2018AVAES0276
Model : HONDA CIVIC 1.6L
VTI AUTO

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	REAR DOOR PROTECTOR WITH CHROME RH	1.0	90.40	20	72.32
2	FRONT DOOR PROTECTOR WITH CHROME RH	1.0	107.40	20	85.92
List Price - Parts Sub Total					158.24
3	REAR BUMPER - REPAIR	1.0			
4	REAR FENDER RH - REPAIR	1.0			
5	REAR DOOR RH - REPAIR	1.0			
6	FRONT DOOR RH - REPAIR	1.0			
7	ROCKER GARNISH RH - REPAIR	1.0			
8	WING MIRROR RH - REPAIR	1.0			
Special Nett Price - Parts Sub Total					0.00
Parts Total					158.24
9	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	800.00	0	800.00
10	SPRAY PAINT ON THE AFFECTED AREAS	1.0	800.00	0	800.00
11	ANTI-RUST COATING	1.0	180.00	0	180.00
12	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					1,930.00
SINGAPORE DOLLARS : TWO THOUSAND TWO HUNDRED THIRTY-FOUR AND CENTS FORTY-TWO ONLY			Less Excess		0.00
			SUBTOTAL		2,088.24
			GST 7.00%		146.18
			TOTAL		2,234.42

Date of accident : 12/02/2019 09:29 AM. Place : TOWARDS JOHOR BAHRU CHECKPOINT

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE