

ASS. REC. BY:

REF: CS/INC19002578/Egd304

Special Instructions:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Daniel Koh

of

INC

Date/Time:

12/2/19 @ 10:11am

Estimated Cost:

Bill to:

OD - ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH1636A

Insured:

SJK 3446B

at Workshop m/s

vermugen

Tel:

63583031

of

6 Bendi Sctor

Policy No:

Claim No:

MT-1031440-001

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11/2/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11:03am @ 12/2/19

Person Contacted:

EZE

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLH1636A - X
	SJK 3446B - X

Steve

REF: INC

SUBJECT

Date 12/2/19

SLH 1636A

25/10/16

Form

Estimated Cost

OD ☒ W5 / TP RES / CD RES / EVA / MV / MV

To inspect Vehicle No.

SLH 1636A

at Work location

vermogen

at

6 Benoi & Cufur

Insured

Policy No.

Claims No.

Same Insured

Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Est. or Market Value

IDAC Accident Report

Consistent? Yes or No

QIA / PR Seen

Consistent? Yes or No

Est. Repair

87

days

Res: Yes or No

Lump Sum

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

lup

Vehicle IN / OUT

Date

Person Contacted

Veh No

SLH 1636A

V Regn

25/10/16

Type ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make

SLH Toyota Con/19 Ax10

15

Colour

Black

AC Insured / Std / NI / NA

Sp/Boarding

243041

T/Title: Insured / Std / NI / NA

Engine

C/H

NKE 1657136410

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Good / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Good / ☐ Jammed / ☐ Leaked / ☐ Burnt orMod: Nil / ☒ R/Rim / ☐ STD A/Rim or

Steel Rim

Tyre Size:

185/60R15

R:

1"

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Road Stone

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

11/2/19

D.O.A.

12/2/19

Survey held at

Vermogen

0322PM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

front LH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV - 60,000

Call Ezel repair for 16 K L/S

PV - 43,391

NV - 16,609

Steve,

Pls see my remarks

17/4/19 finalise confirm \$5600, 7 days
(Red \$ 20429.50, 79%)

RECEIVED 17 APR 2019

Date/Time: File Path to:

☐

Prel. Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Date/Time: File Path to:

☐

Final Report

Transportation

at

Add Fee:

☐

Site Insp \$5

☐

Interview \$5

☐

Form. Insp \$5

☐

Workshop \$5

Report Format

TP

Lump Sum / L/S

5800

250

250

Nivitha (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Tuesday, 12 February 2019 10:11 AM
To: 'assignments@lkkauto.com'
Cc: Teng Ken Leong; Thio Tse Kiat
Subject: FW: TP CASES FARMED OUT TO LKK ON 12/2/2019

Dear Veron / Catherine,

Please assist to survey the vehicles as per Mr Toh's instruction :-

S/NO	THIRD PARTY	OUR INSURED	WORKSHOP / CONTACT	DOA / REF / OFFICER	TIMING
1	SLH1636A	SJK3446B	VERMOGEN ACE / Pila 63583031	11-2-2019 / MT-1031440-001 / Muhammad Airwan	
2	EV6460R	XE783M	VOLKSWAGEN CENTRE / Edmund Goh 63057299	2-2-2019 / MT-1030828-001 / Helena Tan	10:00-12:00
3	SLU8379C	SIN6151R	CAR CRAFTERS / Jie Ren 94316186	25-1-2019 / MT-1029788-002 / Charlotte Chew	
4	SFS41K	SLF646M	C & C AUTOMOTIVE / Tay Jian Ye 81680997	25-1-2019 / MT-1029518-002 / Rajeswary	11:00-16:00
5	SMC5034A	SKW5684S	C & C FRANCE / Edwin Caina 91819978	7-12-2018 / MT-1023039-002 / Serene Lim	

6	SMA7409A	SLU7485K	HUA HONG PTE LTD / Jerleen 66619688	24-11-2018 / MT-1021408-002 / David Phua	10:00-12:00
7	YN1111L	SKJ824G	LEE KUAN HWA MOTOR / Siew Chen 62699192	1-2-2019 / MT-1030591-002 / Jeff Lin	
8	EA2318G	SHD2075E	TAN CHONG MOTOR / Lawrence Teo 64694091	23-1-2019 / MT-1029228-002 / Jared Liu	
9	SLM2790D	SHC6977G	WORLD AUTO / Ainee 63621776	4-2-2019 / MT-1031311-001 / David Phua	

Please contact workshops.

Please ack.

Thank You

Daniel Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7901
www.income.com.sg

income
made different



Steve Chen (LKK Auto)

From: Minoko Chan <minoko@vermogen-group.com>
Sent: Wednesday, April 17, 2019 9:55 AM
To: Steve Chen (LKK Auto)
Cc: Pila Ng; Tejano Exequiel Dawal; Baldoz Juan Paulo Bongon; Vmg admin; Vermogen Ace; Luis Tan; Glorioso Eric Paul Patambang; Edmond Lim
Subject: Re: SLH1636A Finalize

Dear Steve,

We agreed to accept your revise COR @ \$5,600.00 & should be 7 repair days.(excluding PRS/RS/Weekend & PH).

Thank you.

Best Regards,

Minoko

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6904 4596

Fax: 6694 4929

On Fri, Apr 12, 2019 at 4:25 PM Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Minoko,

The above vehicle finalize \$5600. 6 days.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLH1636A
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO HYBRID 1.5G AT D/AIRBAG
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	1NZR422591
Chassis No.:	NKE1657136410
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$27,399.00
Original Registration Date:	25 Oct 2016
First Registration Date:	25 Oct 2016
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Oct 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	24 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,507.00
COE Rebate Amount:	\$39,641.00
Total Rebate Amount:	\$43,391.00

The information contained herein is correct as at 13 Feb 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SLH1636A
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO HYBRID 1.5G AT D/AIRBAG
Chassis No.:	NKE1657136410
Propellant:	Petrol-Electric
Engine No.:	1NZR422591
Motor No.:	H16604888
Engine Capacity:	1496 cc
Power Rating:	45.0 kW
Maximum Power Output:	73.0 kW (97 bhp)
Maximum Laden Weight:	1415 kg
Unladen Weight:	1140 kg
Year Of Manufacture:	2016
Original Registration Date:	25 Oct 2016
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$51,507.00
COE Expiry Date:	24 Oct 2026
Road Tax Expiry Date:	24 Apr 2019
PARF Eligibility Expiry Date:	24 Oct 2026
Inspection Due Date:	24 Oct 2019
Intended Transfer Date:	12 Dec 2019
CO2 Emission:	83.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$25,359.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 25 Apr 2019 to 24 Oct 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	341.00	-	341.00
Total Amount Payable:			366.00

Amount Payable (From 25 Apr 2019 to 24 Apr 2020)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	682.00	-	682.00
Total Amount Payable:			707.00

You may print this page for reference.

OK

Print

X GO FROM THIS...



✓ TO A BELLROY



Both the s

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Cse Renewal Toyota Estima 2.4A



2.36Plus 3.1 Lowest Interest! Cse
Car Financing \$5800
Downpayment Monthly From
\$0.00
GV Credit Pte Ltd

AutoInn
An Inspiration For Car Buyers

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category

10 vehicles

Toyota Corolla axio

Sort by Date Posted

20 results/page

Advanced Search

Search Selection

Toyota Corolla axio

Any

Any

2016

Any

Any

Any

Available

**Toyota Corolla Axio 1.5A X**

\$60,800

\$7,550 /yr

01-Nov-2016

1,496 cc

33,864 km

Sedan

Available

1 Owner, Almost New Japanese Toyota Corolla Axio! Responsive Engine Performance Yet Producing Outstanding Fuel Efficiency! One Of The Best Selling Toyota In The Market! High Trade In, Attractive Loan ...

Henly Enterprises Co

Posted: 09-Feb-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

**Toyota Corolla Axio 1.5A X**

\$54,800

\$7,090 /yr

20-Jun-2016

1,496 cc

38,000 km

Sedan

Available

Single Owner Unit! One Of The Lower Mileage Axios Around. Extremely Well Maintained Unit With Recent Servicing Just Done! Fuss Free Drive With Excellent Fuel Consumption And Extremely Smooth Engine An...

Posted: 08-Feb-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

PREMIUM AD

**Toyota Corolla Axio 1.5A X**

\$60,800

\$7,490 /yr

12-Oct-2016

1,496 cc

-

Sedan

Available

Fast And Easy Loan Approval! Free New Touch Screen Pioneer DVD And Free New Choice Of Colour Whole Set Leather Interior (Seats, Armrest And Door Panel). 6 Months Engine And Gearbox Full Warranty! Buy ...

88 Motor Trading

Posted: 28-Jan-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

**Toyota Corolla Axio 1.5A X**

\$59,800

\$7,810 /yr

07-Mar-2016

1,496 cc

56,000 km

Sedan

Available

Vehicle Well Maintained! Original Paintwork And Interior! Reliable Engine! No Major Repairs Needed! Low Depreciation! No Obligations! In-House & Bank Loans Available! Kindly Contact Our Sales Advisor ...

Posted: 23-Jan-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

Toyota launches completely redesigned Corolla Sedan and Corolla Fielder

Toyota Motor Corporation (TMC) announced today the Japan sales launch of the completely redesigned Corolla sedan now known as the Corolla Axio and completely redesigned Corolla Fielder small station wagon through "Toyota Corolla" dealers nationwide

Read this article

**Toyota Corolla Axio 1.5A X**

\$75,800

\$9,550 /yr

19-Sep-2016

1,496 cc

-

Sedan

Available

Fast And Easy Loan Approval! Free Brand New Touch Screen Pioneer DVD And Free Brand New Choice Of Colour Whole Set Leather Interior (Seats, Armrest And Door Panel). 6 Months Engine And Gearbox Full Wa...

88 Motor Trading

Posted: 21-Jan-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

PREMIUM AD

Toyota Corolla Axio 1.5A X

\$60,800

\$7,620 /yr

06-Sep-2016

1,496 cc

-

Sedan

Available

5 Pass, EP Or LTV Pass Welcome To Loan! In-House Loan Or Bank Loan Available! Balloon Scheme Available! Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing A...

88 Motor Trading

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/02/2019 13:42
Date Of Accident	11/02/2019 10:15
Exact Location Of Accident	TANNERY LANE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH1636A
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	TOYOTA
Model	AXIO
Exact Purpose for which vehicle was being used at time of accident	HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995027
Cover Note Number	

Driver

Name of Driver	CHUA KEK KIM JACKY
NRIC No	S1623224F
Date Of Birth	06/01/1963
Occupation	OUTDOOR
Date Of Driving Pass	07/04/1997
Driving Experience	21 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90106639
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	6 BENOI SECTOR
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - U-TURN
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO FOLLOWING ATTACHED, THANK YOU.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJK3446B
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigations.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TPN No.:

SKETCH PLAN

Tannery Lane



A-SLH1636A

B-SJK3446B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Tannery Lane, Suddenly vehicle B move off from Stationary position as he wanted to u-turn and caused the collision, we stopped our car, exchange particulars and took photos

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: EDMOND
NRIC/PH No.:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1623224F



Name
CHUA KEK KIM JACKY

CHINESE
Date of Birth
06-01-1963
Country/Place of Birth
SINGAPORE

Sex
M
S1623224F

Land Transport & Authority



VOCATIONAL LICENCE

Licence No. S1623224F

Name : CHUA KEK KIM JACKY

Issue Date : 30/6/2016

Please visit www.lta.gov.sg to check the status of this vocational licence

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence No. S1623224F

Name : CHUA KEK KIM JACKY

Date of Birth : 06 Jan 1963

Issue Date : 18 Mar 2003



5854702



ENC No. S1623224F



VMG USE ONLY

Address
APT BLK 674A JIROH WEST STREET 65
#05-78
SINGAPORE 641674

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to the LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type Description
02 TAXI VL

Issue Date
12/09/2006

VMG USE ONLY



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which (including does not exceed 3500 kilograms)

Issue Date

07 Apr 1997



HP 425A



SLH1636A

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : NTUC
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 11/2/2019

Vehicle Reg. No. : SLH1636A
Vehicle Reg. Date: 25/10/20106
Make / Model : T. COROLLA AXIO 1.5G H
Engine No. : 1NZR422591
Chassis No. : NKE1657136410

COST OF CLAIMS

Parts Cost / List Items : \$ 26,285.00
Plus/Less 25% \$ 6,571.25
Total Cost / List : \$ 19,713.75
Special Nett Items : \$ 900.00
Total Parts Amount : \$ 20,613.75
Total Labour Amount : \$ 5,360.00
Gross Total : \$ 25,973.75 26079.10
GST % : 7% \$ 1,818.16
Nett Amount : \$ 27,791.91

Surveyor Name and Company :

Date of survey : _____
Part by Part / Lump Sum : _____ days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : _____
Fax No : _____
HP No : _____

This claim is handled by : MINOKO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No.: **SLH1636A**
 Vehicle Reg. Date: **25/10/20106**
 Make / Model: **T. COROLLA AXIO 1.5G HYBRID**
 Engine No.: **1NZR422591**
 Chassis No.: **NKE1657136410**

Steve (CLKK)
 12/2/19
 5 Days
 L/S

[Signature]
 14/2/19

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	FRONT BUMPER /	IR	\$ 570.00		
2	1set	FRONT BUMPER CLIPS /	NEC	\$ 50.00	40	
3	2	FRONT BUMPER RETAINER LH/RH /	TIP	\$ 85.00		
4	1	FRONT BUMPER SPONGE /	IR	\$ 120.00		
5	1	FRONT BUMPER REINFORCEMENT X	NI	\$ 340.00		
6	1	FRONT BUMPER FOGLAMP GARNISH RH /	IR	\$ 75.00		
7	1	FRONT BUMPER UPPER GRILLE /	IR	\$ 710.00		
8	1	FRONT GRILLE "EMBLEM" LOGO /	NEC	\$ 68.00		
9	1	FRONT GRILLE RUBBER X	NI	\$ 105.00		
10	1set	FRONT GRILLE CLIPS X	NI	\$ 30.00	15	
11	1	FRONT LOWER GRILLE /	CUT	\$ 420.00		
12	2/	HEADLAMP LH/RH LH / RH X NN	IR	\$ 1,650.00	876	
13	2/	HEADLAMP LOWER BRACKET LH/RH RH X LH /	NI	\$ 170.00		
14	2/	HEADLAMP CHROME GARNISH LH/RH X	NI	\$ 360.00		
15	2	HEADLAMP PANEL LH/RH X	NI	\$ 196.00		
16	1	FRONT FENDER LH /	DD	\$ 1,350.00	680	
17	1	FRONT FENDER APRON LH X	NI	\$ 500.00		
18	1	FRONT FENDER EMBLEM "HYBRID" LH /	NEC	\$ 150.00		
19	1	FRONT FENDER INNER SHIELD LH /	CRU	\$ 185.00		
20	1	FRONT FENDER INNER SHIELD CLIP - SET /	NEC	\$ 50.00	30	
21	1	AIR RESONATOR X	NI	\$ 920.00		
22	1	RADIATOR AIR GUIDE RH X	NI	\$ 120.00		
23	2/	FRONT SHOCK ABSORBER /	BT	\$ 864.00	957	
24	2/	FRONT SHOCK ABSORBER MOUNTING /	NI	\$ 242.00		
25	2/	FRONT SHOCK ABSORBER DUST COVER /	NI	\$ 94.00		
26	2/	FRONT SHOCK ABSORBER BEARING /	NI	\$ 130.00		
27	2/	FRONT SHOCK ABSORBER STOPPER /	NI	\$ 76.00		
28	2/	FRONT KNUCKLE ARM /	BT	\$ 1,346.00	487.10	
29	2/	FRONT WHEEL BEARING /	NEC	\$ 214.00	107	
30	2/	FRONT WHEEL HUB /	BT	\$ 474.00	237	
31	2/	FRONT LOWER ARM WITH BALLJOINT /	BT	\$ 994.00	430	
32	2/	FRONT RIM HUB CAP RH LH / RH X NN	IR	\$ 378.00	187	
33	2	FRONT DRIVESHAFT ASSY X	NI	\$ 2,900.00		
34	2/	TIE ROD END / LH /	BT	\$ 300.00	150	
35	2	RACK END /	NI	\$ 360.00		
36	1	FRONT TYRE LH / 7.5	NI	\$ 280.00	176	
37	1	FRONT RIM LH /	BT	\$ 350.00	200	
38	1	STEERING RACK & PINON /	NI	\$ 1,587.00		
39	1	SUPPORT PANEL X	NI	\$ 876.00		
40	1	SUPPORT PANEL TOP GARNISH X	IR	\$ 160.00		

? photos can't see any dash

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No.: SLH1636A
 Vehicle Reg. Date: 25/10/20106
 Make / Model: T. COROLLA AXIO 1.5G HYBRID
 Engine No.: 1NZR422591
 Chassis No.: NKE1657136410

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1SET	SUPPORT PANEL TOP GARNISH CLIP X	NN	\$ 50.00		
42	1	SIDE MIRROR ASSY LH X	NN	\$ 995.00		
43	1	SIDE MIRROR COVER LH X	NN	\$ 99.00		
44	1	SIDE MIRROR GLASS LH X	NN	\$ 150.00		
45	1	FRT DOOR LH X	R	\$ 1,363.00		
46	1	FRT DOOR HINGE TOP X	NN	\$ 85.00		
47	1	FRT DOOR HINGE BOTTOM X	NN	\$ 85.00		
48	1	BRACE PANEL X	NN	\$ 180.00		
49	1	RADIATOR X	NN	\$ 1,410.00		
50	1	AIR CON CONDENSER X	NN	\$ 1,360.00		
51	1	RADIATOR COOLANT X	NN		\$ 120.00	
52	1	AIR CON GAS X	NEC		\$ 150.00	100
53	1	Front bonnet X	R	\$ 720.00		
54	2	Front bonnet hinge X	NN	\$ 54.00		
55	1	Front bonnet insulator X	NN	\$ 395.00		
56	1	Front bonnet insulator clips X	NN	\$ 30.00		
57	1	Front bonnet lock X	NN	\$ 90.00		
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	2				

Parts discount 25% discount

Tel : 6358 3031 | Fax No : 6694 4929

SLH1636A

25/10/20106

T. COROLLA AXIO 1.5G HYBRID

1NZR422591

NKE1657136410

Estimates on Labour

[illegible]



SLH1636A

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

Rguy 21/2/19

ACCIDENT REPAIR ESTIMATE

TP INSURER : NTUC

Vehicle Reg. No. : SLH1636A

OWN INSURER : AIG

Vehicle Reg. Date: 25/10/20106

CLAIM TYPE : TP

Make / Model : T. COROLLA AXIO 1.5G H

Date of Accident : 11/2/2019

Engine No. : 1NZR422591

Chassis No. : NKE1657136410

COST OF CLAIMS

Parts Cost / List Items : \$ 26,285.00

Plus/Less 25% \$ 6,571.25

Total Cost / List : \$ 19,713.75

Special Nett Items : \$ 900.00

Total Parts Amount : \$ 20,613.75

Total Labour Amount : \$ 5,360.00

Gross Total : \$ 25,973.75

GST % : 7% \$ 1,818.16

Nett Amount : \$ 27,791.91

Surveyor Name and Company :

Date of survey : _____

Part by Part / Lump Sum : _____ days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : _____

Fax No : _____

HP No : _____

This claim is handled by : MINOKO

26079.50

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLH1636A**
 Vehicle Reg. Date: **25/10/20106**
 Make / Model : **T. COROLLA AXIO 1.5G HYBRID**
 Engine No. : **1NZR422591**
 Chassis No. : **NKE1657136410**

Steve CLKK)
 6 12/2/19
 Days
 L/S

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	FRONT BUMPER /		\$ 570.00		
2	1set	FRONT BUMPER CLIPS /		\$ 50.00		
3	2	FRONT BUMPER RETAINER LH/RH /		\$ 85.00		
4	1	FRONT BUMPER SPONGE /		\$ 120.00		
5	1	FRONT BUMPER REINFORCEMENT X		\$ 340.00		
6	1	FRONT BUMPER FOGLAMP GARNISH RH /		\$ 75.00		
7	1	FRONT BUMPER UPPER GRILLE /		\$ 710.00		
8	1	FRONT GRILLE "EMBLEM" LOGO /		\$ 68.00		
9	1	FRONT GRILLE RUBBER X		\$ 105.00		
10	1set	FRONT GRILLE CLIPS X		\$ 30.00		
11	1	FRONT LOWER GRILLE /		\$ 420.00		
12	2/	HEADLAMP LH/RH LH / RH X		\$ 1,650.00		
13	2/	HEADLAMP LOWER BRACKET LH/RH RH X LH X		\$ 170.00		
14	2/	HEADLAMP CHROME GARNISH LH/RH X		\$ 360.00		
15	2	HEADLAMP PANEL LH/RH X		\$ 196.00		
16	1	FRONT FENDER LH /		\$ 1,350.00		
17	1	FRONT FENDER APRON LH X		\$ 500.00		
18	1	FRONT FENDER EMBLEM "HYBRID" LH /		\$ 150.00		
19	1	FRONT FENDER INNER SHIELD LH /		\$ 185.00		
20	1	FRONT FENDER INNER SHIELD CLIP - SET /		\$ 50.00		
21	1	AIR RESONATOR X		\$ 920.00		
22	1	RADIATOR AIR GUIDE RH X		\$ 120.00		
23	2/	FRONT SHOCK ABSORBER /		\$ 864.00		
24	2/	FRONT SHOCK ABSORBER MOUNTING X		\$ 242.00		
25	2/	FRONT SHOCK ABSORBER DUST COVER X		\$ 94.00		
26	2/	FRONT SHOCK ABSORBER BEARING X		\$ 130.00		
27	2/	FRONT SHOCK ABSORBER STOPPER X		\$ 76.00		
28	2/	FRONT KNUCKLE ARM /		\$ 1,346.00		
29	2/	FRONT WHEEL BEARING /		\$ 214.00		
30	2/	FRONT WHEEL HUB /		\$ 474.00		
31	2/	FRONT LOWER ARM WITH BALLJOINT /		\$ 994.00		
32	2/	FRONT RIM HUB CAP RH LH / RH X		\$ 378.00		
33	2	FRONT DRIVESHAFT ASSY X		\$ 2,900.00		
34	2/	TIE ROD END LH /		\$ 300.00		
35	2	RACK END X		\$ 360.00		
36	1	FRONT TYRE LH / 70%			\$ 280.00	
37	1	FRONT RIM LH /			\$ 350.00	
38	1	STEERING RACK & PINON /		\$ 1,587.00		
39	1	SUPPORT PANEL X		\$ 876.00		
40	1	SUPPORT PANEL TOP GARNISH X /		\$ 160.00		

Supp — Front Bumper Lower Cover /

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLH1636A**
 Vehicle Reg. Date: **25/10/20106**
 Make / Model : **T. COROLLA AXIO 1.5G HYBRID**
 Engine No. : **1NZR422591**
 Chassis No. : **NKE1657136410**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1SET	SUPPORT PANEL TOP GARNISH CLIP X		\$ 50.00		
42	1	SIDE MIRROR ASSY LH X		\$ 995.00		
43	1	SIDE MIRROR COVER LH X		\$ 99.00		
44	1	SIDE MIRROR GLASS LH X		\$ 150.00		
45	1	FRT DOOR LH X R		\$ 1,363.00		
46	1	FRT DOOR HINGE TOP X		\$ 85.00		
47	1	FRT DOOR HINGE BOTTOM X		\$ 85.00		
48	1	BRACE PANEL X R		\$ 180.00		
49	1	RADIATOR X		\$ 1,410.00		
50	1	AIR CON CONDENSER X NC		\$ 1,360.00		
51	1	RADIATOR COOLANT V			\$ 120.00	
52	1	AIR CON GAS X			\$ 150.00	
53	1	Front bonnet X R		\$ 720.00		
54	2	Front bonnet hinge X		\$ 54.00		
55	1	Front bonnet insulator X		\$ 395.00		
56	1	Front bonnet insulator clips X		\$ 30.00		
57	1	Front bonnet lock X		\$ 90.00		
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	Z				

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

FINALIZATION FORM

ATTN TO:

LKK-STEVE

Surveyor Name and Company

Date of Accident : **11/2/2019**

BILL TO:

NTUC

TP Insurer

VEHICLE REG. NO.

TYPE OF CLAIM:

TP

SLH1636A

Make / Model :

T. COROLLA AXIO 1.5G HYBRID

COST OF CLAIMS

Parts Cost / List : \$ 6,768.00

Supp. Parts : \$ 141.00

Special Nett : \$ 546.00

Total Parts : \$ 5,727.75

Total Labour : \$ 1,620.00

TOTAL REPAIR COST : \$ 7,347.75

Total Parts Cost/List :	\$	6,909.00
Plus / Less : 25%	\$	1,727.25
Total :	\$	5,181.75

Lump Sum Discount : 20%	\$	1,469.55
Lump Sum Amount:	\$	5,878.20

Final Lump Sum Amount : \$ 5,900.00

Submitted by / Date : MINOKO

No. of Repair Days: 7

Confirmed by / Date : _____

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No.: **SLH1636A**
 Vehicle Reg. Date: **25/10/20106**
 Make / Model: **T. COROLLA AXIO 1.5G HYBRID**
 Engine No.: **1NZR422591**
 Chassis No.: **NKE1657136410**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	FRONT BUMPER		\$ 570.00		\$ 570.00
2	1set	FRONT BUMPER CLIPS		\$ 50.00		\$ 50.00
3	2	FRONT BUMPER RETAINER LH/RH		\$ 85.00		\$ 85.00
4	1	FRONT BUMPER SPONGE		\$ 120.00		\$ 120.00
5	1	FRONT BUMPER REINFORCEMENT		\$ 340.00		
6	1	FRONT BUMPER FOGLAMP GARNISH RH		\$ 75.00		\$ 75.00
7	1	FRONT BUMPER UPPER GRILLE		\$ 710.00		\$ 710.00
8	1	FRONT GRILLE "EMBLEM" LOGO		\$ 68.00		\$ 68.00
9	1	FRONT GRILLE RUBBER		\$ 105.00		
10	1set	FRONT GRILLE CLIPS		\$ 30.00		
11	1	FRONT LOWER GRILLE		\$ 420.00		420
12	2	HEADLAMP LH/RH LH		\$ 1,650.00		\$ 825.00
13	2	HEADLAMP LOWER BRACKET LH/RH		\$ 170.00		\$ 85.00
14	2	HEADLAMP CHROME GARNISH LH/RH		\$ 360.00		
15	2	HEADLAMP PANEL LH/RH		\$ 196.00		
16	1	FRONT FENDER LH		\$ 1,350.00		\$ 1,350.00
17	1	FRONT FENDER APRON LH		\$ 500.00		
18	1	FRONT FENDER EMBLEM "HYBRID" LH		\$ 150.00		\$ 150.00
19	1	FRONT FENDER INNER SHIELD LH		\$ 185.00		\$ 185.00
20	1	FRONT FENDER INNER SHIELD CLIP - SET		\$ 50.00		\$ 50.00
21	1	AIR RESONATOR		\$ 920.00		
22	1	RADIATOR AIR GUIDE RH		\$ 120.00		
23	2	FRONT SHOCK ABSORBER LH		\$ 864.00		\$ 432.00
24	2	FRONT SHOCK ABSORBER MOUNTING		\$ 242.00		
25	2	FRONT SHOCK ABSORBER DUST COVER		\$ 94.00		
26	2	FRONT SHOCK ABSORBER BEARING		\$ 130.00		
27	2	FRONT SHOCK ABSORBER STOPPER		\$ 76.00		
28	2	FRONT KNUCKLE ARM LH		\$ 1,346.00		\$ 673.00
29	2	FRONT WHEEL BEARING LH		\$ 214.00		\$ 107.00
30	2	FRONT WHEEL HUB		\$ 474.00		\$ 237.00
31	2	FRONT LOWER ARM WITH BALLJOINT		\$ 994.00		\$ 497.00
32	2	FRONT RIM HUB CAP RH		\$ 378.00		\$ 189.00
33	2	FRONT DRIVESHAFT ASSY		\$ 2,900.00		
34	2	TIE ROD END		\$ 300.00		\$ 150.00
35	2	RACK END		\$ 360.00		
36	1	FRONT TYRE LH			\$ 196.00	
37	1	FRONT RIM LH			\$ 350.00	200
38	1	STEERING RACK & PINON		\$ 1,587.00		
39	1	SUPPORT PANEL		\$ 876.00		
40	1	SUPPORT PANEL TOP GARNISH		\$ 160.00		\$ 160.00

P - 4574.32
 Supp - 105.75
 NI - 496
 L - 1820
 6996.07
 L/S - 5596.85
 = 5600

P - 6099.10
 - 25.2
 4574.32

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLH1636A**

Vehicle Reg. Date: **25/10/20106**

Make / Model : **T. COROLLA AXIO 1.5G HYBRID**

Engine No. : **1NZR422591**

Chassis No. : **NKE1657136410**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1SET	SUPPORT PANEL TOP GARNISH CLIP		\$ 50.00		
42	1	SIDE MIRROR ASSY LH		\$ 995.00		
43	1	SIDE MIRROR COVER LH		\$ 99.00		
44	1	SIDE MIRROR GLASS LH		\$ 150.00		
45	1	FRT DOOR LH		\$ 1,363.00		
46	1	FRT DOOR HINGE TOP		\$ 85.00		
47	1	FRT DOOR HINGE BOTTOM		\$ 85.00		
48	1	BRACE PANEL		\$ 180.00		
49	1	RADIATOR		\$ 1,410.00		
50	1	AIR CON CONDENSER		\$ 1,360.00		
51	1	RADIATOR COOLANT				
52	1	AIR CON GAS				
53	1	Front bonnet		\$ 720.00		
54	2	Front bonnet hinge		\$ 54.00		
55	1	Front bonnet insulator		\$ 395.00		
56	1	Front bonnet insulator clips		\$ 30.00		
57	1	Front bonnet lock		\$ 90.00		
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	Z				

N — 496

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLH1636A
Vehicle Reg. Date: 25/10/20106
Make / Model : T. COROLLA AXIO 1.5G HYBRID
Engine No. : 1NZR422591
Chassis No. : NKE1657136410

PAGE 1

Supplementary Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	FRONT BUMPER LOWER COVER <i>OR</i>		\$ 141.00		\$ 141.00
2						
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

Supp
↓
✓ - 756 (A)
105.75



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19002578/Eqd3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 23-04-2019



ATTN: MUHAMMAD AIRWAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 3446B	Veh. Inspected	SLH 1636A
Policy No.		Coverage (\$)	0.00
Claim No.	MT-1031440-001	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	12/02/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA AXIO	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NKE1657136410	Colour	BLACK
Odometer	243041 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	ROADSTONE	6 mm
L/H Front Tyre	185/60 R15	ROADSTONE	6 mm
R/H Rear Tyre	185/60 R15	ROADSTONE	6 mm
L/H Rear Tyre	185/60 R15	ROADSTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/02/2019	Inspect Date / Time	12/02/2019 (03:27 PM)
Survey held at	6 BENOI SECTOR		
Repairer	VERMOGEN ACE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 1636A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BROKEN	570.00	570.00
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	40.00
2	FRONT BUMPER RETAINER LH/RH	BROKEN	85.00	85.00
1	FRONT BUMPER SPONGE	BROKEN	120.00	120.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	340.00	-
1	FRONT BUMPER FOGLAMP GARNISH RH	BROKEN	75.00	75.00
1	FRONT BUMPER UPPER GRILLE	BROKEN	710.00	710.00
1	FRONT GRILLE "EMBLEM" LOGO	NECESSARY	68.00	68.00
1	FRONT GRILLE RUBBER	NOT NECESSARY	105.00	-
1	SET FRONT GRILLE CLIPS	NOT NECESSARY	30.00	-
1	FRONT LOWER GRILLE	CUT	420.00	420.00
2	HEADLAMP LH/RH	N/S BROKEN / O/S NOT NECESSARY	1,650.00	825.00
2	HEADLAMP LOWER BRACKET LH/RH	NOT NECESSARY	170.00	-
2	HEADLAMP CHROME GARNISH LH/RH	NOT NECESSARY	360.00	-
2	HEADLAMP PANEL LH/RH	NOT NECESSARY	196.00	-
1	FRONT FENDER LH	DENTED	1,350.00	680.00
1	FRONT FENDER APRON LH	NOT NECESSARY	500.00	-
1	FRONT FENDER EMBLEM "HYBRID" LH	NECESSARY	150.00	150.00
1	FRONT FENDER INNER SHIELD LH	CRUSHED	185.00	185.00
1	SET FRONT FENDER INNER SHIELD CLIP	NECESSARY	50.00	30.00
1	AIR RESONATOR	NOT NECESSARY	920.00	-
1	RADIATOR AIR GUIDE RH	NOT NECESSARY	120.00	-
2	FRONT SHOCK ABSORBER	BENT-1PC ONLY	864.00	387.00
2	FRONT SHOCK ABSORBER MOUNTING	NOT NECESSARY	242.00	-
2	FRONT SHOCK ABSORBER DUST COVER	NOT NECESSARY	94.00	-
2	FRONT SHOCK ABSORBER BEARING	NOT NECESSARY	130.00	-
2	FRONT SHOCK ABSORBER STOPPER	NOT NECESSARY	76.00	-
2	FRONT KNUCKLE ARM	BENT-1PC ONLY	1,346.00	481.10
2	FRONT WHEEL BEARING	NECESSARY-1PC ONLY	214.00	107.00

Report Ref No. CS/INC19002578/Eqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT WHEEL HUB	BENT-1PC ONLY	474.00	237.00
2	FRONT LOWER ARM WITH BALLJOINT	BENT-1PC ONLY	994.00	430.00
2	FRONT RIM HUB CAP RH	N/S BROKEN / O/S NOT NECESSARY	378.00	189.00
2	FRONT DRIVESHAFT ASSY	NOT NECESSARY	2,900.00	-
2	TIE ROD END	N/S BENT	300.00	150.00
2	RACK END	NOT NECESSARY	360.00	-
1	STEERING RACK & PINION	NOT NECESSARY	1,587.00	-
1	SUPPORT PANEL	NOT NECESSARY	876.00	-
1	SUPPORT PANEL TOP GARNISH	BROKEN	160.00	160.00
1	SET SUPPORT PANEL TOP GARNISH CLIP	NOT NECESSARY	50.00	-
1	SIDE MIRROR ASSY LH	NOT NECESSARY	995.00	-
1	SIDE MIRROR COVER LH	NOT NECESSARY	99.00	-
1	SIDE MIRROR GLASS LH	NOT NECESSARY	150.00	-
1	FRT DOOR LH	TO REPAIR SEE LABOUR	1,363.00	-
1	FRT DOOR HINGE TOP	NOT NECESSARY	85.00	-
1	FRT DOOR HINGE BOTTOM	NOT NECESSARY	85.00	-
1	BRACE PANEL	NOT NECESSARY	180.00	-
1	RADIATOR	NOT NECESSARY	1,410.00	-
1	AIR CON CONDENSER	NOT NECESSARY	1,360.00	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	720.00	-
2	FRONT BONNET HINGE	NOT NECESSARY	54.00	-
1	FRONT BONNET INSULATOR	NOT NECESSARY	395.00	-
1	FRONT BONNET INSULATOR CLIPS	NOT NECESSARY	30.00	-
1	FRONT BONNET LOCK	NOT NECESSARY	90.00	-
1	FRONT BUMPER LOWER COVER (ADDITIONAL)	BROKEN	141.00	141.00
	LESS 25% DISCOUNT		-6,606.50	-1,560.03
			19,819.50	4,680.07
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT TYRE LH (SN) (70%)	TORN	280.00	196.00
1	FRONT RIM LH (SN)	BENT	350.00	200.00
1	RADIATOR COOLANT (SN)	NOT NECESSARY	120.00	-

Report Ref No. CS/INC19002578/Eqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR CON GAS (SN)	NECESSARY	150.00	100.00
			900.00	496.00
	LABOUR			
	TO KNOCK JACK OUT DAMAGED PARTS, PANEL BEATING WELDING, ALIGN, REFIX & TO REPLACE ACCIDENT PARTS. FRONT PORTION. INCLUSIVE OF THE REPAIR OF FRT DOOR LH AND FRONT BONNET.		2,200.00	600.00
	TO PUTTY, RESPRAY PAINTING AND POLISH AFFECTED AREAS. FRONT PORTION.		1,800.00	900.00
	TO RUST PROOF AFFECTED AREAS.	NOT NECESSARY	200.00	-
	TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD.		350.00	200.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	60.00
	TO REPLACE TYRE AND RIM, TYRE BALANCE.		150.00	30.00
	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND RECONNECT.		150.00	30.00
	TO REMOVE AND TRANSFER FRONT DOOR COMPONENTS LH.	NOT NECESSARY	180.00	-
	TO REMOVE & REFIT RADIATOR, CONDENSER TO ASSIST WORK LOAD.	NOT NECESSARY	180.00	-
			5,360.00	1,820.00
GRAND TOTAL			26,079.50	6,996.07
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				5,600.00

Report Ref No. CS/INC19002578/Eqd3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.