

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

Not Authorized
11 Days @ 2100h
Person After Rain
4 days

To: QBE Insurance International Ltd

Policy No: Third Party

Date: 11.02.2019

Accident Date : 10.02.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Vios" Reg. No. SGA2832P Claiming Against Your Insured Reg. No. GZ6432C		
1pc	Bonnet		<i>R</i> 497.00 —
1pc	Headlamp Assy RH		<i>Ro</i> 310.00 ✓
1pc	Headlamp Panel		<i>R</i> 559.00 X
1pc	Front Fender RH		<i>R</i> 516.00 ✓
1pc	Front Fender Shield		<i>CM</i> 127.00 —
10pcs	Front Fender Shield Clips	3.80	<i>na</i> 38.00 —
1pc	Front Bumper		<i>R</i> 311.00 —
10pcs	Front Bumper Clips	3.80	<i>na</i> 38.00 —
1pc	Front Bumper Bracket RH		<i>R</i> 52.20 X
1pc	Front Bumper Corner Retainer RH		<i>DR</i> 15.60 ✓
1pc	Front Bumper Fog Lamp RH		<i>ngcm</i> 215.00 ✓
1pc	Air Con Condenser Air Guide RH		<i>CM</i> 37.00 —
1pc	Grille		<i>na</i> 259.00 X
1pc	Grille Emblem		<i>na</i> 62.00 X
1pc	Front Wheel Bearing		<i>na</i> 171.00 X
1pc	Wiper Tank		<i>na</i> 97.00 X
1pc	Wiper Tank Motor		<i>na</i> 230.00 X
			3,534.80
	Less 25%		883.70
			2,651.10
1pc	Sport Rim		<i>na</i> 578.00 SN X
	To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc		30.00 <i>20</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		60.00 <i>3</i>
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		<i>na</i> 60.00 X
	To Remove / Refit Air Con Condenser & Refill Gas		<i>na</i> 120.00 X
	To Dismantle / Hi Pressure Press / Wheel Bearing		<i>na</i> 60.00 X
	To Dismantle / Replace Wheel Bearing (Dismantle Under Carriage)		<i>na</i> 70.00 X
	To Conduct Computerize Wheel Alignment Test		<i>na</i> 80.00 X
		C/F	3,709.10

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: QBE Insurance International Ltd

Policy No: Third Party

Date: 11.02.2019

Accident Date : 10.02.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Vios" Reg. No. SGA2832P Claiming Against Your Insured Reg. No. GZ6432C		
	To Conduct High Speed Balancing	B/F	3,709.10
	Labour Charge - Panel Beating, Replacement Of Fender, Front Door, Inner Panel, Bonnet Hinge, Cnt, Weld Headlamp Panel and Parts Replacement		60.00 X 900.00 450/
	To Respray Affected Areas		800.00 540/
	Total :		5,469.10

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: