



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block MND Complex, Singapore 069110 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Kor Choon Seng ADDRESS : 15 Woodlands Avenue 6 #11-11 Singapore 738995 TEL : 96411845MRS		LKK Auto Consultancy WIP : 42615 hence notify the insurer of the EXCESS : • To resurvey before/after spray painting DATE: 11-Feb-19 • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No legal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval by the Insurance Company Acknowledged by Repairer: THIRD PARTY CLAIM Signature: _____ Date: _____	
VEH NO :	SLT3509H	DATE IN :		CONTACT PERSON :	
CHASSIS NO :	JM6KF2WLAJ0129210	MILEAGE :	34698	TYPE OF CLAIM :	
MODEL :	CX5	DATE REG.:	26-Oct-17	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	REAR BUMPER / TV	1		\$ 1,218.00	
2	BRACKET CENTER X NN	1		\$ 5.10	
3	STAY LHS, REAR BUMPER / NCC NCC	1		\$ 24.10	
4	STAY RHS, REAR BUMPER X NN	1		\$ 24.10	
5	REFLECTOR LHS / SCR	1		\$ 200.80	
6	TOWING COVER LHS X NN	1		\$ 4.90	
7	REAR REINFORCEMENT / BT	1		\$ 495.20	
8	RETAINER, SENSOR X	3		\$ 44.10	
9	SENSOR CENTER, ULTRASONIC X NN	2		\$ 346.00	
10	SENSOR SIDE, ULTRASONIC X	1		\$ 193.90	
11	PAD, SENSOR / NCC.	3		\$ 22.20	
12	TAILGATE Repair X	1		\$ 1,559.00	
13	PROTECTOR, TAILGATE GARNISH	6		\$ 67.80	
14	PROTECTOR, TAILGATE GARNISH	1		\$ 11.30	
15	PROTECTOR, TAILGATE GARNISH	1		\$ 31.00	
16	PROTECTOR, TAILGATE GARNISH X NN	6		\$ 36.60	
17	CLIP, TAILGATE GARNISH	2		\$ 10.40	
18	TAPE, TAILGATE GARNISH	1		\$ 12.20	
19	TAPE, TAILGATE GARNISH	1		\$ 12.20	
20	PROTECTOR, TAILGATE GARNISH	2		\$ 14.00	
21	FASTENER, TAILGATE GARNISH	11		\$ 38.50	
22	CLIP, TAILGATE GARNISH	4		\$ 41.60	
23	CLIP, TAILGATE GARNISH	4		\$ 38.40	
24	PROTECTOR, TAILGATE GARNISH	2		\$ 24.40	
25	GROMMET, TAILGATE GARNISH	1		\$ 2.50	
26	SPACER, REAR WINDSCREEN	3		\$ 13.20	
27	FASTENER, REAR WINDSCREEN	2		\$ 14.00	
28	PIN, STUD, REAR WINDSCREEN	1		\$ 10.50	
29	FASTENER, REAR WINDSCREEN	4		\$ 10.40	
30	PROTECTOR, SPOILER	2		\$ 17.40	
31	PROTECTOR, SPOILER	1		\$ 23.80	

32	PROTECTOR, SPOILER	1	MKB8A-51-954	\$	23.90
33	PROTECTOR, SPOILER	5	MBHP2-51-954	\$	13.50
34	FASTENER, SPOILER	6	MKB8A-51-W24A	\$	21.00
35	FASTENER, SPOILER	3	MEG21-51-146	\$	17.70
36	GROMMET, SPOILER	2	MBF67-51-261	\$	4.40
37	CLIP, SPOILER	1	MGB02-67-014	\$	6.20
38	CLIP, SPOILER	3	MB01A-51-958	\$	10.20
39	CLIP, SPOILER	4	MKB8A-51-SJ3	\$	20.80
40	CLIP, SPOILER	2	MTK48-51-9M9	\$	8.80
41	CLIP, SPOILER	2	MKD53-51-0B6B	\$	5.00
42	CLIP, SPOILER	2	MKDY3-51-0A6C	\$	21.60
TOTAL PARTS				\$	4,720.70
LESS 10%				\$	472.07
TOTAL PARTS COST				\$	4,248.63

Labour Description				
1	MZ-BR-REAR04	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND TAILGATE. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	660	\$ 2,640.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE.	1260	\$ 2,520.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	NETT X	\$ 560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	NETT X	\$ 120.00
5	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.	X	\$ 660.00
6	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	330	\$ 660.00
7	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	X	\$ 660.00
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	X	\$ 250.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
11	MZ-BR-SUNDRI	SUNDRIES.	NETT 10.	\$ 100.00

TOTAL LABOUR	\$ -	\$ 8,770.00
TOTAL PARTS	\$ -	\$ 4,248.63
TOTAL	\$ -	\$ 13,018.63
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -

47 days.

before paint photos.

Geo Qianf - 82880282

14/2/19.

GRAND TOTAL	\$	-	\$	-
-------------	----	---	----	---

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD
THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF
REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING
CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED
WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED
ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS
PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature